

INS. CASE OWNER:

sheniti | CC4 / III1800 5786, A 263

LKK:
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

26/7/18

Date / Time:

27/7/18

Registered in Merimen:

26/7/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SH 7692P

Name of Insured : LTPV

Insured Tel No. : HP:

Excess Sec II : \$\$ D.O.A. : 26/7/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : TAN LIEW HEE

Driver Tel No. : (V/L: YES / NO)

SH 7692P → SH 7692P →



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

JEL
W611
YP

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

MIT 181155

MLOMVOIS

MERCEDES

LTA WAS LTA BY

BANKSTIEK RD

OI GIA REPORT: YES NO : TP GIA REPORT: YES NO

Insured Liability: % Final ? Yes / No

SFE 7AB



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

24/7/18
Agh 14

SH 7692P - 24/7/18 - 24/7/18 - 24/7/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: W/P

Repair Cost:

43 SS9,400

(

14 days)

Reduction:

63

%

Email

Call

FINAL SETTLEMENT

Date/Time: 28-6-18

Confirm with: BBA

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia : 100%

Repair Cost:

43 SS10,058.00

3 VEH C.C. ON LAST

Loss of Rental (LOR):

SS 1926.00

(

18 days)

x

100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4600

Total:

SS 11,984.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 28-6-18

Confirm with: BBA

Email

Call

Payee 1:

SS 11,984.00

Name 1:

V-TEL ASIA AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: III

ASSIGNMENT

22/01/10.
2010 Jan.

From: Date: 28/3/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SBN 2188G

at Workshop m/s V-Tec Automotive
of 8 Kaki Bkt Ave & #07-08/09

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

Perry @ 9610 9610

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SBN 2188G. Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante cc 1591

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 182282 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHDU418MAU962057

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Roadstone.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 96 mm L/Bal. 06 mm

D.O.A. D.O.I. 28/03/18.

Survey held at V-tec.

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

IP 111

45: \$ 9,400 (RED: + 16,018 63%)

MV: 20K

PV: 9.7K (9,743)

Nett: 10.3K (10,257)

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. S + RE. \$

1. Photos

1. Other

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III18005786/Aeb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 28-03-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7692P		Veh. Inspected	SBN 2188G
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	28/03/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/03/2018		Inspection Date	28/03/2018
Survey held at	V-TECH ASIA AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4, #07-08/09 PREMIER@KB S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No : SBN 2188 G

TP 111
Ashes

KMH DUAH BARAU 962057

ACCIDENT CAR REPAIR ESTIMATIONS

S/No.	Qty	Parts Descriptions	Condition	Per Unit	Our Estimates
Diagram 1 (Rear Boot)					
1	1 pc	Rear Truck Lid <i>Deformed</i>			\$1,600.00 907
2	2 pcs	Overslam Bumper <i>new</i>		\$15.00	\$30.00 +
4	1pc	Weather Strip <i>cut</i>			\$250.00 98
5	1pc	Latch Assembly <i>Deformed</i>			\$480.00 68
6	1pc	Striker <i>cut</i>			\$100.00 42.
7	2 pcs	Carplate Lamp Assembly <i>new</i>		\$40.00	\$80.00 +
9	1pc	Truck Lid Manual Key Assembly <i>new</i>			\$160.00 +
10	2pcs	LH & RH Hinge <i>cut</i>		\$160.00	\$320.00 264.
14	2 pcs	Torsion bar LH & RH <i>3 new</i>		\$120.00	\$240.00 +
15	1 pc	Torsion Bar Holder			\$20.00 +
	1 pc	Rear Reverse Camera <i>Deformed</i>			\$280.00 ✓
	2 pcs	Carplate Front & Back <i>cut</i>		\$50.00	\$100.00 60
	2 pcs	Carplate Holder <i>Deformed</i>		\$30.00	\$60.00 ✓
	1pc	Boot LH Carpet Cover <i>new</i>			\$60.00 +
	1pc	Rear Truck Lid Cushion <i>Deformed</i>			\$120.00 ✓
	1pc	Hyundai Emblem <i>3 new</i>			\$80.00 43
	1pc	Avante & S Emblem			\$120.00 85
	1 pc	Truck Lid Chrome Strip <i>Deformed</i>			\$60.00 ✓
	1 pc	Spare Tyre Top Cover <i>Deformed</i>			\$180.00 ✓
Diagram 2 (Front Bumper)					
1	1pc	Front Rear Bumper <i>Deformed</i>			\$800.00 453
2	4 pcs	Boot Cover Bolt <i>3 new</i>		\$5.00	\$20.00 +
3	4 pcs	Boot Cover Bolt		\$5.00	\$20.00 +
6	2 pcs	Outer Bracket LH & RH <i>new</i>		\$80.00	\$160.00 72.
9	1 pc	Bumper Grill <i>Deformed</i>			\$160.00 ✓
11	2 pcs	Bumper side cover LH & RH <i>new</i>		\$80.00	\$160.00 +
12	1 pc	Energy Absorber <i>Deformed</i>			\$280.00 113
13	4 pcs	Energy Absorber Clip LH & RH <i>new</i>		\$10.00	\$40.00 +
14	1 pc	Impact Bar <i>crushed</i>			\$680.00 254
15	4 pcs	Impact Bar Bolt <i>3 new</i>		\$10.00	\$40.00 +
17	1 pc	Upper Bracket LH & RH		\$80.00	\$160.00 366
		Front Grill Assembly <i>crushed</i>			\$720.00 45
		Hyundai Emblem <i>new</i>			\$80.00
Diagram 3 (Rear Bumper)					
1	1 pc	Rear Bumper <i>Deformed</i>			\$880.00 442

8	2 pcs	Rear Bumper Side Bracket RH & LH	Na	\$80.00	\$160.00 26
9	1 pc	Energy Absorber	Not in		\$360.00 *
10	1 pc	Rear Impact Bar	cracked		\$800.00 239.
11	2 pcs	Impact Bar Upper Bracket LH & RH	3 mod	\$20.00	\$40.00 ✓
12	1 pc	Impact Bar Lower Bracket			\$40.00 ✓
13	2 pcs	Stay Bracket	Bent	\$240.00	\$480.00 134
	2 pcs	Reverse Sensor	Range	\$120.00	✓ \$240.00 2nd (3rd)
	2 pcs	Rear Bumper Retainer	Not in	\$160.00	\$320.00 78
	2 pcs	Rear Lamp Assembly	cracked	\$360.00	\$720.00 ✓
	1 pc	Rubber Strap	Not in		\$80.00 *
* 1 set		Exhaust Pipe	?		1st 1980 * \$1,200.00 ? 598
Diagram 4 (Front Bonnet)					
	2 Pcs	Front Lamp Assembly	cracked.	\$360.00	\$720.00 ✓
1	1 pc	Front Hood	Derbed		\$1,600.00 1021
2	1 pc	Insulator Pad	Not in		\$600.00 *
8	1 pc	Latch Cover	Not in		\$28.00 ✓
9	1 pc	Support Rod	Not in		\$60.00 *
22	2 pcs	Hinge LH & RH	Bent.	\$120.00	\$240.00 ✓
	1 pc	Rear Wheel Mudguard	Not in		\$80.00 *
	2 pcs	Front LH & RH Fender	Buckled	\$360.00	\$720.00 ✓
	2 pcs	"VVT" Lettering	Not in	\$60.00	\$120.00 68.
Diagram 5 (Cooling System)					
1	1 Set	Fan Motor Assembly	cracked		\$900.00 519.
7	1 Pc	Radiator	Bent		\$480.00 ✓
10	1 Pc	Radiator Cap	Not in		\$80.00 *
13	1 Pc	Reservoir	Not in		\$360.00 *
14	1 Pc	Reservoir cap	Not in		\$60.00 *
	1 Pc	Condenser	Bent		\$360.00 ✓
	1 Set	Front Support Panel	cracked		\$780.00 ✓

Parts Total :

\$20,169.00

List : 10505

Less 20% : 8404



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4, #07-08/09 PREMIER@KB S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No :SBN 2188 G

LABOUR ESTIMATIONS

S/No.	Labour Descriptions	Our Estimates
1	To Straighten, Repair, Re-Alignment Rear Body Frame	\$1,500.00 1000
2	Spray Painting to Rear Boot, Rear Bumper, Front Hood Front Bumper	\$1,500.00 1400.
3	Labour charge for replacing of damaged parts	\$1,200.00 800
4	Labour charge for checking and diagnosing of Electrical Units	\$360.00 100
5	Towing Fee (5 Trips) 1. Accident Scene to Workshop, 2. Workshop to Reporting Centre, 3. Reporting Centre to Workshop due Coolant Leak 4. Tow to Panel Beating 5. Tow to Workshop for repair	\$750.00 600 3360.
Labour Total :		\$5,310.00
Parts Total :		\$20,168.00
Total (Parts & Labour) :		\$25,478.00

For Lump Sum Repairs

The estimated amount calculated is **\$ 25,478.00**

Under normal circumstances, the repairs should be completed within a reasonable period
Of **14 Working Days**. (Exclude waiting days of PRI, Sunday and Public Holiday)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Adrian King total 11764
28/03/18 h/s: 9.4k.
14 Days



V-TEC ASIA AUTOMOTIVE PTE LTD



Date : **24th April 2018**
To : India International Insurance
64 Cecil Street #06-02, IOB Building
(S) 49711

Our Contact : 8402 8402
Email : benjamin@vtecauto.com.sg
VEHICLE NO : **SBN2188G**
MAKE/MODEL : Hyundai Avante

Dear Sir / Madam,

Chang Boon Chui, Desmond

Apt Blk 336 Tampines Street 32 #04-486 (S)520336

ACCIDENT INVOLVING SBN2188G & SH7692P AT CTE BEFORE BALESTIER EXIT HEADING TWDS CITY

Date Of Accident: 23th March 2018 18:15

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 23th March 2018, at CTE BEFORE BALESTIER EXIT HEADING TWDS CITY, involving our Client's motor vehicle number SBN2188G & other motor vehicle SH7692P which was insured by you at the material time

We are instructed that the accident was caused by negligent driving and/or management of the motor vehicle by the driver of SH7692P. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1. Cost of Repairs	\$10,058.00
2. Rental (21 Days)	\$3,049.50
	\$13,107.50

We have on 26th March 2018 notified you of the accident and a pre-repair & after-repair inspection of our client's vehicle was carried out by your appointed surveyors

CHEQUE PAYMENT : **CHEQUE SHOULD BE CROSSED AND MAKE PAYABLE TO "V-TEC ASIA AUTOMOTIVE PTE LTD"**

For avoidance of doubt, kindly note that this claim is made without prejudice to our client's driver/passager's personal injury claims. Prices Above Are Inclusive Of GST

Warmest Regards ,

V-TEC ASIA AUTOMOTIVE PTE LTD

AUTHORIZATION TO ACT

(THIRD PARTY CLAIM)


To:

I, COOLMAC ENGINEERING PTE LTD ("The Third Party claimant") NRIC 199300145N of
1 KAKI BUKIT ROAD 1 #04-50 ENTERPRISE ONE SINGAPORE 415934 (address),
being the owner of SBN2188G (vehicle no.) hereby authorize
V-TEC ASIA AUTOMOTIVE PTE LTD ("the workshop") to act for me
with respect to my claim for repair cost and /or rental and/or loss of use ("claim") for my vehicle
bearing registration no. SBN2188G that was damaged pursuant to the accident
which occurred on 23/03/2018 along CTE BEFORE BALESTIER EXIT HEADING TWDS CITY
involving vehicles SBN2188G AND SH7692P ("the accident")

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability in so far as the driver/owner/insurers of the other vehicle is
concerned.

Dated this 26 day of MAR (month) 20 18 (year)

Signed by "the Third Party claimant"

Signed by "the workshop"



INDIA INTERNATIONAL INSURANCE PTE LTD

Co Reg No: 1987037426 | GST Reg No: M24070000X
#4 | Tech Street | #04 | #05 | #06-02 | 100 Building | Singapore 049311
Office: (65) 63476100 Email: insure@iill.com.sg
Fax: (65) 62244174 Website: www.iill.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18030755
Claimant Ref: SBN 2188G

We/I, V-TEC ASIA AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 10,058.00 (repair cost), S\$ 1,926.00 (loss of ~~use~~ rental), S\$ (search fee), vehicle no. SBN 2188G that was damaged pursuant to the accident which occurred on 23/03/2018 (date) at CTE BEFORE BALESTIER EXIT HEADIN TOWNS CITY (location) involving vehicle no. SH 7692P (insured vehicle). This is pursuant to the inspection conducted on 28/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner COOLMAC ENGINEERING PTE LTD ("the third party claimant") of vehicle no. SBN 2188G to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SBN 2188G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 11,984.00 to V-TEC ASIA AUTOMOTIVE PTE LTD.

Dated this 28 day of JUNE 2018

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

DEEN SHAMIN YEAP

NRIC:

S74350736

Address:

8 PAUL HANCOCK AVE 4
#02-05/09, MAMSA @ PG
131415525

Nationality:

SINGAPOREAN

Occupation:

MANAGER

WITNESS:

Signature:



LWP

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

Nationality:

Occupation:



V-TEC ASIA AUTOMOTIVE PTE LTD

INVOICE

C/O

V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4, #07-08/09 Premier@KB
SINGAPORE 415875

DATE OF ACCIDENT : 23th March 2018

Tel: 6635 2706

NO. : 1800026-VT

DATE : 26th April 2018

CLAIMANT : **Chang Boon Chui, Desmond**

VEHICLE NO : **SBN2188G**

MAKE/MODEL : Hyundai Avante

CLAIM TYPE : THIRD PARTY

Page : 1 of 1

S/N	Description	Quantity	Unit Price	Amount S\$
1	Lump sum Repairs as per recommendation	1 set	\$ 9,400.00	\$ 9,400.00
Eight Thousand Nine Hundred Only				Sub Total 9,400.00
				GST 7.00 % 658.00
				Amount to Paid 10,058.00

TERM AND CONDITIONS

PAYMENT : CREDIT CARD / CASH

WARRANTY : ALL NEW PARTS REPLACED C/W ONE(01) MONTH WARRANTY AGAINST MANUFACTURER UNLESS OTHERWISE STATED

CHEQUE PAYMENT : **CHEQUE SHOULD BE CROSSED AND MAKE PAYABLE TO "V-TEC ASIA AUTOMOTIVE PTE LTD"**

Thank you for your support, we glad to provide you with out service,
Kindly give us a feedback in our Facebook or in Sgcarmart =>

Warmest Regards ,

V-TEC ASIA AUTOMOTIVE PTE LTD

**V-TEC ASIA AUTOMOTIVE PTE LTD****TAX INVOICE**

COMPANY NAME :
BILLING ADDRESS :
(S)
ATTENTION : MR CHANG BOON CHUI , DESMOND
CONTACT :
EMAIL :

NO. : **18000218-VT**
DATE : 23 Mar 2018
TERM : **Cash On Delivery**
VEHICLE NO : **SJS 7473 D**
MAKE/MODEL : HONDA FIT
MILEAGE : -
CHASSIS NO: -


S/N	Description	Quantity	Unit Price S\$	Amount S\$
1	RENTAL OF HONDA FIT SJS 7473 D (23-03-2018 - 06-04-2018)	15 DAYS	\$ 130.00	\$ 1,950.00
2	RENTAL OF RENAULT LATITUDE SKC 6427 S (06-04-2018 - 11-04-2018)	6 DAYS	\$ 150.00	\$ 900.00
Date 25/8/2017 __/_/__ __/_/__ __/_/__ __/_/__ __/_/__ Payment Details ☐ Cash : \$ 1605.00 ☐ Visa : \$ _____ ☐ Mastercard : \$ _____ ☐ DBS/POSB Instalment : 6 Mths / 12 ☐ Cheque No : _____ \$ _____ ☐ Transfer : \$ _____ \$ _____ Sub Total \$2,850.00 GST 7% \$199.50 Total Amt \$3,049.50				

WARRANTY : ALL NEW PARTS REPLACED INCLUDE ONE MONTH WARRANTY AGAINST MANUFACTURER UNLESS OTHERWISE STATED
CHEQUE PAYMENT : **CHEQUE SHOULD BE CROSSED AND MAKE PAYABLE TO "V-TEC ASIA AUTOMOTIVE PTE LTD"**

Thank you for your support, we are glad to provide you with our service,
Kindly give us a feedback in our Facebook or in Sgcarmart =)

Warmest Regards ,

V-TEC ASIA AUTOMOTIVE PTE LTD



This Vehicle Leasing Agreement is made between V-TEC ASIA AUTOMOTIVE PTE LTD ("Owner") and
 ✓ Mr. CHANG BOON CHUI, DESMOND (Leasee) ID No: S8715016Z
 With Registered Address BLK 336 Tampines Street 32 #04-486
Singapore 520336 Contact No: 9170 1972
 The agreed starting date is from 06 04 2018 to 11 04 2018
 Total leasing rate, agreed at \$ (Total Leasing Period is months)

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2018 Edit Reg		27 Mar 2018 00:00 Edit Adj Rpt	\$9,400.00 Edit Estimates	\$9,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	COOLMAC ENGINEERING PTE LTD, Co. Reg. No.: 199300145N		
Vehicle Reg. No.:	SBN2188G	Date of Loss:	23/03/2018 18:00 - :59 [98 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18030755	Policy/Cover Note No.:	MCDM0015
Vehicle Reg. No. (Insured):	SH7692P	Policy No. (Claimant):	GA087423
		Excess:	
Repairer:	V-tec Asia Automotive Pte Ltd (HQ) 8 KAKI BUKIT AVE 4, #07-08/09 PREMIER@KB, 415875 Kaki Bukit - Tel: 66352706		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/04/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (07/06/2018): Alert - Adj Mandate Approved (\$11984.00) - SBN2188G - Claim Handler: Sherini Pl...
- III_SG (03/04/2018): Alert - Adj Mandate Approved (\$0.00) - SBN2188G - Claim Handler: Sherini Pillai

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBN2188G (MCT18030755)
[SH7692P]
TP
COOLMAC ENGINEERING PTE LTD
Mar 23 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
V-tec Asia Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	25/04/18 19:29	General View		Load JPG	☒					
2	25/04/18 19:29	General View		Load JPG	☒					
3	25/04/18 19:29	General View		Load JPG	☒					
4	25/04/18 19:29	General View		Load JPG	☒					
5	25/04/18 19:29	General View		Load JPG	☒					
6	25/04/18 19:29	General View		Load JPG	☒					
7	25/04/18 19:29	General View		Load JPG	☒					
8	25/04/18 19:29	General View		Load JPG	☒					
9	25/04/18 19:29	General View		Load JPG	☒					
10	25/04/18 19:29	General View		Load JPG	☒					
11	25/04/18 19:29	General View		Load JPG	☒					
12	25/04/18 19:29	General View		Load JPG	☒					
13	25/04/18 19:29	General View		Load JPG	☒					
14	25/04/18 19:29	General View		Load JPG	☒					
15	25/04/18 19:29	General View		Load JPG	☒					
16	25/04/18 19:29	General View		Load JPG	☒					
17	25/04/18 19:29	General View		Load JPG	☒					
18	25/04/18 19:29	General View		Load JPG	☒					
19	25/04/18 19:29	General View		Load JPG	☒					
20	25/04/18 19:29	General View		Load JPG	☒					
21	25/04/18 19:29	General View		Load JPG	☒					
22	25/04/18 19:29	General View		Load JPG	☒					
23	25/04/18 19:29	General View		Load JPG	☒					
24	25/04/18 19:29	General View		Load JPG	☒					
25	25/04/18 19:29	General View		Load JPG	☒					
26	25/04/18 19:29	General View		Load JPG	☒					
27	25/04/18 19:29	General View		Load JPG	☒					
28	25/04/18 19:29	General View		Load JPG	☒					
29	25/04/18 19:29	General View		Load JPG	☒					
30	25/04/18 19:29	General View		Load JPG	☒					
31	25/04/18 19:29	General View		Load JPG	☒					
32	25/04/18 19:29	General View		Load JPG	☒					
33	25/04/18 19:29	General View		Load JPG	☒					
34	25/04/18 19:29	General View		Load JPG	☒					
35	25/04/18 19:29	General View		Load JPG	☒					
36	25/04/18 19:29	General View		Load JPG	☒					
37	25/04/18 19:30	General View		Load JPG	☒					

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/04/18 19:30	General View	 Load JPG	☒
39	25/04/18 19:30	General View	 Load JPG	☒
40	25/04/18 19:30	General View	 Load JPG	☒
41	25/04/18 19:30	General View	 Load JPG	☒
42	25/04/18 19:30	General View	 Load JPG	☒
43	25/04/18 19:30	General View	 Load JPG	☒
44	25/04/18 19:30	General View	 Load JPG	☒
45	25/04/18 19:30	General View	 Load JPG	☒
46	25/04/18 19:30	General View	 Load JPG	☒
47	25/04/18 19:30	General View	 Load JPG	☒
48	25/04/18 19:30	General View	 Load JPG	☒
49	25/04/18 19:30	General View	 Load JPG	☒
50	25/04/18 19:30	General View	 Load JPG	☒
51	25/04/18 19:30	General View	 Load JPG	☒
52	25/04/18 19:30	General View	 Load JPG	☒
53	25/04/18 19:30	General View	 Load JPG	☒
54	25/04/18 19:30	General View	 Load JPG	☒
55	25/04/18 19:30	General View	 Load JPG	☒
56	25/04/18 19:30	General View	 Load JPG	☒
57	25/04/18 19:30	General View	 Load JPG	☒
58	25/04/18 19:30	General View	 Load JPG	☒
59	25/04/18 19:30	General View	 Load JPG	☒
60	25/04/18 19:30	General View	 Load JPG	☒
61	25/04/18 19:30	General View	 Load JPG	☒
62	25/04/18 19:30	General View	 Load JPG	☒
63	25/04/18 19:30	General View	 Load JPG	☒
64	25/04/18 19:30	General View	 Load JPG	☒
65	25/04/18 19:30	General View	 Load JPG	☒
66	25/04/18 19:30	General View	 Load JPG	☒
67	25/04/18 19:30	General View	 Load JPG	☒
68	25/04/18 19:30	General View	 Load JPG	☒
69	25/04/18 19:30	General View	 Load JPG	☒
70	25/04/18 19:30	General View	 Load JPG	☒
71	25/04/18 19:30	General View	 Load JPG	☒
72	25/04/18 19:30	General View	 Load JPG	☒
73	25/04/18 19:30	General View	 Load JPG	☒
74	25/04/18 19:30	General View	 Load JPG	☒
75	25/04/18 19:30	General View	 Load JPG	☒
76	25/04/18 19:30	General View	 Load JPG	☒
77	25/04/18 19:30	General View	 Load JPG	☒
78	25/04/18 19:30	General View	 Load JPG	☒
79	25/04/18 19:30	General View	 Load JPG	☒
80	25/04/18 19:30	General View	 Load JPG	☒
81	25/04/18 19:30	General View	 Load JPG	☒
82	25/04/18 19:30	General View	 Load JPG	☒
83	25/04/18 19:30	General View	 Load JPG	☒
84	25/04/18 19:30	General View	 Load JPG	☒
85	25/04/18 19:30	General View	 Load JPG	☒
86	25/04/18 19:30	General View	 Load JPG	☒
87	25/04/18 19:30	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	25/04/18 19:30	General View	 Load JPG	☒
89	25/04/18 19:30	General View	 Load JPG	☒
90	25/04/18 19:30	General View	 Load JPG	☒
91	25/04/18 19:30	General View	 Load JPG	☒
92	25/04/18 19:30	General View	 Load JPG	☒
93	25/04/18 19:30	General View	 Load JPG	☒
94	25/04/18 19:30	General View	 Load JPG	☒
95	25/04/18 19:30	General View	 Load JPG	☒
96	25/04/18 19:30	General View	 Load JPG	☒
97	25/04/18 19:30	General View	 Load JPG	☒
98	25/04/18 19:30	General View	 Load JPG	☒
99	25/04/18 19:30	General View	 Load JPG	☒
100	25/04/18 19:30	General View	 Load JPG	☒
101	25/04/18 19:30	General View	 Load JPG	☒
102	25/04/18 19:30	General View	 Load JPG	☒
103	25/04/18 19:30	General View	 Load JPG	☒
104	25/04/18 19:30	General View	 Load JPG	☒
105	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
106	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
107	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
108	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
109	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
110	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
111	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
112	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
113	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
114	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
115	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
116	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
117	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
118	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
119	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
120	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
121	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
122	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
123	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
124	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
125	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
126	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
127	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
128	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
129	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
130	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
131	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
132	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
133	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
134	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
135	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
136	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
137	25/04/18 19:30	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
138	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
139	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
140	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
141	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
142	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
143	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
144	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
145	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
146	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
147	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
148	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
149	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
150	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
151	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
152	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
153	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
154	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
155	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
156	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
157	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
158	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
159	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
160	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
161	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
162	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
163	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
164	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
165	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
166	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
167	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
168	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
169	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
170	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
171	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
172	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
173	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
174	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
175	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
176	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
177	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
178	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
179	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
180	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
181	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
182	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
183	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
184	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
185	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
186	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓
187	25/04/18 19:30	Reinspection Photo	1	Load JPG	✓

Photos/Images			3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
188	25/04/18 19:30	Reinspection Photo		Load JPG	☒
189	25/04/18 19:30	Reinspection Photo		Load JPG	☒
190	25/04/18 19:30	Reinspection Photo		Load JPG	☒
191	25/04/18 19:30	Reinspection Photo		Load JPG	☒
192	25/04/18 19:30	Reinspection Photo		Load JPG	☒
193	25/04/18 19:30	Reinspection Photo		Load JPG	☒
194	25/04/18 19:30	Reinspection Photo		Load JPG	☒
195	25/04/18 19:30	Reinspection Photo		Load JPG	☒
196	25/04/18 19:30	Reinspection Photo		Load JPG	☒
197	25/04/18 19:30	Reinspection Photo		Load JPG	☒
198	25/04/18 19:30	Reinspection Photo		Load JPG	☒
199	25/04/18 19:30	Reinspection Photo		Load JPG	☒
200	25/04/18 19:30	Reinspection Photo		Load JPG	☒
201	25/04/18 19:30	Reinspection Photo		Load JPG	☒
202	25/04/18 19:30	Reinspection Photo		Load JPG	☒
203	25/04/18 19:30	Reinspection Photo		Load JPG	☒
204	25/04/18 19:30	Reinspection Photo		Load JPG	☒
205	25/04/18 19:30	Reinspection Photo		Load JPG	☒
206	25/04/18 19:30	Reinspection Photo		Load JPG	☒
207	25/04/18 19:30	Reinspection Photo		Load JPG	☒
208	25/04/18 19:30	Reinspection Photo		Load JPG	☒
209	25/04/18 19:30	Reinspection Photo		Load JPG	☒
210	25/04/18 19:30	Reinspection Photo		Load JPG	☒
211	25/04/18 19:30	Reinspection Photo		Load JPG	☒
212	25/04/18 19:30	Reinspection Photo		Load JPG	☒
213	25/04/18 19:30	Reinspection Photo		Load JPG	☒
214	25/04/18 19:30	Reinspection Photo		Load JPG	☒
215	25/04/18 19:30	Reinspection Photo		Load JPG	☒
216	25/04/18 19:30	Reinspection Photo		Load JPG	☒
217	25/04/18 19:30	Reinspection Photo		Load JPG	☒
218	25/04/18 19:30	Reinspection Photo		Load JPG	☒
219	25/04/18 19:30	Reinspection Photo		Load JPG	☒
220	25/04/18 19:30	Reinspection Photo		Load JPG	☒
221	25/04/18 19:30	Reinspection Photo		Load JPG	☒
222	25/04/18 19:30	Reinspection Photo		Load JPG	☒
223	25/04/18 19:30	Reinspection Photo		Load JPG	☒
224	25/04/18 19:30	Reinspection Photo		Load JPG	☒
225	25/04/18 19:30	Reinspection Photo		Load JPG	☒
226	25/04/18 19:30	Reinspection Photo		Load JPG	☒
227	25/04/18 19:30	Reinspection Photo		Load JPG	☒
228	25/04/18 19:30	Reinspection Photo		Load JPG	☒
229	25/04/18 19:30	Reinspection Photo		Load JPG	☒
230	25/04/18 19:30	Reinspection Photo		Load JPG	☒
231	25/04/18 19:30	Reinspection Photo		Load JPG	☒
232	25/04/18 19:30	Reinspection Photo		Load JPG	☒
233	25/04/18 19:30	Reinspection Photo		Load JPG	☒
234	25/04/18 19:30	Reinspection Photo		Load JPG	☒
235	25/04/18 19:30	Reinspection Photo		Load JPG	☒
236	25/04/18 19:30	Reinspection Photo		Load JPG	☒
237	25/04/18 19:30	Reinspection Photo		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
238	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
239	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
240	25/04/18 19:30	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/18 17:11	EMAIL FROM III DD 27032018	 Load PDF	
2	28/03/18 17:11	TP GIA REPORT	 Load PDF	
3	30/05/18 17:01	WORKSHOP INVOICE	 Load PDF	
4	30/05/18 17:01	RENTAL RECEIPT	 Load PDF	
5	18/06/18 14:31	LOD - REVISED	 Load PDF	
6	11/07/18 11:05	AUTHORISATION TO ACT FORM	 Load PDF	
7	11/07/18 11:05	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 08:44	Singapore Accident Statement	 Load PDF	
2	25/04/18 08:56	LOD from V Tech	 Load PDF	
3	25/04/18 08:56	LOD from V Tech	 Load PDF	
4	25/04/18 08:56	LOD from V Tech	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18005786/AEB3Q2

Date: 11/07/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SBN2188G Insured Vehicle No: SH7692P
 Date of Loss: 23/03/2018 Nature of Claim: TP Claim No: MCT18030755

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBN2188G**
 Make & Model: HYUNDAI AVANTE, 1.6 HD (M) Engine No: G4FC9U797018
 Reg. Date: 22/01/2010 (Man. Year: 2009) Chassis No: KMHDU41BMAU962057
 Colour: Silver Odometer: 182282 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm
 Front Right Side: Roadstone 6 mm Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,168.00	8,404.00	11,764.00	58.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,310.00	3,360.00	1,950.00	36.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,478.00	11,764.00	13,714.00	53.83
Approved Total (Overridden) (S\$)		9,400.00		
(S\$)	25,478.00	9,400.00	16,078.00	63.11
+ GST 7.00/7.00% (S\$)	1,783.46	658.00	1,125.46	63.11
Nett Amount (S\$)	27,261.46	10,058.00	17,203.46	63.11
+ Car Rental (18.0 x S\$100.00/day + 7.00% GST) (S\$)		1,926.00		
Nett Liability (S\$)		11,984.00		

INSPECTION

Date of Assignment: 27/03/2018
 Date Inspected: 28/03/2018 Inspected At:

V-tec Asia Automotive Pte Ltd (HQ)
 8 KAKI BUKIT AVE 4, #07-08/09
 PREMIER@KB
 Singapore 415875

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2018)
Parts: 143	HYUNDAI AVANTE 1.6 HD (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SBN2188G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUCK LID	Dented	1,600.00 F	*907.00 FL
2	2		*OVERSLAM BUMPER	Not Necessary	30.00 F	*- FL
3	1		*WEATHER STRIP	Cut	250.00 F	*98.00 FL
4	1		*LATCH ASSEMBLY	Damaged	480.00 F	*68.00 FL
5	1		*STRIKER	Bent	100.00 F	*42.00 FL
6	2		*CARPLATE LAMP ASSEMBLY	Not Necessary	80.00 F	*- FL
7	1		*TRUCK LID MANUAL KEY ASSEMBLY	Not Necessary	160.00 F	*- FL
8	2		*LH & RH HINGE	Bent	320.00 F	*264.00 FL
9	2		*TORSION BAR LH & RH	Not Necessary	240.00 F	*- FL
10	1		*TORSION BAR HOLDER	Not Necessary	20.00 F	*- FL
11	1		*REAR REVERSE CAMERA	Damaged	280.00 F	*280.00 FL
12	2		*CARPLATE FRONT & BACK	Bent	100.00 F	*60.00 FL
13	2		*CARPLATE HOLDER	Deformed	60.00 F	*60.00 FL
14	1		*BOOT LH CARPET COVER	Not Necessary	60.00 F	*- FL
15	1		*REAR TRUNK LID CUSHION	Deformed	120.00 F	*120.00 FL
16	1		*HYUNDAI EMBLEM	Necessary	80.00 F	*43.00 FL
17	1		*AVANTE & S EMBLEM	Necessary	120.00 F	*85.00 FL
18	1		*TRUCK LID CHROME STRIP	Deformed	60.00 F	*60.00 FL
19	1		*SPARE TYRE TOP COVER	Deformed	180.00 F	*180.00 FL
20	1		*FRONT BUMPER	Deformed	800.00 F	*453.00 FL
21	4		*BOOT COVER BOLT	Not Necessary	20.00 F	*- FL
22	4		*BOOT COVER BOLT	Not Necessary	20.00 F	*- FL
23	2		*OUTER BRACKET LH & RH	Necessary	160.00 F	*72.00 FL
24	1		*BUMPER GRILL	Deformed	160.00 F	*160.00 FL
25	2		*BUMPER SIDE COVER LH & RH	Not Necessary	160.00 F	*- FL
26	1		*ENERGY ABSORBER	Deformed	280.00 F	*113.00 FL
27	4		*ENERGY ABSORBER CLIP LH & RH	Not Necessary	40.00 F	*- FL
28	1		*IMPACT BAR	Cracked	680.00 F	*254.00 FL
29	4		*IMPACT BAR BOLT	Not Necessary	40.00 F	*- FL
30	2		*UPPER BRACKET LH & RH	Not Necessary	160.00 F	*- FL
31	1		*FRONT GRILLE ASSEMBLY	Cracked	720.00 F	*366.00 FL
32	1		*HYUNDAI EMBLEM	Necessary	80.00 F	*45.00 FL
33	1		*REAR BUMPER	Distorted	880.00 F	*442.00 FL
34	2		*REAR BUMPER SIDE BRACKET LH & RH	Necessary	160.00 F	*26.00 FL
35	1		*ENERGY ABSORBER	Not Necessary	360.00 F	*- FL
36	1		*REAR IMPACT BAR	Cracked	800.00 F	*239.00 FL
37	2		*IMPACT BAR UPPER BRACKET LH & RH	Damaged	40.00 F	*40.00 FL
38	1		*IMPACT BAR LOWER BRACKET	Damaged	40.00 F	*40.00 FL
39	2		*STAY BRACKET	Bent	480.00 F	*134.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*REVERSE SENSOR	Damaged	240.00 F	*120.00 FL
41	2		*REAR BUMPER RETAINER	Necessary	320.00 F	*78.00 FL
42	2		*REAR LAMP ASSEMBLY	Cracked	720.00 F	*720.00 FL
43	1		*RUBBER STRAP	Not Necessary	80.00 F	*- FL
44	1		*SET EXHAUST PIPE	Not Necessary	1,200.00 F	*- FL
45	2		*FRONT LAMP ASSEMBLY	Cracked	720.00 F	*720.00 FL
46	1		*FRONT HOOD	Dented	1,600.00 F	*1,021.00 FL
47	1		*INSULATOR PAD	Not Necessary	600.00 F	*- FL
48	1		*LATCH COVER	Deformed	28.00 F	*28.00 FL
49	1		*SUPPORT ROD	Not Necessary	60.00 F	*- FL
50	2		*HINGE LH & RH	Bent	240.00 F	*240.00 FL
51	1		*REAR WHEEL MUDGUARD	Not Necessary	80.00 F	*- FL
52	2		*FRONT LH & RH FENDER	Buckled	720.00 F	*720.00 FL
53	2		*VVT LETTERING	Necessary	120.00 F	*68.00 FL
54	1		*SET FAN MOTOR ASSEMBLY	Cracked	900.00 F	*519.00 FL
55	1		*RADIATOR	Bent	480.00 F	*480.00 FL
56	1		*RADIATOR CAP	Not Necessary	80.00 F	*- FL
57	1		*RESERVOIR	Not Necessary	360.00 F	*- FL
58	1		*RESERVOIR CAP	Not Necessary	60.00 F	*- FL
59	1		*CONDENSER	Bent	360.00 F	*360.00 FL
60	1		*SET FRONT SUPPORT PANEL	Cracked	780.00 F	*780.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	20,168.00	10,505.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	2,101.00
Total Parts (\$\$)	20,168.00	8,404.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN ,REPAIR ,RE-ALIGNMENT REAR BODY FRAME	New	1,500.00	1,000.00
2	SPRAY PAINTING TO REAR BOOT ,REAR BUMPER ,FRONT HOOD FRONT BUMPER	New	1,500.00	1,400.00
3	LABOUR CHARGE FOR REPLACING OF DAMAGED PARTS	New	1,200.00	800.00
4	LABOUR CHARGE FOR CHECKING AND DIAGNOSING OF ELECTRICAL UNITS	New	360.00	100.00
5	TOWING FEE (5 TRIPS) -1) ACCIDENT SCENE TO WORKSHOP,2) WORKSHOP TO REPORTING CENTRE,3) REPORTING CENTRE TO WORKSHOP DUE COOLANT LEAK,4) TOW TO PANEL BEATING,5) TOW TO WORKSHOP FOR REPAIR	New	750.00	60.00
Gross Labour Cost (S\$)			5,310.00	3,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >