CQMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHD 4255P

MAKE



MODEL	: HYUNDAI SONATA		,		1
Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 578.40	
	Rear Bumper Reinforcement			\$ 483.30	
	Rear Bumper Clip — ***			\$ 22.00	
	Rear Bumper Sponge Rear Bumper Under Cover			\$ 137.40	
	Rear Bumper Under Cover			\$ 185.80	
	Rear Bumper Protector (LH/RH) Utskir Nuv	679	\$ 38.00	\$ 76.00	
	SUB TOTAL			\$ 1,482.90	-
	LESS 20%			\$ 296.58	
	DISCOUNTED TOTAL			\$ 1,186.32	1
				1000 0000 000 000 000 000 000 000 000 0	
	Rear Bumper Reverse Sensor X 555			\$ 135.70	
	Rear Bumper Rubber Mat			\$ 50.00	
	Rear Bumper Advertisement Logo			\$ 50.00	
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
			,	\$ 435.70	-
				0 100170	1
	Labour Charge			7.00	
	Panel Beating			\$ 250.00	
	Spray Painting Charge			\$ 250.00	200
	Wiring Charge			\$ 50.00	14.
	Remove/Refix Reverse Sensor			\$ 120.00	20
			*	6 (70.00	-
	TOTAL LABOUR	R		\$ 670.00	+
	ESTIMATE TOTAL			\$ 2,292.02	
	23.1				7
	Kaluz ((KK)				
			-		-
	2 2/3/18 11.05h		LKK Auto Consultants I the Repairer of the follo		
	// 24/3/8 1105h		To resurvey before after sp	ray painti ng	
			To display damaged part s Parts prices are subject to		
	2 /274		Third party - Till a chall	a Plandise" bas	is
			No illegal must succept as Successor as a mass or a second successor.		
	45 Affer Regar P.	1/	Suppliers the mask to a specific suppliers		a,
	1. M. Kep of P.		Acknowled		
	Alm		Signat ret		
			Date		+
	This is an initial estimate based on a visual inspection of	the above v	ehicle The final repair	quantum will	