

Attn: Motor Claim Dept

Date : Pages : 1 - 7

ACCIDENT REPAIR ESTIMATES

X 3rd Party Make & Model : MAZDA BI Windscreen Year of Manufacture : Chassis No. : JM6CC10 Ins Company : AIG ASIA PACIFIC INS PTE LTD Engine No. : PE3 Excess Policy No. : SD18V017 Date of Accident : 23/3/2018 Time of Accident : Suggested Days of Repair : 7 DAYS In-house Vehicle Assessor Repair Estimates Name Document	
Windscreen Year of Manufacture Chassis No. : JM6CC10 Ins Company : AIG ASIA PACIFIC INS PTE LTD Excess : Policy No. : SD18V017 Date of Accident : 23/3/2018 Suggested Days of Repair : 7 DAYS Repair Estimates Name : Do Signature Parts (a) Cost / List Price Items Plus/Less	W6886C
Ins Company : AIG ASIA PACIFIC INS PTE LTD	ANTE 5-DOOR
Ins Company	2016
Ins Company : AIG ASIA PACIFIC INS PTE LTD	71G0110571
Policy No. SD18V017	1005913
Date of Accident : 23/3/2018 Time of Accident : 1 Suggested Days of Repair : 7 DAYS In-house Vehicle Assessor Repair Estimates Name : Do Parts (a) Cost / List Price Items Contact No : E- mail : Less%	743/VPC2/R00
Suggested Days of Repair : 7 DAYS In-house Vehicle Assessor Repair Estimates Name : Do Signature : Contact No : E- mail : Less	1830
Parts (a) Cost / List Price Items Signature	
Plus/Less	oreen
Contact No	
Less %	
(c) Special Nett Items	
Total Parts Cost (Appendix A) \$0.00	
Labour (Appendix B)	
Total Repair Cost \$0.00	
The above total will be subjected to 7% G.S.T.	
Name of Surveyor Rame (LKK) Company	
Survey conducted on : 03/04/18 at 1150	
Remarks By Surveyor	_
(a) The repair of this vehicle is authorized / is not authorized until further notice.	
(b) Recommended Days of Repair : day(s)	
(c) Resurvey Required 64 point	
(d) Excess :\$	- 1
(e) Signature of surveyor : Date: 03/04/08	- 1

This is an initial estimate based on a visual inspection of the above mentioned vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company



	1.100.00	COLAG	Sei
Spare	Parts		

Vehicle No. : Make & Model MAZD	SDW6886C	Submit By :	Doreen
Chassis No. :	JM6CC1071G0110571	Year Manufactur:	2016
	100110071	Engine No. : Cost / List	PE31005913

S/No	Part Description	Qty	ost / List		
1	REAR BUMPER	4.9	Price	Amount	Disposition by Surveyor
	REAR BUMPER CHROME RHS	1	\$1,114.70	\$1,114.70	sul/
3	REAR BUMPER CLIPS	1	\$89.00	\$89.00	n-
	EN CLIPS	10	\$3.50	\$35.00	re -
		+		\$1,238.70	•
Ī	ABOUR				
1 L	ABOUR TO REMOVE AND REPLACE REAR	\Box			
В	UMPER		\$100.00		
2 T	O PANEL BEAT RHS REAR FENDER		\$80.00		60
3 TO	PUTTY AND SPRAY PAINT REAR FENDER,				00
BL	JMPER	\vdash	\$400.00		- /
			\$400.00		360
TO	PUTTY AND SPRAY PAINT REAR RHS TYRE				
RI	M		\$80.00		250
+	KASUL				20
	HP 9001006X	-			
	3 days				
-	10	+			
	4/1			KK Auto Consi he Repairer of	itants nence notify
	03/04/18 @1150			To display display	and spray painting
10			- 1:	Parts prices are su	blect to confirmation

Note: If any of the quoted parts are recommended to be repaired, then an additional appropriate under supplementary.

*Note: If any of the quoted parts are recommended to be repaired, then an additional appropriate under supplementary.

*Note: If any of the quoted parts are recommended to be repaired, then an additional appropriate under supplementary.

*Note: If any of the quoted parts are recommended to be repaired, then an additional appropriate under supplementary.

*Note: If any of the quoted parts are recommended to be repaired, then an additional appropriate under supplementary.

*Note: If any of the quoted parts are recommended to be repaired, then an additional appropriate under supplementary.

*Note: If any of the quoted parts are recommended to be repaired, then an additional appropriate under supplementary.

Remy 54 print

Acknowledged by Repairer

Signature: Date: