

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0380/2018/JT  
**Date** : 28-Mar-18

**Vehicle IN workshop. Kindly arrange for survey.**

### **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Ling Yong Wah  
**Address** : 1F Shelford Road  
#04-43  
Singapore 286891  
**Telephone** : HP +65 9732 1397  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 2100306561-05000  
**Vehicle No** : **SGU 3899 K**  
**Model Code** : Audi S5 Cab 3.0 TFSI qu  
**Model / Year** : Jul-12  
**Engine No** : CGW 043655  
**Chassis No** : WAUZZZ8F2CN012309  
**Mileage** :  
**Date In** : 27-Mar-18  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 23-Mar-18  
**Place of Accident** : Traffic junction at Paya Lebar road & Ubi Ave 3

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SGU 3899 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horn, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To remove and transfer aircond condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system.	S/N \$ 1,200.00 ✓	
3	To dismantle front bumper, both front fender and bonnet. Renew front lock carrier and align to	\$ <del>5,400.00</del>	<del>3750</del> 3750 .
4	To respray front bumper, both front fender and bonnet. ✓	\$ <del>3,000.00</del>	2200
5	To carry out diagnostic checks.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 10,272.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SGU 3899 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 2,635.00	✓
2	LOWER GRILLE <i>new</i>	\$ 295.00	x
3	AIR GRILLE - RHS/LHS <i>RH Missing, LH?</i>	\$ <del>614.00</del>	307.
4	RADIATOR GRILLE <i>crushed</i>	\$ 1,954.00	✓
4	FOAM PIECE <i>Rehd</i>	\$ 109.00	✓
5	FRONT REINFORCEMENT BEAM <i>Beut</i>	\$ 770.00	✓
6	REINFORCEMENT BRACKET - LHS/RHS <i>?</i>	\$ 390.00	?
7	BUMPER SUPPORT <i>Byd</i>	\$ 21.00	✓
8	TOP COVER <i>crushed</i>	\$ 109.00	✓
9	CAUTION SIGN <i>n</i>	\$ 12.00	✓
10	PARKING AID <i>Missing</i>	\$ 211.00	✓
11	FRONT FENDER - LHS/RHS <i>crushed</i>	\$ 1,860.00	✓
12	FRONT FENDER INNER BRACKET - LHS/RHS <i>new</i>	\$ 100.00	+
13	FRONT FENDER OUTER BRACKET - LHS/RHS <i>new</i>	\$ 100.00	x
14	RIVET <i>n</i>	16 \$ 48.00	✓
15	FRONT FENDER BRACE - LHS/RHS <i>new</i>	\$ 212.00	x
16	"V6T" EMBLEM <i>n</i>	\$ 215.00	✓
17	HEADLIGHT - LHS/RHS <i>crushed</i>	\$ 4,682.00	✓
18	HEADLIGHT BRACKET - LHS/RHS <i>?</i>	\$ 184.00	?
19	HEADLIGHT MOUNTING - LHS/RHS <i>?</i>	\$ 218.00	?
20	HEADLIGHT WASHER - LHS/RHS <i>?</i>	\$ 482.00	?
<b>SUB-TOTAL SPARE PARTS</b>		<b>\$ 15,221.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SGU 3899 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	ELBOW FITTING <i>New</i>	2 \$	45.00 ✗
22	BONNET <i>Distorted</i>	\$	2,499.00 ✓
23	BONNET CATCH HOOK <i>new</i>	\$	122.00 ✗
24	BONNET SEAL <i>new</i>	\$	24.00 ✓
25	BONNET SWITCH <i>new</i>	\$	188.00 ✗
26	A/C STICKER <i>new</i>	\$	21.00 ✓
27	LOCK CARRIER <i>Cont'd</i>	\$	923.00 ✓
28	LOCK CARRIER AIR GUIDE - LHS/RHS ?	\$	40.00 ?
29	A/C CONDENSER <i>Best</i>	\$	461.00 ✓
30	A/C CONDENSER VALVE ?	\$	46.00 ?
31	PRESSURE SENDER ?	\$	165.00 ?
32	RADIATOR <i>Best</i>	\$	1,439.00 ✓
33	RADIATOR BUSH ?	6 \$	41.00 ?
34	RADIATOR SUPPORT ?	\$	66.00 ?
35	COOLANT <i>new</i>	\$	134.00 ✓
36	FRONT NUMBER PLATE <i>Best</i>	S/N \$	25.00 ✓
37	SUNDRIES ?	\$	400.00 ?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 21,860.00</b>
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 10,272.00</b>
<b>GRAND TOTAL</b>		:	<b>\$ 32,132.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lim  
Surveyed Date : 28/03/18.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 10 Days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant