

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0380/2018/JT  
**Date** : 28-Mar-18

**Vehicle IN workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Ling Yong Wah  
**Address** : 1F Shelford Road  
#04-43  
Singapore 286891  
**Telephone** : HP +65 9732 1397  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 2100306561-05000  
**Vehicle No** : **SGU 3899 K**  
**Model Code** : Audi S5 Cab 3.0 TFSI qu  
**Model / Year** : Jul-12  
**Engine No** : CGW 043655  
**Chassis No** : WAUZZZ8F2CN012309  
**Mileage** :  
**Date In** : 27-Mar-18  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 23-Mar-18  
**Place of Accident** : Traffic junction at Paya Lebar road & Ubi Ave 3

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SGU 3899 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horn, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To remove and transfer aircond condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system.	S/N \$ 1,200.00 ✓	✓
3	To dismantle front bumper, both front fender and bonnet. Renew front lock carrier and align to ✓	\$ 5,400.00 ✓	<del>3750</del> 3750 ✓
4	To respray front bumper, both front fender and bonnet. ✓	\$ 3,000.00 ✓	2200 ✓
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 10,272.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SGU 3899 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 2,635.00	✓ 2108
2	LOWER GRILLE <i>new</i>	\$ 295.00	✗
3	AIR GRILLE - RHS/LHS <i>RH Missing, LH? X Not Nec</i>	\$ <del>614.00</del>	307 245.00
4	RADIATOR GRILLE <i>cluded</i>	\$ 1,954.00	✓ 1563.00
4	FOAM PIECE <i>Rehd</i>	\$ 109.00	✓ 87.00
5	FRONT REINFORCEMENT BEAM <i>Best</i>	\$ 770.00	✓ 616
6	REINFORCEMENT BRACKET - LHS/RHS <i>Not Nec.</i>	\$ 390.00	? X
7	BUMPER SUPPORT <i>Byd</i>	\$ 21.00	✓ 16.80
8	TOP COVER <i>cluded</i>	\$ 109.00	✓ 87.00
9	CAUTION SIGN <i>n</i>	\$ 12.00	✓ 9.08
10	PARKING AID <i>Missing</i>	\$ 211.00	✓ 168.40
11	FRONT FENDER - LHS/RHS <i>Replaced</i>	\$ 1,860.00	✓ 744
12	FRONT FENDER INNER BRACKET - LHS/RHS <i>new</i>	\$ 100.00	+
13	FRONT FENDER OUTER BRACKET - LHS/RHS <i>new</i>	\$ 100.00	✗
14	RIVET <i>n</i>	16 \$ 48.00	✓ 38.40
15	FRONT FENDER BRACE - LHS/RHS <i>new</i>	\$ 212.00	✗
16	"V6T" EMBLEM <i>the</i>	\$ 215.00	✓ 172
17	HEADLIGHT - LHS/RHS <i>cluded</i>	\$ 4,682.00	✓ 3745.60
18	HEADLIGHT BRACKET - LHS/RHS <i>RH cluded</i>	\$ 184.00	? 73.52
19	HEADLIGHT MOUNTING - LHS/RHS <i>cluded.</i>	\$ 218.00	? 174.40
20	HEADLIGHT WASHER - LHS/RHS <i>Not Nec.</i>	\$ 482.00	? X
<b>SUB-TOTAL SPARE PARTS</b>		<b>\$ 15,221.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SGU 3899 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	ELBOW FITTING <i>New</i>	2 \$	45.00 <i>x.</i>
22	BONNET <i>Distorted</i>	\$	2,499.00 <i>✓</i> 1999.00
23	BONNET CATCH HOOK <i>new</i>	\$	122.00 <i>x</i>
24	BONNET SEAL <i>new</i>	\$	24.00 <i>✓</i> 18.98
25	BONNET SWITCH <i>new</i>	\$	188.00 <i>x.</i>
26	A/C STICKER <i>new</i>	\$	21.00 <i>✓</i> 16.16
27	LOCK CARRIER <i>cond.</i>	\$	923.00 <i>✓</i> 738.40
28	LOCK CARRIER AIR GUIDE - LHS/RHS <i>Reband.</i>	\$	40.00 <i>?</i> 31.84
29	A/C CONDENSER <i>Best</i>	\$	461.00 <i>✓</i> 520.40
30	A/C CONDENSER VALVE <i>Not nec</i>	\$	46.00 <i>?</i> <i>x</i>
31	PRESSURE SENDER <i>Not nec.</i>	\$	165.00 <i>?</i> <i>x</i>
32	RADIATOR <i>Best</i>	\$	1,439.00 <i>✓</i> 1151.00
33	RADIATOR BUSH <i>the new</i>	6 \$	41.00 <i>?</i> <i>x</i>
34	RADIATOR SUPPORT <i>the new</i>	\$	66.00 <i>?</i> <i>x</i>
35	COOLANT <i>new</i>	\$	134.00 <i>✓</i> 106.24
36	FRONT NUMBER PLATE <i>Best</i>	S/N \$	25.00 <i>✓</i> 25
37	SUNDRIES <i>Nec.</i>	\$	400.00 <i>?</i> 58.48
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 21,860.00</b>
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 10,272.00</b>
<b>GRAND TOTAL</b>		:	<b>\$ 32,132.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lim  
Surveyed Date : 28/03/18.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 10 Days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0380/2018/JT  
Date : 28-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Hi Adrian,  
10 days repair ok - Carrine 17/09/2019

Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ling Yong Wah  
Address : 1F Shelford Road  
#04-43  
Singapore 286891  
Telephone : HP + 65 9732 1397  
Type of Claim : Own Damage Claim  
Policy No. : 2100306561-05000  
Vehicle No : **SGU 3899 K**  
Model Code : Audi S5 Cab 3.0 TFSI qu  
Model / Year : Jul-12  
Engine No : CGW 043655  
Chassis No : WAUZZZ8F2CN012309  
Mileage :  
Date In : 27-Mar-18  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 23-Mar-18  
Place of Accident : Traffic junction at Paya Lebar road & Ubi Ave 3

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SGU 3899 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horn, fog lamps, outside temperature sensor headlight washer assv	S/N \$ 480.00	\$ 480.00
2	To remove and transfer aircond condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system	S/N \$ 1,200.00	\$ 1,200.00
3	To dismantle front bumper, both front fender and bonnet. Renew front lock carrier	\$ 5,400.00	\$ 3,750.00
4	To respray front bumper, both front fender and bonnet.	\$ 3,000.00	\$ 2,200.00
5	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 10,272.00	\$ 7,822.00

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SGU 3899 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,635.00	\$ 2,108.00
2	LOWER GRILLE	\$ 295.00	
3	AIR GRILLE - RHS/LHS	\$ 614.00	\$ 245.20
4	RADIATOR GRILLE	\$ 1,954.00	\$ 1,563.20
4	FOAM PIECE	\$ 109.00	\$ 87.20
5	FRONT REINFORCEMENT BEAM	\$ 770.00	\$ 616.00
6	REINFORCEMENT BRACKET - LHS/RHS	\$ 390.00	
7	BUMPER SUPPORT	\$ 21.00	\$ 16.80
8	TOP COVER	\$ 109.00	\$ 87.20
9	CAUTION SIGN	\$ 12.00	\$ 9.28
10	PARKING AID	\$ 211.00	\$ 168.40
11	FRONT FENDER - LHS/RHS	\$ 1,860.00	\$ 744.00
12	FRONT FENDER INNER BRACKET - LHS/RHS	\$ 100.00	
13	FRONT FENDER OUTER BRACKET - LHS/RHS	\$ 100.00	
14	RIVET	16 \$ 48.00	\$ 38.40
15	FRONT FENDER BRACE - LHS/RHS	\$ 212.00	
16	"V6T" EMBLEM	\$ 215.00	\$ 172.00
17	HEADLIGHT - LHS/RHS	\$ 4,682.00	\$ 3,745.60
18	HEADLIGHT BRACKET - LHS/RHS	\$ 184.00	\$ 73.52
19	HEADLIGHT MOUNTING - LHS/RHS	\$ 218.00	\$ 174.40
20	HEADLIGHT WASHER - LHS/RHS	\$ 482.00	
<b>SUB-TOTAL SPARE PARTS</b>		<b>\$ 15,221.00</b>	<b>\$ 9,849.20</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SGU 3899 K.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 9,849.20
21	ELBOW FITTING	2	\$ 45.00	
22	BONNET		\$ 2,499.00	\$ 1,999.20
23	BONNET CATCH HOOK		\$ 122.00	
24	BONNET SEAL		\$ 24.00	\$ 18.88
25	BONNET SWITCH		\$ 188.00	
26	A/C STICKER		\$ 21.00	\$ 16.16
27	LOCK CARRIER		\$ 923.00	\$ 738.40
28	LOCK CARRIER AIR GUIDE - LHS/RHS		\$ 40.00	\$ 31.84
29	A/C CONDENSER		\$ 461.00	\$ 520.40
30	A/C CONDENSER VALVE		\$ 46.00	
31	PRESSURE SENDER		\$ 165.00	
32	RADIATOR		\$ 1,439.00	\$ 1,151.20
33	RADIATOR BUSH	6	\$ 41.00	
34	RADIATOR SUPPORT		\$ 66.00	
35	COOLANT		\$ 134.00	\$ 106.24
36	FRONT NUMBER PLATE	S/N	\$ 25.00	\$ 25.00
37	SUNDRIES		\$ 400.00	\$ 58.48
	<b>TOTAL SPARE PARTS</b>	:	<b>\$ 21,860.00</b>	<b>\$ 14,515.00</b>
	<b>TOTAL LABOUR CHARGES</b>	:	<b>\$ 10,272.00</b>	<b>\$ 7,822.00</b>
	<b>GRAND TOTAL</b>	:	<b>\$ 32,132.00</b>	<b>\$ 22,337.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SGU 3899 K**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/0380/2018/NH

6<sup>TH</sup> JAN 2020

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

Dear Sir,

**RE: INSURANCE CLAIM FOR SGU 3899 K, Audi S5 CAB 3.0 TFSI qu.**

With reference to the above-mentioned vehicle, no. **SGU 3899 K**, claimant, **Mr. Ling Yong Wah**, please find the related document per attached.

1. A copy of the Original invoice no. 85014666 – S\$ 21,760.59.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai  
Claims Dept

Encl  
AIG – SGU 3899 K

total pages

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6336 2323  
Telefax (65) 684 11183

# Premium Automobiles Pte Ltd



**Audi Centre Singapore**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6836 2223  
Main Telefax 6471 3733

**Alexandra Service Centre**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6388 2223  
Main Telefax 6475 1023

**Ubi Service Centre**  
55 Ubi Road 1  
Singapore 408699  
Main Telephone 6388 2323  
Main Telefax 6841 1183

**Customer Service**  
Service Appointment 6366 2323  
24-hour Breakdown Service 9828 1233  
Email customer.care@premiumauto.com.sg

## INS TAX INVOICE

Page 1 13:26

Company Reg. No. 199902271W  
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	<b>Invoice No:</b> 85014666	<b>Account:</b> A0006 (T 0)
	<b>Date :</b> 31/12/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	<b>Order :</b> SGU3899K	
	<b>Term :</b> 30	

**Regn No:** SGU3899K (V 18366) **Regn Date:** 10/07/2012 **Mileage:** 136276 **WIP No.:** 60313

**Model:** S5 CAB 3.0 TFSI QU 8F7S4Y (YOM) **Chassis:** WAUZZZ8F2CN012309 **Engine:** CGW 043655 **Dept:** U

You have been assisted by :- UB-Tony Foong ( 33 )

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-2000.00	1.00	-2,000.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORN, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AI	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCOND CONDENSER, RADIATOR ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL U TO CARRY OUT VACUUM / REGAS AND TO PRESSURIZE COOL SYSTEM.	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, RHS FRONT FENDER, HEADLIGHTS AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	3750.00	1.00	3,750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER AND BONNET.	2200.00	1.00	2,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECKS.	192.00	1.00	192.00
X	A8T0807065F GRU	COVER	Less 020%	1.00	2635.00
X	A8T0807682M 01C	GRILL (V)	Less 020%	1.00	306.50
X	A8T0853651N 1RR	RADGRILLE	Less 020%	1.00	1954.00
X	A8T0807550L	FOAM INSER	Less 020%	1.00	109.00
X	A8K0807113F	BEAM	Less 020%	1.00	770.00
X	A8K0807333B	SUPPORT	Less 020%	2.00	10.50
X	A8T0807081B	COVER (V)	Less 020%	1.00	109.00
X	A8K0010520A	PLATE	Less 020%	1.00	11.60
X	A1S0919275C GRU	SENSOR	Less 020%	1.00	210.50
X	A8T0821106H	FENDER	Less 020%	1.00	930.00
					744.00

# Premium Automobiles Pte Ltd



**Audi Centre Singapore**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6836 2223  
Main Telefax 6471 3733

**Alexandra Service Centre**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6388 2223  
Main Telefax 6475 1023

**Ubi Service Centre**  
55 Ubi Road 1  
Singapore 408699  
Main Telephone 6388 2323  
Main Telefax 6841 1183

**Customer Service**  
Service Appointment 6366 2323  
24-hour Breakdown Service 9828 1233  
Email customer.care@premiumauto.com.sg

## INS TAX INVOICE

Page 2 13:26

Company Reg. No. 199902271W  
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014666	Account: A0006 (T 0)
	Date : 31/12/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SGU3899K	
	Term : 30	

Regn No: SGU3899K (V 18366)	Regn Date: 10/07/2012	Mileage: 136276	WIP No.: 60313
Model: S5 CAB 3.0 TFSI QU 8F7S4Y (YOM)	Chassis: WAUZZZ8F2CN012309	Engine: CGW 043655	Dept: U
You have been assisted by :- UB-Tony Foong ( 33 )			

	Details	Qty	Unit Price	Amount		
X	AN 0161857	POP-RIVET	Less 020%	8.00	1.40	8.96
X	A8K0853601	INSCRIPTION 'V6T'	Less 020%	2.00	107.50	172.00
X	A8T0941753A	HEADLAMP	Less 020%	1.00	2341.00	1,872.80
X	A8T0941754A	HEADLAMP (V)	Less 020%	1.00	2341.00	1,872.80
X	A8T0941454D	BRACKET	Less 020%	1.00	91.90	73.52
X	A8T0805607D	MOUNTING	Less 020%	1.00	109.00	87.20
X	A8T0805608D	MOUNTING	Less 020%	1.00	109.00	87.20
X	A8T0823029H	HOOD	Less 020%	1.00	2499.00	1,999.20
X	A8T0823126J	EDGING	Less 020%	1.00	23.60	18.88
X	A8K0010515BF	STICKER	Less 020%	1.00	20.20	16.16
X	A8F0805594	CARRIER (V) (G)	Less 020%	1.00	923.00	738.40
X	A8T0121283T	AIR DUCT	Less 020%	1.00	19.90	15.92
X	A8T0121284T	AIR DUCT	Less 020%	1.00	19.90	15.92
X	A8T0260403C	CONDENSER (V)	Less 020%	1.00	650.50	520.40
X	A7H0820896	SEAL	Less 020%	1.00	2.30	1.84
X	A4E0260749A	WASHER	Less 020%	1.00	3.20	2.56
X	A4E0260749B	WASHER	Less 020%	1.00	4.20	3.36
X	A8K0121251AL	RADIATOR	Less 020%	1.00	1439.00	1,151.20
X	AWHT001506A	BOLT	Less 020%	2.00	1.50	2.40
X	AG A13A8JM1	COOLANT ADDITIVE	Less 020%	4.00	33.20	106.24
X	A8K0820536D	BRACKET	Less 020%	1.00	15.60	12.48
X	AN 90765701	RIVET	Less 020%	4.00	1.30	4.16
X	A8T0941741	COUPLPIECE	Less 020%	1.00	28.40	22.72
X	A8T0823359	RIVET	Less 020%	1.00	48.00	38.40

Parts 14,490.00  
Labour 0.00  
Sublet 7,847.00  
Menus 0.00  
Lubricant 0.00

Sub-Total 20,337.00

7% GST 1,423.59

Grand Total 21,760.59



Received by

For & on behalf of  
Premium Automobiles Pte Ltd

# Premium Automobiles

## Telefax

to **AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Motor Claims Dept**  
**Yr Ref: SGU 3899 K**

Norah Khai  
6768 9828  
6841 1183

Body Repair

PA/OD/0380/2018/GW  
25 April 2018

from  
Telephone +65-  
Telefax +65-  
Mobile +65-  
Our department  
Your Claim Ref  
Our Ref  
Date

1

total pages

**RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER**

**Make & Model** : Audi S5 Cab 3.0 TFSI qu  
**Vehicle Chassis No.** : WAUZZZ8F2CN012309  
**Vehicle Regn No.** : **SGU 3899 K**  
**Vehicle Mileage** : 107989 KM  
**Vehicle Owner** : Mr. Ling Yong Wah  
**Certificate No** : 210030651-05000  
**Policy Excess** : **S\$2140.00** (inclusive 7% GST)  
**Accident Date** : 23/03/2018  
**Place** : Traffic Junc at Payar Lebar Rd & Ubi Ave 3  
**Repair Cost** : \$ 21,760.59  
**WIP No.** : **60313**  
**Repairer's Name** : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Road 1  
Singapore 408699  
Telephone (65) 6366 2323  
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

**Owner / Insured Signature** : \_\_\_\_\_  
**Time** : \_\_\_\_\_  
**Date** : \_\_\_\_\_