

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0393/2018/NK
Date : 31-Mar-18

Kindly arrange for survey. Your Insured SLL 5585 M

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Emily Tan Gee Heng Mrs Wong Shoon Huaan
Address : 20 Li Hwan Drive

Singapore 557054

Telephone : HP +65 91118982
Type of Claim : Third Party Claim
Policy No. : 2100460972-01000
Vehicle No : **SFL 71 K**
Model Code : Audi A4 1.8 TFSI Mu
Model / Year : Dec-13
Engine No : CJE068108
Chassis No : WAUZZZ8K9EA058291
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Mar-18
Place of Accident : Junction of Swiss Club Rd & Bukit Timah Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFL 71 K

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper assy. Reorganise rear crash management components. Reinstall all parts removed.	\$ 900.00 500	
3	To respray rear bumper.	\$ 800.00 550	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,172.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFL 71 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>deformed.</i>	\$ 2,038.00	✓
2	REAR BUMPER SPOILER <i>not in</i>	\$ 232.00	X
3	REAR BUMPER REINFORCEMENT <i>Not in</i>	\$ 563.00	X
4	REAR BUMPER SENSOR <i>not in</i>	2 TBC	X
5	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 3,133.00
TOTAL LABOUR CHARGES		:	\$ 2,172.00
GRAND TOTAL		:	\$ 5,305.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183


Telefax

Name : Adrian Ling
Surveyed Date : 03/04/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 03 Days .

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager


Allan Wu
Claims Consultant