

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 10 Apr 2018

Preliminary Advice

Insured Vehicle No : SGW7878J

TP Vehicle No : SJL8491G

Make : AUDI A4

Date of Inspection : 29/03/2018

Inspection At : Auto Wheels Motorworks Pte Ltd (HQ)
No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA
Singapore 658064

Accident Date : 24/03/2018

Assignment Date : 28/03/2018

Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,651.64
Revised Amount	:S\$	6,253.71
Check Items (Estimated)	:S\$	3,047.13
Total	:S\$	9,300.84

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.