ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550
Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

Vehicle Insured : PH 9955D Accident Date : 17-Mar-2018

Date: 27-Feb-2018

No.: 05753

Our Ref : 218056 (AXA) / CHAN

PAGE: 1

CHEN RENQIAN EVAN 56 TREVOSE CRESCENT #02-08 Singapore 298088 11 Suy 8? Resury After Pains

ESTIMATED COST OF REPAIR FOR BMW 1201 SFU2121P

1	pc	Bonnet R, 1 177 25 -
1	pc	Bonnet logo 1,177.25 — 69.50 —
2	pcs	Bonnet hinge @ S\$ 73.25 Pri 146.50
2	pcs	Bonnet damper @ S\$109.45 218.90 7 DAM
1		Bonnet hook stopper 18.90 ? ~ Missing 4
1	pc	Bonnet hook 23.65 7 V BU
1	pc	Bonnet lock press open handle \$\frac{1}{45} \tag{37.50 \times \square DAM}
1	pc	Bonnet lock plate
1	pc	Bonnet lock plate cover
1	pc	Bonnet lock 0.7125.95 —
1	pc	Bonnet cable
1	pc	Front bumper fascia
1	pc	- The samper top rubber
2	pcs	Frt bumper top rubber bracket @ \$\$ 8.65 17.30 7 SVC
2	pcs	Front bumper grille chrome grave a S\$188.50 377 00 William / X2
2	pcs	Front bumper nozzle $4/3 cm$ @ S\$ 67.50 135.00 $4/3$
2	pcs	Front bumper nozzle cover (0 S\$ 34.20 all mi68 40 L+ x 2
2	pes	Front bumper nozzle cover seal @ \$\$ 6.80 4/4/13 60 4/2
1	pc	Front npzzle hose 48 75 7 V DAM
1	pc	Front bumper lower grille CM 113 90 .
1	pc	Front bumper tow cover
1	pc	Front bumper reinforcement 3 600 75.
2	pcs	Headlamp lower bracket of an a st 56.25 112.50 C+ X2
2	pcs	Headlamp assy M5 (M @ \$1716.35 3 432 70 , —
2	pcs	neadlamp control unit @ \$\$867.85 1 735.70 - V DAM
2	DCS	Headlamp top bracket
2	pes	Headlamp top garnish Alsem @ S\$ 15.15\ 30.30 Lt N/S ONLY
1	pc	Front air duct assy
		, , , , , , , , ,

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550
Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

Vehicle Insured: PH 9955D

Page: 2

```
770.80 7 DAM
      Radiator assy -auto
1 pc
1 pc
      Radiator o/s cover
                                                   ar 17.95 -
1 pc
      Radiator o/s cover seal
                                                  cm 62.35 -
1 pc
      Radiator n/s cover
                                                       8.95 7 MISSING
1 pc Radiator top stopper
2 pcs Radiator lower stopper
2 pcs Radiator lower support
                                                       30.40 7 missions
                                      @ S$ 15.20
                                                       39.40 7 - missinh
                                      @ S$ 19.70
1 pc Radiator fan assy
                                                   1,153.75 7 V DAM
                                                       77.50 7 V DAM
1 pc
      Radiator s/tank by pass hose
                                                      130.75 7 DAM
1 pc Radiator n/s top hose
                                                       96.90 7 DAM
1 pc Radiator o/s lower hose
                                             Arlfn 1,179.45
1 pc
      Air con condenser
                                                      356.45 7 V DAM
1 pc Air con liquid pipe
                                                      247.00 7 × svc
1 pc Air con discharge hose
                                                     283.30 7 DAM
      Air con suction hose
1 pc
1 pc Air cleaner assy
                                                     493.10 7 DAM
                                                 CM 197.20 ~
1 pc Air cleaner top cover
                                                     489.20 7V DAM
1 pc Oil cooler
                                                      98.80 7 V DAM
1 pc Power steering tank
                                                     277.55 Z DAM
1 pc Power steering tank bracket
                                                              16137.40
                                                  16,416.85
                                      Less 10% :
                                                   1,641.69
                                                                14573.6
                                                             14,775.16
                                                           451 50.00 sn
Ne 40.00 sn30sa
     Front no.plate with box
1 pc
1 pc Radiator coolant
                                                             Me 40.00 sn
2 pcs auto oil
                                      @ S$ 20.00
                                                             Nex 30.00 sn
2 pcs Cooler oil
                                      @ S$ 15.00
2 pcs Power steering oil
                                                             1 30.00 sn
                                      @ S$ 15.00
                                                          (Bill)
To towing (king trolley)
                                                                120.00 -
                                                          00
To rewire damaged parts and refocus
                                                                180.00 1001
headlamp beam, diagnostic & reset
To remove air con condenser, pipes
and drier, vacuum and to recharge
                                                                120.00 1001
```

Con't Page 3 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642. Tel: 6453 8686 (3 Lines) Fax: 6459 6550 Company Reg. No.: 201113667N GST Reg. No.: 201113667N

Vehicle Insured: PH 9955D

Page: 3

To putty and spray replaced parts

1,200.00

9001

To remove, cut-out damaged parts. panel beating, welding, align, refix and to renew above parts

9001 1,600.00

Total:

\$\$18,185.16 ==========

Singapore Dollars Eighteen Thousand One Hundred and Eighty Five and Cents Sixteen Only

SUM

SURMITHMANDIAN 15350.00 MINNY

TO SET MANDIAN PUS CONTRA

KENNEN PUS CONTRA

COR TAYS ILL TAY

SUF WORK ONT

TOR MANDIAN

TOR MAND 1935.81 SN 125.00 L 2100,00 L 2100,00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer Signature: Date: