



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18005820/Kga3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 14-09-2020



ATTN: KIAN CHUAN

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	PH 9955D	<b>Veh. Inspected</b>	SFU 2121P
<b>Policy No.</b>	VFX/P1549257	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S8M00B70	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	KIAN CHUAN	<b>Assign Date</b>	27/03/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	B.M.W. 120I (A)	<b>c.c</b>	1995
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2011
<b>Chassis No.</b>	WBAUC52080VJ99897	<b>Colour</b>	WHITE
<b>Odometer</b>	092279	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/40 R18	CONTINENTAL	6 mm
<b>L/H Front Tyre</b>	225/40 R18	CONTINENTAL	6 mm
<b>R/H Rear Tyre</b>	225/40 R18	CONTINENTAL	4 mm
<b>L/H Rear Tyre</b>	225/40 R18	CONTINENTAL	4 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

<b>Accident Date</b>	17/03/2018	<b>Inspection Date</b>	28/03/2018
<b>Survey held at</b>	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>14 Working Days</b>
-------------------------------------	------------------------