Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642. Tel: 6453 8686 (3 Lines) Fax: 6459 6550 Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured: PH 9955D

Accident Date : 17-Mar-2018

No. : 05753

Date: 27-Feb-2018

Our Ref : 218056 (AXA) / CHAN

PAGE: 1

CHEN RENQIAN EVAN 56 TREVOSE CRESCENT #02-08 Singapore 298088 Not Notherial Ully 8? Reany After Pains

ESTIMATED COST OF REPAIR FOR BMW 1201 SFU2121P

	1	pc	Bonnet R 1 177 25 -
	1	рс	
	2	pcs	Bonnet hinge @ S\$ 73.25 Pi) 146.50
	2		Bonnet damper @ \$\$109.45 218.90 7 DAM
	1	pc	Bonnet hook stopper 18.90? \ mssr-4
	1	pc	10,00
	1	рс	Bonnet lock press open handle 23.65 7 V BU 37.50 X V DAM
	1	pc	
	1	pc	Bonnet lock plate Bonnet lock plate cover Bonnet lock plate cover 5.35 DAM
	1	pc	Bonnet lock 0.7125.95
	1	pc	Bonnet cable 33.05 7 V DAM
	1		Front bumper fascia Front bumper top rubber
	1	pc	Front bumper top rubber 7 15.75
	2	pcs	Frt bumper top rubber bracket @ S\$ 8.65 17.30 7 SVC
	2	pcs	Front bumper grille chrome & S\$188.50 377.00 N/Sun _ XZ
	2	pcs	Front bumper nozzle 4/3 cm @ S\$ 67.50 135.00 4 12
	2	pcs	Front bumper nozzle cover @ S\$ 34.20 4 88.40 4 × 2
	2	pcs	Front bumper nozzle cover seal @ S\$ 6.80 4 13.60 47
	1	pc	Front npzzle hose 48.75 7 DAM
	1	pc	Front bumper lower grille cm 113.90
	1	pc	Front bumper tow cover
	1	pc	Front bumper reinforcement 3 600 75
	2	pcs	Headlamp lower bracket Asim @ S\$ 56.25 112 50 Ct XZ
2	4	pcs	Headlamp assy M3 (M @ \$1716.35 3 432 70 ,
175	2	pcs	Headlamp control unit @ \$\$867.85 1 735.70 \rightarrow DAM
2			
2	2	pcs .	Headlamp top garnish Alson @ S\$ 15.15 30.30 L
1		pc	Front air duct assy

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550
Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

Vehicle Insured: PH 9955D

Page: 2

```
770.80 7 V DAM
      Radiator assy -auto
                                                 CM 72.35
1 pc
      Radiator o/s cover
                                                 ar 17.95
1 pc
      Radiator o/s cover seal
      Radiator n/s cover
                                                 CM 62.35 -
1 pc
                                                      8.95 7 MISSING
1 pc
      Radiator top stopper
                                                     30.40 7 ~ missions
2 pcs Radiator lower stopper
                                     @ S$ 15.20
                                                     39.40 ? - missinh
2 pcs Radiator lower support
                                     @ S$ 19.70
                                                  1,153.75 7 V DAM
1 pc Radiator fan assy
                                                     77.50 7 V DAM
1 pc
      Radiator s/tank by pass hose
                                                    130.75 7 DAM
      Radiator n/s top hose
1 pc
1 pc
      Radiator o/s lower hose
                                                     96.90 7 DAM
                                           Arlfn 1,179.45
      Air con condenser
1 pc
                                                    356.45 7 Y DAM
1 pc Air con liquid pipe
                                                    247.00 7 × svc
1 pc Air con discharge hose
      Air con suction hose
                                                    283.30 7 DAM
1 pc
1 pc Air cleaner assy
                                                    493.10 7 DAM
                                                CM 197.20 ~
1 pc Air cleaner top cover
                                                    489.20 7V DAM
1 pc Oil cooler
1 pc Power steering tank
                                                     98.80 7 V DAM
                                                           7 V DAM
1 pc Power steering tank bracket
                                                    277.55
                                                 16,416.85
                                     Less 10% :
                                                  1,641.69
                                                               14573
                                                            14,775.16
                                                         451n
      Front no.plate with box
                                                               50.00 sn
                                                           Na 40.00 sn3051
1 pc Radiator coolant
                                                           Ma 40.00 sn
2 pcs auto oil
                                     @ S$ 20.00
                                                           Nex 30.00 sn
2 pcs Cooler oil
                                     @ S$ 15.00
2 pcs Power steering oil
                                                           M 30.00 sn
                                     @ S$ 15.00
                                                        (Bill) 120.00 -
To towing (king trolley)
                                                        00
To rewire damaged parts and refocus
                                                              180.00 1001
headlamp beam, diagnostic & reset
To remove air con condenser, pipes
and drier, vacuum and to recharge
                                                              120.00 1001
gas
```

Con't Page 3 ...

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642. Tel: 6453 8686 (3 Lines) Fax: 6459 6550 Company Reg. No.: 201113667N GST Reg. No.: 201113667N

Vehicle Insured: PH 9955D

Page: 3

To putty and spray replaced parts

1,200.00

9001

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

9001 1,600.00

Total:

\$\$18,185.16 =========

Singapore Dollars Eighteen Thousand One Hundred and Eighty Five and Cents Sixteen Only

Sum Sum 15350.00 many
This manders you son
The manders for Contract

COR Trays 14 Tray
Tor mondimer
Tor mondimer S-6 873.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured: PH9955D (AXA) Accident Date: 17-03-2018 Date: 05-04-2018

Our Ref : 218056 / CHAN

CHEN RENQIAN EVAN
C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR BMW120I SFU2121P

1 PC	RADIATOR SPARE TANK		\$192.70	DAM
1 PC	FRONT LOWER AIR INTAK DUCT		\$68.75	DAM
1 PC	FAN BELT		\$104.65	BU
1 PC	OIL FILTER HOUSING O RING		\$20.05	MISSING
1 PC	WATER HOSE HOUSING		\$50.50	DAM
1 PC	WATER TO ENGINE INLET HOSE		\$87.50	DAM
1 PC	RADIATOR GRILLE COWLING		\$56.65	DAM
2 PCS	AUTO COOLER PIPE @ \$167.05		\$334.10 \$914.90	DAM
		LESS 10%	\$91.49	-
			\$823.41	

Singapore Dollars Eight Hundred Twenty Three And Cents Forty One Only