

CHINA-LKK (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2001Z

DATE 3/24/2018 9:19

Jumani

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	Rear Bumper Reflector Lamp (RH)			\$ 32.00
	Rear Bumper Clips 10 pcs			\$ 22.00
	SUB TOTAL			\$ 1,890.35
	LESS 20%			\$ 378.07
	DISCOUNTED TOTAL			\$ 1,512.28
	Rear Bumper Reverse Sensor			\$ 135.70
				\$ 135.70
	Labour Charge			
	Panel Beating			\$ 250.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 650.00
	ESTIMATE TOTAL			\$ 2,297.98

200
180
60
Nett?

Repair
Ap 90000008
2 days
P/P
26/03/18 @ 1155
Resy 54 point

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.