

VIFI PTE LTD

Your Ref: SJY4594B
 Our Ref: SJK2039A

To: LONPAC INSURANCE BHD

Date: 28/3/2018
 From: Ezuwan

CC

Contact: 88111110
 Make / Model: TOYOTA ALLION A15 A

Email

Chassis No.: NZT2603022573

Fax

Engine No.: 1NZC993374

Year of Make: 2008

Accident Date: 24/3/2018

ESTIMATE FOR VEHICLE NO. : SJK2039A

DESCRIPTION	QTY	List Price
✓ REAR BUMPER <i>det</i>	1	\$ 1,250.00
✓ REAR BUMPER CLIPS <i>hec</i>	10	\$ 50.00
✓ REAR RIGHT TAIL LAMP <i>orc</i>	1	\$ 325.00
✓ REAR LEFT TAIL LAMP <i>orc</i>	1	\$ 325.00
✓ SPARE TYRE COMPARTMENT <i>R</i>	1	\$ 850.00
✓ REAR BOOT COVER - 164401 <i>det</i>	1	\$ 350.00
✓ REAR BOOT COVER CLIP <i>hec</i>	10	\$ 50.00
✓ REAR BOOT WEATHER STRIP 64401 <i>dis</i>	1	\$ 195.00
✓ REAR BOOT <i>bot</i>	1	\$ 980.00
✓ REAR CAMERA <i>orc</i>	1	\$ 650.00
✓ REAR BOOT LOCK HINGE 64610 <i>bot</i>	1	\$ 160.00
✓ REAR BOOT MOULDING PROTECTOR 53B7 <i>dis</i>	1	\$ 140.00
✓ REAR BUMPER REFLECTIVE LEFT <i>orc</i>	1	\$ 60.00
✓ REAR BUMPER RETAINER <i>dis</i>	2	\$ 160.00
✓ REAR BOOT TOYOTA LOGO <i>hec</i>	1	\$ 50.00
✓ REAR BOOT ALLION LOGO <i>hec</i>	1	\$ 50.00
✓ REAR BOOT A1.5 LOGO <i>hec</i>	1	\$ 40.00
✓ REAR BOOT CHROME GARNISH <i>orc</i>	1	\$ 135.00
✓ REAR END PANEL <i>bot</i>	1	\$ 375.00
✓ REAR BUMPER SPONGE <i>kl sp.</i>	3	\$ 180.00
✓ REAR BOOT PLATFORM 64711 <i>orc</i>	1	\$ 150.00
✓ FRONT BUMPER <i>det</i>	1	\$ 600.00
✓ FRONT BUMPER CLIP <i>hec</i>	10	\$ 50.00
✓ FRONT BUMPER RETAINER <i>dis</i>	2	\$ 160.00
✓ FRONT BUMPER UPPER GRILLE <i>orc</i>	1	\$ 385.00
✓ FRONT BUMPER LOWER GRILLE <i>det</i>	1	\$ 190.00
✓ FRONT REINFORCEMENT PANEL <i>orc</i>	1	\$ 215.00
✓ FRONT END PANEL <i>R</i>	1	\$ 375.00
✓ FRONT SUPPORT PANEL <i>R</i>	1	\$ 300.00
✓ FRONT LEFT HEADLAMP <i>orc</i>	1	\$ 550.00
✓ FRONT RIGHT HEADLAMP <i>orc</i>	1	\$ 550.00
✓ FRONT BUMPER LOGO <i>x MIN</i>	1	\$ 60.00

X RADIATOR ASSY *err*
 AC condenser *✓* *107*

1	\$	600.00
Total:		\$ 10,560.00
LESS 20%:		\$ (2,112.00)
Parts Total:		\$ 8,448.00

SPECIAL NETT

ANTI RUST COATING	1	\$	<i>un 60</i> 80.00
BODY SEALANT	1	\$	<i>un</i> 60.00
REAR REVERSE SENSOR	1	\$	<i>shd 220</i> 350.00
FRONT NUMBER PLATE WITH CASING	1	\$	<i>107</i> 60.00
REAR NUMBER PLATE WITH CASING	1	\$	<i>bt</i> 60.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$	<i>1200</i> 1,500.00
TO DISMANTLE & TRANSFER REAR BOOT FITTINGS & MECHANISM TO FACILITATE REPAIR	\$	<i>40</i> 100.00
TO CUT AND WELD REAR SPARE TYRE COMPARTMENT	\$	<i>X</i> 350.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>30</i> 100.00
TO SPRAY PAINTING ON THE AFFECTED AREA	\$	<i>1200</i> 1,800.00

Total:	\$	12,908.00
7% GST:	\$	903.56
Total:	\$	13,811.56
Lumsump -20%:	\$	(2,762.31)
Grand Total:	\$	11,049.25

Not Auction
US Repair
AAE paint shop
HEB Auto Club
9 weekdays
29/8/2018

Please survey the vehicle at :-
 1 Bukit Batok Crescent
 #06-12, WCEGA PLAZA
 SINGAPORE 658064
 (Kindly contact Ezuwan @ 8833 6463)

VIFI PTE LTD
 1 BUKIT BATOK CRESCENT
 #06-12, WCEGA PLAZA
 t 67670011
 Company Registration Number : 201315095D

MM

MAX

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

9 weekdays

etc