

22/03/2002

ASS. REC. BY:

REF: CS/MSH18005833/Kvb02 Special Instruction:

Survivor: Keanah.**ASSIGNMENT (Office)**

Merimen

From (Person): Irene Tanof MSHDate/Time: 29032018 1133am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 5848YInsured: SJR 812Kat Workshop m/s Trans CabTel: 62876666of No. 2 Amk St 63 =Policy No: 28961220 TmpClaim No: 553892

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25132018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI'

H.O.D. Endorsement:

Date/Time: 29032018 1147am

Person Contacted:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 5848Y - X
	SJR 812K - CS/AT/13010768/KvN Dm: 25012
3/4/18	Send preli revised by merimen



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005833/Kvb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-03-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJR 812K	Veh. Inspected	SHD 5848Y	
Policy No.	28961220TMP	Coverage (\$)	0.00	
Claim No.	553892	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	29/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/03/2018	Inspection Date	29/03/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Irene Tan Gek Ing	Date: 03 Apr 2018

Preliminary Advice

Insured Vehicle No	: SJR812K		
TP Vehicle No	: SHD5848Y	Accident Date	: 25/03/2018
Make	: RENAULT LATITUDE	Assignment Date	: 29/03/2018
Date of Inspection	: 29/03/2018	Est. Duration of Repair	: 2.5
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD (ANG MO KIO) 2, ANG MO KIO STREET 63 SINGAPORE 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,547.07
Revised Amount	:S\$	7,498.75
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair (estimated)	:S\$	6,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2018		29 Mar 2018 11:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN CHYE YONG VINCENT, ID: S7337346H		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD5848Y	Date of Loss:	25/03/2018 21:00 - :59
Claim Type:	TP / 553892	Policy/Cover Note No.:	28961220TMP (Third Party Only) Coverage: 11/06/2017 - 10/06/2018
Vehicle Reg. No. (Insured):	SJR812K	Policy No. (Claimant):	
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/03/2018]		
Adj Asg. Remarks:	I wish to select 2. Kenneth Kong.		

ASSOCIATED MAIL RECEIVED

View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

3/26/2018

PARF/COE Rebate Enquiry

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD5848Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Mar 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001813
Chassis No.:	VF1ABL15AUC278841
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	11 Jul 2014
First Registration Date:	11 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jul 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	10 Jul 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$53,269.00
COE Rebate Amount:	\$28,552.00
Total Rebate Amount:	\$37,925.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/03/2018 16:21
Date Of Accident	25/03/2018 21:50
Exact Location Of Accident	JUNCTION OF ESPLANADE DRIVE AND FULLERTON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5848Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LIM TECK HOCK
NRIC No	S1189264G
Date Of Birth	02/11/1956
Occupation	OUTDOOR
Date Of Driving Pass	31/03/1978
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82818981
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 765 BEDOK RESERVOIR VIEW #15-255
Postcode	470765
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20180326/2068

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR812K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HOH XIN EN JOVELL
NRIC/Passport Number	S9527059Z
Contact Number	87143306
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Esplanade Drive
Fullerton Road

A
B

A SHD5848Y
B SJR812K

↑ ↑

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



SINGAPORE
POLICE FORCE



T/20180326/2068

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

3 of 3

Report No. T/20180326/2068

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /
Sgt 3 LIYANA BINTE MOHD RAZALI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

26/03/2018 12:57

Officer In Charge Of Case:

TP / AEIT /

SSI 2 YEO GEAK ENG CECILIA

Contact No.: 65475404 SINGAPORE
POLICE FORCE

Classification Of Case:

SN 061

Authentication Stamp

NP158

SIGNATURE

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180326/2068

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

2 of 3

Report No. T/20180326/2068

CONTINUATION OF REPORT

Driver			
Name	LIM TECK HOCK	ID No.	S1189264G
Related Vehicle	SHD5848Y (Car)	Contact No.	82818981
Hospital/Clinic	HORIZON MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	26/03/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	HOH XIN EN, JOVELL	ID No.	S9527059Z
Related Vehicle	SJR812K (Car)	Contact No.	87143306
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

25/03/2018 at about 2150hrs, I was at the junction of Esplanade Drive and Fullerton Road (before ERP gantry). I was on the 2nd lane from the left when the traffic light just turned green. The vehicle in front of me moved forward slightly, so I inched forward too. Suddenly I felt an impact coming from the rear of my vehicle (SHD5848Y). I alighted from my vehicle and noted that my vehicle had collided with a vehicle bearing SJR812K. Both me and the said driver managed to exchange particulars.

After the incident I felt pain on my body so I went to see the doctor. I then received a 3 days' medical leave.

I wish to state that there is no government property damaged. No traffic police and no ambulance at scene. I do not have any in built camera installed in my vehicle.

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180326/2068

1 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20180326/2068

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/03/2018 12:57	Vide Report No.:	Station Diary No.: 67
--	------------------	--------------------------

Informant's Particulars

Informant's Particulars			
Name of Informant: LIM TECK HOCK		Address: APT BLK 765 BEDOK RESERVOIR VIEW #15-255 SINGAPORE 470765	
ID Type / ID No.: NRIC NO / S1189264G		Contact No.: Home/Office:	Mobile: 82818981
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 62	Date of Birth: 11/02/1956	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 2B,2A,2,3,4	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 24/03/2018 21:50	Type of Location: T-Junction
Location: Along Road 1 ESPLANADE DRIVE FULLERTON ROAD Junction of Esplanade Drive and Fullerton Road (before ERP gantry)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD5848Y	Car				Slightly Damaged	0
SJR812K	Car					1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5848Y**AAD1803-229***Not Notified
L1 Imp 86000h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD 5848Y

VF1ABL15AUC278841

RENAULT

LATITUDE

25.3.2018

*MSIG.***PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>nd/lt</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>Bt</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Rt</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Rt</i> 225.95	X
13	1 BOOT REAR	\$	<i>Bt</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Rt</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>Rt</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>Rt</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>Rt</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1 BOOT LOCK	\$	<i>Rt</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>Rt</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	
30	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45	

Trans-cab Auto Services Pte Ltd**AAD1803-229**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5848Y

31	1 FENDER PANEL REAR LH	\$	<i>N</i>	3,299.13	} X
32	1 WHEELARCH REAR LH	\$	<i>Sn</i>	543.47	
33	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i>	671.45	
34	1 FENDER PANEL REAR RH	\$	<i>N</i>	3,299.13	
35	1 WHEELARCH REAR RH	\$	<i>Sn</i>	543.47	
36	1 TAILLAMP RH	\$	<i>Sn</i>	552.55	
37	1 TAILLAMP PANEL RH	\$	<i>N</i>	986.70	
38	1 TAILLAMP LH	\$	<i>Sn</i>	552.55	
39	1 TAILLAMP PANEL LH	\$	<i>N</i>	986.70	
40	1 OUTER PANEL REAR (End Panel)	\$	<i>N</i>	1,471.77	
41	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i>	404.56	
42	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>N</i>	2,189.88	
43	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i>	612.21	
44	1 EXHAUST REAR	\$	<i>N</i>	7,489.05	
45	1 EXHAUST CAP REAR	\$	<i>N</i>	230.49	

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET PARKING AID	\$	<i>Shen</i>	700.00	✓
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	—
4	1SET BUMPR BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i>	17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>na</i>	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i>	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i>	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	<i>na</i>	28.00	X

Trans-cab Auto Services Pte Ltd

AAD1803-229

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5848Y

18	1 FENDER INNER TRIM CLIP LH	\$	28.00	} X
19	1 TAILLAMP CLIP RH	\$	5.00	
20	1 TAILLAMP CLIP LH	\$	5.00	
21	2 REAR WINDSCREEN SELANT	\$	80.00	
22	1 WINDSCREEN MOULDING	\$	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	
25	1 SPARE TYRE	\$	330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 34,507.07****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	~ X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	~ X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	~ X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	~ X

Trans-cab Auto Services Pte Ltd**AAD1803-229**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5848Y

To supply and re-do rear luggage floor panel insulation padding.	\$	<i>~</i>	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>~</i>	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>~</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>~</i>	220.00	X

TOTAL \$ 11,040.00**Over All Total \$ 45,547.07**

05

(LUMP SUM)**Repair Days**~~15 Days~~*2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005833/KVBN2

Date: 19/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28961220TMP
Claimant Vehicle No :	SHD5848Y	Insured Vehicle No :	SJR812K
Date of Loss:	25/03/2018	Nature of Claim:	TP
		Claim No:	553892

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5848Y		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C001813
Reg. Date:	11/07/2014 (Man. Year: 2014)	Chassis No:	VF1AB15AUC278841
Colour:	White/Red	Odometer:	612021 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	34,507.05	6,508.75	27,998.30	81.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,040.00	990.00	10,050.00	91.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	45,547.05	7,498.75	38,048.30	83.54
Approved Total (Overridden) (\$\$)		6,000.00		
(\$\$)	45,547.05	6,000.00	39,547.05	86.83
+ GST 7.00/7.00% (\$\$)	3,188.29	420.00	2,768.29	86.83
Nett Amount (\$\$)	48,735.34	6,420.00	42,315.34	86.83

INSPECTION

Date of Assignment:	29/03/2018	
Date Inspected:	29/03/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.5 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2018)
Parts:	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5848Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Dented/Cut	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1	*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1	*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1	*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1	*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1	*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1	*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1	*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1	*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1	*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1	*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1	*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1	*BOOT LOCK	Repair	202.67 FL	*- FL
27	1	*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1	*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
31	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
32	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
33	1	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
34	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
35	1	*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
36	1	*TAILLAMP RH	Serviceable	552.55 FL	*- FL
37	1	*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1	*TAILLAMP LH	Serviceable	552.55 FL	*- FL
39	1	*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
40	1	*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
41	1	*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
42	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
43	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
44	1	*EXHAUST REAR	Repair	7,489.05 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
46	1	*SET PARKING AID	Shorted	700.00 FS	*700.00 FS
47	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
48	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
49	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
50	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
51	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
52	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
53	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
54	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
55	1	*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
56	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
57	1	*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
58	1	*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
59	1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
60	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
61	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
62	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
63	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
64	1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
65	1	*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
66	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
67	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
68	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
69	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Not Necessary	385.00 FS	*- FS
70	1	*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,093.94	7,129.17
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,586.89	620.42
Total Parts (\$\$)	34,507.05	6,508.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TO TRANSFER OF REAR LUGGAGE PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANELINSULATION PADDING	New	380.00	-
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
Gross Labour Cost (S\$)			11,040.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >