

Hui Yang Motor Pte Ltd (Co. Reg. No: 201629438M)176 Sin Ming Drive #04-02, Sin Ming AutoCare
Singapore 575721

Tel: 64515752 Fax: 64514658 Email: hui_yang_motor@hotmail.com

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type: OD (OWN DAMAGE)
 Policy No: A28795104MCX
 Vehicle Reg. No.: SLB15E
 Driver Age/Info: 41 / MALE
 TP Injury Involved? NO
 Insured/Claimant: SKYWAY MOTOR PTE LTD
 Driver: MOHAMAD RAIZAL BIN RAHIM

Ref. No:
 Date of Loss: 27/03/2018
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES

Make/Model: TOYOTA WISH, 1.8 X (A)
 Vehicle Colour: BLUE
 Engine No: ZZR1835717
 Odometer: 80907 KM

Vehicle Reg. Date: 22/02/2017
 Chassis No: ZGE206035420

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day)

26 days



Not Authorise
 I.B.I
 Resurvey B4 painting
 Ex @ Fuel
 Fax: 62564315

Description of Accident/Loss: REFER TO ACCIDENT REPORT
 Present Location: HUI YANG MOTOR PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	5,482.40
Miscellaneous Items	0.00
Paintwork Materials	1,400.00
Labour	1,490.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	8,372.40
- Excess (S\$)	700.00
(S\$)	7,672.40
+ GST 7.00% (S\$)	537.07
Nett Amount (S\$)	8,209.47

This claim is handled by: NEO WEE EEK

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Reparer
 Signature:
 Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Mar 2018)
Parts: M1-MPV TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLB15E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*front bonnet	0.00	0.00	Per *190.00 F	✓
2	1		*front bonnet inner lock	0.00	0.00	Dir *45.00 F	✓
3	1		*front bonnet TOYOTA logo	0.00	0.00	Me *35.00 F	✓
4	2		*front bonnet hinge	0.00	0.00	*50.00 F	?
5	1		*front bonnet inner cardboard	0.00	0.00	Sm *150.00 F	X
6	6		*front bonnet inner cardboard clip	0.00	0.00	Na *9.00 F	X
7	1		*front bonnet inner stopper RH	0.00	0.00	Mis *8.00 F	✓
8	2		*front headlamp	0.00	0.00	Mis CM *540.00 F	✓
9	1		*front bumper	0.00	0.00	Per *170.00 F	✓
10	2		*front bumper side retainer	0.00	0.00	Dir *70.00 F	✓
11	20		*front bumper clip	0.00	0.00	Me *20.00 F	✓
12	1		*front bumper sponge	0.00	0.00	CM *45.00 F	✓
13	1		*front bumper reinforcement	0.00	0.00	*95.00 F	?
14	1		*front centre grille	0.00	0.00	Dir *120.00 F	✓
15	1		*front centre grille chrome	0.00	0.00	*120.00 F	?
16	1		*front centre grille top garnish	0.00	0.00	Dir *50.00 F	✓
17	8		*front centre grille top garnish clip	0.00	0.00	Me *12.00 F	✓
18	1		*front support panel	0.00	0.00	Per *380.00 F	✓
19	1		*front support panel centre pillar	0.00	0.00	Dir *150.00 F	X
20	1		*front support panel side garnish	0.00	0.00	*35.00 F	?
21	1		*front A/C condensor	0.00	0.00	*480.00 F	?
22	1		*front A/C condensor pipe 1	0.00	0.00	*180.00 F	?
23	1		*front A/C condensor pipe 2	0.00	0.00	*190.00 F	?
24	1		*front A/C condensor motor	0.00	0.00	*90.00 F	?
25	1		*front A/C condensor motor fan	0.00	0.00	*70.00 F	?
26	1		*front radiator	0.00	0.00	*580.00 F	?
27	1		*front radiator top hose	0.00	0.00	Sm *35.00 F	X
28	1		*front radiator lower hose	0.00	0.00	Sm *25.00 F	X
29	1		*front radiator cowling	0.00	0.00	*90.00 F	?
30	1		*front radiator cowling top garnish	0.00	0.00	*50.00 F	?
31	1		*front radiator cowling lower garnish	0.00	0.00	*90.00 F	?
32	1		*front radiator cowling motor	0.00	0.00	*150.00 F	?
33	1		*front radiator cowling motor fan	0.00	0.00	*90.00 F	?
34	1		*front radiator spare tank	0.00	0.00	Mis Dir *75.00 F	✓
35	2		*front fender	0.00	0.00	Per *390.00 F	✓
36	2		*front wiper garnish side garnish	0.00	0.00	Sm *70.00 F	X
37	1		*front battery bracket	0.00	0.00	Per *35.00 F	✓
Sub Total (S\$)						4,984.00	
+ Margin on L,N Items 10.00% (S\$)						498.40	
Total Parts (S\$)						5,482.40	

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Materials			
1	1	spray painting	1,400.00
Sub Total (S\$)			1,400.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Materials			
1	1	spray painting	1,400.00
Sub Total (S\$)			1,400.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	1set front number plate & casing	New	50.00
2	remove & refit radiator & cooler	New	180.00
3	remove & refit air-con & gas	New	180.00
4	wiring	New	80.00
5	labour	New	1,000.00
Gross Labour Cost (S\$)			1,490.00

Hui Yang Motor Pte Ltd/SLB15E/28/03/2018 12:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >