

22/03/2002

ASS. REC. BY:

REF:

C9/MS618005835/Kyber

Special Instruction:

Survivor: Kenneth
merimenASSIGNMENT (Office)

From (Person): Joslin Lim

of

MS6

Date/Time: 29032018 10am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 15E

Insured:

at Workshop m/s

Hui Yang Motor

Tel:

64515752

of

176 Sin Ming Drive #04-02

Policy No:

A28745104 MCX

Claim No:

553830

Sum Insured:

Excess:

\$ 700.00

Make of Veh:

(Client's Record)

D.O.A. 29032018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

29032018

1052am

Person Contacted:

Bel

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 15E
2/4/18	Revert by merimen
2/4/18	Rece app from Huey Ni by merimen
2/4/18	Informed Bel c/a ex \$700 by email

REF: MSLH

merimen

ASSIGNMENT

From:

Date:

21/3/2018

Estimated Cost:

(OD) / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLB 15E

at Workshop m/s

Hui Yang

of

176 Sin Ming Drive #04-02

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

\$700.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$95k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SLB 15E Yr Regn: 02, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

C.C.

1797

Colour

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

80907

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

7GE20 6035420

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Davant

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/3/18

D.O.I.

29/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/4 Mr pass to Catherine

12/4 @ 6609.80 sent 5709.80 Carbur Marco. (Red 262.60, 32)

RECEIVED 12 APR 2018

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

12/4 - typist

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation

3. J+B

3. J+B

3. J+B

3. J+B

3. J+B

Report Format :

merimen

Lump Sum / I.B.I. (\$) :

5709.80

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wheel end (\$

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005835/Kvb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 29-03-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLB 15E
Policy No.	A28795104MCX	Coverage (\$)	0.00
Claim No.	553830	Excess (\$)	700.00
Assign From	MERIMEN (JOSLIN LIM)	Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	27/03/2018	Inspection Date	29/03/2018
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Mar 2018 Sendback Est	28 Mar 2018 12:43 S\$8,372.40	29 Mar 2018 10:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Vehicle Reg. No.:	SLB15E	Date of Loss:	27/03/2018 12:00 - :59
Claim Type:	OD / 553830	Policy/Cover Note No.:	A28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018
		Excess:	S\$700.00
Repalrer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/03/2018]		
Driver/Custodian:	MOHAMAD RAIZAL BIN RAHIM (41 / Male), NRIC: S7625509A		
Adj Asg. Remarks:	Please revert.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS**

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SLB15E (553830)
OD
Mar 27 2018 12:00PM
[SKYWAY MOTOR PTE LTD]
Hui Yang Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 12/04/2018 17:28 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5709.80) - SLB15E - Claim Handler: Joslin Lim

Approved:5709.80:check items of \$2596.00 to be verified

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 12 Apr 2018

Preliminary Advice

Vehicle No	: SLB15E	Accident Date	: 27/03/2018
Make	: TOYOTA WISH	Policy No.	: A28795104MCX
Assignment Date	: 29/03/2018	Excess	: S\$700.00
Date of Inspection	: 29/03/2018	Est. Duration of Repair	: 6.00
Inspection At	: HUI YANG MOTOR PTE LTD (HQ) 176 SIN MING DRIVE #04-02, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,372.40
Revised Amount	:S\$	5,709.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,709.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	58,298.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,702.00

Remarks

(X)

The vehicle is economical for repair.

()

The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 2 April 2018 4:44 PM
To: Hui Yang Motor
Cc: SUR
Subject: SLB 15E-DOA:27/3/2018 (MSIG OD)

Dear Bel,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SLB 15E (Excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLB15E (553830)

OD

Mar 27 2018 12:00PM

[SKYWAY MOTOR PTE LTD]

Hui Yang Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 02/04/2018 16:11 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5363.50) - SLB15E - Claim Handler: Joslin Lim

Approved:5363.50:check items of \$2596.00 to be verified

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 02 Apr 2018

Preliminary Advice

Vehicle No	: SLB15E	Accident Date	: 27/03/2018
Make	: TOYOTA WISH	Policy No.	: A28795104MCX
Assignment Date	: 29/03/2018	Excess	: S\$700.00
Date of Inspection	: 29/03/2018	Est. Duration of Repair	: 6.00
Inspection At	: HUI YANG MOTOR PTE LTD (HQ) 176 SIN MING DRIVE #04-02, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,372.40
Revised Amount	:S\$	5,363.50
Check Items (Estimated)	:S\$	2,596.00
Total	:S\$	7,959.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	58,298.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,702.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

4194N

Vehicle Details

Vehicle No.:

SLB15E

Vehicle to be Exported:

No

Intended De-registration Date:

02 Apr 2018

Vehicle Make:

TOYOTA

Vehicle Model:

WISH 1.8X A

Primary Colour:

Blue

Manufacturing Year:

2016

Engine No.:

2ZR1835717

Chassis No.:

ZGE206035420

Maximum Power Output:

105.0 kW (140 bhp)

Open Market Value:

\$20,420.00

Original Registration Date:

22 Feb 2017

First Registration Date:

22 Feb 2017

Transfer Count:

0

Actual ARF Paid:

\$20,588.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

21 Feb 2027

PARF Rebate Amount:

\$15,441.00

Intended COE Rebate Details

COE Expiry Date:

21 Feb 2027

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$48,556.00

COE Rebate Amount:

\$42,857.00

Total Rebate Amount:**\$58,298.00**

The information contained herein is correct as at 02 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/03/2018 09:37
Date Of Accident	27/03/2018 12:20
Exact Location Of Accident	ALONG BUKIT TIMAH RD (OUTSIDE LTA)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB15E
Insured/Policyholder	
Name Of Registered Owner	SKYWAY MOTOR PTE LTD
Co Reg No	199904194N
Email Address	PEILIN@SKYWAY.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63336333

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE HIRE
------------------	--------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A 28795104 MCX
Cover Note Number	

Driver

Name of Driver	MOHAMAD RAIZAL BIN RAHIM
NRIC No	S7625509A
Date Of Birth	24/08/1976
Occupation	OUTDOOR
Date Of Driving Pass	31/07/1999
Driving Experience	18 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91845076
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Hui Yang Motor Pte Ltd (Co.Reg.No:201629438M)

176 Sin Ming Drive #04-02, Sin Ming AutoCare

Singapore 575721

Tel: 64515752 Fax: 64514658 Email: hui_yang_motor@hotmail.com

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type: OD (OWN DAMAGE)
 Policy No: A28795104MCX
 Vehicle Reg. No.: SLB15E
 Driver Age/Info: 41 / MALE
 TP Injury Involved? NO
 Insured/Claimant: SKYWAY MOTOR PTE LTD
 Driver: MOHAMAD RAIZAL BIN RAHIM

Ref. No:
 Date of Loss: 27/03/2018
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES

Make/Model: TOYOTA WISH, 1.8 X (A)
 Vehicle Colour: BLUE
 Engine No: 2ZR1835717
 Odometer: 80907 KM

Vehicle Reg. Date: 22/02/2017
 Chassis No: ZGE206035420

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day)

6 days



Not Authorise
 1-B.1
 Resurvey B4 painting
 Ex @ 7000
 Fax 62564315

Description of Accident/Loss: REFER TO ACCIDENT REPORT
 Present Location: HUI YANG MOTOR PTE LTD (HQ)

COST OF CLAIMS

Parts
 Miscellaneous Items
 Paintwork Materials
 Labour
 Paintwork Labour
 Towing

Amount
 5,482.40
 0.00
 1,400.00
 1,490.00
 0.00
 0.00

Calculated Gross Total (\$) 8,372.40
- Excess (\$) 700.00
(\$) 7,672.40
+ GST 7.00% (\$) 537.07
Nett Amount (\$) 8,209.47

3/4/18

This claim is handled by: NEO WEE EEK

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Mar 2018)

Parts: M1-MPV TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB15E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*front bonnet 255	0.00	0.00	Ar	*190.00 F ✓
2	1		*front bonnet inner lock	0.00	0.00	DIT	*45.00 F ✓
3	1		*front bonnet TOYOTA logo 25	0.00	0.00	Ar	*35.00 F ✓
4	2		*front bonnet hinge	0.00	0.00	DIST	*50.00 F ✓
5	1		*front bonnet inner cardboard	0.00	0.00	Sm	*150.00 F X
6	6		*front bonnet inner cardboard clip	0.00	0.00	Ar	*9.00 F X
7	1		*front bonnet inner stopper RH 6	0.00	0.00	Ar	*8.00 F ✓
8	2		*front headlamp 500	0.00	0.00	M3 CRA	*540.00 F ✓
9	1		*front bumper 180	0.00	0.00	Ar	*170.00 F ✓
10	2		*front bumper side retainer 65	0.00	0.00	DIT	*70.00 F ✓
11	20		*front bumper clip	0.00	0.00	Ar	*20.00 F ✓
12	1		*front bumper sponge 50	0.00	0.00	CRA	*45.00 F ✓
13	1		*front bumper reinforcement 85	0.00	0.00	BT	*95.00 F ?
14	1		*front centre grille 145	0.00	0.00	NU/DIT	*120.00 F ✓
15	1		*front centre grille chrome	0.00	0.00	SVC	*120.00 F ?
16	1		*front centre grille top garnish	0.00	0.00	NU	*50.00 F ✓
17	8		*front centre grille top garnish clip	0.00	0.00	Ar	*12.00 F ✓
18	1		*front support panel 400	0.00	0.00	DIT	*380.00 F ✓
19	1		*front support panel centre pillar 45	0.00	0.00	Ar	*150.00 F X
20	1		*front support panel side garnish 40	0.00	0.00	dd	*35.00 F ?
21	1		*front A/C condensor 400	0.00	0.00	BT	*480.00 F ?
22	1		*front A/C condensor pipe 1	0.00	0.00	SVC	*180.00 F ?
23	1		*front A/C condensor pipe 2	0.00	0.00	SVC	*190.00 F ?
24	1		*front A/C condensor motor	0.00	0.00	SVC	*90.00 F ?
25	1		*front A/C condensor motor fan	0.00	0.00	SVC	*70.00 F ?
26	1		*front radiator 480	0.00	0.00	BT	*580.00 F ?
27	1		*front radiator top hose	0.00	0.00	Sm	*35.00 F X
28	1		*front radiator lower hose	0.00	0.00	Sm	*25.00 F X
29	1		*front radiator cowlng 70	0.00	0.00	CRA	*90.00 F ?
30	1		*front radiator cowlng top garnish 40	0.00	0.00	CRA	*50.00 F ?
31	1		*front radiator cowlng lower garnish	0.00	0.00	SVC	*90.00 F ?
32	1		*front radiator cowlng motor	0.00	0.00	SVC	*150.00 F ?
33	1		*front radiator cowlng motor fan	0.00	0.00	SVC	*90.00 F ?
34	1		*front radiator spare tank 70	0.00	0.00	M3 DIT	*75.00 F ✓
35	2		*front fender 400	0.00	0.00	Ar	*390.00 F ✓
36	2		*front wiper garnish side garnish	0.00	0.00	Sm	*70.00 F X
37	1		*front battery bracket 25	0.00	0.00	Ar	*35.00 F ✓

F=Franchise part.

Sub Total (\$)	4,984.00
+ Margin on L,N Items 10.00% (\$)	498.40
Total Parts (\$)	5,482.40

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Materials			
1	1	spray painting	1,400.00
Sub Total (\$)			1,400.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Materials			
1	1	spray painting	1,400.00
Sub Total (S\$)			1,400.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	1set front number plate & casing	New	50.00
2	remove & refit radiator & cooler	New	180.00
3	remove & refit air-con & gas	New	180.00
4	wiring	New	80.00
5	labour	New	1,000.00
Gross Labour Cost (S\$)			1,490.00

Hui Yang Motor Pte Ltd/SLB15E/28/03/2018 12:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5709.80
 8 6609.80 BY excess
 —————
 —————

PAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 28 Mar 2018)

Parts: M1-MPV

TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB15E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*front bonnet			255
2	1		*front bonnet inner lock	0.00	0.00	198.00F
3	1		*front bonnet TOYOTA logo	0.00	0.00	45.00F
4	2		*front bonnet hinge	0.00	0.00	25.00F
5	1		*front bonnet inner cardboard	0.00	0.00	50.00F
6	6		*front bonnet inner cardboard clip	0.00	0.00	150.00F
7	1		*front bonnet inner stopper RH	0.00	0.00	3.00F
8	2		*front headlamp	0.00	0.00	2.76
9	1		*front bumper	0.00	0.00	500
10	2		*front bumper side retainer @ 30 RH 25 LH TOTAL 65	0.00	0.00	178.00F
11	20		*front bumper clip	0.00	0.00	65
12	1		*front bumper sponge	0.00	0.00	20.00F
13	1		*front bumper reinforcement	0.00	0.00	50
14	1		*front centre grille	0.00	0.00	86
15	1		*front centre grille chrome	0.00	0.00	145
16	1		*front centre grille top garnish	0.00	0.00	120.00F
17	8		*front centre grille top garnish clip	0.00	0.00	50.00F
18	1		*front support panel	0.00	0.00	12.00F
19	1		*front support panel centre pillar	0.00	0.00	400
20	1		*front support panel side garnish	0.00	0.00	45
21	1		*front A/C condensor	0.00	0.00	40
22	1		*front A/C condensor pipe 1	0.00	0.00	400
23	1		*front A/C condensor pipe 2	0.00	0.00	180.00F
24	1		*front A/C condensor meter	0.00	0.00	190.00F
25	1		*front A/C condensor meter fan	0.00	0.00	90.00F
26	1		*front radiator	0.00	0.00	70.00F
27	1		*front radiator top hose	0.00	0.00	480
28	1		*front radiator lower hose	0.00	0.00	35.00F
29	1		*front radiator cowl	0.00	0.00	25.00F
30	1		*front radiator cowl top garnish	0.00	0.00	70
31	1		*front radiator cowl lower garnish	0.00	0.00	40
32	1		*front radiator cowl motor	0.00	0.00	90.00F
33	1		*front radiator cowl motor fan	0.00	0.00	150.00F
34	1		*front radiator spare tank	0.00	0.00	90.00F
35	2		*front fender	0.00	0.00	70
36	2		*front wiper garnish side garnish	0.00	0.00	10
37	1		*front battery bracket	0.00	0.00	70.00F
						25
Sub Total (\$)						4,984.00
+ Margin on L,N Items 10.00% (\$)						498.40
Total Parts (\$)						5,482.40

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Materials

1 1 spray painting

Total: Parts cost b/f GST \$3468.00

Amount

1,400.00

Sub Total (\$)

1,400.00

Estimates on Labour

No Particulars

Lab.Type

Amount



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL : 64515752 / LEE83336725 FAX : 64514658

ATTN : LEE / AH WEI :98625891.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9938



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 64

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201804-0003:
DATE : 02/04/2018
CUSTOMER ID : HUI00:
VEH REG. NO. : SLB15H
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID

T53292-68020

ZGE20

16

DESCRIPTION

RAD SUPPORT TOP GARNISH

StkLoc

U1

I.2-A14

QTY

1

U/PRICE

50.00

AMOUNT

50.00

SUB-TOTAL :

50.00

ADD GST 7.00 %

3.50

E & O.E

TOTAL AMOUNT SGD :

53.50

[P] 02/04/2018 5:44:51PM

[E] 02/04/2018 5:33:36PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JASON



* A R 2 0 1 8 0 4 - 0 0 0 3 8 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL : 64515752 / LEE83336725 FAX : 64514658

ATTN : LEE / AH WEI :98625891.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9839



Dept Direct: 6305 9510

Dept Direct: 6305 9511

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

TAX INVOICE : AR201804-0004
DATE : 02/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB151
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGI

SQ STOCKID

1. T53510-68020

ZGE20

2. T16470-37030

ZGE20

DESCRIPTION

FRT BONET LOCK

RAD SPARE TANK

StkLoc

UI

SUPPLIER

UI

SUPPLIER

QTY

1

1

U/PRICE

45.00

70.00

AMOUNT

45.00

70.00

SUB-TOTAL : 115.00
ADD GST 7.00 % 8.05

[P] 02/04/2018 9:59:33AM

E & OE

TOTAL AMOUNT SGD : 123.05

[E] 02/04/2018 5:47:25PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JASON



* AR201804-00040 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9839

Arrange By

Driver

[Signature]



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL : 64515752 / LEE83336725 FAX : 64514658

ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-0003
DATE : 02/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB15
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of
CURR : SGI

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T81130-68070 ZGE20	HEAD LAMP RH (9)	PA PL2-E1-050	1	250.00	250.0
2.	T81170-68070 ZGE20	HEAD LAMP LH (9)	PA PL2-D1-11A	1	250.00	250.0
3.	T53410-68030 ZGE20	FRT BONET HINGE RH (X)	PA PL2-J1-08A	1	25.00	25.0
4.	T53420-68030 ZGE20	FRT BONET HINGE LH (X)	PA PL2-K1-09I	1	25.00	25.0
5.	T52119-68909 ZGE20	FRT BUMPER (a)	PA PL4-E1-28	1	180.00	180.0
6.	T52611-68030 ZGE20	FRT BUMPER SPONGE (12)	PA PL2-H1-11A	1	50.00	50.0
7.	T53201-68021 ZGE20	RAD SUPPORT PANEL (18)	PA PL2-A1-14A	1	400.00	400.0

CONTINUE NEXT PAGE

[P] 29/03/2018 5:45:45PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 02/04/2018 5:33:27PM

[Signature]



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9839



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9798

Dept Direct: 6417 9792

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL : 64515752 / LEE83336725 FAX : 64514658

ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-0003
DATE : 02/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB15
TERMS : 30 day
PO NO. :
PAGE NO. : Page 2 of
CURR : SGI

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUN
8.	T52021-68020 ZGE20	(13) FRT BUMPER REINFORCEMENT	PA PL2-G1-07B	1	85.00	85.0
9.	T53811-68060 ZGE20	FRT FENDER RH (35)	PA PL2-E1-08B	1	195.00	195.0
10.	T75303-68010 ZGE20	FRT EMBLEM (3)	PA PL2-K1-09Y	1	25.00	25.0

SUB-TOTAL : 1,485.00
ADD GST 7.00 % 103.95

E. & O.E

TOTAL AMOUNT SGD : 1,588.95

[P] 29/03/2018 5:45:45PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 02/04/2018 5:33:27PM

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.

No signature is required.



AR201804-00037

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9839



TOYOTA
KIA

LEXUS

DA

Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9782



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea).
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL: 64515752 / LEE83336725 FAX : 64514658

ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-00312

DATE : 02/04/2018

CUSTOMER ID : HUI001

VEH REG. NO. : SLB15E

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53301-68020	FRT BONET	U1	1	255.00	255.00
ZGE20		SUPPLIER			
2. T53101-68010	FRT GRILLE	U1	1	145.00	145.00
ZGE20		SUPPLIER			
3. T53812-68060	FRT FENDER L.H	U1	1	215.00	215.00
ZGE20		SUPPLIER			
4. T74404-20640	BATTERY CLAMP	U1	1	25.00	25.00
NZT260		SUPPLIER			

SUB-TOTAL : 640.00
ADD GST 7.00 % 44.80

E & O.E

TOTAL AMOUNT SGD : 684.80

[P] 02/04/2018 11:17:08AM

[E] 02/04/2018 11:14:42AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : LOON



This is computer generated document.

No signature is required.

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL: 64515752 / LEE83336725 FAX: 64514658

ATTN: LEE / AH WEI :98625891.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9839



Dept Direct: 6305 9810

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 64

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

TAX INVOICE : AR201804-0004
DATE : 02/04/2018
CUSTOMER ID : HUI001
VEH REG. NO. : SLB15E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID

1. T53208-68020

ZGE20

DESCRIPTION
BRACE PANEL

StkLoc

QTY

U/PRICE

AMOUNT

UI

1

45.00

45.00

SUPPLIER

SUB-TOTAL : 45.00

ADD GST 7.00 % 3.15

E. & O.E

TOTAL AMOUNT SGD : 48.15

[P] 02/04/2018 10:00:05AM

[E] 02/04/2018 9:59:42AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JASON



* AR 201804-00044 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 8745 9630



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 64

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL: 64515752 / LEE83336725 FAX: 64514658

ATTN: LEE / AH WEI :98625891.

TAX INVOICE : AR201804-0074
DATE : 02/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB15
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of
CURR : SGI

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
T90467-07211 GRS190	RAD TOP SEAL CLIP	PA PL2-K1-03I	8	1.50	12.0

SUB-TOTAL : 12.00
ADD GST 7.00 % 0.84

E. & O.E

TOTAL AMOUNT SGD : 12.84

[P] 02/04/2018 4:17:52PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 02/04/2018 4:16:03PM

JAE Auto Pte. Ltd.

Sales Executive: JASON



AR201804-00741

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454444 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9930



Dept Direct: 6417 9794

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct: 6417 8792

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL: 64515752 / LEE 83336725 FAX: 64514658

ATTN: LEE / AH WEI 98625891.

TAX INVOICE : AR201804-00045
DATE : 02/04/2018
CUSTOMER ID : HUI001
VEH REG. NO. : SLB15E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
190541-15004	STOPPER	U1	1	6.00	6.00
ACV40		I.2-77-9			
T52115-68030/1	FRT BUMPER S/RETAINER RH	U1	1	30.00	30.00
ZGE20		I.2-B8-C			
T52161-16010 ROC	BUMPER CLIP	U1	20	1.00	20.00
ALL MODEL		I.2-T9			
16410-37201	RADIATOR	U1	1	480.00	480.00
ZGE20		I.3-D6			

SUB-TOTAL : 536.00
ADD GST 7.00 % 37.52

E. & O.E TOTAL AMOUNT SGD : 573.52

[P] 02/04/2018 4:16:48PM

[E] 02/04/2018 10:00:13AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JASON



AR201804-00045

Goods Received in Good Order

[Signature]

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 198307741M

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL: 64515752 / LEE83336725 FAX: 64514658

ATTN: LEE / AH WEI :98625891.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9839



Dept Direct: 6417 9794



Dept Direct: 6305 9810



TOYOTA
DEPT. DIR. 6305 9810

LEXUS
DEPT. DIR. 6417 9792

HONDA
DEPT. DIR. 6417 9796

SUBARU
DEPT. DIR. 6417 9792

NISSAN
DEPT. DIR. 6417 9792

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201804-00743
DATE : 02/04/2018
CUSTOMER ID : HUI001
VEH REG. NO. : SLB15E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

STOCKID

T52116-68030/1
ZGE20



DESCRIPTION
FRT BUMPER S/RETAINER LH

StkLoc	QTY	U/PRICE	AMOUNT
UI	1	35.00	35.00
SUPPLIER			

SUB-TOTAL : 35.00
ADD GST 7.00 % 2.45

E. & O.E

TOTAL AMOUNT SGD : 37.45

[P] 03/04/2018 12:33:40PM

[E] 02/04/2018 4:17:02PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JASON



AR201804-00743

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL : 64515752 / LEE83336725 FAX : 64514658

ATTN : LEE / AH WEI :98625891.

WINDSCREEN GLASS
 Dept Direct: 6417 9791 / 6745 9030



Dept Direct: 6305 9610



Dept Direct: 6417 9794



Dept Direct: 6305 9611



Dept Direct: 6417 9795



Dept Direct: 6305 9611



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795



Dept Direct: 6417 9795

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

TAX INVOICE : AR201804-01401
DATE : 03/04/2018
CUSTOMER ID : HU001
VEH REG. NO. : SLB15E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID

T88450-12280-J

NZE141 ZGE20

T16711-37070

ZGE20

DESCRIPTION

A/C CONDENSER (1331) (J)

RAD FAN COWING

StkLoc

U1

L3-A17

U1

L3-Q8

QTY

1

1

U/PRICE

400.00

70.00

AMOUNT

400.00

70.00

SUB-TOTAL : 470.00

ADD GST 7.00 % 32.90

E. & O.E

TOTAL AMOUNT SGD : 502.90

[P] 03/04/2018 2:51:22PM

[E] 03/04/2018 2:49:39PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JASON



* A R 2 0 1 8 0 4 - 0 1 4 0 1 *

Goods Received in Good Order

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 641

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL : 64515752 / LEE83336725 FAX : 64514658

ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-0144
DATE : 03/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB15
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of
CURR : SGI

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53299-68010 ZGE20	RAD SUPPORT GARNISH LH	PA PL2-E1-04D	1	40.00	40.00

SUB-TOTAL : 40.00
ADD GST 7.00 % 2.80

E. & O.E

TOTAL AMOUNT SGD : 42.80

[P] 03/04/2018 3:12:27PM

[E] 03/04/2018 3:09:58PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.

No signature is required.



* A R 2 0 1 8 0 4 - 0 1 4 4 0 *

ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9639

Arrange By

Driver

W. CORN



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 641

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL : 64515752 / LEE83336725 FAX : 64514658

ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-0140
DATE : 03/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB15
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of
CURR : SGI

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T16712-37040 ZGE20	RAD FAN COWING TOP GUIDE	PA PL2-D1-04B	1	40.00	40.00

30

SUB-TOTAL : 40.00
ADD GST 7.00 % 2.80

E. & O.E

TOTAL AMOUNT SGD : 42.80

[P] 03/04/2018 2:52:59PM

[F] 03/04/2018 2:51:29PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.

No signature is required.



AR201804-01405

ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Mar 2018 Sendback Est	28 Mar 2018 12:43 \$8,372.40	29 Mar 2018 10:00 Edit Adj Rpt	\$5,709.80 Edit Estimates	\$5,709.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N								
Vehicle Reg. No.:	SLB15E	Date of Loss:	27/03/2018 12:00 - :59 [13 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 553830	Policy/Cover Note No.:	A28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018						
		Excess:	S\$700.00						
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/04/2018]								
Driver/Custodian:	MOHAMAD RAIZAL BIN RAHIM (41 / Male), NRIC: S7625509A								
Adj Asg. Remarks:	Please revert.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (12/04/2018): Alert - Adj Mandate Approved (\$5709.80) - SLB15E - Claim Handler: Joslin Lim - MSIG_SG (02/04/2018): Alert - Adj Mandate Approved (\$5363.50) - SLB15E - Claim Handler: Joslin Lim - MSIG_SG (02/04/2018): Re: SLB15E									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLB15E (553830)
OD
Mar 27 2018 12:00PM
[SKYWAY MOTOR PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View In Browser v	
Assessment Reports				1 per page v	☒
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)		Thumbnail	Print
1	28/03/18 12:43	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/04/18 11:49	Adjuster Immediate Advice		Load HTM	
2	12/04/18 12:03	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/04/18 11:24	General View		Load JPG	☒
2	02/04/18 11:24	General View		Load JPG	☒
3	02/04/18 11:24	General View		Load JPG	☒
4	02/04/18 11:24	General View		Load JPG	☒
5	02/04/18 11:24	General View		Load JPG	☒
6	02/04/18 11:24	General View		Load JPG	☒
7	02/04/18 11:24	General View		Load JPG	☒
8	02/04/18 11:24	General View		Load JPG	☒
9	02/04/18 11:24	General View		Load JPG	☒
10	02/04/18 11:24	General View		Load JPG	☒
11	02/04/18 11:24	General View		Load JPG	☒
12	02/04/18 11:24	General View		Load JPG	☒
13	02/04/18 11:24	General View		Load JPG	☒
14	02/04/18 11:24	General View		Load JPG	☒
15	02/04/18 11:24	General View		Load JPG	☒
16	02/04/18 11:24	General View		Load JPG	☒
17	02/04/18 11:24	General View		Load JPG	☒
18	02/04/18 11:24	General View		Load JPG	☒
19	02/04/18 11:24	General View		Load JPG	☒
20	02/04/18 11:24	General View		Load JPG	☒
21	02/04/18 11:24	General View		Load JPG	☒
22	02/04/18 11:24	General View		Load JPG	☒
23	02/04/18 11:24	General View		Load JPG	☒
24	02/04/18 11:25	General View		Load JPG	☒
25	02/04/18 11:25	General View		Load JPG	☒
26	02/04/18 11:25	General View		Load JPG	☒
27	02/04/18 11:25	General View		Load JPG	☒
28	02/04/18 11:25	General View		Load JPG	☒
29	02/04/18 11:25	General View		Load JPG	☒
30	02/04/18 11:25	General View		Load JPG	☒
31	02/04/18 11:25	General View		Load JPG	☒
32	02/04/18 11:25	General View		Load JPG	☒
33	12/04/18 11:33	Reinspection Photo		Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)	Thumbnail	Print
				☒
34	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
35	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
36	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
37	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
38	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
39	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
40	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
41	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
42	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
43	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
44	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
45	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
46	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
47	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
48	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
49	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
50	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
51	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
52	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
53	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
54	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
55	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
56	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
57	12/04/18 11:33	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/18 11:49	MARK ESTIMATE	 Load PDF	
2	12/04/18 12:03	1ST MARK ESTIMATE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18005835/KVBE2

Date: 19/04/2018

REFERENCE

Insured/Claimant:	SKYWAY MOTOR PTE LTD	Policy No:	A28795104MCX	
Date of Loss:	27/03/2018	Nature of Claim:	OD	Claim No: 553830

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB15E	Engine No:	2ZR1835717
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE206035420
Reg. Date:	22/02/2017 (Man. Year: 2016)	Odometer:	80907 km
Colour:	Metallic Blue		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 8 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,482.40	3,814.80	1,667.60	30.42
Miscellaneous Items	0.00	0.00	0.00	
Paintwork Materials	1,400.00	1,080.00	320.00	22.86
Labour	1,490.00	815.00	675.00	45.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,372.40	5,709.80	2,662.60	31.80
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	7,672.40	5,009.80	2,662.60	34.70
+ GST 7.00/7.00% (S\$)	537.07	350.69	186.38	34.70
Nett Amount (S\$)	8,209.47	5,360.49	2,848.98	34.70

INSPECTION

Date of Assignment:	29/03/2018 Present Location:	Hui Yang Motor Pte Ltd (HQ)
Date Inspected:	29/03/2018 Inspected At:	176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2018)

Parts: M1-MPV TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB15E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*front bonnet	Buckled	190.00 F	*255.00 F
2	1		*front bonnet inner lock	Distorted	45.00 F	*45.00 F
3	1		*front bonnet TOYOTA logo	Necessary	35.00 F	*25.00 F
4	2		*front bonnet hinge	Distorted	50.00 F	*50.00 F
5	1		*front bonnet inner cardboard	Serviceable	150.00 F	*- F
6	6		*front bonnet inner cardboard clip	Not Necessary	9.00 F	*- F
7	1		*front bonnet inner stopper RH	Missing	8.00 F	*6.00 F
8	2		*front headlamp	MTG Cracked	540.00 F	*500.00 F
9	1		*front bumper	Buckled	170.00 F	*180.00 F
10	2		*front bumper side retainer	Distorted	70.00 F	*65.00 F
11	20		*front bumper clip	Necessary	20.00 F	*20.00 F
12	1		*front bumper sponge	Cracked	45.00 F	*50.00 F
13	1		*front bumper reinforcement	Bent	95.00 F	*85.00 F
14	1		*front centre grille	Dented / Distorted	120.00 F	*145.00 F
15	1		*front centre grille chrome	Serviceable	120.00 F	*- F
16	1		*front centre grille top garnish	Dented	50.00 F	*50.00 F
17	8		*front centre grille top garnish clip	Necessary	12.00 F	*12.00 F
18	1		*front support panel	Buckled	380.00 F	*400.00 F
19	1		*front support panel centre pillar	Distorted	150.00 F	*45.00 F
20	1		*front support panel side garnish	Dented	35.00 F	*40.00 F
21	1		*front A/C condensor	Bent	480.00 F	*400.00 F
22	1		*front A/C condensor pipe 1	Serviceable	180.00 F	*- F
23	1		*front A/C condensor pipe 2	Serviceable	190.00 F	*- F
24	1		*front A/C condensor motor	Serviceable	90.00 F	*- F
25	1		*front A/C condensor motor fan	Serviceable	70.00 F	*- F
26	1		*front radiator	Bent	580.00 F	*480.00 F
27	1		*front radiator top hose	Serviceable	35.00 F	*- F
28	1		*front radiator lower hose	Serviceable	25.00 F	*- F
29	1		*front radiator cowl	Cracked	90.00 F	*70.00 F
30	1		*front radiator cowl top garnish	Cracked	50.00 F	*40.00 F
31	1		*front radiator cowl lower garnish	Serviceable	90.00 F	*- F
32	1		*front radiator cowl motor	Serviceable	150.00 F	*- F
33	1		*front radiator cowl motor fan	Serviceable	90.00 F	*- F
34	1		*front radiator spare tank	MTG Distorted	75.00 F	*70.00 F
35	2		*front fender	Buckled	390.00 F	*410.00 F
36	2		*front wiper garnish side garnish	Serviceable	70.00 F	*- F
37	1		*front battery bracket	Bent	35.00 F	*25.00 F

F=Franchise part.

Sub Total (S\$) 4,984.00 3,468.00

+ Margin on L,N Items 10.00/10.00% (S\$) 498.40 346.80

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					5,482.40	3,814.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Materials				
1	1	spray painting	1,400.00	1,080.00
Sub Total (S\$)			1,400.00	1,080.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	1set front number plate & casing (DENTED)	New	50.00	45.00
2	remove & refit radiator & cooler	New	180.00	50.00
3	remove & refit air-con & gas	New	180.00	100.00
4	wiring	New	80.00	20.00
5	labour	New	1,000.00	600.00
Gross Labour Cost (S\$)			1,490.00	815.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >