

AS REC. BY:

REF: CS/ms6718005836/Urb⁷²

Special Instruction:

Surveyor: MARWIS

ASSIGNMENT (Office)

From (Person): Meimien Pearllyn Kang

of MSIH

Date/Time: 29/03/2018 10:32am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGM 9797 Z

Insured:

at Workshop m/s Tan Lim Motor

Tel:

of 51 Defu Lane 10

Policy No: ASD415703 QMX

Claim No: 553883

Sum Insured:

Excess: \$ 500.00

Make of Veh:

D.O.A. 27/03/2018

(Client's Record)

02.04.2018 @ after 10am

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 29/03/2018 10:48am

Person Contacted: William

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SGM 9797 Z - X</u>
	<u>Sent preli thru meimien</u>
	<u>Mandate approve ; Inform William to proceed.</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005836/Urb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-03-2018	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
	Insured Veh.	Veh. Inspected	SGM 9797Z
	Policy No. A80415703QMX	Coverage (\$)	0.00
	Claim No.	Excess (\$)	500.00
	Assign From MERIMEN (PEARLLYN KANG)	Assign Date	29/03/2018
2. Vehicle Particulars & Condition			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre		Balance
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date 27/03/2018	Inspection Date	02/04/2018
	Survey held at TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 02 Apr 2018

Preliminary Advice

Vehicle No	: SGM9797Z	Accident Date	: 27/03/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: A80415703QMX
Assignment Date	: 29/03/2018	Excess	: S\$500.00
Date of Inspection	: 02/04/2018	Est. Duration of Repair	: 4.00
Inspection At	: TAN LIM MOTOR PTE LTD (DEFU) 51 DEFU LANE 10 SINGAPORE 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,019.70
Revised Amount	:S\$	1,815.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,815.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	24,000.00
COE / PARF Rebate	:S\$	18,491.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,509.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2018 Sendback Est	28 Mar 2018 11:59 S\$4,019.70	29 Mar 2018 10:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CHIA YONG SOON, ID: S0195623Z, Tel: +6598231709, Email: chia.y.s@hotmail.com									
Vehicle Reg. No.:	SGM9797Z	Date of Loss:	27/03/2018 08:00 - :59						
Claim Type:	OD / 553883	Policy/Cover Note No.:	A80415703QMX (Comprehensive) Coverage: 02/11/2017 - 01/11/2018						
		Excess:	S\$500.00						
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearlyn Kang Yen Lin - 6594 2588]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/03/2018]								
Driver/Custodian:	CHIA ZONG HUA (30 / Male), NRIC: S8717139F, Tel: +6598511165								
Adj Asg. Remarks:	Please survey and revert. Please advise on the MV as well. Thank you.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5623Z
Vehicle Details	
Vehicle No.:	SGM9797Z
Vehicle to be Exported:	No
Intended De-registration Date:	02 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4608758
Chassis No.:	MR053ZEC107133107
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,498.00
Original Registration Date:	02 Nov 2006
First Registration Date:	02 Nov 2006
Transfer Count:	0
Actual ARF Paid:	\$17,048.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Nov 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$25,821.00
COE Rebate Amount:	\$18,491.00
Total Rebate Amount:	\$18,491.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Apr 2018

OK

Print Received Message

This mail is associated with :

SGM9797Z (553883)

OD

Mar 27 2018 8:00AM

[CHIA YONG SOON]

Tan Lim Motor Pte Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 03/04/2018 09:40 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1815.80) - SGM9797Z - Claim Handler: Pearllyn Kang Yen Lin

Approved:1815.80.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, April 03, 2018 10:40 AM
To: 'wei.shong@tlmotor.com.sg'
Cc: SUR
Subject: SGM 9797Z MSIG OD DOA: 27.03.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGM 9797Z (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2018 17:26
Date Of Accident	27/03/2018 08:30
Exact Location Of Accident	AYE TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM9797Z
Insured/Policyholder	
Name Of Registered Owner	CHIA YONG SOON
NRIC No	S0195623Z
Email Address	CHIA.YS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98231709
Alternative Phone No	OFFICE-98231709

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80415703QMX
Cover Note Number	

Driver

Name of Driver	CHIA ZONG HUA
NRIC No	S8717139F
Date Of Birth	04/06/1987
Occupation	INDOOR
Date Of Driving Pass	30/03/2007
Driving Experience	10 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98511165
Fax Number	
Contact Number	
E-Mail Address	XIE.ZONGHUA@GMAIL.COM

Address	BLOCK 698D HOUGANG STREET 52 #04-23
Postcode	538698
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 27.03.2018 at about 0830hours, I was driving my vehicle (A: SGM9797Z) along AYE towards CTE. The traffic was congested due to the wet weather. The vehicle (B: SKZ1771J) in front of me was inching forward due to road congestion. I followed suit and tried to make a brake, but to no avail. My vehicle's front portion had hit onto the rear portion of vehicle B. Vehicle A (SGM9797Z) : no passenger onboard. Vehicle B (SKZ1771J) : 1 female passenger onboard.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ1771J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 27/03/18
1800hrs.


Driver's Signature

(If driver is not the policyholder)
Date & Time: 27/03/18
1800hrs

Reporting Centre Personnel's Signature

Name: Raymen On
NRIC/FIN No.: 62859646X

SKETCH PLAN



Aye towards
CTE

A: SG M9797Z


B: SKZ1771J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to GIA report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time: 27/03/18
1800hrs


Driver's Signature
(If driver is not the policyholder)
Date & Time: 27/03/18
1800hrs


Reporting Centre Personnel's Signature
Name: Caymen Ow
NRIC/FIN No.: G2859646X

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5623Z

Vehicle Details

Vehicle No.: SGM9797Z
Vehicle to be Exported: Yes
Intended De-registration Date: 27 Mar 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Silver
Manufacturing Year: 2006
Engine No.: 3ZZ4608758
Chassis No.: MR053ZEC107133107
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$15,498.00
Original Registration Date: 02 Nov 2006
First Registration Date: 02 Nov 2006
Transfer Count: 0
Actual ARF Paid: \$17,048.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 01 Nov 2021
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$25,821.00
COE Rebate Amount: \$18,574.00
Total Rebate Amount: \$18,574.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Mar 2018

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD021032018
Policy No:	A80415703QMX	Date of Loss:	27/03/2018
Vehicle Reg. No.:	SGM9797Z	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHIA YONG SOON	Contact No:	+6598231709
Driver:	CHIA ZONG HUA		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	02/11/2006
Vehicle Colour:	SILVER	Chassis No:	MR053ZEC107133107
Engine No:	3ZZ4608758		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

*NOT Authorized 4 day.
Tel: 62563581
Excess?
Take photo before repairing
2/4/18*

Description of Accident/Loss
ON 27.03.2018 AT ABOUT 0830HOURS, I WAS DRIVING MY VEHICLE (A: SGM9797Z) ALONG AYE TOWARDS CTE. THE TRAFFIC WAS CONGESTED DUE TO THE WET WEATHER. THE VEHICLE (B: SKZ1771J) IN FRONT OF ME WAS INCHING FORWARD DUE TO ROAD CONGESTION. I FOLLOWED SUIT AND TRIED TO MAKE A BRAKE, BUT TO NO AVAIL. MY VEHICLE'S FRONT PORTION HAD HIT ONTO THE REAR PORTION OF VEHICLE B.

Present Location: TAN LIM MOTOR PTE LTD (DEFU)
VEHICLE A (SGM9797Z) : NO PASSENGER ONBOARD. VEHICLE B (SKZ1771J) : 1 FEMALE PASSENGER ONBOARD.

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	2,229.70
Labour	0.00
Paintwork Labour	1,790.00
Towing	0.00
	0.00
Calculated Gross Total (\$\$)	4,019.70
- Excess (\$\$)	500.00
	3,519.70
+ GST 7.00% (\$\$)	246.38
Nett Amount (\$\$)	3,766.08

KK Auto Consultants hence notify the Repairer of the following:
 • To repair by buff, weather spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No remedial modification(s) is allowed
 • Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Mar 2018)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Tan Lim Motor Pte Ltd/SGM9797Z/28/03/2018 11:59
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet - repair	0.00	0.00	1 *260.00 F X
2	1		*Front Support Panel	0.00	0.00	1 *300.00 F X
3	1		*Front Bumper	0.00	0.00	1 *120.00 F
4	1		*Front bumper reinforcement	0.00	0.00	1 *120.00 F
5	2		*Front bumper side retainer	0.00	0.00	2 *16.00 F
6	8		*Front bumper clips	0.00	0.00	8 *12.00 F
7	1		*Front bumper lower splashield cover	0.00	0.00	1 *60.00 F X
8	6		*Front bumper lower splashield cover clips	0.00	0.00	6 *9.00 F X
9	1		*Front licence plate	0.00	0.00	1 *20.00 F
10	1		*Front licence plate radiator assy	0.00	0.00	1 *330.00 F X
11	1		*Radiator grille	0.00	0.00	1 *100.00 F
12	1		*Radiator grille emblem badge	0.00	0.00	1 *15.00 F
13	1		*Radiator grille brace panel	0.00	0.00	1 *35.00 F
14	1		*Horn	0.00	0.00	1 *30.00 F X
15	2		*Head-lamp assy	0.00	0.00	2 *240.00 F
16	1		*Air Con condenser	0.00	0.00	1 *360.00 F X

F=Franchise part.

Sub Total (S\$)	2,027.00
+ Margin on L,N Items 10.00% (S\$)	202.70
Total Parts (S\$)	2,229.70

Tan Lim Motor Pte Ltd/SGM9797Z/28/03/2018 11:59. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

P-658

Estimate Report

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	450 700.00
2	Putty and spray painting of the affected portion.	New	600 850.00
3	To check electrical lighting concerned.	New	20 60.00
4	To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	New	190 180.00
Gross Labour Cost (S\$)			1,790.00

Tan Lim Motor Pte Ltd/SGM9797Z/28/03/2018 11:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlimotor.com.sg www.tlimotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: TAN LIM MOTOR PTE LTD**

51 DEFU LANE 10

SINGAPORE 539216

ZZE121TH (SGM 9797Z)

ATT: AH HWA

NO: DLI9201463

PAGE: 1

DATE: 02/04/2018

A/C CODE: LDTL178

TERMS: CR

P/O NO: SGM 9797Z ✓

P/O 90029

OP 201803021

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
1	2119-02923	BUMPER FR	DB2C	1	120.00	120.00
2	T52021-02101	BUMPER REINF FR	DB116L	1	120.00	120.00
3	T52115-12400-1	BUMPER RETAINER FR RH	DU1AD29-1 ✓	1	8.00	8.00
4	T52116-12360-1	BUMPER RETAINER FR LH	DU1AD43-4 ✓	1	8.00	8.00
5	T52161-0K040	CLIP,FR BUMPER	DU1AD10-10 ✓	8	1.50	12.00
6	T53100-02220	GRILLE	DB113	1	100.00	100.00
7	T75311-02160	GRILLE LOGO	DD1AS2-27	1	15.00	15.00
8	T53208-12500-TH	BRACE PANEL	DDS	1	35.00	35.00
9	T81130-02300	H/LAMP RH	DB1HS	1	120.00	120.00
10	T81170-02290	H/LAMP LH	DDS	1	120.00	120.00
TOTAL QUANTITY:			17	TOTAL	SIN 658.00	
					ADD GST @ 7%	46.06
					GRAND TOTAL	SIN 704.06

Print: YAM / 02/04/2018 10:26:35 AM

SALESMAN: YAM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



E.O.E
CHEVROLET
PARTS

GOODS RECEIVED BY



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18005836/URBN2

Date: 09/04/2018

REFERENCE

Insured/Claimant: CHIA YONG SOON	Policy No: A80415703QMX	Claim No: 553883	
Date of Loss: 27/03/2018	Nature of Claim: OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGM9797Z	Engine No: 3ZZ4608758
Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No: MR053ZEC107133107
Reg. Date: 02/11/2006 (Man. Year: 2006)	Odometer: 175148 km
Colour: Silver	
Engine Capacity: 1598 cc	
Market Value/New Car Price: S\$24,000.00	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/70R14	Rear Tyre Size: 185/70R14
Front Left Side: Sumitomo 5 mm	Rear Left Side: Sumitomo 5 mm
Front Right Side: Sumitomo 5 mm	Rear Right Side: Sumitomo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,229.70	743.80	1,485.90	66.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	1,070.00	720.00	40.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,019.70	1,813.80	2,205.90	54.88
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	3,519.70	1,313.80	2,205.90	62.67
+ GST 7.00/7.00% (S\$)	246.38	91.97	154.41	62.67
Nett Amount (S\$)	3,766.08	1,405.77	2,360.31	62.67

INSPECTION

Date of Assignment: 29/03/2018	Present Location: Tan Lim Motor Pte Ltd (Defu)	
Date Inspected: 02/04/2018	Inspected At: Tan Lim Motor Pte Ltd (Defu)	
	51 Defu Lane 10	
	Singapore 539216	

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM9797Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet - repair (WCP)	Repair	260.00 F	*- F
2	1		*Front Support Panel (WCP)	Repair	300.00 F	*- F
3	1		*Front Bumper (WCP)	Dented/Torn	120.00 F	*120.00 F
4	1		*Front bumper reinforcement (WCP)	Dented	120.00 F	*120.00 F
5	2		*Front bumper side retainer (WCP)	Bent	16.00 F	*16.00 F
6	8		*Front bumper clips (WCP)	Necessary	12.00 F	*12.00 F
7	1		*Front bumper lower splashshield cover (WCP)	Not Necessary	60.00 F	*- F
8	6		*Front bumper lower splashshield cover clips (WCP)	Not Necessary	9.00 F	*- F
9	1		*Front licence plate (SN)	Bent	20.00 F	*20.00 FS
10	1		*Front licence plate radiator assy (WCP)	Not Necessary	330.00 F	*- F
11	1		*Radiator grille (WCP)	Cracked	100.00 F	*100.00 F
12	1		*Radiator grille emblem badge (WCP)	Necessary	15.00 F	*15.00 F
13	1		*Radiator grille brace panel (WCP)	Twisted	35.00 F	*35.00 F
14	1		*Horn (WCP)	Not Necessary	30.00 F	*- F
15	2		*Head-lamp assy (WCP)	Cracked	240.00 F	*240.00 F
16	1		*Air Con condenser (WCP)	Not Necessary	360.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,027.00	678.00
+ Margin on L,N Items 10.00/10.00% (S\$)	202.70	65.80
Total Parts (S\$)	2,229.70	743.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	700.00	450.00
2	Putty and spray painting of the affected portion.	New	850.00	600.00
3	To check electrical lighting concerned.	New	60.00	20.00
4	To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	New	180.00	-
Gross Labour Cost (S\$)			1,790.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >