



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2009 MITSUBISHI LANCER EX 2.0 (SBJ2633J)

Date of Loss 26 March 2018

Time of Loss 14.55

Loss Description SBJ2633J(INS) HIT THE REAR OF
GBB9238M(TP)

Comment

Workshop Details

Total Rebate Amount 14772

Nett Loss Amount \$7,228.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work
completion * 160



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SBJ2633J

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

27/08/2009



Mileage

277876

Age of Vehicle

8

Driver Details

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2009

2009

Make

MITSUBISHI

MITSUBISHI

Model

LANCER EX 2.0

LANCER EX GT 2.0

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

CHIANG WENG HAO

Date of Birth

21 March 1966

dd/mm/yyyy



Age

52

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		▼
Type of Paint		
Chassis No	JMYSTCY4AAU000336	JMYSTCY4AAU00
Engine No	4B11DB3106	4B11DB3106
Engine Capacity		1998
Sum Insured	0	0
Market Value	0	22000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	▼
Driving Experience	32	
Driver License #		
License Type		▼
License Issue Date		dd/mm/yy 
License Expiration Date		dd/mm/yy 
Address	BLK 35, BANGKIT ROAD, #04-02, 679975, Singapore	
Address type	Residential	▼

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Single	
Identification #	S1750509B	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

29/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/40ZR18

Rear Tyre Size

225/40ZR18

Front left side

KUMHO6mm

Rear left side

KUMHO6mm

Front right side

KUMHO6mm

Rear right side

KUMHO6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts					
Add Approve Deny Submit All																
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			BONNET			Dented	400				400	Reviewing	
		2	2			BONNET HINGE			Bent	55				110	Reviewing	
		3	1			BONNET INSULATION			Deformed	70				70	Reviewing	
		4	10			BONNET INSULATION CLIPS			Necessary	3				30	Reviewing	
		5	1			BONNET RUBBER STRIP			Deformed	30				30	Reviewing	
		6	2			BONNET RUBBER STOPPER			Necessary	8				16	Reviewing	
		7	1			BONNET CENTRE RUBBER STOPPER			Necessary	5				5	Reviewing	
		8	1			BATTERY			Serviceable	0	0	0	0	0	Deny	
		9	1			AIR DUCT CLEANER			Serviceable	0	0	0	0	0	Deny	
		10	1			AIR DUCT			Cracked	90				90	Reviewing	
		11	1			FRONT SUPPORT PANEL TOP COVER			Deformed	50				50	Reviewing	
		12	10			FRONT SUPPORT PANEL TOP COVER CLIPS			Necessary	3				30	Reviewing	
		13	1			FRONT SUPPORT PANEL			Bent	650				650	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		14	1			FRONT TOP PANEL			Bent	160				160	Reviewing	
		15	1			WIPER TANK			Serviceable	0	0	0	0	0	Deny	
		16	1			FRONT BUMPER			Cracked	500				500	Reviewing	
		17	1			FRONT BUMPER TOP RETAINER BRACKET			Cracked	60				60	Reviewing	
		18	1			FRONT BUMPER TOP RUBBER			Deformed	40				40	Reviewing	
		19	2			FRONT GRILLE			Cracked	40				80	Reviewing	
		20	1			FRONT GRILLE GARNISH			Cut	320				320	Reviewing	
		21	1			FRONT GRILLE EMBLEM			Cracked	50				50	Reviewing	
		22	10			FRONT GRILLE CLIPS			Necessary	3				30	Reviewing	
		23	1			SET FRONT GRILLE MOULDING			Cracked	310				310	Reviewing	
		24	2			HEADLAMP (RHS & LHS)			Cracked	650				1300	Reviewing	
		25	2			HORN (HIGH & LOW TONE) }			Damaged	70				140	Reviewing	
		26	1			HORN BRACKET }			Bent	0				0	Reviewing	
		27	1			FRONT BUMPER REINFORCEMENT			Dented	250				250	Reviewing	
		28	1			FRONT FOG LAMP N/S			Cracked	280				280	Reviewing	
		29	1			FRONT FOG LAMP O/S			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		30	2			FRONT FOG LAMP COVER			Cut	35				70	Reviewing	
		31	10			FRONT BUMPER CLIPS			Necessary	3				30	Reviewing	
		32	1			TOW HOOK COVER			Serviceable	0	0	0	0	0	Deny	
		33	2			FRONT BUMPER SIDE RETAINER			Necessary	18				36	Reviewing	
		34	2			FRONT FENDER SPLASH SHIELD			Serviceable	0	0	0	0	0	Deny	
		35	20			FRONT FENDER SPLASH SHIELD CLIPS			Serviceable	0	0	0	0	0	Deny	
		36	1			BONNET STAND			Serviceable	0	0	0	0	0	Deny	
		37	1			BONNET STAND CLIP			Serviceable	0	0	0	0	0	Deny	
		38	1			RHS FRONT FENDER			Dented	300				300	Reviewing	
		39	1			A/C CONDENSER C/W RECEIVER DRYER			Dented	500				500	Reviewing	
		40	1			A/C ELECTRICAL FAN ASSY			Damaged	300				300	Reviewing	
		41	1			A/C HIGH PRESSURE HOSE			Serviceable	0	0	0	0	0	Deny	
		42	1			A/C SUCTION HOSE			Serviceable	0	0	0	0	0	Deny	
		43	1			A/C LIQUID HOSE			Serviceable	0	0	0	0	0	Deny	
		44	10			A/C HOSE CLIPS			Serviceable	0	0	0	0	0	Deny	
		45	1			RADIATOR			Dented	80				80	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		46	1			RADIATOR FAN COWLING			Cracked	180				180	Reviewing	
		47	1			RADIATOR ELECTRIC FAN ASSY			Damaged	300				300	Reviewing	
		48	1			RADIATOR TOP HOSE			Cracked	80				80	Reviewing	
		49	1			RADIATOR LOWER HOSE			Necessary	80				80	Reviewing	
		50	10			RADIATOR HOSE CLIP			Necessary	10				100	Reviewing	
		51	1			RADIATOR COOLANT			Necessary	20				20	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD FRONT PANELLING; TO STRAIGHTEN & REPAIRS FRONT FENDERS INNER PANELS & WHEELHOUSINGS AND FRONT CHASSIS MEMBERS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE	1000	0	0	Reviewing		
		2		TO SPRAY PAINTING ON: BONNET (INNER & OUTER), RHS & LHS FRONT FENDERS, FENDERS SUPPORT PANEL & WHEELHOUSINGS, FRONT BUMPER AND BUMPER REINFORCEMENT, BONNET HINGES	900	0	0	Reviewing		
		3		TO REMOVE & REPLACE A/C CONDENSER C/W RECEIVER DRYER & HOSES AS LISTED ABOVE; TO VACUUM & CHARGE UP GAS	100	0	0	Reviewing		
		4		TO REMOVE & REPLACE RADIATOR & HOSES, ELECTRIC FANS AND COWLING TO PRESSURIZE COOLING SYSTEM	60	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		5		TO REMOVE & REPLACE HEADLAMPS; TO CHECK ELECTRICAL WIRINGS & LIGHTS FUNCTIONS AND FOCUS HEADLIGHTS	40	0	0	Reviewing		
		6		TOWING CHARGES	60	0	0	Reviewing		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 7 DAYS	Reviewing			
☐		2	FRONT NUMBER PLATE C/W HOLDER	Reviewing	40	DISTORTED	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$9,277.00			Claim Amount	\$9,277.00			

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$7,077.00	\$7,077.00
Labour	\$2,160.00	\$2,160.00
Miscellaneous	\$40.00	\$40.00

Submit for Review

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

Submit All

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	FINAL LUMP SUM	Reviewing	7400		

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$7,400.00

Claim Amount

\$7,400.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$7,400.00	\$7,400.00

Submit for Review