

Estimate : TP/18-040

M/s AXA Insurance Singapore Pte Ltd

8 Shenton Way
B1-01 AXA Tower
Singapore 068811

Asher

Date : 28th March 2018

Vehicle No : SJK 2517L

Make/ Model : Toyota Vios

Chassis No : 01/00/00

Acc. Date : 02.11.17

Policy No :

Attn : Motor Claims

Tel: 63387288

Fax: 68804838

Email: motor.survey@axa.com.sg

Your Ref : SHC 5476S

S/n.	Qty	Particulars	Unit Price	Amount
<u>Materials</u>				
1	1	Rear Bumper <i>Reh-d</i>		\$ 437.54 ✓
2	1	Rear Bumper Side Holder L/R <i>m</i>	\$ 131.35	\$ 262.70 ✓
3	1	Rear Bumper Lower Spoiler <i>Repr</i>		\$ 681.90 x.
				\$ 1,382.14
			Less 25%	\$ 345.54
				\$ 1,036.61
4	1 set	Reverse Sensor <i>Repr</i>	S/Nett	\$ 250.00 <i>200</i>
				\$ 1,286.61
<u>Labour</u>				
1		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.		\$ 450.00 <i>200</i>
2		To putty and respray painting on rear bumper, rear boot lid, lower spoiler.		\$ 650.00 <i>400</i>
Total				\$ 2,386.61



Success United Pte Ltd

No of Days _____

Re-Survey Before/After Paint

Part By Part/Lump Sum

Surveyed By _____

Contact No. _____

Date of Survey _____

Fax No. _____

NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
L/s 04/04/18
02 Days.

total: 1325.18
L/s: 1050.