



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120
Tel: 64193000
Fax: 68357416

*NOT Authorized
2/18
2/5
Tel: 62563561
Take photo After repair
Tel: 62563561
3 day.*

Dear Sir/Madam

28.03.2018

RE: THIRD PARTY CLAIMS FOR FR4958U AGAINST YOUR
INSURED SLJ4918G , ACCIDENT ON 25.03.2018 AT ALONG ROAD 1
B/363 HOUGANG AVENUE 5 OPEN CARPARK

1 MAGNETO COVER GASKET		\$ 8.40	?
2 MAGNETO COVER		\$ 78.96	?
3 UNDER COWLING ASSY LH	em	\$ 947.16	✓
4 MUFFLER BODY LH	em	\$ 734.64	✓
5 REAR VIEW MIRROR ASSY LH	a	\$ 155.28	α
6 FRONT FENDER	a	\$ 279.50	α
7 PROP STAND	a	\$ 104.96	x
8 FRAME COVER (BLACK)	a	\$ 674.52	α
9 SEAT RAIL	em	\$ 1,048.80	✓
		\$ 4,032.22	
	Less 10%	\$ 403.22	
	Sub Total	\$ 3,629.00	
NETT ITEM			
1 ENGINE OIL (3 X \$28)		\$ 84.00	?
2 TRANSPORT		\$ 30.00	✓
3 LABOUR CHARGES		\$ 250.00	180
	Total	\$ 364.00	
	Sub Total	\$ 3,993.00	

Thanks
TSP

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: