

08/11/18
Summary

REF: ASM (AXA)

W

ASSIGNMENT

Front: Date: 29/03/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 5429P
at Workshop m/s Optima Werkz
of 9A Serangoon North Ave 5

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 879K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res: Yes or No

Lum Sum: 2.8-7 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLK 5429P Yr Regn: 01 / 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Tug Agor C.C. 1496

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 89934 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: N1HP10 02577760

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A/Rim or

Tyre Size: Hapsen 185/65R15

R: Acc

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 9 mm R/Bal: 7 mm

L/Bal: 9 mm L/Bal: 7 mm

D.O.A. 26/3/18 D.O.I. 29/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/4 File m/s to Carline

5/10/18 Confirm 2.8-7 \$16901.60 with 12 working day

(201.8368.88
18/1)

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair:

11

☐ : Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

Survey Fee:

Transportation

2)

Add Fee: ☐ Site Insp \$

1 \$ + RS \$

☐ Interview \$

1 Photos

☐ Tech Insp \$

1 Others

☐ Weekend \$

1

Report Format :

Lump Sum / I.B.I: \$

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2455W
Vehicle Details	
Vehicle No.:	SLK5429P
Vehicle to be Exported:	No
Intended De-registration Date:	02 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	AQUA HYBRID 1.55 A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1NZ8045138
Chassis No.:	NHP102577760
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$19,508.00
Original Registration Date:	19 Jan 2017
First Registration Date:	19 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$44,746.00
Total Rebate Amount:	\$48,496.00

The information contained herein is correct as at 02 Apr 2018

OK

Not Authorized
1-B1
Resony B4 painy
12 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 28 March 2018

Third Party Insurer: AXA

Vehicle No: SLK5429P

Third Party Veh No: SDP1970L

Model: TOYOTA AQUA HYBRID 1.55 A

Date of Accident: 26.03.18

Chassis: NHP102577760

ESTIMATE

QTY	DESCRIPTION	UNIT	SS	AMOUNT	SS
1	REAR TAILGATE			B ₁	\$820.00
1	REAR TAILGATE WINDSCREEN MOULDING			Re	\$35.00
1	REAR TAILGATE LOGO EMBLEM			Re	\$45.90
1	REAR TAILGATE AQUA EMBLEM			Re	\$48.60
1	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM			Re	\$35.00
1	REAR TAILGATE MECHANISM LOCK			Re	\$452.71
1	REAR TAILGATE WEATHERSTRIP			Re	\$291.80
2	REAR TAILLAMP LH + RH			Re	\$1,057.60
2	REAR TAILLAMP LOWER BRACKET LH + RH		\$42.57	Re	\$85.14
1	REAR BUMPER			Re	\$408.31
10	REAR BUMPER CLIP		\$5.78	Re	\$57.80
1	REAR BUMPER LOWER UNDER COVER			CM	\$139.10
2	REAR BUMPER SIDE RETAINER LH + RH		\$68.28	Re	\$136.56
1	REAR BUMPER REINFORCEMENT			Re	\$278.40
2	REAR BUMPER REINFORCEMENT BRACKET LH + RH		\$115.70	Re	\$231.40
1	REAR END PANEL			Re	\$629.80
1	REAR END PANEL INNER TOP GARNISH			Re	\$191.40
4	REAR END PANEL INNER TOP GARNISH CLIP		\$6.21	Re	\$24.84
1	REAR END PANEL TAILGATE ANTENNA SENSOR			Re	\$144.20
1	FRONT BONNET			Re	\$665.50
2	FRONT BONNET HINGES LH + RH		NA \$65.70	Re	\$131.40
5	FRONT BONNET INSULATOR MAT CLIP		\$5.50	Re	\$27.50
1	FRONT BONNET MECHANISM LOCK			Re	\$130.30
2	FRONT HEADLAMP LH + RH			Re	\$2,965.00
2	FRONT HEADLAMP TOP PANEL LH + RH		Re \$125.80	Re	\$251.60
2	FRONT HEADLAMP CLIP LH + RH		\$6.50	Re	\$13.00
1	FRONT SUPPORT PANEL			Re	\$1,006.15
1	FRONT SUPPORT PANEL TOP GARNISH			CM	\$132.40
5	FRONT SUPPORT PANEL TOP GARNISH CLIP		\$6.50	Re	\$32.50
1	FRONT BRACE PANEL			Re	\$170.70
1	HORN			Re	\$158.70
1	FRONT BUMPER			Re	\$1,124.50
1	FRONT BUMPER LOGO EMBLEM			Re	\$72.10

13426.30

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 28 March 2018

Third Party Insurer: AXA

Vehicle No: SLK5429P

Third Party Veh No: SDP1970L

Model: TOYOTA AQUA HYBRID 1.5S A

Date of Accident: 26.03.18

Chassis: NHP102577760

ESTIMATE

QTY	DESCRIPTION	UNIT	SS	AMOUNT	SS
1	FRONT BUMPER CENTER GARNISH			CM	\$288.00
1	FRONT BUMPER CENTER GARNISH COVER			2.1	\$29.60
1	FRONT BUMPER TOP GRILLE			CM	\$255.00
1	FRONT BUMPER LOWER CENTER GRILLE			11.1	\$187.50
1	FRONT BUMPER TOP BEAM			Bar	\$238.50
1	FRONT BUMPER TOP RUBBER SEAL			2.2	\$75.50
3	FRONT BUMPER TOP RUBBER SEAL CLIP		\$5.50	2.2	\$16.50
10	FRONT BUMPER CLIP		\$6.50	2.2	\$65.00
2	FRONT BUMPER SIDE RETAINER LH + RH		\$115.20	0.1	\$230.40
1	FRONT BUMPER INNER SPONGE			CM	\$69.80
1	FRONT BUMPER LOWER UNDER COVER			CM	\$383.90
1	FRONT BUMPER REINFORCEMENT			2.2	\$323.50
1	FRONT BUMPER TOW HOOK COVER			2.2	\$24.50
1	AIRCON CONDENSER			2.2	\$1,133.70
2	AIRCON CONDENSER AIR GUIDE TOP LH + RH		\$75.20	2.2	\$150.40
2	AIRCON CONDENSER AIR GUIDE LOWER LH + RH		\$70.50	2.2	\$141.00
1	RADIATOR			2.2	\$1,735.80
1	RADIATOR TOP COWLING			CM	\$85.20
1	RADIATOR FAN COWLING			CM	\$283.60
1	RADIATOR FAN BLADE			2.2	\$147.50
1	RADIATOR FAN MOTOR			2.2	\$549.60
1	WASHER TANK			2.2	\$212.90

SUB TOTAL	\$21,587.31	#18528.80
Less 25%	\$5,396.83	#4632.20
PARTS TOTAL	\$16,190.48	#13896.60

P - 13896.60
 S/W - 305.00
 L - 2700.00
16901.60 P/P

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 28 March 2018

Third Party Insurer: AXA

Vehicle No: SLK5429P

Third Party Veh No: SDP1970L

Model: TOYOTA AQUA HYBRID 1.55 A

Date of Accident: 26.03.18

Chassis: NHP102577760

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$	
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	pc	\$100.00	40.50
1	REAR TAILGATE NUMBER PLATE WITH CASING	pc	\$50.00	X
1	REAR BUMPER REVERSE SENSOR	pc	\$280.00	200.50
1	FRONT BUMPER NUMBER PLATE WITH CASING	pc	\$50.00	45.50
1	RADIATOR COOLANT	pc	\$80.00	20.50
	S/N TOTAL		\$560.00	\$305.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,800.00	120.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,600.00	120.00
TO TUFF KOTE / ANTI-RUST	\$60.00	✓
TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST	\$80.00	40.00
TO DISMANTLE & REPLACED AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL AIRCON GAS/OIL	\$120.00	100.00
TO DISMANTLE & REPLACED RADIATOR WITH HIGH PRESSURE TEST	\$120.00	50.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	50.00
	LABOUR TOTAL	\$3,840.00
		\$2700.00
WINSON	TOTAL	\$20,590.48

Not Authorized
I.B.I
Resony B4pain
12 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 28 March 2018

Third Party Insurer: AXA

Vehicle No: SLK5429P

Third Party Veh No: SDP1970L

Model: TOYOTA AQUA HYBRID 1.5S A

Date of Accident: 26.03.18

Chassis: NHP10257760

ESTIMATE

QTY	DESCRIPTION	UNIT	S\$	AMOUNT S\$
1	REAR TAILGATE			By \$820.00
1	REAR TAILGATE WINDSCREEN MOULDING			Re \$35.00
1	REAR TAILGATE LOGO EMBLEM			Re \$45.90
1	REAR TAILGATE AQUA EMBLEM			Re \$48.60
1	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM			Re \$35.00
1	REAR TAILGATE MECHANISM LOCK			Re \$452.71
1	REAR TAILGATE WEATHERSTRIP			\$291.80
2	REAR TAILLAMP LH + RH	N/S ?	0/1/1/1 X \$528.80	Re \$1,057.60
2	REAR TAILLAMP LOWER BRACKET LH + RH		\$42.57	Re \$85.14
1	REAR BUMPER			Re \$408.31
10	REAR BUMPER CLIP		\$5.78	Re \$57.80
1	REAR BUMPER LOWER UNDER COVER			\$139.10
2	REAR BUMPER SIDE RETAINER LH + RH		\$68.28	Re \$136.56
1	REAR BUMPER REINFORCEMENT			\$278.40
2	REAR BUMPER REINFORCEMENT BRACKET LH + RH		\$115.70	\$231.40
1	REAR END PANEL			\$629.80
1	REAR END PANEL INNER TOP GARNISH			\$191.40
4	REAR END PANEL INNER TOP GARNISH CLIP		\$6.21	\$24.84
1	REAR END PANEL TAILGATE ANTENNA SENSOR			\$144.20
1	FRONT BONNET			Re \$665.50
2	FRONT BONNET HINGES LH + RH		\$65.70	Re \$131.40
5	FRONT BONNET INSULATOR MAT CLIP		\$5.50	Re \$27.50
1	FRONT BONNET MECHANISM LOCK			Dis \$130.30
2	FRONT HEADLAMP LH + RH	mf cm	\$2,965.00	\$5,930.00
2	FRONT HEADLAMP TOP PANEL LH + RH		\$125.80	Re \$251.60
2	FRONT HEADLAMP CLIP LH + RH		\$6.50	Re \$13.00
1	FRONT SUPPORT PANEL			Re \$1,006.15
1	FRONT SUPPORT PANEL TOP GARNISH			cm \$132.40
5	FRONT SUPPORT PANEL TOP GARNISH CLIP		\$6.50	Re \$32.50
1	FRONT BRACE PANEL			\$170.70
1	HORN			\$158.70
1	FRONT BUMPER			Re \$1,124.50
1	FRONT BUMPER LOGO EMBLEM			Re \$72.10

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 28 March 2018

Third Party Insurer: AXA

Vehicle No: SLK5429P

Third Party Veh No: SDP1970L

Model: TOYOTA AQUA HYBRID 1.5S A

Date of Accident: 26.03.18

Chassis: NHP102577760

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CENTER GARNISH		CM \$288.00
1	FRONT BUMPER CENTER GARNISH COVER		DIY \$29.60
1	FRONT BUMPER TOP GRILLE		CM \$255.00
1	FRONT BUMPER LOWER CENTER GRILLE		DIY \$187.50
1	FRONT BUMPER TOP BEAM		Bar \$238.50
1	FRONT BUMPER TOP RUBBER SEAL		M \$75.50
3	FRONT BUMPER TOP RUBBER SEAL CLIP	\$5.50	M \$16.50
10	FRONT BUMPER CLIP	\$6.50	M \$65.00
2	FRONT BUMPER SIDE RETAINER LH + RH	\$115.20	DIY \$230.40
1	FRONT BUMPER INNER SPONGE		CM \$69.80
1	FRONT BUMPER LOWER UNDER COVER		\$383.90
1	FRONT BUMPER REINFORCEMENT		\$323.50
1	FRONT BUMPER TOW HOOK COVER		DIY \$24.50
1	AIRCON CONDENSER		\$1,133.70
2	AIRCON CONDENSER AIR GUIDE TOP LH + RH	\$75.20	\$150.40
2	AIRCON CONDENSER AIR GUIDE LOWER LH + RH	\$70.50	\$141.00
1	RADIATOR		\$1,735.80
1	RADIATOR TOP COWLING		\$85.20
1	RADIATOR FAN COWLING		\$283.60
1	RADIATOR FAN BLADE		\$147.50
1	RADIATOR FAN MOTOR		\$549.60
1	WASHER TANK		\$212.90
SUB TOTAL			\$21,587.31
Less 25%			-\$5,396.83
PARTS TOTAL			\$16,190.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the repair painting
- To display damaged parts during resurvey
- Parts price is subject to confirmation
- Third party insurance is on "Without Prejudice" basis
- No liability is accepted for any delay
- Supply of parts to be resurveyed and is subject to insurance Company

Acknowledged by Repairer:

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	28 March 2018	Third Party Insurer:	AXA
Vehicle No:	SLK5429P	Third Party Veh No:	SDP1970L
Model:	TOYOTA AQUA HYBRID 1.5S A	Date of Accident:	26.03.18
Chassis:	NHP102577760		

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	re	\$100.00
1	REAR TAILGATE NUMBER PLATE WITH CASING	rm	\$50.00
1	REAR BUMPER REVERSE SENSOR		\$280.00
1	FRONT BUMPER NUMBER PLATE WITH CASING	nu	\$50.00
1	RADIATOR COOLANT	re	\$80.00
		S/N TOTAL	\$560.00

40sn
x
7
45sn
20sn

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,800.00	1200
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,600.00	1200
TO TUFF KOTE / ANTI-RUST	\$60.00	✓
TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST	\$80.00	400
TO DISMANTLE & REPLACED AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL AIRCON GAS/OIL	\$120.00	1000
TO DISMANTLE & REPLACED RADIATOR WITH HIGH PRESSURE TEST	\$120.00	500
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	500

LABOUR TOTAL	\$3,840.00
--------------	------------

WINSON	TOTAL	\$20,590.48
--------	--------------	--------------------



mandate

Type

🔔 Question

Message

hi, please offer \$50 /day for LOU and may proceed for COR

Reply

Our Ref : SLK5429P / TP#638
Your Ref : SDP1970L

WITHOUT PREJUDICE

Date : 26 September 2018

AXA INSURANCE PTE LTD
NO.8 Shenton Way
#27-01/02 AXA Tower
Singapore 068811
Attention: Motor Claims Department

**ACCIDENT INVOLVING SLK5429P & SDP1970L ON 26/03/2018
ALONG ECP**

We refer to the above captioned.

We are claiming the below followings :

- Cost of Repair (incl. of GST)	S\$18,084.71
- Loss of Use	S\$1,200.00 (\$100.00 x 12 days)
- LTA/GIA search Fees	S\$2.00
Grand Total	<u>S\$19,286.71</u>

If you have any enquiries, please contact our representative, Ms. Sharon Ten & Ms Lily at 64849919 or email sharon@ow.sg / lily.loi@ow.sg

All payment is to be issued direct to **Optima Werkz Pte Ltd.**

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD

Encl.

This is a computer generated printout and no signature is required.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

03 April 2018

Han Hwee Too

Blk 310 Tampines Street 32
#10-130
Singapore 520310

Dear Sir/ Mdm

OUR REF : CC4/ASM18005859/Kwb3

YOUR REF : SDP 1970L

**ACCIDENT INVOLVING SDP 1970L & SLK 5429P ALONG ECP TWDS MARINE
PARADE ON 26/03/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Optima Werkz Pte Ltd acting on behalf of the owner of SLK 5429P against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT

I/We, Optima Workz Pte Ltd ("the third party claimant") of BIK 158 Woodlands Street 13 #06-711 (S) 730158 (address), owner of SLK5429P (vehicle no.) hereby authorize Optima Workz Pte Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SLK5429P that was damaged pursuant to the accident which occurred on 26/3/2018 (date) along ECP (location) involving vehicle no/s SDP 1970 L ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 26 (day) of March (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)



redefining / insurance

CLAIM REF : S8M00C1Q
INSURED : HAN HWEE TOO

DISCHARGE VOUCHER

We/I OPTIMA WERKZ PTE LTD hereby agree to accept the sum of dollars Eighteen Thousand Six Hundred Eighty Six and Cents Seventy One Only (S\$ 18,686.71) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their insured or the driver of motor vehicle no. SDP 1970L as a result of an accident along ECP BY MARINE PARADE on 26/03/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLK 5429P.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SDP 1970L in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SDP 1970L.

Dated this 5th day of December 2018

Claimant's Signature :



NRIC no./ Company Stamp :

201212455W

Occupation/ Business :

Admin

Address :

9A Serangoon North Ave 5 (S) 554500


Telephone No. :

6848 9919

Witness's Name :

Ten Chai Ling

Witness's Signature :



Witness's NRIC No. :

G7028734N



Without Prejudice

The contents of this document apply to property damages claim only. All personal injuries and damages arising therefore are not included from the ambit and application of this document."

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500
Tel (+65) 6484 9919 Fax: (+65) 6481 1101
Co Reg & GST No: 201212455W

TAX INVOICE

To: AXA INSURANCE PTE LTD

8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Tel 68804888
Fax: 63382522

INV NO. : 121806186
INVOICE DATE : 25/09/2018
REF : TP#638
VEH NO. : SLK5429P
CAR MODEL : AQUA HYBRID 1.5S A
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
REAR TAILGATE	1	PC	615.00	615.00
REAR TAILGATE WINDSCREEN MOULDING	1	PC	26.25	26.25
REAR TAILGATE LOGO EMBLEM	1	PC	34.43	34.43
REAR TAILGATE AQUA EMBLEM	1	PC	36.45	36.45
REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	1	PC	26.25	26.25
REAR TAILGATE WEATHERSTRIP	1	PC	218.85	218.85
REAR TAILLAMP LH + RH	1	PC	396.60	396.60
REAR BUMPER	1	PC	306.23	306.23
REAR BUMPER CLIP	1	SET	43.35	43.35
REAR BUMPER LOWER UNDER COVER	1	PC	104.33	104.33
REAR BUMPER REINFORCEMENT	1	PC	208.80	208.80
REAR BUMPER REINFORCEMENT BRACKET LH + RH	2	PCS	86.78	173.55
REAR END PANEL	1	PC	472.35	472.35
REAR END PANEL INNER TOP GARNISH	1	PC	143.55	143.55
REAR END PANEL INNER TOP GARNISH CLIP	1	SET	18.63	18.63
FRONT BONNET	1	PC	499.13	499.13
FRONT BONNET HINGES LH + RH	2	PCS	49.28	98.55
FRONT BONNET MECHANISM LOCK	1	PC	97.73	97.73
FRONT HEADLAMP LH + RH	2	PCS	2,223.75	4,447.50
FRONT HEADLAMP TOP PANEL LH + RH	2	PCS	94.35	188.70
FRONT HEADLAMP CLIP LH + RH	2	PCS	4.88	9.75
FRONT SUPPORT PANEL	1	PC	754.61	754.61
FRONT SUPPORT PANEL TOP GARNISH	1	PC	99.30	99.30
FRONT SUPPORT PANEL TOP GARNISH CLIP	1	SET	24.38	24.38
FRONT BRACE PANEL	1	PC	128.03	128.03
FRONT BUMPER	1	PC	843.38	843.38
FRONT BUMPER LOGO EMBLEM	1	PC	54.08	54.08
FRONT BUMPER CENTER GARNISH	1	PC	216.00	216.00
FRONT BUMPER CENTER GARNISH COVER	1	PC	22.20	22.20
FRONT BUMPER TOP GRILLE	1	PC	191.25	191.25
FRONT BUMPER LOWER CENTER GRILLE	1	PC	140.63	140.63
FRONT BUMPER TOP BEAM	1	PC	178.88	178.88
FRONT BUMPER TOP RUBBER SEAL	1	PC	56.63	56.63
FRONT BUMPER TOP RUBBER SEAL CLIP	3	PCS	4.13	12.38
FRONT BUMPER CLIP	10	PCS	4.88	48.75
FRONT BUMPER SIDE RETAINER LH + RH	2	PCS	86.40	172.80

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500
Tel (+65) 6484 9919 Fax: (+65) 6481 1101
Co Reg & GST No: 201212455W

TAX INVOICE

To: AXA INSURANCE PTE LTD

8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Tel 68804888
Fax: 63382522

INV NO. : 121806186
INVOICE DATE : 25/09/2018
REF : TP#638
VEH NO. : SLK5429P
CAR MODEL : AQUA HYBRID 1.5S A
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
FRONT BUMPER INNER SPONGE	1	PC	52.35	52.35
FRONT BUMPER LOWER UNDER COVER	1	PC	287.93	287.93
FRONT BUMPER TOW HOOK COVER	1	PC	18.38	18.38
AIRCON CONDENSER	1	PC	850.28	850.28
RADIATOR	1	PC	1,301.85	1,301.85
RADIATOR TOP COWLING	1	PC	63.83	63.83
RADIATOR FAN COWLING	1	PC	212.70	212.70
REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	1	PC	40.00	40.00
REAR BUMPER REVERSE SENSOR	1	PC	200.00	200.00
FRONT BUMPER NUMBER PLATE WITH CASING	1	PC	45.00	45.00
RADIATOR COOLANT	1	PC	20.00	20.00
TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	1	JOB	1,200.00	1,200.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	1	JOB		1,200.00
TO TUFF KOTE / ANTI-RUST	1	JOB	60.00	60.00
TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST	1	JOB	40.00	40.00
TO DISMANTLE & REPLACED AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL AIRCON GAS/OIL	1	JOB	100.00	100.00
TO DISMANTLE & REPLACED RADIATOR WITH HIGH PRESSURE TEST	1	JOB	50.00	50.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	1	JOB		50.00

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500
Tel (+65) 6484 9919 Fax: (+65) 6481 1101
Co Reg & GST No: 201212455W

TAX INVOICE

To: AXA INSURANCE PTE LTD

8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Tel 68804888
Fax: 63382522

INV NO. : 121806186
INVOICE DATE : 25/09/2018
REF : TP#638
VEH NO. : SLK5429P
CAR MODEL : AQUA HYBRID 1.5S A
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
-------------	-----	-----	----------------	---------------

Remarks: DOA: 26/03/18 @ 0910 HRS
CLAIMANT: OPTIMA WERKZ P/L
REG NO: 201212455W
TP VEHICLE: SDP1970L

Singapore Dollars: Eighteen Thousand Eighty-Four And Cent Seventy-One Only

Name: _____

NRIC No.: _____

Signature: _____

SUB TOTAL	SGD	16,901.60
GST 7.00%	SGD	1,183.11
GRAND TOTAL	SGD	<u>18,084.71</u>

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs.
I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

- 1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 3) Goods sold are not refundable/returnable.

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount.

for Optima Werkz Pte Ltd

AUTHORISED SIGNATURE(S)

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-045184

Date of Request: 26/03/2018

Your Ref No: Online Purchase

Optima Werkz Pte Ltd
6 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Enquiry Date 26/03/2018
Enquiry By Casi Riza Pocallan
TP Vehicle No. SDP1970L
Accident Date 26/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-045184
Date of Request: 26/03/2018

Your Ref No: Online Purchase

Optima Werkz Pte Ltd
6 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Enquiry Date: 26/03/2018
Enquiry By: Casi Riza Pocallan
TP Vehicle No.: SDP1970L
Accident Date: 26/03/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SDP1970L	AXA Insurance Pte Ltd	23/03/2018-22/03/2020	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDP 1970L (Insd veh)	Model:	TOYOTA AQUA (A)
	SLK 5429P (TP veh)		
Date of Accident:	26/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	22,031.81
Final Repair Cost	:	\$	18,084.71
Loss of Use	:	\$	600.00
Rental (if any)	:	\$	12days at \$50.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	18,686.71

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No _____ BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	OPTIMA WERKZ PTE LTD	:	\$ 18,686.71

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

11/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18005859/Kwb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:ERNEST TAY		Date : 11-01-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SDP 1970L	Veh. Inspected	SLK 5429P
Policy No.	VPA/P2065545	Coverage (\$)	0.00
Claim No.	S8M00C1Q	Excess (\$)	0.00
Assign From		Assign Date	29/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA AQUA (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NHP1025777760	Colour	METALLIC PEARL WHITE
Odometer	89934	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	KAPSEN	9 mm
L/H Front Tyre	185/65 R15	KAPSEN	9 mm
R/H Rear Tyre	185/65 R15	REAC	7 mm
L/H Rear Tyre	185/65 R15	REAC	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/03/2018	Inspection Date	29/03/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 5429P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE (CONSISTENT)	BENT	820.00	820.00
1	REAR TAILGATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR TAILGATE LOGO EMBLEM (CONSISTENT)	NECESSARY	45.90	45.90
1	REAR TAILGATE AQUA EMBLEM (CONSISTENT)	NECESSARY	48.60	48.60
1	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR TAILGATE MECHANISM LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	452.71	-
1	REAR TAILGATE WEATHERSTRIP (CONSISTENT)	DENTED / CUT	291.80	291.80
2	REAR TAILLAMP LH+RH @\$528.80 (CONSISTENT)	N/S MTG CRACKED / O/S SERVICEABLE	1,057.60	528.80
2	REAR TAILLAMP LOWER BRACKET LH+RH @\$42.57 (CONSISTENT)	SERVICEABLE	85.14	-
1	REAR BUMPER (CONSISTENT)	BUCKLED	408.31	408.31
10	REAR BUMPER CLIP @\$5.78 (CONSISTENT)	NECESSARY	57.80	57.80
1	REAR BUMPER LOWER UNDER COVER (CONSISTENT)	CRACKED	139.10	139.10
2	REAR BUMPER SIDE RETAINER LH+RH @\$68.28 (CONSISTENT)	SERVICEABLE	136.56	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	278.40	278.40
2	REAR BUMPER REINFORCEMENT BRACKET LH+RH @\$115.70 (CONSISTENT)	BENT	231.40	231.40
1	REAR END PANEL (CONSISTENT)	BENT	629.80	629.80
1	REAR END PANEL INNER TOP GARNISH (CONSISTENT)	DENTED	191.40	191.40
4	REAR END PANEL INNER TOP GARNISH CLIP @\$6.21 (CONSISTENT)	NECESSARY	24.84	24.84
1	REAR END PANEL TAILGATE ANTENNA SENSOR (CONSISTENT)	SERVICEABLE	144.20	-
1	FRONT BONNET (CONSISTENT)	BUCKLED	665.50	665.50
2	FRONT BONNET HINGES LH+RH @\$65.70 (CONSISTENT)	NECESSARY	131.40	131.40
5	FRONT BONNET INSULATOR MAT CLIP @\$5.50 (CONSISTENT)	NOT NECESSARY	27.50	-
1	FRONT BONNET MECHANISM LOCK (CONSISTENT)	DISTORTED	130.30	130.30

Report Ref No. CC4/ASM18005859/Kwb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT HEADLAMP LH+RH @\$2965.00 (CONSISTENT)	MTG CRACKED	5,930.00	5,930.00
2	FRONT HEADLAMP TOP PANEL LH+RH @\$125.80 (CONSISTENT)	NECESSARY	251.60	251.60
2	FRONT HEADLAMP CLIP LH+RH @\$6.50 (CONSISTENT)	NECESSARY	13.00	13.00
1	FRONT SUPPORT PANEL (CONSISTENT)	BUCKLED	1,006.15	1,006.15
1	FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	CRACKED	132.40	132.40
5	FRONT SUPPORT PANEL TOP GARNISH CLIP @\$6.50 (CONSISTENT)	NECESSARY	32.50	32.50
1	FRONT BRACE PANEL (CONSISTENT)	BENT	170.70	170.70
1	HORN (CONSISTENT)	SERVICEABLE	158.70	-
1	FRONT BUMPER (CONSISTENT)	BENT	1,124.50	1,124.50
1	FRONT BUMPER LOGO EMBLEM (CONSISTENT)	DENTED	72.10	72.10
1	FRONT BUMPER CENTER GARNISH (CONSISTENT)	CRACKED	288.00	288.00
1	FRONT BUMPER CENTER GARNISH COVER (CONSISTENT)	MISSING	29.60	29.60
1	FRONT BUMPER TOP GRILLE (CONSISTENT)	CRACKED	255.00	255.00
1	FRONT BUMPER LOWER CENTER GRILLE (CONSISTENT)	DISTORTED	187.50	187.50
1	FRONT BUMPER TOP BEAM (CONSISTENT)	BUCKLED	238.50	238.50
1	FRONT BUMPER TOP RUBBER SEAL (CONSISTENT)	NECESSARY	75.50	75.50
3	FRONT BUMPER TOP RUBBER SEAL CLIP @\$5.50 (CONSISTENT)	NECESSARY	16.50	16.50
10	FRONT BUMPER CLIP @\$6.50 (CONSISTENT)	NECESSARY	65.00	65.00
2	FRONT BUMPER SIDE RETAINER LH+RH @\$115.20 (CONSISTENT)	DISTORTED	230.40	230.40
1	FRONT BUMPER INNER SPONGE (CONSISTENT)	CRACKED	69.80	69.80
1	FRONT BUMPER LOWER UNDER COVER (CONSISTENT)	CRACKED	383.90	383.90
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	323.50	-
1	FRONT BUMPER TOW HOOK COVER (CONSISTENT)	DENTED	24.50	24.50
1	AIRCON CONDENSER (CONSISTENT)	PUNCTURE	1,133.70	1,133.70
2	AIRCON CONDENSER AIR GUIDE TOP LH+RH @\$75.20 (CONSISTENT)	SERVICEABLE	150.40	-
2	AIRCON CONDENSER AIR GUIDE LOWER LH+RH @\$70.50 (CONSISTENT)	SERVICEABLE	141.00	-
1	RADIATOR (CONSISTENT)	PUNCTURE	1,735.80	1,735.80
1	RADIATOR TOP COWLING (CONSISTENT)	CRACKED	85.20	85.20

Report Ref No. CC4/ASM18005859/Kwb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR FAN COWLING (CONSISTENT)	CRACKED	283.60	283.60
1	RADIATOR FAN BLADE (CONSISTENT)	SERVICEABLE	147.50	-
1	RADIATOR FAN MOTOR (CONSISTENT)	SERVICEABLE	549.60	-
1	WASHER TANK (CONSISTENT)	SERVICEABLE	212.90	-
	LESS 25% DISCOUNT		-5,396.83	-4,632.20
			16,190.48	13,896.60
	SPECIAL NETT ITEMS			
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER (SN) (CONSISTENT)	NECESSARY	100.00	40.00
1	REAR TAILGATE NUMBER PLATE WITH CASING (SN) (CONSISTENT)	SERVICEABLE	50.00	-
1	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	FRONT BUMPER NUMBER PLATE WITH CASING (SN) (CONSISTENT)	DENTED	50.00	45.00
1	RADIATOR COOLANT (SN) (CONSISTENT)	NECESSARY	80.00	20.00
			560.00	305.00
	LABOUR			
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION .INCLUSIVE OF THE REPAIR OF REAR TAILGATE MECHANISM LOCK .		1,800.00	1,200.00
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION .		1,600.00	1,200.00
	TO TUFF KOTE/ANTI-RUST.		60.00	60.00
	TO CHECK WIRING ,REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST .		80.00	40.00
	TO DISMANTLE & REPLACE AIRCON SYSTEM ,VACUUM WITH FLUSHING /REFILL AIRCON GAS/OIL.		120.00	100.00
	TO DISMANTLE & REPLACED RADIATOR WITH HIGH PRESSURE TEST.		120.00	50.00
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR .		60.00	50.00
			-	-
			-	-
			-	-
			3,840.00	2,700.00

Report Ref No. CC4/ASM18005859/Kwb3q2



GRAND TOTAL		20,590.48	16,901.60
RECOMMENDED COST OF REPAIRS			16,901.60

Report Ref No. CC4/ASM18005859/Kwb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim	SBA000C1Q
Reference	CCAUAGM18005859/Kwb3o2
Loss Date	26 March 2018
Request Date	24 July 2018
Due Date	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for Approve Invoice

Hold Invoice

Vehicle Information	
Incident Vehicle Registration #	SLK54298
Make	TPVD TOYOTA
Model	AQUA HYBRID 1.5 E S CVT (A)
Service Address	
...	
Primary Contact/Insured	
HAN HWEE TOO @ HAN WEE CHOO BLK 310 TAMMINES ST 32, #10-130, 520310, Singapore 97527226 CATHERINEHAN19@YAHOO.COM.SG	
Claims Handler	
TAN Jia 6568804844 jia.tan@axa.com.sg	

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

+

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKXInvoice1 (2).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	14 January 2019

