

Not Authorized
I.B.I
Resony B4pain
12 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 28 March 2018

Third Party Insurer:

AXA

Vehicle No: SLK5429P

Third Party Veh No:

SDP1970L

Model: TOYOTA AQUA HYBRID 1.5S A

Date of Accident:

26.03.18

Chassis: NHP102577760

ESTIMATE

QTY	DESCRIPTION	UNIT	S\$	AMOUNT S\$
1	REAR TAILGATE			<i>Bu</i> \$820.00
1	REAR TAILGATE WINDSCREEN MOULDING			<i>Mc</i> \$35.00
1	REAR TAILGATE LOGO EMBLEM			<i>Mc</i> \$45.90
1	REAR TAILGATE AQUA EMBLEM			<i>Mc</i> \$48.60
1	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM			<i>Mc</i> \$35.00
1	REAR TAILGATE MECHANISM LOCK			<i>Mc</i> \$452.71
1	REAR TAILGATE WEATHERSTRIP			\$291.80
2	REAR TAILLAMP LH + RH		<i>Mc</i> \$528.80	<i>Sm</i> \$1,057.60
2	REAR TAILLAMP LOWER BRACKET LH + RH		\$42.57	<i>Sm</i> \$85.14
1	REAR BUMPER			<i>Bu</i> \$408.31
10	REAR BUMPER CLIP		\$5.78	<i>Mc</i> \$57.80
1	REAR BUMPER LOWER UNDER COVER			\$139.10
2	REAR BUMPER SIDE RETAINER LH + RH		\$68.28	<i>Mc</i> \$136.56
1	REAR BUMPER REINFORCEMENT			\$278.40
2	REAR BUMPER REINFORCEMENT BRACKET LH + RH		\$115.70	\$231.40
1	REAR END PANEL			\$629.80
1	REAR END PANEL INNER TOP GARNISH			\$191.40
4	REAR END PANEL INNER TOP GARNISH CLIP		\$6.21	\$24.84
1	REAR END PANEL TAILGATE ANTENNA SENSOR			\$144.20
1	FRONT BONNET			<i>Bu</i> \$665.50
2	FRONT BONNET HINGES LH + RH		\$65.70	<i>Mc</i> \$131.40
5	FRONT BONNET INSULATOR MAT CLIP		\$5.50	<i>Mc</i> \$27.50
1	FRONT BONNET MECHANISM LOCK			<i>Dr's</i> \$130.30
2	FRONT HEADLAMP LH + RH		<i>Mc</i> \$2,965.00	\$5,930.00
2	FRONT HEADLAMP TOP PANEL LH + RH		\$125.80	<i>Mc</i> \$251.60
2	FRONT HEADLAMP CLIP LH + RH		\$6.50	<i>Mc</i> \$13.00
1	FRONT SUPPORT PANEL			<i>Bu</i> \$1,006.15
1	FRONT SUPPORT PANEL TOP GARNISH			<i>CM</i> \$132.40
5	FRONT SUPPORT PANEL TOP GARNISH CLIP		\$6.50	<i>Mc</i> \$32.50
1	FRONT BRACE PANEL			\$170.70
1	HORN			\$158.70
1	FRONT BUMPER			<i>Bu</i> \$1,124.50
1	FRONT BUMPER LOGO EMBLEM			<i>Mc</i> \$72.10

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 28 March 2018

Third Party Insurer: AXA

Vehicle No: SLK5429P

Third Party Veh No: SDP1970L

Model: TOYOTA AQUA HYBRID 1.5S A

Date of Accident: 26.03.18

Chassis: NHP102577760

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CENTER GARNISH		CM \$288.00
1	FRONT BUMPER CENTER GARNISH COVER		CM \$29.60
1	FRONT BUMPER TOP GRILLE		CM \$255.00
1	FRONT BUMPER LOWER CENTER GRILLE		DIY \$187.50
1	FRONT BUMPER TOP BEAM		Bar \$238.50
1	FRONT BUMPER TOP RUBBER SEAL		RM \$75.50
3	FRONT BUMPER TOP RUBBER SEAL CLIP	\$5.50	RM \$16.50
10	FRONT BUMPER CLIP	\$6.50	RM \$65.00
2	FRONT BUMPER SIDE RETAINER LH + RH	\$115.20	DIY \$230.40
1	FRONT BUMPER INNER SPONGE		CM \$69.80
1	FRONT BUMPER LOWER UNDER COVER		\$383.90
1	FRONT BUMPER REINFORCEMENT		\$323.50
1	FRONT BUMPER TOW HOOK COVER		RM \$24.50
1	AIRCON CONDENSER		\$1,133.70
2	AIRCON CONDENSER AIR GUIDE TOP LH + RH	\$75.20	\$150.40
2	AIRCON CONDENSER AIR GUIDE LOWER LH + RH	\$70.50	\$141.00
1	RADIATOR		\$1,735.80
1	RADIATOR TOP COWLING		\$85.20
1	RADIATOR FAN COWLING		\$283.60
1	RADIATOR FAN BLADE		\$147.50
1	RADIATOR FAN MOTOR		\$549.60
1	WASHER TANK		\$212.90
SUB TOTAL			\$21,587.31
Less 25%			-\$5,396.83
PARTS TOTAL			\$16,190.48

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supply of parts must be resurveyed and is subject to approval from Insurance Company

Acknowledge by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 28 March 2018

Third Party Insurer: AXA

Vehicle No: SLK5429P

Third Party Veh No: SDP1970L

Model: TOYOTA AQUA HYBRID 1.5S A

Date of Accident: 26.03.18

Chassis: NHP102577760

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	na	\$100.00
1	REAR TAILGATE NUMBER PLATE WITH CASING	sm	\$50.00
1	REAR BUMPER REVERSE SENSOR		\$280.00
1	FRONT BUMPER NUMBER PLATE WITH CASING	na	\$50.00
1	RADIATOR COOLANT	na	\$80.00
		S/N TOTAL	\$560.00

40sn
X
7
45sn
20sn

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$1,800.00 1200

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$1,600.00 1200

TO TUFF KOTE / ANTI-RUST

\$60.00 ✓

TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST

\$80.00 400

TO DISMANTLE & REPLACED AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL
AIRCON GAS/OIL

\$120.00 1000

TO DISMANTLE & REPLACED RADIATOR WITH HIGH PRESSURE TEST

\$120.00 500

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$60.00 500

LABOUR TOTAL \$3,840.00

WINSON

TOTAL \$20,590.48