

ASS. REC. BY:

REF: CS/FCL18005876 / Kvbna2 Special Instruction:

Surveyor: _____ ASSIGNMENT (Office)

From (Person): CS Joanne Yong of FCL Date/Time: 29032018 3:01pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GLM 9018E Insured: SHA 3827L

at Workshop m/s Esteem Performance Tel: 6484 1221

of Blk 5033 Amk Ind Park 2 #01-251

Policy No: _____ Claim No: D18002443MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement: _____

Date/Time: 29032018 3:40pm Person Contacted: Carmen Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 9018E - x
	SHA 3827L - NFA / INC 09022233 / 11 DCA: 280909
<u>10/4/18</u>	<u>Email preli revised to FCL</u>
<u>12/6</u>	<u>81296-20 Confirm by email (Red 170, 129) ✓ 12/6.</u>

REF: FCL

ASSIGNMENT

From: _____ Date: 07/06/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 9018E

at Workshop m/s: Extreme Performance

of: AMK

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLM 9018E Yr Regn: 04/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toy Prius³ c.c. 1798

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 82639 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU803555422

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: Yokohama 195/65R15

R: Agence _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 9 mm	R/Bal. 7 mm
L/Bal. 9 mm	L/Bal. 7 mm
D.O.A. 23/3/18	D.O.I. 9/4/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

PM o/s door

The U/C / Chassis frame / Body Structure affected due to collision.

After 11:30am

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 890k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

14 File pass to Catherine

RECEIVED 1 2 JUN 2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) 12/6 - typist

Report Format: CWS

Lump Sum / I.B.I: (\$) 1296.00

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee: 100

Transportation: 50

S+RS: 50

Photos: 12

Other: _____

TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005876/Kvb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 29-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3827L	Veh. Inspected	SLM 9018E
Policy No.		Coverage (\$)	0.00
Claim No.	D18002443MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/03/2018	Inspection Date	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002443MFSH

Our ref: CS/FCI18005876/Kvb

Date : 10/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLM 9018E


We thank for your instruction on 29/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 9/4/2018 at the premises of M/s ESTEEM PERFORMANCE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$1,466.20
Revised Estimate Amount	: S\$1,296.20
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s door



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-03-2018	Our Ref No. D18002443MFSH
Accident Date	23-03-2018	Claim Type. Third Party
Insured Vehicle	SHA3827L	Third Party Vehicle. SLM9018E
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	CARMEN LIM	
Contact No.	64841221/ 0	Fax No. 64847829
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236358)  PRI Documents  Close 

PRI Header Details

Claim No	D18002443MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & ES
Workshop Name	ESTEEM PERFORMANCE PTE LTD (Contact Person : CARMEN LIM)	Survey Location & Contact Details	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/ Mobile: 0 , Phone: 64841221 , Fax: 6484782 EmailId: CARMEN@ESTEEMPERF.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3827L	TP Vehicle No	SLM90
PRI Recieved Date	29-03-2018 04:54:04 PM	Surveyor Appointed Date	29-03-2018 03:01:48 PM	Surveyor Accept Date	29-03-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	29-03-2018	Upload Survey Report *:	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name	Action

Surveyor Job Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 10 April 2018 11:45 AM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002443MFSH/1, SLM 9018E
Attachments: SLM 9018E PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLM 9018E
Date of survey: 9/4/2018
Number of days:2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 29 March 2018 3:42 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002443MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 29 March, 2018 3:01 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002443MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

*7.6 ALG
LCC
Catherine
11:30*



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLM 9018 E

Parts	(a) Cost / List Price Items	\$	<u>1,461.60</u>
	Plus/Less 25%	\$	<u>365.40</u>
	Total of Cost / List	\$	<u><u>1,096.20</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items		_____
Total Parts Cost		\$	<u><u>1,096.20</u></u>
Labour		\$	<u><u>370.00</u></u>
Total		\$	<u><u>1,466.20</u></u>

*Not Authorized
1-B-1
Resurvey B4 painting*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LCC

Survey conducted on : 9/4/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 9/4/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLM 9018 E
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU803555422

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (arm)	1			
2	RH wing mirror (signal lamp) <i>Bv</i>	1	\$1,374.20		✓
3	RH wing mirror (glass)	1			
4	RH wing mirror (cover) <i>not km</i>	1	\$87.40		✓
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569535.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.osteemporf.com.sg

Repair Estimates

SLM 9018 E

Finalized

Parts (a) Cost / List Price Items	\$	1,461.60	1461.60
Plus/Less 25%	\$	365.40	365.40
Total of Cost / List	\$	1,096.20	1096.20
(b) Nett Price Items			
Less			
Total of Nett Item			
(c) Special Nett Items			
Total Parts Cost	\$	1,096.20	1096.20
Labour	\$	370.00	200
Total	\$	1,466.20	1296.20 ✓ dk

Not Authorized
1-B-1
Resurvey B4 repair

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : CKK

Survey conducted on : 9/4/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Se Date: 9/4/18



**ESTEEM
PERFORMANCE**

EST-100 PERFORMANCE No. 0121 115

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLM 9018 E
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU803555422

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (arm)	1			
2	RH wing mirror (signal lamp) <i>Brn</i>	1	\$1,374.20		✓
3	RH wing mirror (glass)	1			
4	RH wing mirror (cover) <i>Red Km</i>	1	\$87.40		✓
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005876/Kvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 3827L	Veh. Inspected	SLM 9018E
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18002443MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	29/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU803555422	Colour	METALLIC SILVER
Odometer	82639	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm
R/H Rear Tyre	195/65 R15	AGENDA	7 mm
L/H Rear Tyre	195/65 R15	AGENDA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/03/2018	Inspection Date	09/04/2018
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 9018E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RH WING MIRROR (SIGNAL LAMP) }	BROKEN	1,374.20	1,374.20
1	RH WING MIRROR (ARM) }		-	-
1	RH WING MIRROR (GLASS) }		-	-
1	RH WING MIRROR (COVER)	DENTED / CRACKED	87.40	87.40
	LESS 25% DISCOUNT		-365.40	-365.40
			1,096.20	1,096.20
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (RH SIDE MIRROR).		100.00	60.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (RH SIDE MIRROR).		100.00	60.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD.		120.00	60.00
			370.00	200.00
	GRAND TOTAL		1,466.20	1,296.20
RECOMMENDED COST OF REPAIRS				1,296.20

Report Ref No. CS/FC118005876/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.