

ASS. REC. BY:

REF:

CS/MSG18005877/A116<sup>nt</sup>

Special Instruction:

SURVAYOR

Rasul

ASSIGNMENT (Office)

From (Person):

Muhaimin

Clara

Muh Yeo

of

MSH

Date/Time: 29/03/2018 1:58pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 481C

Insured:

at Workshop m/s

Volkswagen

Tel:

6922 3502 / 9386 7833

of

1 Kompong Ampat Off Macpherson Rd

Policy No:

A28667303AVW

Claim No:

Sum Insured:

Excess:

\$5000

Make of Veh:

D.O.A.

28/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

17 Tans Ave 9

H.O.D. Endorsement:

Date/Time:

29/03/2018 2:08pm

Person Contacted:

Shushi

Vehicle: IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 481C - X

2/4-

Report via merimen

2/4-

authorise repair by Ng Chen How

2/4-

inform Tang Shu Shi authorise repair excess \$500/-

Confirm final figure @ \$11,742.30. 12 days

(Data 157.12h 71.90)

REF:

7133E

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKZ 481Cat Workshop m/s Volkswagenof 17, TWO AVE 9Insured: MSH

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 500

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 85K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKZ 481C Yr Regn: 2016 / JANType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: VOLKSWAGEN JETTA 1.4 c.c. 1390Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 30058 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVW ZZZ 162GM006161Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 1BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 28/03/18D.O.I. 29/03/18Survey held at VOLKSWAGEN TWSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 APR 2018

Date/Time, File Pass to?

1) 12/4 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prel. Report☒ : Final ReportDays Of Repair: 12Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

300

10

310

Report Format: ODLump Sum / B.I. (\$) 11,742.30



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005877/R11b

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 29-03-2018



Code : MSG

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKZ 481C
Policy No. A28667303AVW	Coverage (\$)	0.00
Claim No.	Excess (\$)	500.00
Assign From MERIMEN (CLARA MILAH)	Assign Date	29/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date 28/03/2018	Inspection Date 29/03/2018
Survey held at VOLKSWAGEN GROUP SINGAPORE PTE LTD NO 17 TUAS AVE 9 SINGAPORE 639197	

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2018		29 Mar 2018 13:58 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS**

[Created by insurer]

<b>Insured:</b>	CHEW MUI LIN, ID: S0037133E, Tel: +6591063807, Email: NOEMAIL		
<b>Vehicle Reg. No.:</b>	SKZ481C	<b>Date of Loss:</b>	28/03/2018 19:00 - :59
<b>Claim Type:</b>	OD	<b>Policy/Cover Note No.:</b>	A28667303AVW (Comprehensive) Coverage: 06/01/2018 - 05/01/2019
		<b>Excess:</b>	S\$500.00
<b>Repairer:</b>	Volkswagen Centre Singapore (Alexandra) 247 Alexandra Road, 159934 Alexandra - Tel: 64748288		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/03/2018]		
<b>Driver/Custodian:</b>	CHEW MUI LIN (66 / Female), NRIC: S0037133E, Tel: +6591063807		
<b>Adj Asg. Remarks:</b>	Please revert. Thanks.		

**ASSOCIATED MAIL RECEIVED**

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 2 April 2018 5:13 PM  
**To:** 'Tang, Shu Shi (VWG Singapore)'  
**Cc:** SUR  
**Subject:** RE: surveyor marking SKZ481C

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKZ481C (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tang, Shu Shi (VWG Singapore) [<mailto:shushi.tang@vw.com.sg>]  
**Sent:** Thursday, 29 March 2018 6:33 PM  
**To:** Fievel Foo <[Fievel\\_Foo@sg.msigg-asia.com](mailto:Fievel_Foo@sg.msigg-asia.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** Clara Milah Yeo <[Milah@sg.msigg-asia.com](mailto:Milah@sg.msigg-asia.com)>; Ng Chen How <[ChenHow\\_Ng@sg.msigg-asia.com](mailto:ChenHow_Ng@sg.msigg-asia.com)>; Ong, Germaine (VWG Singapore) <[Germaine.ong@vw.com.sg](mailto:Germaine.ong@vw.com.sg)>  
**Subject:** RE: surveyor marking SKZ481C

Hi,

The vehicle number for this email is SKZ481C.

Please don't mixed up, thank you.

Best Regards,

Tang Shu Shi  
Insurance Service Advisor  
Aftersales

Volkswagen Centre Singapore (Macpherson)  
1 Kampong Ampat  
Singapore 368314

DID: +65 6922-3502  
Mobile: +65 9386-7833  
Main Line : +65 6305-7299  
Main Fax: +65 6285-8620

## View Received Message

This mail is associated with :

\*SKZ481C (553979)

OD

Mar 28 2018 7:00PM

[CHEW MUI LIN]

Volkswagen Group Singapore

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 02/04/2018 16:10 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$11006.54) - SKZ481C - Claim Handler: Clara Milah Yeo

Approved:11006.54.

### DOCUMENTS SUMMARY

There are no documents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/03/2018 12:16
Date Of Accident	28/03/2018 19:30
Exact Location Of Accident	ALONG THE ROAD OF 568 SIMS AVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ481C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEW MUI LIN
NRIC No	S0037133E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91063807
Alternative Phone No	OFFICE-91063807

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA TSI (DSG) HIGHLINE HIDC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28667303 AVW
Cover Note Number	

### Driver

Name of Driver	CHEW MUI LIN
NRIC No	S0037133E
Date Of Birth	28/12/1951
Occupation	INDOOR
Date Of Driving Pass	29/06/1981
Driving Experience	36 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91063807
Fax Number	
Contact Number	OFFICE-91063807
EMail Address	NOEMAIL

Address	11 KUO CHUAN AVE
Postcode	426907
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD5315X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SYED SHEKENDER BIN SYED SULTAN
NRIC/Passport Number	S7216181E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

12-35  
29/3/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:




Authorised Driver's Signature

Name:

NRIC/FIN No.:

29/3/18

# Sketch Plan #2 Pg. 1



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28 April 2018 about 7.30pm vehicle SLB 5315X driver Mr. Shekender Bin Syed I/C # 597216181E bang into rear of my vehicle SKZ 481C driven by me Chew Mui Lin I/C # 50037133E badly damaging rear portion of my vehicle. The accident occurred on the right lane of green traffic light at Lor 39 Geylang road along 568 Sims Ave. I was driving my car through the green light traffic when suddenly the car SLB 5315X bang my vehicle from behind.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Chew*  
 Policyholder's Signature  
 Date & Time: 12.35/29/3/18

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:



Recorded by Policyholder's Signature  
 Name:  
 NRIC/FIN No.:

29/3/18



MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807  
Tel: (65) 6827 7888 Fax: (65) 6827 7800  
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

## Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1  
Individual Ownership

VW DRIVEEASY  
Comprehensive

Certificate No. A 28667303 AVW

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle  
SKZ481C

2. Name of Policyholder  
Chew Mui Lin

3. Effective Date of the Commencement of Insurance for the purposes of the Act  
06/01/2018

4. Date of Expiry of Insurance  
05/01/2019

5. Persons or Classes of Persons entitled to drive\*

Chew Mui Lin

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.  
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.



Signature / Date

Counter-Signatory:

Winner Consultancy Pte. Ltd.

MSIG Insurance (Singapore) Pte. Ltd.  
Approved Insurers

Amy Ler  
Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

XWCPLSASX2018010316259621

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S0037133E



Name

CHEW MUI LIN



Race

CHINESE

Date of Birth

28-12-1951

Sex

F

Country of Birth

SINGAPORE

S0037133E

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence No: S0037133E

Name

CHEW MUI LIN



Birth Date: 28 Dec 1951

Issue Date: 12 Aug 2003



000736282J

321204E



NRIC No: S0037133E



Blood Group

O+

Date of issue

10-11-2000

11 KOO CHUAN AVENUE  
SINGAPORE 428907

NRIC No: S0037133E

Date: 18/02/2018


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

29 Jun 1981

NP 428A



Licence No: S0037133E

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7133E
Vehicle Details	
Vehicle No.:	SKZ481C
Vehicle to be Exported:	No
Intended De-registration Date:	02 Apr 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T HL HID 1634G5
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	CAXF82202
Chassis No.:	WVWZZZ16ZGM006161
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$21,584.00
Original Registration Date:	06 Jan 2016
First Registration Date:	06 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$22,218.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jan 2026
PARF Rebate Amount:	\$16,663.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,301.00
COE Rebate Amount:	\$42,127.00
Total Rebate Amount:	\$58,790.00

The information contained herein is correct as at 02 Apr 2018

OK

85,000  
~~58,790~~  
26,210



## Service Order Confirmation

SERVICE ORDER NO: 18IP0844

CUSTOMER NO.: CV032294

CUSTOMER NAME: CHEW MUI LIN

TELEPHONE NO.:

ADDRESS: 102 BEDOK RESERVOIR ROAD #01-442

Singapore

VEH No.: SKZ481C

Order Date: 03/29/18

Reg Date: 01/08/16

KM: 27,519

VIN NO.: WWWZZZ16ZGM006161

ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
<b>Labor</b>						
1	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	200		✓ 200
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	360		✓ 360
3	B&P MACP LABOUR LABOUR	8	UNIT	475		✓ 3,800 2850
4	B&P MACP PAINT SPRAY PAINT	7	UNIT	500		✓ 3,500 2500
5	B&P MACP LABOUR TRANSFER BOOT LID MECH	1	UNIT	475		✓ 237.5 475 237.5
6	B&P MACP LABOUR R&R REAR LUGGAGE TRIM	1	UNIT	475		✓ 237.5 475 237.5
7	B&P NUMBER PLATE B&P NUMBER PLATE -NETT	1	ST	80		✓ 80 80
<b>Item</b>						
8	5C6827025E BOOT LID	1	PCS	1,222.87	28	✓ 880.47 PA
9	5C6827301E HINGE LH	1	PCS	82.26	28	✓ 59.23 PA
10	5C6827302D HINGE RH	1	PCS	82.26	28	✓ 59.23 PA
11	WHT007341 NUT	4	PCS	2.18	28	✓ 6.28 6.28
12	5C6827505G LOCK	1	PCS	167.96	28	✓ 120.93 PA
13	5C6827520B 9B9 LOCK COVER	1	PCS	15.45	28	✓ 11.12 11.12
14	8D0853419D RR NUMBER PLATE PACKING	1	PCS	12.66	28	✓ 9.12 9.12
15	5C6827566F BOOT LOCK PUSH BUTTON	1	PCS	850.00	28	X 612.00 XSVL
16	5C6827705A 5AP WTHRSTRIP	1	PCS	219.10	28	✓ 157.75 157.75
17	5C6827507B LOCK STRIKER	1	PCS	44.60	28	✓ 32.11 XSVL
18	5C6853630F ULM VW SIGN	1	PCS	108.42	28	✓ 78.06 78.06
19	5C6853687 739 NAME PLATE ( JETTA )	1	PCS	65.96	28	✓ 47.49 47.49
20	5C6853675APGQF NAME PLATE ( TSI )	1	PCS	49.68	28	✓ 35.77 35.77
21	5C6867605B 9B9 BOOT LID TRIM COVER	1	PCS	166.01	28	X 119.53 XSVL
22	5C6945093H LH INNER TAILLIGHT	1	PCS	181.49	28	X 130.67 XSVL
23	5C6945094J RH INNER TAILLIGHT	1	PCS	181.49	28	X 130.67 XSVL
24	5C6945095N TAILLIGHT OUTER LH	1	PCS	370.74	28	✓ 266.93 266.93
25	5C6945096L TAILLIGHT OUTER RH	1	PCS	357.91	28	X 257.70 CRA
26	3AF943021A LED LICENCE PLATE LIGHT	2	PCS	109.65	28	✓ 157.90 XSVL
27	5C6807421H GRU RR BUMPER	1	PCS	1,258.64	28	✓ 905.22 DE
28	5C6919491D SENSOR BRACKET	1	PCS	23.79	28	✓ 17.13 17.13



## Service Order Confirmation

SERVICE ORDER NO: 18IP0844

CUSTOMER NO.: CV032294

CUSTOMER NAME: CHEW MUI LIN

TELEPHONE NO.:

ADDRESS: 102 BEDOK RESERVOIR ROAD #01-442

Singapore

VEH No.: SKZ481C

Order Date: 03/29/18

Reg Date: 01/06/16

KM: 27,519

VIN NO.: WWWZZZ16ZGM006161

ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	5C6919491E SENSOR BRACKET	2	PCS	23.79	28	✓ 34.26 ne
30	5C6919492D SENSOR BRACKET	1	PCS	23.79	28	✓ 17.13 ne
31	D 180KU2A1 2KADHESIVE	1	PCS	89.84	28	✓ 64.68 ne
32	D B22150A1 BONDAGENT	1	PCS	64.27	28	✓ 46.27 ne
33	5Q0919275B GRU SENSOR	2	PCS	144.40	28	✓ 207.94 ne
34	5Q0919133 9B9 SENSOR O-RING	2	PCS	1.71	28	✓ 2.46 ne
35	5CU971104 SEOSOR WIRE HARNESS	1	PCS	161.14	28	✓ 116.02 ? act
36	5C6807433J SPOILER	1	PCS	412.76	28	✓ 297.19 DE
37	5C6807305 REINFORCEMENT	1	PCS	445.64	28	✓ 320.86 ? HA
38	5C6807251F FOAM INSERT	1	PCS	142.24	28	✓ 102.41 CRT
39	5C6807863B BUMPER CENTRE BRACKET	1	PCS	96.99	28	✓ 69.83 CA
40	5C6807393D TAILLIGHT LOWER BRACKET LH	1	PCS	69.81	28	✓ 50.26 ? XSV
41	5C6807394D TAILLIGHT LOWER BRACKET RH	1	PCS	69.81	28	CA ✓ 50.26 ? XSV
42	5C6807375 BUMPER SIDE BRACKET LH	1	PCS	83.31	28	✓ 59.98 ? XSV
43	5C6807376 BUMPER SIDE BRACKET RH	1	PCS	83.31	28	✓ 59.98 ne
44	N 10621301 NUT	10	PCS	1.85	28	✓ 13.32 ne
45	5C6825205 BUMPER LOWER COVER RH	1	PCS	145.96	28	X 105.09 ? XSV
46	5C6813301 REAR END PANEL	1	PCS	1,111.35	28	✓ 800.17 Bt photo
47	D 007600A1 INOXSPRAY	1	PCS	67.97	28	✓ 48.94 ne
48	D 180003M2 2KADHESIV	1	PCS	286.20	28	✓ 206.06 ne
49	D 476KD1M2 SEALANT	1	PCS	77.38	28	✓ 55.71 ne
50	5C6863459G 9B9 END PANEL TRIM COVER	1	PCS	72.44	28	✓ 52.16 DE
51	5K0962131 SENSOR AERIAL	1	PCS	67.37	28	✓ 48.51 CRT
52	8K0973702G WIRE HOUSING	1	PCS	10.29	28	CA ✓ 7.41 ? XSV
53	5C6945105B LH REAR REFLECTOR	1	PCS	53.98	28	X 38.87 ? XSV
54	5C6945105B RH REAR REFLECTOR	1	PCS	53.98	28	X 38.87 ? XSV

Remarks: MSIG (IN-HOUSE) OD CLAIM

DOA: 28/03/2018

SURVEY BY:

EXCESS: \$



## Service Order Confirmation

SERVICE ORDER NO: 18IP0844  
CUSTOMER NO.: CV032294  
CUSTOMER NAME: CHEW MUI LIN  
TELEPHONE NO.:  
ADDRESS: 102 BEDOK RESERVOIR ROAD #01-442  
Singapore  
VEH No.: SKZ481C  
Order Date: 03/29/18  
Reg Date: 01/06/16 KM: 27,519  
VIN NO.: WWWZZZ16ZGM006161 ENGINE NO:  
MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

SA: Tang Shu Shi

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Handwritten:*  
Rasul  
Hp 90010068  
12 days  
29/03/18 @ 1700  
EXCESS: 500  
REJECT  
Resurvey 64 part

TOTAL	15,900.96
GST AMOUNT	1,113.07
TOTAL AMOUNT	17,014.02

On Behalf Of COMPANY



Authorized Signature

Certified Goods/Service received:

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT



## Service Order Confirmation

SERVICE ORDER NO: 18IP0844

CUSTOMER NO.: CV032294

CUSTOMER NAME: CHEW MUI LIN

TELEPHONE NO.:

ADDRESS: 102 BEDOK RESERVOIR ROAD #01-442  
Singapore

**VEH No.: SKZ481C**

Order Date: 29/03/18

Reg Date: 06/01/16 KM: 30,057

VIN NO.: WVVZZZ16ZGM006161 ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC. %	AMOUNT
<b>Labor</b>						
1	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	200		200
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	360		360
3	B&P INSURANCE EXCESS INSURANCE EXCESS / DEDUCTIBLE	1	TU	-500		-500
4	B&P MACP LABOUR LABOUR	6	UNIT	475		2,850
5	B&P MACP PAINT SPRAY PAINT	5	UNIT	500		2,500
6	B&P MACP LABOUR TRANSFER BOOT LID MECH	0.5	UNIT	475		237.5
7	B&P MACP LABOUR R&R REAR LUGGAGE TRIM	0.5	UNIT	475		237.5
8	B&P NUMBER PLATE B&P NUMBER PLATE -NETT	1	ST	80		80
9	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
10	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
<b>Item</b>						
11	5C6827025E BOOT LID	1	PCS	1,222.87	28	880.47
12	5C6827301E BOOT LID HINGE LHS	1	PCS	82.26	28	59.23
13	5C6827302D BOOT LID HINGE RHS	1	PCS	82.26	28	59.23
14	WHT007341 NUT	4	PCS	2.18	28	6.28
15	5C6827505D LOCK	1	PCS	167.96	28.00071	120.93
16	5C6827520B 989 LOCK COVER	1	PCS	15.45	28	11.12
17	8D0853419D RR NUMBER PLATE PACKING	1	PCS	12.66	28	9.12
18	5C6827705A 5AP WTHRSTRIP	1	PCS	219.10	28	157.75
19	5C6853630F ULM VW SIGN	1	PCS	108.42	28	78.06
20	5C6853687 739 NAME PLATE ( JETTA )	1	PCS	65.96	28	47.49
21	5C6853875APGQF NAME PLATE ( TSI )	1	PCS	49.88	28	35.77
22	5C68945096L TAILLIGHT OUTER RH	1	PCS	370.74	28.00076	266.93
23	5C6807421H GRU RR BUMPER	1	PCS	1,258.64	28	906.22
24	5C6919491D SENSOR BRACKET	1	PCS	23.79	28	17.13
25	5C6919491E SENSOR BRACKET	2	PCS	23.79	28	34.26
26	5C6919492D SENSOR BRACKET	1	PCS	23.79	28	17.13
27	D 180KU2A1 2KADHESIVE	1	PCS	89.84	28	64.68
28	D 822150A1 BONDAGENT	1	PCS	64.27	28	46.27

## Service Order Confirmation

SERVICE ORDER NO: 18IP0844

CUSTOMER NO.: CV032294

CUSTOMER NAME: CHEW MUI LIN

TELEPHONE NO.:

ADDRESS: 102 BEDOK RESERVOIR ROAD #01-442

Singapore

**VEH No.: SKZ481C**

Order Date: 29/03/18

Reg Date: 06/01/16

KM: 30,057

VIN NO.: WVVZZZ16ZGM006161

ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE HDCMODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	5Q0919275B GRU	2	PCS	144.40	28	207.94
30	5Q0919133 9B9	2	PCS	1.71	28	2.46
31	5CU971104	1	PCS	161.14	28	116.02
32	5C6807433J	1	PCS	412.76	28	297.19
33	5C6807305	1	PCS	445.64	28	320.86
34	5C6807251F	1	PCS	142.24	28	102.41
35	5C6807863B	1	PCS	96.99	28	69.83
36	5C6807394D	1	PCS	69.81	28	50.26
37	5C6807376	1	PCS	83.31	28	59.96
38	N 10621301	10	PCS	1.85	28	13.32
39	5C6813301	1	PCS	1,111.35	28	800.17
40	D 007600A1	1	PCS	67.97	28	48.94
41	D 180003M2	1	PCS	286.20	28	206.06
42	D 476KD1M2	1	PCS	77.38	28	55.71
43	5C6863459G 9B9	1	PCS	72.44	28	52.16
44	5K0962131	1	PCS	67.37	28	48.51
45	8K0973702G	1	PCS	10.29	28	7.41

Remarks: MSIG (IN-HOUSE) OD CLAIM

DOA: 28/03/2018

SURVEY BY:

EXCESS: \$

## Service Order Confirmation

SERVICE ORDER NO: 18IP0844

CUSTOMER NO.: CV032294

CUSTOMER NAME: CHEW MUI LIN

TELEPHONE NO.:

ADDRESS: 102 BEDOK RESERVOIR ROAD #01-442

Singapore

**VEH No.: SKZ481C**

Order Date: 29/03/18

Reg Date: 06/01/16 KM: 30,057

VIN NO.: WVVZZZ16ZGM006161 ENGINE NO:

SA: Tang Shu Shi

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G7

<u>No.</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>DISC %</u>	<u>AMOUNT</u>
------------	--------------------	------------	------------	-------------------	---------------	---------------

TOTAL	11,242.31
GST AMOUNT	786.96
TOTAL AMOUNT	12,029.27

On Behalf Of "COMPANY"

Certified Goods/Service received:

\_\_\_\_\_  
Authorized Signature

\_\_\_\_\_  
Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG18005877/R1TBN2

Date: 20/04/2018

## REFERENCE

Insured/Claimant: CHEW MUI LIN Policy No: A28667303AVW  
Date of Loss: 28/03/2018 Nature of Claim: OD Claim No: 553979

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKZ481C  
Make & Model: VOLKSWAGEN JETTA GP, 1.4 TSI 90 A/T (A) Engine No: CAXF82202  
Reg. Date: 06/01/2016 (Man. Year: 2015) Chassis No: WWWZZZ16ZGM006161  
Colour: Blue Odometer: 30058 km  
Engine Capacity: 1390 cc  
Market Value/New Car Price: S\$85,000.00  
Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,090.95	5,357.30	1,733.65	24.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,810.00	6,385.00	2,425.00	27.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>15,900.95</b>	<b>11,742.30</b>	<b>4,158.65</b>	<b>26.15</b>
<b>- Excess (\$\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>15,400.95</b>	<b>11,242.30</b>	<b>4,158.65</b>	<b>27.00</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,078.07</b>	<b>786.96</b>	<b>291.11</b>	<b>27.00</b>
<b>Nett Amount (\$\$)</b>	<b>16,479.02</b>	<b>12,029.26</b>	<b>4,449.76</b>	<b>27.00</b>

## INSPECTION

Date of Assignment: 29/03/2018  
Date Inspected: 29/03/2018 Inspected At: Volkswagen Group Singapore (HQ)  
17 Tuas Ave 9  
Singapore 639197

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2018)
<b>Parts:</b>	143	VOLKSWAGEN JETTA GP 1.4 TSI 90 A/T (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKZ481C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	880.47 FS	*880.47 FS
2	1		*HINGE LH	Bent	59.23 FS	*59.23 FS
3	1		*HINGE RH	Bent	59.23 FS	*59.23 FS
4	4		*NUT	Necessary	6.28 FS	*6.28 FS
5	1		*LOCK	Bent	120.93 FS	*120.93 FS
6	1		*LOCK COVER	Scratched	11.12 FS	*11.12 FS
7	1		*RR NUMBER PLATE PACKING	Necessary	9.12 FS	*9.12 FS
8	1		*BOOT LOCK PUSH BUTTON	Serviceable	612.00 FS	*- FS
9	1		*WTHRSTRIP	Necessary	157.75 FS	*157.75 FS
10	1		*LOCK STRIKER	Serviceable	32.11 FS	*- FS
11	1		*VW SIGN	Necessary	78.06 FS	*78.06 FS
12	1		*NAME PLATE (JETTA)	Necessary	47.49 FS	*47.49 FS
13	1		*NAME PLATE (TSI)	Necessary	35.77 FS	*35.77 FS
14	1		*BOOT LID TRIM COVER	Serviceable	119.53 FS	*- FS
15	1		*LH INNER TAILLIGHT	Serviceable	130.67 FS	*- FS
16	1		*RH INNER TAILLIGHT	Serviceable	130.67 FS	*- FS
17	1		*TAILLIGHT OUTER LH	Scratched	266.93 FS	*266.93 FS
18	1		*TAILLIGHT OUTER RH	Serviceable	257.70 FS	*- FS
19	2		*LED LICENCE PLATE LIGHT	Serviceable	157.90 FS	*- FS
20	1		*RR BUMPER	Deformed	906.22 FS	*906.22 FS
21	2		*SENSOR BRACKET	Necessary	34.26 FS	*34.26 FS
22	1		*SENSOR BRACKET	Necessary	17.13 FS	*17.13 FS
23	1		*2KADHESIVE	Necessary	64.68 FS	*64.68 FS
24	1		*BOND AGENT	Necessary	46.27 FS	*46.27 FS
25	2		*SENSOR	Necessary	207.94 FS	*207.94 FS
26	2		*SENSOR O-RING	Necessary	2.46 FS	*2.46 FS
27	1		*SENSOR WIRE HARNESS	Cut	116.02 FS	*116.02 FS
28	1		*SPOILER	Deformed	297.19 FS	*297.19 FS
29	1		*REINFORCEMENT	Bent	320.86 FS	*320.86 FS
30	1		*FOAM INSERT	Cracked	102.41 FS	*102.41 FS
31	1		*BUMPER CENTRE BRACKET	Cracked	69.83 FS	*69.83 FS
32	1		*TAILLIGHT LOWER BRACKET LH	Serviceable	50.26 FS	*- FS
33	1		*TAILLIGHT LOWER BRACKET RH	Cracked	50.26 FS	*50.26 FS
34	1		*BUMPER SIDE BRACKET LH	Serviceable	59.98 FS	*- FS
35	1		*BUMPER SIDE BRACKET RH	Necessary	59.98 FS	*59.98 FS
36	1		*NUT	Necessary	13.32 FS	*13.32 FS
			10 Pcs			
37	1		*BUMPER LOWER COVER RH	Serviceable	105.09 FS	*- FS
38	1		*REAR END PANEL	Bent	800.17 FS	*800.17 FS
39	1		*INOXSPRAY	Necessary	48.94 FS	*48.94 FS
40	1		*2KADHESIV	Necessary	206.06 FS	*206.06 FS
41	1		*SEALANT	Necessary	55.71 FS	*55.71 FS
42	1		*END PANEL TRIM COVER	Deformed	52.16 FS	*52.16 FS
43	1		*SENSOR AERIAL	Cracked	48.51 FS	*48.51 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*WIRE HOUSING	Cracked	7.41 FS	*7.41 FS
45	1		*LH REAR REFLECTOR	Serviceable	38.87 FS	*- FS
46	1		*RH REAR REFLECTOR	Serviceable	38.87 FS	*- FS
47	1		*B&P NUMBER PLATE	Scratched	80.00 FS	*80.00 FS
48	1		*SENSOR BRACKET	Necessary	17.13 FS	*17.13 FS
F=Franchise part. S=SpcNett.				<b>Total Parts (S\$)</b>	<b>7,090.95</b>	<b>5,357.30</b>

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRE HARNESS ECU SENSOR SOCKET	New	200.00	200.00
2	PROGRAMMING & CALIBRATION	New	360.00	360.00
3	LABOUR	New	3,800.00	2,850.00
4	SPRAY PAINT	New	3,500.00	2,500.00
5	TRANSFER BOOT LID MECH	New	475.00	237.50
6	R&R REAR LUGGAGE TRIM	New	475.00	237.50
Gross Labour Cost (S\$)			<b>8,810.00</b>	<b>6,385.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >