

22/03/2002

- 85

ASS. REC. BY:

REF: CS/CT118005878/Kcd302

Special Instruction:

Surveyor: Kenneth
MerimenASSIGNMENT (Office)

From (Person): Irene Tay of CT1 Date/Time: 29032018 231pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJX 1237H Insured:

at Workshop m/s Cheng Hoe Motor Tel: 6481 2001

of 51k 1019 Yishun Ind Park A #01-374 / 382

Policy No: DMPCSN3118701600 Claim No: SNM18D01596C01

Sum Insured: Excess: # 0

Make of Veh: D.O.A. 17032018
(Client's Record)

CA / REX / REP. / REV 24 HRS

51k 10AMK Ind Park A #01-04 @ 04-04-2018 (9am-1pm)

H.O.D. Endorsement:

Date/Time: 29032018 3:26pm Person Contacted: Doreen Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJX 1237H - X
	Sent preli thru merimen
9/4/18	Authorise repair and called Doreen to inform authorise repair. She said no need to sent email

108/11/13

REF: CM

ASSIGNMENT

From: _____ Date: 04042018

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJX 1237H

at Workshop m/s: Cheng Hoo Motor

of: Blk 10 Amk Ind Park 2A #01-04

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$0

(Client's Record)

Make of Veh: _____

9am - 1pm.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$27K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJX 1237H Yr Regn: 93 10

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Proton Exora CPS 1597

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 113577 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PL 1F 86 Y RRA FC 28017

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ling long

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 7 mm

L/Bal. 8 mm L/Bal. 7 mm

D.O.A. 17/3/18 D.O.I. 4/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 141

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>5/4</u>	<u>File pass to Catherine</u>
<u>8/18.93</u>	<u>-7 to chuk.</u>
<u>13/3/18am</u>	<u>Confirmed final sig \$1818.93 and 4 days with Ekeeda. (Fed. 192, 9%)</u>

Date/Time: File Pass to?	<input type="checkbox"/> : Preli. Report	Days Of Repair: <u>4</u>	Survey Fee: <u>220</u>
1)	<input type="checkbox"/> : Final Report	Resurvey No. of Trip: <u>1</u>	Transportation: _____
Date/Time: File Return to?			S + RS. St _____
2)		Add Fee: <input type="checkbox"/> Site Insp (\$ _____)	Photos _____
Report Format: <u>OD</u>		<input type="checkbox"/> Interview (\$ _____)	Others _____
Lump Sum / <input checked="" type="radio"/> IB: (\$ <u>1,818.93</u>)		<input type="checkbox"/> Tech. Invs (\$ _____)	
		<input type="checkbox"/> Weekend (\$ _____)	
			TOTAL <u>220</u>




Service Request Details

Claim

S8M00BNB

Reference

None 

Loss Date

March 11, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▼

Request Date

March 27, 2018

Due Date

April 4, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

27032018 @ 3:17pm
Khim veh in

Ethnicar2

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

YP7857T

Make

TPVD HINO



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18005878/Krb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 29-03-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJX 1237H
Policy No.	DMPCSN3118701600	Coverage (\$)	0.00
Claim No.	SNM18D01596C01	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/03/2018	Inspection Date	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2018 Sendback Est	29 Mar 2018 12:18 S\$2,010.93	29 Mar 2018 14:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SHIRIN BINTE YAHYA, ID: S8521297D, Tel: +6594777151, Email: shirin.miyake@gmail.com		
Vehicle Reg. No.:	SJX1237H	Date of Loss:	17/03/2018 19:00 - :59
Claim Type:	OD / SNM18D01596C01	Policy/Cover Note No.:	DMPCSN3118701600 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/04/2018]		
Driver/Custodian:	SHIRIN BINTE YAHYA (32 / Female), NRIC: S8521297D, Tel: +6594777151		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Wednesday, 13 March 2019 11:11 AM
To: Efeeda (Cheng Hoe -Yishun)
Cc: SUR
Subject: RE: OD CLAIM - CHINA TAIPING - SJX 1237H - DOA: 17/03/2018

Dear Efeeda,

Confirm repair cost of \$1,818.93 @ 4 days of repairs.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Celine Fong (LKKAUTO)
Sent: Tuesday, 12 March 2019 4:23 PM
To: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM - CHINA TAIPING - SJX 1237H - DOA: 17/03/2018

Hi Efeeda,

Sorry, please see attached.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Celine Fong (LKKAUTO)
Sent: Tuesday, 12 March 2019 2:30 PM
To: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: OD CLAIM - CHINA TAIPING - SJX 1237H - DOA: 17/03/2018

Dear Efeeda,

WITHOUT PREJUDICE

Finalise amount \$1,799.89 before GST @ 4 working days.

Please check and confirm.

Print Received Message

This mail is associated with :

SJX1237H (SNM18D01596C01)

OD

Mar 17 2018 7:00PM

[SHIRIN BINTE YAHYA]

Cheng Hoe Motor Pte Ltd

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 09/04/2018 15:39 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1844.89) - SJX1237H - Claim Handler: Irene Tay Hui Ping

Approved:1844.89.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte.
Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 05 Apr 2018

Preliminary Advice

Vehicle No	: SJX1237H	Accident Date	: 17/03/2018
Make	: PROTON EXORA	Policy No.	: DMPCSN3118701600
Assignment Date	: 29/03/2018	Excess	: S\$0.00
Date of Inspection	: 04/04/2018	Est. Duration of Repair	: 4.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,010.93
Revised Amount	:S\$	1,609.89
Check Items (Estimated)	:S\$	235.00
Total	:S\$	1,844.89

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	27,000.00
COE / PARF Rebate	:S\$	14,160.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,840.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

.() Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1297D
Vehicle Details	
Vehicle No.:	SJX1237H
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Mar 2018
Vehicle Make:	PROTON
Vehicle Model:	EXORA 1.6L AT (M-LINE) ABS D/AB 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	S4PHQG9616
Chassis No.:	PL1FZ6YRRAF028017
Maximum Power Output:	93.0 kW (124 bhp)
Open Market Value:	\$14,113.00
Original Registration Date:	29 Mar 2010
First Registration Date:	29 Mar 2010
Transfer Count:	1
Actual ARF Paid:	\$14,113.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2020
PARF Rebate Amount:	\$8,467.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$28,389.00
COE Rebate Amount:	\$5,693.00
Total Rebate Amount:	\$14,160.00

The information contained herein is correct as at 26 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/03/2018 15:40
Date Of Accident	17/03/2018 19:30
Exact Location Of Accident	SEA HORIZON CONDO BASEMENT CARPARK TWDS EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJX1237H
Insured/Policyholder	
Name Of Registered Owner	SHIRIN BINTE YAHYA
NRIC No	S8521297D
Email Address	SHIRIN.MIYAKE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94777151
Alternative Phone No	OTHERS-94777151
Vehicle Particulars	
Manufacturer	PROTON
Model	EXORA-1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3118701600
Cover Note Number	29/03/2017 - 28/03/2018
Driver	
Name of Driver	SHIRIN BINTE YAHYA
NRIC No	S8521297D
Date Of Birth	30/06/1985
Occupation	INDOOR
Date Of Driving Pass	08/08/2005
Driving Experience	12 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94777151
Fax Number	
Contact Number	OTHERS-94777151
Email Address	SHIRIN.MIYAKE@GMAIL.COM

Address	BLK 176D EDGEFIELD PLAINS #02-186
Postcode	824176
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE DRIVING OUT TOWARDS THE EXIT, MY VEHICLE FRONT RH PORTION HAD ACCIDENTALLY GRAZED ONTO THE WALL. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN


VEHICLE NO.: SJX 1237H
INSURER : China
DATE & TIME: 17/03/18 @ 1930

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 26/3/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Danyu (AWEK)
NRIC/FIN No.: 26/03/18

exit

A: SJX1237M
alone

Location: Sea Horizon
Condo basement
Carpark → exit

Vehicle No: SJX1237M (China)
Date & Time: 17/03/18 @ 19:30 (Friday)
While driving out towards the exit, my vehicle front RH portion had accidentally grazed onto the wall. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: (AMK)
NRIC/FIN No.:

☒ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☐ Claim OD/TP at other workshop ()

**CHENG HOE MOTOR PTE
LTD
BLK 1019, YISHUN
INDUSTRIAL PARK A
#01-374/382
SINGAPORE 768761**

Claim Reference:
Assessment Number: CSJX1237
Version: CHENGHOE/1
Date Calculated: 29/03/2018 01:25

Full Report - V1
Registration: SJX1237H
Printed: 29/03/2018 12:16

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	CHENG HOE MOTOR PTE LTD	Date of Incident:	17/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	4 day(s) ✓
Policy Number:	DMPCSN3118701600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	PROTON
Model:	Exora
Sub Model:	M-LINE
Model Sheet Number:	1509 02
Registration:	SJX1237H
Registration Month:	March
Registration Year:	2010
VIN Number:	DMPCSN3118701600
Manufacture Year:	2010
Odometer:	Not Known
Colour:	White
Engine Number:	
Fuel Level:	%

Model Specs

FROM 01/2010	AIR CONDITIONING
FOG LAMPS	1.6 LTR 93 KW VTEC
GEARBOX 5 SPEED	PASSENGER AIRBAG
ANTI LOCK BRAKES	DRIVER AIRBAG
TYRES 205/55 R 16	WHEELS 6J X 15
MULTIMEDIA SYSTEM	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA	

Not Authorised
0154
1.B.1
Repair by painting
Ex ML

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	29/03/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:		
Tread Depth LHR:		
Damage Areas:		

LKK Auto Consultants
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be provided and is subject to final approval

Acknowledged by:
Signature:
Date:

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSJX1237



Version: CHENGHOE/1

Date Calculated: 29/03/2018 01:25

Full Report - V1

Registration: SJX1237H

Printed: 29/03/2018 12:16



Addresses

Repairer

Name : CHENG HOE MOTOR PTE LTD (AMK)

Address :

10. ANG MO KIO IND PK 2A

01-04

Post Code : 568047

Cost Summary

Total Labour	\$785.40
Total Paint/Material	\$163.53
Total Parts	\$1,062.00
Excess:	TBA
Grand Total Exc GST:	\$2,010.93
7 % GST:	\$140.77
Grand Total Inc GST:	\$2,151.70

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR

Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	PREPARATION TIME	2.0	8.40
NO NUMBER	R + R FRONT BUMPER	8.0	33.60
NO NUMBER	R + R FRONT BUMPER	4.0	16.80
NO NUMBER	RENEW FRONT BUMPER	7.0	29.40
NO NUMBER	ADJUST BOTH HEADLAMPS	3.0	12.60
NO NUMBER	R + R R/F WING	14.0	58.80
NO NUMBER	R + R WASHER RESERVOIR (BUMPER REMOVED)	6.0	25.20
NO NUMBER	R + R R/A-PILLAR COVER	2.0	8.40
NO NUMBER	R + R LOWER FRONT SCREEN COVER	5.0	21.00
NO NUMBER	R + R R/SILL SIDE SPOILER	10.0	42.00
NO NUMBER	R + R BATTERY	2.0	8.40
0930	REPAIR FRONT PANEL CPL	10 15.0*	63.00
1120	REPAIR R/F OUT SIDE MEMBER	10 10.0*	42.00 X
4465	CHECK CONDENSER	10 10.0*	42.00 X
7761	CHECK RADIATOR	10 10.0*	42.00 X

LABOUR COST

Total Work Units

108.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

Sub Total

10.8HRS

\$453.60

CHENG HOE MOTOR PTE LTD

Claim Reference:
Assessment Number: CSJX1237
Version: CHENGHOE/1
Date Calculated: 29/03/2018 01:25

Full Report - V1
Registration: SJX1237H
Printed: 29/03/2018 12:16

Paint Labour	7.9HRS	\$331.80
Total Labour	18.7HRS	\$785.40

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
340	FRT BUMPER REINF SURFACE PAINT	4.0	
742	R/F WING NEW PART PAINTING	9.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	11.0	
471	BONNET SURFACE PAINT	10.0	
741	L/F WING SURFACE PAINT	5.0	
930	FRONT PANEL CPL SURFACE PAINT	6.0	
1120	R/F OUT SIDE MEMBER SURFACE PAINT	4.0	
LABOUR COST - PAINT			
TIME(PAINT)		49.0	
Preparation Main Work Plastic		5.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		79.0	
Total Paintwork Labour		7.9HRS	\$331.80
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$16.51
New Part Painting - Plastic K1R			\$52.15
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$57.27
Material-Const Main Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$163.53
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$163.53

PARTS

				Price Valid: 01/01/2001	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
283	1	FRONT BUMPER COVER	PW838303	Bu	0% 220.00*
340	1	FRT BUMPER REINF	PW838311	Bu	0% 190.00*
356	1	R/F BUMPER BRACKET	PW838314	D17	0% 32.00*
298	1	R/F FOG LAMP GRILLE	PW838310		0% 45.00*
562	1	R/F HEADLAMP CPL	PW856306		0% 240.00*
742	1	R/F WING	PW837666ED	Bu	0% 160.00*
842	1	R/WING SPLASH SHIELD	PW838442		0% 75.00*
f: OEM Parts			Sub Total		\$962.00
g: Original			Sundry Parts	(Fixed)	\$100.00
h: Secondhand			Total Parts		\$1,062.00
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts	\$1,062.00
Labour	

CHENG HOE MOTOR PTE LTD

Claim Reference:
Assessment Number: CSJX1237
Version: CHENGHOE/1
Date Calculated: 29/03/2018 01:25

Full Report - V1
Registration: SJX1237H
Printed: 29/03/2018 12:16

Total Panel/Mechanical	\$453.60	366.60
Total Paintwork	\$331.80	✓
Total Labour		\$785.40
Total Paint/Material Costs		\$163.53 ✓
Grand Total Excludes GST		\$2,010.93
GST @ 7 %		\$140.77
Grand Total Includes GST		\$2,151.70

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore

408933

Adjust auto dex

Claim Reference:
Assessment Number: CSJX1237
Version: CHENGHOE/1
Date Calculated: 05/04/2018 09:51

Full Report - V1
Registration: SJX1237H
Printed: 05/04/2018 16:52

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	17/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	4 day(s)
Policy Number:	DMPCSN3118701600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	PROTON
Model:	Exora
Sub Model:	M-LINE
Model Sheet Number:	1509 02
Registration:	SJX1237H
Registration Month:	March
Registration Year:	2010
VIN Number:	DMPCSN3118701600
Manufacture Year:	2010
Odometer:	Not Known
Colour:	White
Engine Number:	
Fuel Level:	%

Model Specs

FROM 01/2010	AIR CONDITIONING
FOG LAMPS	1.6 LTR 93 KW VTEC
GEARBOX 5 SPEED	PASSENGER AIRBAG
ANTI LOCK BRAKES	DRIVER AIRBAG
TYRES 205/55 R 16	WHEELS 6J X 15
MULTIMEDIA SYSTEM	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	29/03/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Claim Reference:

Full Report - V1



Assessment Number: CSJX1237

Registration: SJX1237H

Version: CHENGHOE/1

Printed: 05/04/2018 16:52

Date Calculated: 05/04/2018 09:51

**Addresses****Repairer**

Name : CHENG HOE MOTOR PTE LTD (AMK)

Address :

10. ANG MO KIO IND PK 2A

01-04

Post Code : 568047

Cost Summary

Total Labour	\$621.60
Total Paint/Material	\$161.29
Total Parts	\$1,062.00
Excess:	TBA
Grand Total Exc GST:	\$1,844.89
7 % GST:	\$129.14
Grand Total Inc GST:	\$1,974.03

Repair Information**LABOUR**Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR**Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	PREPARATION TIME	2.0	8.40
NO NUMBER	R + R FRONT BUMPER	8.0	33.60
NO NUMBER	R + R FRONT BUMPER	4.0	16.80
NO NUMBER	RENEW FRONT BUMPER	7.0	29.40
NO NUMBER	ADJUST BOTH HEADLAMPS	3.0	12.60
NO NUMBER	R + R R/F WING	14.0	58.80
NO NUMBER	R + R WASHER RESERVOIR (BUMPER REMOVED)	6.0	25.20
NO NUMBER	R + R R/A-PILLAR COVER	2.0	8.40
NO NUMBER	R + R LOWER FRONT SCREEN COVER	5.0	21.00
NO NUMBER	R + R R/SILL SIDE SPOILER	10.0	42.00
NO NUMBER	R + R BATTERY	2.0	8.40
0930	REPAIR FRONT PANEL CPL	10.0*	42.00

LABOUR COST**Total Work Units**

73.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

Sub Total

7.3HRS

\$306.60

Paint Labour

7.5HRS

\$315.00

Total Labour

14.8HRS

\$621.60

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Claim Reference:

Full Report - V1

Assessment Number: CSJX1237

Registration: SJX1237H

Version: CHENGHOE/1

Printed: 05/04/2018 16:52

Date Calculated: 05/04/2018 09:51

Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
340	FRT BUMPER REINF SURFACE PAINT	4.0	
742	R/F WING NEW PART PAINTING	9.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	11.0	
471	BONNET SURFACE PAINT	10.0	
741	L/F WING SURFACE PAINT	5.0	
930	FRONT PANEL CPL SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	45.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	75.0	
	Total Paintwork Labour	7.5HRS	\$315.00
MATERIAL COST - PAINT			
	Cost Price		
	New Part Painting		\$16.51
	New Part Painting - Plastic K1R		\$52.15
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$55.03
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$161.29
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$161.29

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/01/2001	Bet.	Price (\$)
283	1	FRONT BUMPER COVER	PW838303		0%		220.00*
340	1	FRT BUMPER REINF	PW838311		0%		190.00*
356	1	R/F BUMPER BRACKET	PW838314		0%		32.00*
298	1	R/F FOG LAMP GRILLE	PW838310		0%		45.00*
562	1	R/F HEADLAMP CPL	PW856306		0%		240.00*
742	1	R/F WING	PW837666ED		0%		160.00*
842	1	R/WING SPLASH SHIELD	PW838442		0%		75.00*
f: OEM Parts			Sub Total				\$962.00
g: Original			Sundry Parts	(Fixed)			\$100.00
h: Secondhand			Total Parts				\$1,062.00
p: Parallel							
x: Exchange							

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00**Final Calculation**

Total Parts		\$1,062.00
Labour		
Total Panel/Mechanical	\$306.60	
Total Paintwork	\$315.00	
Total Labour		\$621.60
Total Paint/Material Costs		\$161.29
Grand Total Excludes GST		\$1,844.89
GST @ 7 %		\$129.14

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: CSJX1237

Registration: SJX1237H

Version: CHENGHOE/1

Printed: 05/04/2018 16:52

Date Calculated: 05/04/2018 09:51

Grand Total Includes GST

\$1,974.03

Assessment Notes

**CHENG HOE MOTOR PTE
LTD
BLK 1019, YISHUN
INDUSTRIAL PARK A
#01-374/382
SINGAPORE 768761**

Claim Reference:
Assessment Number: CSJX1237
Version: CHENGHOE/1

Full Report - V1
Registration: SJX1237H
Printed: 03/05/2018 14:21

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	CHENG HOE MOTOR PTE LTD	Date of Incident:	17/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	4 day(s)
Policy Number:	DMPCSN3118701600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	PROTON
Model:	Exora
Sub Model:	M-LINE
Model Sheet Number:	1509 02
Registration:	SJX1237H
Registration Month:	March
Registration Year:	2010
VIN Number:	DMPCSN3118701600
Manufacture Year:	2010
Odometer:	Not Known
Colour:	White
Engine Number:	
Fuel Level:	%



Model Specs

FROM 01/2010	AIR CONDITIONING
FOG LAMPS	1.6 LTR 93 KW VTEC
GEARBOX 5 SPEED	PASSENGER AIRBAG
ANTI LOCK BRAKES	DRIVER AIRBAG
TYRES 205/55 R 16	WHEELS 6J X 15
MULTIMEDIA SYSTEM	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	29/03/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

CHENG HOE MOTOR PTE LTD**Claim Reference:****Assessment Number: CSJX1237****Version: CHENGHOE/1****Full Report - V1****Registration: SJX1237H****Printed: 03/05/2018 14:21****Addresses****Repairer**

Name : CHENG HOE MOTOR PTE LTD (AMK)

Address :

10, ANG MO KIO IND PK 2A

01-04

Post Code : 568047

Cost Summary

Total Labour	\$638.40
Total Paint/Material	\$163.53
Total Parts	\$1,017.00
Excess:	TBA
Grand Total Exc GST:	\$1,818.93
7 % GST:	\$127.33
Grand Total Inc GST:	\$1,946.26

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	PREPARATION TIME	2.0	8.40
NO NUMBER	R + R FRONT BUMPER	8.0	33.60
NO NUMBER	R + R FRONT BUMPER	4.0	16.80
NO NUMBER	RENEW FRONT BUMPER	7.0	29.40
NO NUMBER	ADJUST BOTH HEADLAMPS	3.0	12.60
NO NUMBER	R + R R/F WING	14.0	58.80
NO NUMBER	R + R WASHER RESERVOIR (BUMPER REMOVED)	6.0	25.20
NO NUMBER	R + R R/A-PILLAR COVER	2.0	8.40
NO NUMBER	R + R LOWER FRONT SCREEN COVER	5.0	21.00
NO NUMBER	R + R R/SILL SIDE SPOILER	10.0	42.00
NO NUMBER	R + R BATTERY	2.0	8.40
0930	REPAIR FRONT PANEL CPL	10.0*	42.00

LABOUR COST**Total Work Units**

73.0

Sub Total

7.3HRS

\$306.60

Paint Labour

7.9HRS

331.80

Total Labour

15.2HRS

\$638.40

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number Description

WU

Cost Price (\$)

- PREPARE OFF VEHICLE
- TWO COAT PEARL/MICA

AUTO MART SUPPLY PTE LTD

BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #01-17 AMK AUTOPOINT SINGAPORE 568047 E-mail: automartsupply@gmail.com
 TEL 6481-5290 FAX 6481-3904
 Business Reg & GST No: 19-3902359-4

DELIVERY ORDER

CHENG HOE MOTOR PTE LTD

Delivery Order: B150571

BLK 10, ANG MO KIO INDUSTRIAL PARK 2A BLK 1019 YISHUN IND PK A Delivery Date : 11 APR 2018
 #01-04 AMK AUTOPOINT SINGAPORE 568047 #01-374 15:20

Page : 1 of 1 Page.

PRODUCT CODE	DESCRIPTIONS	QUANTITY	UNIT PRICE	AMOUNT
BUMPER, FF	FRONT BUMPER EXORA/SJX1237H	1 PC	220.00	220.00 ✓
REINFORCEMENT, FF	FRONT BUMPER REINFORCEMENT EXORA/SJX1237	1 PC	190.00	190.00 ✓
RETAINER, FF BUMP	FRONT BUMPER SIDE RETAINER (RH) EXORA	1 PC	32.00	32.00 ✓
MUDGUARD, FF	FRONT FENDER (RH) EXORA/SJX1237H	1 PC	160.00	160.00 ✓
SHIELD, FF MUDGUA	FRONT FENDER COWLING (RH) EXORA/SJX1237D	1 PC	75.00	75.00 ✓
LAMP, FF H/LAMP	FRONT HEADLAMP ASSY (RH) EXORA/SJX1237H	1 PC	240.00	240.00 ✓

Subject To 7% Goods & Services Tax (917.00)

Issued By : BOON HUA

Checked By

Customer's Signature

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSJX1237

Version: CHENGHOE/1

Full Report - V1

Registration: SJX1237H

Printed: 03/05/2018 14:21

340	FRT BUMPER REINF SURFACE PAINT	4.0	
742	R/F WING NEW PART PAINTING	9.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	11.0	
471	BONNET SURFACE PAINT	10.0	
741	L/F WING SURFACE PAINT	5.0	
930	FRONT PANEL CPL SURFACE PAINT	6.0	
1120	R/F OUT SIDE MEMBER SURFACE PAINT	4.0	
LABOUR COST - PAINT			
	TIME(PAINT)	49.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	79.0	
	Total Paintwork Labour	7.9HRS	\$331.80
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$16.51
	New Part Painting - Plastic K1R		\$52.15
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$57.27
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$163.53
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$163.53

PARTS

Guide No. Qty		Description	Part Number	Supplier	Price Valid: 01/01/2001	
					Bet.	Price (\$)
283	1	FRONT BUMPER COVER	PW838303		0%	220.00*
340	1	FRT BUMPER REINF	PW838311		0%	190.00*
356	1	R/F BUMPER BRACKET	PW838314		0%	32.00*
562	1	R/F HEADLAMP CPL	PW856306		0%	240.00*
742	1	R/F WING	PW837666ED		0%	160.00*
842	1	R/WING SPLASH SHIELD	PW838442		0%	75.00*
f: OEM Parts			Sub Total			\$917.00
g: Original			Sundry Parts	(Fixed)		\$100.00
h: Secondhand			Total Parts			\$1,017.00
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Final Calculation

Total Parts		\$1,017.00
Labour		
Total Panel/Mechanical	\$306.60	
Total Paintwork	\$331.80	
Total Labour		\$638.40
Total Paint/Material Costs		\$163.53
Grand Total Excludes GST		\$1,818.93
GST @ 7 %		\$127.33
Grand Total Includes GST		\$1,946.26

Assessment Notes

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSJX1237

Version: CHENGHOE/1

Full Report - V1

Registration: SJX1237H

Printed: 03/05/2018 14:21

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: 18/1596
Assessment Number: CSJX1237
Version: LKKAUTOC/4
Date Calculated: 12/03/2019 09:30

Full Report - V1
Registration: SJX1237H
Printed: 12/03/2019 17:31

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	17/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	18/1596	Estimated Repair Time:	4 day(s)
Policy Number:	DMPCSN3118701600	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	PROTON
Model:	Exora
Sub Model:	M-LINE
Model Sheet Number:	1509 02
Registration:	SJX1237H
Registration Month:	March
Registration Year:	2010
VIN Number:	DMPCSN3118701600
Manufacture Year:	2010
Odometer:	Not Known
Colour:	White
Engine Number:	
Fuel Level:	%



Model Specs

FROM 01/2010	AIR CONDITIONING
FOG LAMPS	1.6 LTR 93 KW VTEC
GEARBOX 5 SPEED	PASSENGER AIRBAG
ANTI LOCK BRAKES	DRIVER AIRBAG
TYRES 205/55 R 16	WHEELS 6J X 15
MULTIMEDIA SYSTEM	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	29/03/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Addresses

Repairer

Name : CHENG HOE MOTOR PTE LTD (AMK)

Address :

10. ANG MO KIO IND PK 2A

01-04

Post Code : 568047

Cost Summary

Total Labour	\$638.40
Total Paint/Material	\$163.53
Total Parts	\$1,017.00
Excess:	TBA
Grand Total Exc GST:	\$1,818.93
7 % GST:	\$127.33
Grand Total Inc GST:	\$1,946.26

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	PREPARATION TIME	2.0	8.40
NO NUMBER	R + R FRONT BUMPER	8.0	33.60
NO NUMBER	R + R FRONT BUMPER	4.0	16.80
NO NUMBER	RENEW FRONT BUMPER	7.0	29.40
NO NUMBER	ADJUST BOTH HEADLAMPS	3.0	12.60
NO NUMBER	R + R R/F WING	14.0	58.80
NO NUMBER	R + R WASHER RESERVOIR (BUMPER REMOVED)	6.0	25.20
NO NUMBER	R + R R/A-PILLAR COVER	2.0	8.40
NO NUMBER	R + R LOWER FRONT SCREEN COVER	5.0	21.00
NO NUMBER	R + R R/SILL SIDE SPOILER	10.0	42.00
NO NUMBER	R + R BATTERY	2.0	8.40
0930	REPAIR FRONT PANEL CPL	10.0*	42.00

LABOUR COST

Total Work Units	73.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	7.3HRS	\$306.60
Paint Labour	7.9HRS	\$331.80
Total Labour	15.2HRS	\$638.40

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
340	FRT BUMPER REINF SURFACE PAINT	4.0	
742	R/F WING NEW PART PAINTING	9.0	
1120	R/F OUT SIDE MEMBER SURFACE PAINT	4.0*	
283	FRONT BUMPER COVER NEW PART PAINT K1R	11.0	
471	BONNET SURFACE PAINT	10.0	
741	L/F WING SURFACE PAINT	5.0	
930	FRONT PANEL CPL SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	49.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	79.0	
	Total Paintwork Labour	7.9HRS	\$331.80
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$16.51
	New Part Painting - Plastic K1R		\$52.15
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$57.27
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$163.53
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$163.53

PARTS

					Price Valid: 01/01/2001	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER COVER	PW838303		0%	220.00*
340	1	FRT BUMPER REINF	PW838311		0%	190.00*
356	1	R/F BUMPER BRACKET	PW838314		0%	32.00*
298	1	R/F FOG LAMP GRILLE	PW838310		0%	0.00F
562	1	R/F HEADLAMP CPL	PW856306		0%	240.00*
742	1	R/F WING	PW837666ED		0%	160.00*
842	1	R/WING SPLASH SHIELD	PW838442		0%	75.00*
f: OEM Parts			Sub Total			\$917.00
g: Original			Sundry Parts	(Fixed)		\$100.00
h: Secondhand			Total Parts			\$1,017.00
p: Parallel						
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts		\$1,017.00
Labour		
Total Panel/Mechanical	\$306.60	
Total Paintwork	\$331.80	
Total Labour		\$638.40
Total Paint/Material Costs		\$163.53

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: 18/1596

Full Report - V1

Assessment Number: CSJX1237

Registration: SJX1237H

Version: LKKAUTOC/4

Printed: 12/03/2019 17:31

Date Calculated: 12/03/2019 09:30

Grand Total Excludes GST	\$1,818.93
GST @ 7 %	\$127.33
Grand Total Includes GST	\$1,946.26

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2018 Sendback Est	29 Mar 2018 12:18 S\$2,010.93	29 Mar 2018 14:31 Edit Adj Rpt	S\$1,818.93 Edit Estimates	S\$1,818.93 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: SHIRIN BINTE YAHYA , ID: S8521297D, Tel: +6594777151, Email: shirin.miyake@gmail.com									
Vehicle Reg. No.: SJX1237H		Date of Loss: 17/03/2018 19:00 - :59 [95 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D01596C01		Policy/Cover Note No.: DMPCSN3118701600 (Comprehensive)							
		Excess: S\$0.00							
Repairer: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/04/2018]									
Driver/Custodian: SHIRIN BINTE YAHYA (32 / Female) , NRIC: S8521297D, Tel: +6594777151 Email: shirin.miyake@gmail.com									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (09/04/2018): Alert - Adj Mandate Approved (S\$1844.89) - SJX1237H - Claim Handler: Irene Tay H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJX1237H (SNM18D01596C01)

OD

Mar 17 2018 7:00PM



[SHIRIN BINTE YAHYA]

Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)					Thumbnail	Print		
1	29/03/18 12:18	Repairer Estimates					Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	05/04/18 17:20	Adjuster Immediate Advice					Load HTM			
Photos/Images							3 per page	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
2	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
3	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
4	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
5	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
6	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
7	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
8	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
9	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
10	05/04/18 17:22	General View					Load JPG	<input checked="" type="checkbox"/>		
11	13/03/19 11:20	Reinspection Photo					Load PDF			
Documentation							1 per page	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	05/04/18 17:22	AUTODEX ADJUSTMENT					Load PDF			
2	05/04/18 17:30	SJX 1237H ESTIMATE					Load PDF			

Linked Accident Report Documents

			View <input type="button" value="View in Browser"/>	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		
1	26/03/18 16:07	Accident Statement		
			Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		
1	26/03/18 16:07	Accident Photo		
			Load JPG	<input checked="" type="checkbox"/>
2	26/03/18 16:07	Accident Photo		
			Load JPG	<input checked="" type="checkbox"/>
3	26/03/18 16:07	Accident Photo		
			Load JPG	<input checked="" type="checkbox"/>
4	26/03/18 16:07	Accident Photo		
			Load JPG	<input checked="" type="checkbox"/>
5	26/03/18 16:07	Accident Photo		
			Load JPG	<input checked="" type="checkbox"/>
6	26/03/18 16:07	Accident Photo		
			Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		
1	26/03/18 16:06	Sketch Plan		
			Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
		Cheng Hoe Motor Pte Ltd (Yishun)		<input checked="" type="checkbox"/>
2	26/03/18 16:06	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	26/03/18 16:06	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18005878/KRBE2

Date: 14/03/2019

REFERENCE

Insured/Claimant: SHIRIN BINTE YAHYA Policy No: DMPCSN3118701600
Date of Loss: 17/03/2018 Nature of Claim: OD Claim No: SNM18D01596C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX1237H**
Make & Model: PROTON EXORA, 1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A) Engine No: S4PHQG9616
Reg. Date: 29/03/2010 (Man. Year: 2010) Chassis No: PL1FZ6YRRAF028017
Colour: White Odometer: 113577 km
Engine Capacity: 1597 cc
Market Value/New Car Price: S\$27,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Linglong 8 mm Rear Left Side: Linglong 7 mm
Front Right Side: Linglong 8 mm Rear Right Side: Linglong 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	962.00	917.00	45.00	4.68
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	948.93	801.93	147.00	15.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,010.93	1,818.93	192.00	9.55
+ GST 7.00/7.00% (S\$)	140.77	127.33	13.44	9.55
Nett Amount (S\$)	2,151.70	1,946.26	205.44	9.55

INSPECTION

Date of Assignment: 29/03/2018 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 04/04/2018 Inspected At: 10 ANG MO KIO IND PARK 2A #01-04
Repairer : Cheng Hoe Motor Pte Ltd (Yishun)
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2019)
Parts:	M1-MPV	PROTON EXORA 1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX1237H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER COVER	Buckled	220.00 F	*220.00 F
2	1	NA	*FRT BUMPER REINF	Bent	190.00 F	*190.00 F
3	1	NA	*R/F BUMPER BRACKET	Distorted	32.00 F	*32.00 F
4	1	NA	*R/F FOG LAMP GRILLE	Serviceable	45.00 F	*- F
5	1	NA	*R/F HEADLAMP CPL	Cut	240.00 F	*240.00 F
6	1	NA	*R/F WING	Buckled	160.00 F	*160.00 F
7	1	NA	*R/WING SPLASH SHIELD	Distorted	75.00 F	*75.00 F
				Total Parts (S\$)	962.00	917.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (S\$)			100.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	331.80	331.80
2	Total Paint Materials	New	163.53	163.53
3	Total Panel/Mechanical Labour	New	453.60	306.60
Gross Labour Cost (S\$)			948.93	801.93

Report was unsubmitted during this print-out.

< END OF ESTIMATES >