



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S Tong Tar Transport Svc Pte Ltd
No 8 Soon Lee Road
SINGAPORE 628072
Insured Tong Tar Transport Svc Pte Ltd
Policy 5067768759-03

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 26/3/2018
Our Case Ref. SC18/03/061/4TT-TP
Accident Date 9/2/2018

Damaged Vehicle No: PH2992S

S/no	Description	QTY	Price	Disc	Amount
Replaced Parts					
1	REAR BUMPER LAMP	2 PC	\$125.00	25.00% <i>cra</i>	\$187.50
2	REAR BUMPER BRACKET RHS	1 PC	\$264.78	25.00% <i>N/A</i>	\$198.59
3	REAR BUMPER BRACKET LHS	1 PC	\$264.78	25.00% <i>bt</i>	\$198.59
4	REAR BUMPER	1 PC	\$2,608.00	25.00% <i>bt</i>	\$1,956.00
5	TAILLAMP	<i>330.8V-2P</i> 4 PC	\$165.40	25.00% <i>cra</i>	\$496.20
6	EMERGENCY DOOR STICKER	1 PC	\$15.00	- <i>N/A</i>	\$15.00
7	60 KM/HR STICKER	1 PC	\$15.00	- <i>N/A</i>	\$15.00
Labour Charges					
1	LABOUR FOR WIRING	1	\$120.00	- <i>30</i>	\$120.00
2	SPRAY PAINTING	1	\$1,800.00	- <i>900</i>	\$1,800.00
3	REAR PORTION LABOUR	1	\$4,480.00	- <i>2005</i>	\$4,480.00
KK Auto Consultants hence notify the Repairer of the following: • Survey before/after spray painting • Spray damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Not Authorised</i> <i>43 Regm</i> <i>After paint Photo</i> <i>Let KK Auto Unit</i> <i>27/3/2018</i> <i>6 w day S</i> <i>84228474</i>					
Sub Total					\$ 9,466.88

Authorised Signature