

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0389/2018/NK
Date : 31-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ho Khar Tin Winnie Mrs Winnie Au
Address : 109 Greenwood Ave

Singapore 287028

Telephone : HP 65 96379379
Type of Claim : Third party claims
Policy No. : GA210104/1
Vehicle No : **SGV 109 Y**
Model Code : Audi Q2 1.0 TFSI S-TRONIC
Model / Year : May-17
Engine No : CHZ365609
Chassis No : WAUZZZGAXHA048656
Mileage :
Date In : 29-Mar-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Mar-18
Place of Accident : Alexandra Rd Near Alexandra Point

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGV 109 Y.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper assy. Inspect rear panels for damages. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray rear bumper	\$ 900.00 550.	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,422.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGV 109 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Deformed</i>	\$ 1,016.00	✓
2	REAR BUMPER SPOILER <i>Deformed</i>	\$ 247.00	✓
3	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	\$ 480.00	?
4	REAR BUMPER HOLDING STRAP LH & RH <i>3 need</i>	\$ 22.00	✓
5	REAR BUMPER GUIDE SECTION LH & RH	2 \$ 92.00	✓
6	REAR SENSOR INNER <i>new</i>	2 \$ 421.00	✓
7	SEAL RING <i>new</i>	4 \$ 15.00	✓
8	WHEEL COVER REAR LH & RH <i>new</i>	2 \$ 298.00	✓
9	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 2,891.00	
TOTAL LABOUR CHARGES		\$ 2,422.00	
GRAND TOTAL		\$ 5,313.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *02/04/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *xire Authorised, 03 Days*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant