

8933 / An- (u)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0402/2018/GW
Date : 3-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chan Teck Meng
Address : 132 Lorong L Telok Kurau
#01-09
Singapore 425569
Telephone : (HP) 96670108
Type of Claim : Third Party Claims
Policy No. : 2100503822-00000
Vehicle No : **SLD 6744 J**
Model Code : Audi Q7 2.0 TFSI Qu
Model / Year : Jun-16
Engine No : CYR 008376
Chassis No : WAUZZZ4M3GD046808
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Apr-18
Place of Accident : Lorong L Telok Kurau

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLD 6744 J.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper assy. re-organise front crash management components. Reinstall all parts removed.	\$ 1,200.00 600	
3	To respray front bumper, lower spoiler and wheel arch trims.	\$ 2,100.00 1200	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>3,972.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 6744 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>deformed</i>	\$	2,132.00 ✓
2	FRONT BUMPER SPOILER <i>Not m</i>	\$	183.00 X
3	UNDERRUN BAR <i>lt</i>	\$	700.00 ✓
4	FRONT BUMPER GRILLE <i>Not New</i>	\$	180.00 X
5	RADIATOR GRILLE <i>lt</i>	\$	2,027.00 ✓
6	RADIATOR GRILLE COVER <i>3 New</i>	\$	60.00 X
7	FRONT BUMPER INNER COVER <i>3 New</i>	\$	54.00 X
8	FRONT BUMPER AIR GUIDE GRILLE-RH <i>lt</i>	\$	260.00 ✓
9	FRONT BUMPER END CAP-RH <i>3 New</i>	\$	29.00 X
10	FRONT BUMPER COVER CAP-RH <i>3 New</i>	\$	30.00 X
11	FRONT WHEEL COVER-LH/RH <i>New</i>	2 \$	1,004.00 ✓
12	FRONT NO. PLATE <i>New</i>	S/N \$	25.00 ✓
13	SUNDRIES <i>?</i>	\$	300.00 ?
TOTAL SPARE PARTS		:	\$ 6,984.00
TOTAL LABOUR CHARGES		:	\$ 3,972.00
GRANDTOTAL		:	\$ 10,956.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 02/04/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 04 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant