FIRST AUTOWORKS

MUDDAU

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

11.30

Repair Estimate

MANCLES

Date: 28/3/2018

Reference:

Make:

OPEL

Mokka

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SLQ 4997R

CHASSIS NO.: W0LJD7EC2HB181508 ENGINE NO.: A2170185GU7X0563

Name of insured .: Edwin Yeo Date of accident.: 18/03/2018

Not Anthomas Hale Tulne photo After regain HY/18

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Front bumper, fascia upper	2 1,450.00
2	1	Front bumper, fascia lower	600.00

Parts Total:

2050.00

Less 10%:

205.00

Total:

1845.00

Price (SGD)

Labour

No.

Labour Description

Front portion			
1	To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts.	1500.00	250
2	Carry out spray painting on accident affected area	1300.00	550
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair		50

Labour Total:

2920.00

Other Description

No. Qty

Price (SGD)

Cre Frt Bumper Clip Sot I cence Note who law 1 1 50.00

Other Total:

50.00

4,815.00 Total: \$ 7% GST: \$ 337.05

Grand Total: \$

5,152.05

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor Ronnie Tan

HP: 8298 8933 Fax:6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after soray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: