

INSURANCE CASE OWNER:

CC 6/021 1800 5945, Kuala Lumpur

LKK:
IDAC:

INSURANCE:

Kenneth

DOI:

ASSIGNMENT

28/03/18

Date / Time:

28/03/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SJY 1586C

Claim No. :

DM1871000772-JG

Name of Insured :

LUXS LEASING & MANAGEMENT SERVICES P/L

Policy No. :

DM18710-0006 CX

Insured Tel No. :

HP:

Make / Model :

Mit Lancer

Excess Sec II :SS

D.O.A. :

Place of Accident :

PIE

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

ASBOLLATA BIN HAMAW

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

90503458 (V/L: YES / NO)

Insured Liability: % Final ? Yes / No

SHP 533C

SJY 1586C

SLP 2685 A



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability: m
RMKS:



INSRS:
WSP: m
Tel:
Liability: TP
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

28/03/18

SHP 533C - X ; SJY 1586C - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

> THIN 12/4

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

3 vehicles chain collision, OI 2nd vehicle. Send letter to OI

RECEIVED 30 AUG 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:		Confirm by:
Repair Cost:	S\$	(days)	Reduction:	%	Email	Call
FINAL SETTLEMENT		Date/Time: 30/8/18	Confirm with: Sharon	Email	Call	
Final Liability:	%	100 (Agreed/ Assessed)	BOLA S/N No. :	28	If NO or B 28, Ass. Lia: 0%	
Repair Cost:	S\$	2585.06				
Loss of Rental (LOR):	S\$	(days)				
Loss of Use (LOU):	S\$	640.00 (\$80 x 8 days)				
Loss of Income (LOI):	S\$	(\$ x days)				
LOR only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>	LOR + LOU	<input type="checkbox"/>	LOR + LOI
[Tick only one]						
GIA/LTA Search	S\$	2.00				
Medical:	S\$					
Disbursement:	S\$		(e.g. Tow/ Independent)			
Legal Cost	S\$					
Total:	S\$	3227.06	Global Sum S\$:	3100.00		
FINAL PAYMENT		Date/Time:	Confirm with:	Email	Call	
Payee 1:	S\$	3100.00	Name 1:	OPTIMA WERKZ PTE LTD		
Payee 2 (Strike if N.A.)	S\$		Name 2:			
Payee 3 (Strike if N.A.)	S\$		Name 3:			

COPIES SENT 30/8/18 arc 6/9/18

ASS. REC. BY:

REF: EQ /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Copina

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B, 1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLP 2845A Yr Regn: 05, 17

Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Ty A900 c.c. 1496

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 62137 T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: NHPIC 659315

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: MI / S/Rim / STD A/Rim or

Tyre Size: F: Kepler 175/65R15

R: B.S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 23/3/18

Survey held at _____

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 28/3/18

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
29/3 File pass to Catherine

\$ 2415.94 (Red: \$ 1350.70 / 36%)

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____
S - RS, St

Photos

Others

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ118005945/Kua3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Date : 02-04-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 1566C	Veh. Inspected	SLP 2645A
Policy No.	DMCFHQ17-000160	Coverage (\$)	0.00
Claim No.	DM18HO00772-JG	Excess (\$)	0.00
Assign From		Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/03/2018	Inspection Date	28/03/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Your ref: DM18HO00772-JG
Our ref: CC6/EQI18005945/Kua3

Date: 04.04.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SLP 2645A


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28.03.2018 at the premises of M/s Optima Werkz Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	<u>3,766.64</u>
Revised Estimate Amount	: S\$	<u>1,327.96</u>
"Check" Items Amount	: S\$	<u>224.76</u>
Total (Including Check Items)	: S\$	<u>1,552.72</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the Rear O/S portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Ku

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 27 March 2018

Third Party Insurer: EQ

Vehicle No: SLP2645A

Third Party Veh No: SJY1566C

Model: TOYOTA AQUA HYBRID 1.55

Date of Accident: 23/03/2018

Chassis: NHP106593159

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE		By \$820.00
1	REAR TAILGATE WINDSCREEN MOULDING		Me \$35.00
1	REAR TAILGATE LOGO EMBLEM		Me \$45.90
1	REAR TAILGATE AQUA EMBLEM		Me \$48.60
1	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM		Me \$35.00
1	REAR TAILGATE MECHANISM LOCK		PC \$452.71
1	REAR TAILGATE WEATHERSTRIP		Pure \$291.80
1	REAR BUMPER		Phr \$408.31
10	REAR BUMPER CLIP	\$5.78	Me \$57.80
1	REAR BUMPER LOWER UNDER COVER		Sm \$139.10
2	REAR BUMPER REINFORCEMENT BRACKET LH + RH	droi \$115.70	Phr \$231.40
2	REAR BUMPER SIDE RETAINER LH + RH	cls ? Me \$68.28	Phr LH \$136.56
SUB TOTAL			\$2,702.18
Less 25%			\$675.55
PARTS TOTAL			\$2,026.64

✓
—
—
—
—
X
M X
—
—
X
7 ✓ \$115.70
* ✓ \$68.28
1972.39
451.60
1444.79

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		Me \$100.00
1	REAR BUMPER REVERSE SENSOR		Phr \$280.00
S/N TOTAL			\$380.00

405m
2005m
240

Not Authorized
IB1
Pulvey Bhopain
4 days

8 2415.94

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	27 March 2018	Third Party Insurer:	EQ
Vehicle No:	SLP2645A	Third Party Veh No:	SJY1566C
Model:	TOYOTA AQUA HYBRID 1.5S	Date of Accident:	23/03/2018
Chassis:	NHP106593159		

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	REAR END PANEL (REPAIR)	\$600.00	400 (600)
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION		\$700.00	500 (500)
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR		\$60.00	50
	LABOUR TOTAL	\$1,360.00	1100
WINSON	TOTAL	\$3,766.64	

P - 1444.79
 SN - 242.00
 L - 1150.00
 P/P - \$ ~~2834.79~~

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112
 Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011
 Co. Reg. No. 201212455W

Date: 27 March 2018 Third Party Insurer: EQ
 Vehicle No: SLP2645A Third Party Veh No: SJY1566C
 Model: TOYOTA AQUA HYBRID 1.5S Date of Accident: 23/03/2018
 Chassis: NHP106593159

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE		<i>Bj</i> \$820.00 ✓
1	REAR TAILGATE WINDSCREEN MOULDING		<i>Mc</i> \$35.00 ✓
1	REAR TAILGATE LOGO EMBLEM		<i>Mc</i> \$45.90 ✓
1	REAR TAILGATE AQUA EMBLEM		<i>Mc</i> \$48.60 ✓
1	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM		<i>Mc</i> \$35.00 ✓
1	REAR TAILGATE MECHANISM LOCK		<i>R</i> \$452.71 X
1	REAR TAILGATE WEATHERSTRIP		<i>Puc</i> \$291.80 X
1	REAR BUMPER		<i>Ber</i> \$408.31 ✓
10	REAR BUMPER CLIP	\$5.78	<i>Mc</i> \$57.80 ✓
1	REAR BUMPER LOWER UNDER COVER		<i>Sm</i> \$139.10 X
2	REAR BUMPER REINFORCEMENT BRACKET LH + RH	\$115.70	\$231.40 ?
2	REAR BUMPER SIDE RETAINER LH + RH	<i>cls ?</i> \$68.28	<i>MS Sm</i> \$136.56 #
SUB TOTAL			\$2,702.18
Less 25%			-\$675.55
PARTS TOTAL			\$2,026.64

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		<i>Mc</i> \$100.00 <i>405n</i>
1	REAR BUMPER REVERSE SENSOR		<i>Rd</i> \$280.00 <i>2005n</i>
S/N TOTAL			\$380.00

Not authorized
1 B1
McKroy B & Pain
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	27 March 2018	Third Party Insurer:	EQ
Vehicle No:	SLP2645A	Third Party Veh No:	SJY1566C
Model:	TOYOTA AQUA HYBRID 1.5S	Date of Accident:	23/03/2018
Chassis:	NHP106593159		

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$600.00	<i>400</i>
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$700.00	<i>400</i>
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	<i>50</i>
	<u>LABOUR TOTAL</u>	<u>\$1,360.00</u>
<u>WINSON</u>	<u>TOTAL</u>	<u>\$3,766.64</u>

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLP2645A		
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	AQUA HYBRID 1.5S AT ABS D/AIRBAG 2WD		
Chassis No. :	NHP106593159		
Propellant :	Petrol-Electric		
Engine No. :	1NZR508806		
Motor No. :	H17209676		
Engine Capacity :	1496 cc		
Power Rating :	45.0 kW		
Maximum Power Output :	73.0 kW (97 bhp)		
Maximum Laden Weight :	1365 kg		
Unladen Weight :	1090 kg		
Year Of Manufacture :	2017		
Original Registration Date :	30 May 2017		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$46,489.00		
COE Expiry Date :	29 May 2027		
Road Tax Expiry Date :	29 Nov 2018		
PARF Eligibility Expiry Date :	29 May 2027		
Inspection Due Date :	29 May 2020		
Intended Transfer Date :	13 Aug 2018		
CO2 Emission :	92.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$16,840.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

Our Ref : SLP2645A / TP#636
Your Ref : SJY1566C

WITHOUT PREJUDICE

Date : 13 August 2018

EQ Insurance Company Limited

5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

Attention: Motor Claims Department

**ACCIDENT INVOLVING SLP2645A & SJY1566C ON 23/03/2018
ALONG PIE TOWARDS TUAS**

We refer to the above captioned.

We are claiming the below followings:

- Cost of Repair (incl.of GST)	SS2,585.06
- Loss of Use/Rental	SS800.00 (\$100 x 08 days)
- GIA/LTA Search Fees	SS2.00

Grant Total SS3,387.06

If you have any enquiries, please contact our representative, Ms. Sharon Ten at 64849919 or email sharon@ow.sg / lily.loi@ow.sg

All payment is to be issued direct to **Optima Werkz Pte Ltd.**

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD

Encl.

This is a computer generated printout and no signature is required.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/EQ118005945/Kua3

12 APRIL 2018

LUXS LEASING & LIMOUSINES SERVICES PTE LTD
1 KAKI BUKIT AVE 6
SINGAPORE 417833

Dear Sir/Madam,

ACCIDENT INVOLVING SJY 1566C / SLP 2645A & OTHERS ON 23/03/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500

Tel (+65) 6484 9919 Fax: (+65) 6481 1101

Co Reg & GST No: 201212455W

TAX INVOICE

To: EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

Tel 62239433
Fax: 62234190

INV NO. : 121805169
INVOICE DATE : 10/08/2018
REF : TP#636
VEH NO. : SLP2645A
CAR MODEL : AQUA HYBRID 1.5S
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
REAR TAILGATE	1	PC	615.00	615.00
REAR TAILGATE WINDSCREEN MOULDING	1	PC	26.25	26.25
REAR TAILGATE LOGO EMBLEM	1	PC	34.43	34.43
REAR TAILGATE AQUA EMBLEM	1	PC	36.45	36.45
REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	1	PC	26.25	26.25
REAR BUMPER	1	PC	306.23	306.23
REAR BUMPER CLIP	10	PCS	4.34	43.35
REAR BUMPER REINFORCEMENT BRACKET LH + RH	1	PC	86.78	86.78
REAR BUMPER SIDE RETAINER LH + RH	1	PC	51.20	51.20
REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	1	PC	40.00	40.00
REAR BUMPER REVERSE SENSOR	1	PC	200.00	200.00
TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	1	JOB	400.00	400.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	1	JOB	500.00	500.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	1	JOB	50.00	50.00

Remarks: DOA: 23/03/18 @ 1640HRS
CLAIMANT: OPTIMA WERKZ P/L
REG NO: 201212455W
TP VEHICLE: SJY1566C

Singapore Dollars: Two Thousand Five Hundred Eighty-Five And Cent Six Only

Name: _____

NRIC No.: _____

Signature: _____

SUB TOTAL	SGD	2,415.94
GST 7.00%	SGD	169.12
GRAND TOTAL	SGD	2,585.06

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs.

I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

3) Goods sold are not refundable/returnable.

for Optima Werkz Pte Ltd

AUTHORISED SIGNATURE(S)

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-16-044810
Date of Request: 24/03/2018

Your Ref No: Online Purchase

Optima Werkz Pte Ltd
6 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Enquiry Date: 24/03/2018
Enquiry By: Casi Riza Pocallan
TP Vehicle No: SJY1566C
Accident Date: 23/03/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJY1566C	EQ Insurance Company Ltd	28/09/2017-27/09/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



To : M/s EQ INSURANCE COMPANY LTD

Date: 07/09/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SJY 1566C (Insd Veh)	Your Ref. No. : DM18HO00772-JG
	SLP 2645A (TP Veh)	Our Ref. No. : CC6/EQI18005945/Kua3q2
Date of Accident	23/3/2018	

Liability	100%	
Final Repair Cost	: \$ 2,585.06	
Loss of Use	: \$ 640.00	8 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	3,227.06	
Final Settlement Sum	: \$ 3,100.00	GLOBAL SUM
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	OPTIMA WERKZ PTE LTD	: \$ 3,100.00
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI18005945/Kua3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 07-09-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJY 1566C	Veh. Inspected	SLP 2645A
Policy No.	DMCFHQ17-000160	Coverage (\$)	0.00
Claim No.	DM18HO00772-JG	Excess (\$)	0.00
Assign From		Assign Date	28/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA AQUA (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NHP106593159	Colour	WHITE
Odometer	62137	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/65 R15	KAPSEN	9 mm
L/H Front Tyre	175/65 R15	KAPSEN	9 mm
R/H Rear Tyre	175/65 R15	BRIDGESTONE	3 mm
L/H Rear Tyre	175/65 R15	BRIDGESTONE	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/03/2018	Inspection Date	28/03/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2645A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	820.00	820.00
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	35.00	35.00
1	REAR TAILGATE LOGO EMBLEM	NECESSARY	45.90	45.90
1	REAR TAILGATE AQUA EMBLEM	NECESSARY	48.60	48.60
1	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	NECESSARY	35.00	35.00
1	REAR TAILGATE MECHANISM LOCK	TO REPAIR SEE LABOUR	452.71	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	291.80	-
1	REAR BUMPER	BUCKLED	408.31	408.31
1	REAR BUMPER CLIP @\$5.78	NECESSARY	57.80	57.80
1	REAR BUMPER LOWER UNDER COVER	SERVICEABLE	139.10	-
2	REAR BUMPER REINFORCEMENT BRACKET LH +RH @\$115.70	O/S DISTORTED	231.40	115.70
2	REAR BUMPER SIDE RETAINER LH+RH @\$68.28	O/S NECESSARY / N/S SERVICEABLE	136.56	68.28
	LESS 25% DISCOUNT		-675.55	-408.65
			2,026.63	1,225.94
<u>SPECIAL NETT ITEMS</u>				
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER (SN)	NECESSARY	100.00	40.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			380.00	240.00
<u>LABOUR</u>				
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION INCLUSIVE OF THE REPAIR OF REAR TAILGATE MECHANISM LOCK.		600.00	400.00
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION.		700.00	500.00
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR .		60.00	50.00
			1,360.00	950.00
GRAND TOTAL			3,766.63	2,415.94