

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 27 March 2018 Third Party Insurer: EQ
 Vehicle No: SLP2645A Third Party Veh No: SJY1566C
 Model: TOYOTA AQUA HYBRID 1.5S Date of Accident: 23/03/2018
 Chassis: NHP106593159

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE		<i>B1</i> \$820.00
1	REAR TAILGATE WINDSCREEN MOULDING		<i>Mc</i> \$35.00
1	REAR TAILGATE LOGO EMBLEM		<i>Mc</i> \$45.90
1	REAR TAILGATE AQUA EMBLEM		<i>Mc</i> \$48.60
1	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM		<i>Mc</i> \$35.00
1	REAR TAILGATE MECHANISM LOCK		<i>R</i> \$452.71
1	REAR TAILGATE WEATHERSTRIP		<i>Puc</i> \$291.80
1	REAR BUMPER		<i>Bur</i> \$408.31
10	REAR BUMPER CLIP	\$5.78	<i>Mc</i> \$57.80
1	REAR BUMPER LOWER UNDER COVER		<i>Sm</i> \$139.10
2	REAR BUMPER REINFORCEMENT BRACKET LH + RH	\$115.70	\$231.40
2	REAR BUMPER SIDE RETAINER LH + RH	<i>cls ?</i> \$68.28	<i>MS Sm</i> \$136.56
SUB TOTAL			\$2,702.18
Less 25%			-\$675.55
PARTS TOTAL			\$2,026.64

✓
✓
✓
✓
✓
X
X
✓
X
?

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		<i>Mc</i> \$100.00
1	REAR BUMPER REVERSE SENSOR		<i>Mc</i> \$280.00
S/N TOTAL			\$380.00

4052
20052

Not Attached
1 B1
Revised B & paint
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	27 March 2018	Third Party Insurer:	EQ
Vehicle No:	SLP2645A	Third Party Veh No:	SJY1566C
Model:	TOYOTA AQUA HYBRID 1.5S	Date of Accident:	23/03/2018
Chassis:	NHP106593159		

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$600.00	<i>400</i>
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$700.00	<i>400</i>
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	<i>50</i>
	<u>LABOUR TOTAL</u>	<u>\$1,360.00</u>
<u>WINSON</u>	<u>TOTAL</u>	<u>\$3,766.64</u>