

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0383/2018/GW
Date : 29-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : Mr. Lie Khin Sin
Address : 16 Vanda Drive
Singapore 287854

Telephone : HP 97893436
Type of Claim : Own Damage Claims
Policy No. : A 28820191 QMY
Vehicle No : **SFR 578 J**
Model Code : Audi A6 C7 2.0 TFSI Mu 4G
Model / Year : Sep-14
Engine No : CDN 385691
Chassis No : WAUZZZ4GXEN074591
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Mar-18
Place of Accident : Clementi Rd BEF AYE Turning Off

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFR 578 J.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$ 1,200.00	?
1 3	<i>one lock repair</i> To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$ 6,300.00	2100 (Not including lock carrier)
4	To respray front bumper, both front fenders, bonnet and hinges.	\$ 3,600.00	2800
5	To renew front windscreen.	S/N \$ 480.00	✓
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 12,252.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 2,326.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 236.00	+
3	RADIATOR GRILLE <i>CanLd</i>	\$ 1,174.00	✓
4	RADIATOR GRILLE COVER <i>CanLd</i>	\$ 32.00	✓
5	FRONT SUPPORT PARKING AID-LH/RH ?	2 \$ 118.00	?
6	FRONT BUMPER GRILLE-LH/RH <i>RH Missing</i>	2 \$ 268.00 134.	
7	FRONT BUMPER END CAP-LH ?	\$ 34.00	✓
8	FOAM FILLER PIECE <i>DeLd</i>	\$ 85.00	✓
9	FRONT BUMPER HOLDER BRACKET-LH/RH	\$ 446.00	
10	FRONT BUMPER SUPPORT- LH/RH	2 \$ 21.00	
11	FRONT BUMPER GUIDE PIECE-LH/RH <i>new</i>	2 \$ 64.00	+
12	FRONT BUMPER COVER <i>DeLd</i>	\$ 105.00	✓
13	SIGN "CUATION" <i>new</i>	\$ 12.00	✓
14	FRONT FENDER-LH/RH <i>Repair</i>	2 \$ 2,440.00	+
15	FENDER ATTACHMENT PARTS	\$ 36.00	
16	FRONT STONE GUARD CHIP-LH <i>new</i>	\$ 105.00	✓
17	FRONT FENDER BRACE-LH/RH <i>new</i>	2 \$ 144.00	+
18	FRONT WHEEL SPOILER-LH/RH <i>new</i>	2 \$ 404.00	+
19	HEADLIGHT GAS DISCHARGE-LH/RH <i>new RH CanLd</i>	\$ 5,806.00 2903.	
20	GAS DISCHARGE LAMP <i>new ?</i>	\$ 394.00	+
SUB - TOTAL SPARE PARTS		\$ 14,250.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	GAS DISCHARGE BULB RETAINING RING ?	\$ 75.00	?
22	GAS DISCHARGE CONTROL UNIT ?	\$ 1,018.00	?
23	HEADLIGHT POWER MODULE ?	\$ 501.00	?
24	HOSE ?	\$ 14.00	?
25	HEADLIGHT MOUNTING-LH/RH RH ?	2 \$ 206.00	?
26	HEADLIGHT COVER CAP-LH/RH RH ?	2 \$ 98.00	?
27	HEADLIGHT LIFT CYLINDER ?	\$ 208.00	?
28	ELBOW FITTING new	2 \$ 45.00	?
29	HEADLIGHT WASHER HOSE new	5 \$ 172.00	?
30	BONNET Distorted	\$ 4,771.00	✓
31	BONNET ONE ATTACHMENT PARTS ?	\$ 123.00	?
32	BONNET LID HINGE-LH/RH new	2 \$ 282.00	?
33	BONNET CATCH HOOK ?	\$ 122.00	?
34	BONNET LOCK BAR ?	2 \$ 87.00	?
35	BONNET HOOD LATCH ?	\$ 15.00	?
36	BONNET LID LOCK WITH MICRO ?	2 \$ 376.00	?
37	BOWDEN CABLE new	\$ 50.00	?
38	BONNET LID LOCK CABLE new	\$ 64.00	?
39	BONNET LOCK CARRIER WITH MOUNTING ?	\$ 1,024.00	?
40	AIR GUIDE-LH/RH ?	2 \$ 54.00	?
SUB - TOTAL SPARE PARTS		\$ 9,305.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SFR 578 J.

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/NETT	REMARKS
41	CHARGE AIR COOLER <i>Not New</i>	\$ 492.00	X
42	A/C CONDENSOR ?	\$ 683.00	?
43	RADIATOR ?	\$ 674.00	?
44	RUBBER BUSH ?	6 \$ 52.00	?
45	COOLANT CONCENTRATE ?	4 \$ 133.00	?
46	FRONT NO. PLATE <i>du</i>	S/N \$ 25.00	✓
47	TWIN FAN RING ?	\$ 226.00	?
48	RADIATOR FAN ?	2 \$ 1,439.00	?
49	RADIATOR CONTROL UNIT ?	\$ 740.00	?
50	AIR DUCT ?	\$ 22.00	?
51	INTAKE AIR DUCT ?	\$ 65.00	?
52	AIR FILTER ?	\$ 256.00	?
53	EXTERNAL TEMPERATURE SENSOR ?	\$ 54.00	?
54	AIR TEMPERATURE SENSOR BRACKET ?	\$ 20.00	?
55	WINDSHIELD WIPER COVER <i>Not New</i>	\$ 174.00	+
56	WATER DEFLECTOR <i>new</i>	\$ 66.00	X
57	GEL FOIL FOR RAIN SENSOR <i>m</i>	\$ 127.00	✓
58	PRIMER <i>m</i>	\$ 19.00	✓
59	WATER DEFLECTOR STRIP ?	\$ 58.00	?
60	FRONT NO. PLATE <i>Repeated</i>	S/N \$ 25.00	X
SUB-TOTAL SPARE PARTS		\$ 5,350.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFR 578 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	FRONT WINDSCREEN SEALANT <i>m</i>	S/N \$ 200.00	✓
42	SUNDRIES ?	\$ 1,000.00	?
TOTAL SPARE PARTS		: \$ 30,105.00	
TOTAL LABOUR CHARGES		: \$ 12,252.00	
GRAND TOTAL		: \$ 42,357.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 02/04/18
Authorised Date :
Excess Cost : \$ 200
Liability :
Remarks : Not Authorised

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant