

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9907U**AAD1803-241***Not Authorized
21 Sep \$1900/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9907U

VF1ABL15AUC273465

RENAULT

LATITUDE

27.3.2018

TH**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bur</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Not/la</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Dis</i> 44.99	✓
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	} X
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	
13	1 TAILLAMP LH	\$	<i>Sn</i> 552.55	
14	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	
15	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	
16	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56	
17	1 EXHAUST REAR	\$	<i>R</i> 7,489.05	
18	1 EXHAUST CAP REAR	\$	<i>R</i> 230.49	

TOTAL	\$	14,804.47
10%	\$	3,586.89
	\$	11,217.57

Specical Nett

1	1SET PARKING AID	\$	<i>Sn</i> 700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>Sn</i> 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>Sn</i> 33.00	✓
4	1SET BUMEP R BRACKET SIDE CLIP RH RR	\$	<i>Sn</i> 10.00	X
5	1SET BUMEP R RETAINER RH CLIP RR	\$	<i>Sn</i> 20.00	X

Trans-cab Auto Services Pte Ltd**AAD1803-241**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9907U

6 1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7 1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10 1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
11 1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
12 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
13 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
14 1 TAILLAMP CLIP RH	\$	na	5.00	X

TOTAL \$ 1,078.00**TOTAL PARTS \$ 12,295.57****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	2,450.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	2001
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1803-241**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9907U

To supply and re-do rear luggage floor panel
insulation padding.

\$ *nn* 380.00 X

To transfer of rear fender fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 X

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X**TOTAL \$ 6,990.00****Over All Total \$ 19,285.57****(LUMP SUM)****Repair Days**~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: