

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

A19

Name : Muhamad Asyraf
Bin Mohamed Akbar

Accident Date : 22-Mar-18

Vehicle No : FB 2581 U

Vehicle Model : Yamaha RXK

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
1	Front fender	\$ 1 70.00 X
2	Fork inner tubes	\$ 11 220.00 X
1	Front brake disc	\$ 11 145.00 X
1	Front rim shaft	\$ 11 45.00 X
1	Front rim	\$ 11 160.00 X
1	Front rim spooky (1 set)	\$ 11 60.00 X
1	Headlamp	\$ 11 90.00 X
1	Front signal -R/H	\$ 11 45.00 X
1	Handle bar	\$ 34 125.00
1	Hand grip (1 set)	\$ 10.1 50.00
1	Side mirror -R/H	\$ 47 40.00
1	Brake lever	\$ 11 25.00 X
1	Front footrest	\$ 34 48.00
2	Front footrest rubbers	\$ 10.1 40.00
1	Brake pedal	\$ 47 35.00
1	Gear pedal	\$ 11 35.00 X
1	Rear footrest -R/H	\$ 11 28.00 X
1	Exhaust pipe	\$ 11 450.00
2	Rear signals	\$ 0/5/11 90.00 120
1	Rear taillamp	\$ 510 90.00
1	Rear fender	\$ 11 70.00 X
1	Rear handle	\$ 47 40.00
1	Rear rim	\$ 34 160.00
1	Rim spooky (1 set)	\$ 11 60.00
1	Horn	\$ 11 42.00 X
		\$ 2,263.00
Less 10%		\$ 226.30
		\$ 2,036.70

Not Authorized
LKR

2/5/18
Hdy.

7.1m photo After repair
2/4/18

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Muhamad Asyraf
Bin Mohamed Akbar

Accident Date : 22-Mar-18

Vehicle No : FB 2581 U

Vehicle Model : Yamaha RXK

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$	34	28.00	10
2	Fork oils	\$	ru	30.00	=
2	Fork oil seals	\$	ru	56.00	=
1	Steering cone (1 set)	\$	11	85.00	g
1	Front tyre	\$	17	120.00	x
		\$		319.00	

S/No.

Labour

1	To provide towing service.	\$		50.00	✓
2	To check wiring and reset headlamp focusing.	\$	17	80.00	x
3	To provide labour.	\$		380.00	250
		\$		510.00	

Grand Total

\$ 2,865.70

Dollars: Two Thousand Eight Hundred Sixty-Five And Seventy Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Business Reg No : 53240921c
H/P No : 9222 8511

Received From : Erofica.

Vehicle No : FB 2581

From : Woodlands - IDAC - workshop.

Handphone No : 96710452.

Amount : \$60-

OFFICIAL RECEIPT

No : 1133

Date : 24/3/18

A handwritten signature in black ink, appearing to be "S. E.", written over a horizontal line.

Issued By

NOTE : Vehicle is transported at owner's risk. The company accepts no responsibility for damages or other misdemeanor to your vehicle whilst being transported.