

SMRT Accident Vehicle Repair Estimates

AIG CIL

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6279H
 Ref. No : TAX/03/18/2128
 Reg. Date : 28/06/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : VICTOR LIM TAU CHIAK
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 26/03/2018 03:28:00 PM
 Accident Reported Date / Time : 26/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095235
 Special Instruction to ARC, if any :
 GBG9818M
 Prepared Date : 26/03/2018 05:03:54 PM



Sebastian
 28/3/18
 - Part by part repair.
 - Question Mark Item Photo
 - Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Assis No : JTDKN36U705768289

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,494.00	0.00
Total Material Charges	: 3,360.18	4,030.98
Other Charges	: 580.00	0.00
TOTAL	: 6,279.18	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sing Off Date	: 26/03/2018 06:44:07 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/03/2018 06:42:48 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 3/26/2018 6:43:12 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	845.00	0.00 2400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 50
TO RESPRAY FRONT DOOR LH	378.00	0.00 X
TO RESPRAY VIEW MIRROR	180.00	0.00 50
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	580.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
2119-7930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>R</i>	No
2116-7040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>✓</i>	No
3802-7050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>R</i>	No
5374-7051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>✓ NEC</i>	No
3876-7030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>✓ TW</i>	No
7002-7070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Repair	Replace <i>X</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>X</i>	No
7940-7310		6505599	MIRROR ASSY, LH	1	1,224.90	25.00	918.67	Replace	Replace <i>R</i>	No ?
1740-2040		6505465	MIRROR LAMP LH	1	65.30	10.00	58.77	Replace	Replace <i>✓ SCR</i>	No
7945-4010		6505597	COVER, OUTER MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace <i>R</i>	No
2611-7140 Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>R</i>	No
TOTAL MATERIALS								3,360.20	4,030.98	
TOTAL MATERIALS(Discounted)							3,360.18	4,030.98		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									