

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J**AAD1803-238***Not Notified
Reserve B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 18J

VF1ABL15AUC282698

RENAULT

LATITUDE

26.3.2018

*Ah***PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Div</i> 181.75 ✓
3	1	BUMPER ABSORBER FRT	\$	394.68 ?
4	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 151.41 X
5	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Div</i> 150.77 ✓
7	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>CM</i> 266.80 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	914.08 ?
13	1	TOW COVER FRT	\$	<i>Sn</i> 28.61 X
14	1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Re</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>Sn</i> 314.17 X
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43 X
23	1	HEADLAMP RH	\$	<i>mg CM</i> 1,184.43 ✓
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
26	1	BONNET	\$	<i>R</i> 1,941.63 ✓
27	1	BONNET INSULATOR	\$	<i>Sn</i> 405.73 X
28	1	BONNET STRUT LH	\$	<i>Sn</i> 88.61 X
29	1	BONNET STRUT RH	\$	<i>Sn</i> 88.61 X
30	1	BONNET HINGE LH	\$	<i>R</i> 348.31 X

Trans-cab Auto Services Pte Ltd**AAD1803-238**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J

31	1	BONNET HINGE RH	\$	348.31	X
32	1	BONNET LOCK	\$	305.48	X
33	1	BONNET CABLE	\$	119.19	X
34	1	BONNET CABLE COVER	\$	161.03	X
35	1	BONNET SEAL OUTER	\$	92.36	X
36	1	BONNET SEAL INNER	\$	157.28	✓
37	1	FENDER PANEL FRT LH	\$	783.83	X
38	1	FENDER PANEL FRT RH	\$	783.83	✓
39	1	WHEELARCH FRT LH	\$	278.84	X
40	1	WHEELARCH FRT RH	\$	278.84	X
41	1	FENDER BRACKET LOWER LH	\$	15.79	X
42	1	FENDER BRACKET LOWER RH	\$	15.79	X
43	1	FENDER INSULATOR LH	\$	130.84	} X
44	1	FENDER INSULATOR RH	\$	130.84	
45	1	WIPER RESERVOIR	\$	348.25	
46	1	WIPER RESERVOIR NECK	\$	136.11	
47	1	WIPER RESERVOIR MOTOR	\$	270.06	
48	1	AIR CLEANER LOWER	\$	271.26	
49	1	AIR CLEANER HOSE	\$	76.14	
55	1	ENGINE TOP COVER 2.0	\$	555.12	
56	1	ENGINE OIL SUMP	\$	484.67	
58	1	BASE BATTERY TRAY	\$	363.40	
59	1	AIR CLEANER BOX	\$	464.20	
60	1	TURBO DUCT	\$	1,027.80	
61	1	A/C HEATER VALVE	\$	484.50	
63	1	SUBFRAME OUTER FRT	\$	2,652.45	
64	1	SUBFRAME BRACKET OUTER LH	\$	92.36	
65	1	SUBFRAME BRACKET OUTER RH	\$	92.36	
66	1	ENGINE UNDERTRAY	\$	564.98	
67	1	A/C CONDENSER	\$	2,020.37	
68	1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	
69	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	
70	1	A/C CONDENSER GARNISH LH	\$	58.81	
71	1	A/C CONDENSER GARNISH RH	\$	59.60	
72	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39	
73	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72	
74	1	A/C PIPE COMPRESSOR	\$	334.29	
75	1	A/C PIPE	\$	658.72	
76	1	A/C COMRPRESSOR	\$	2,684.61	

Trans-cab Auto Services Pte Ltd**AAD1803-238**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J

77	1	AIR COOLER	\$	Sin	792.60	}	X
78	1	AIR INTERCOOLER HOSE (LONG)	\$	Sin	1,014.13		
79	1	AIR INTERCOOLER HOSE (Short)	\$	Sin	375.14		
80	1	TRANSMISSION COOLER	\$	Sin	1,219.30		
81	1	TRANSMISSION COOLER PAD	\$	Sin	17.96		
82	1	RADIATOR	\$	Sin	1,202.20		
83	2	RADIATOR STUD UPPER	\$	Sin	14.41		
84	2	RADIATOR BUSH UPPER	\$	Sin	50.12		
85	2	RADIATOR MTG LOWER	\$	Sin	55.85		
86	1	RADAITOR FAN COWLING	\$	Sin	820.54		
87	1	RADIATOR FAN MOTOR LH	\$	Sin	967.36		
88	1	RADIATOR FAN MOTOR RH	\$	Sin	1,479.46		
89	1	RADIATOR TANK	\$	Sin	324.62		
90	1	RADIATOR HOSE UPPER	\$	Sin	240.56		
91	1	RADIATOR HOSE LOWER	\$	Sin	491.18		
92	1	RADIATOR TANK HOSE	\$	Sin	61.18		
93	1	WINDSCREEN FRT	\$	Sin	1,364.06		

TOTAL	\$	43,292.41
10%	\$	4,329.24
	\$	38,963.17

Specical Nett

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	na	52.00	}	X
2	1SET	BUMPER CLIP FRT	\$	na	66.00		
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00		
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50		
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00		
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50		
7	1	TOW COVER FRT	\$	Sin	14.50		
8	1SET	RADAITOR GRILLE SCREW	\$	na	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00		
21	1	Windscreen moulding	\$	na	100.00	}	455na
22	1SET	Front licence plate with holder	\$	na	80.00		

Trans-cab Auto Services Pte Ltd

AAD1803-238

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J

TOTAL	\$	562.50
TOTAL PARTS	\$	39,525.67

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,400.00 <i>6001</i>
Towing Fees.	\$	120.00 <i>501</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	6,000.00 <i>6601</i>
To rust-proofing of the affected areas.	\$	170.00 <i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To lift-up engine with gear box and refit.	\$	<i>nn</i> 440.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1803-238**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	X
To remove and refit air bag system and reset.	\$	480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	100%
To replace, refix and top up coolant for radiator	\$	170.00	50%
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	50%
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X

TOTAL	\$	16,400.00
--------------	-----------	------------------

Over All Total	\$	55,925.67
-----------------------	-----------	------------------

< parts by parts > Repair Days

~~20 DAYS~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: