

ASS. REC. BY:

REF: C9/CTU8005959/Kvb32

Special Instruction:

SURVIVAL

Kenneth

ASSIGNMENT (Office)

merimen

From (Person):

Chong Boon Sen

of

CTI

Date/Time: 29032018 3.12pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SEN 99193

Insured:

at Workshop m/s

Lai Huet (Meng Kee)

Tel:

6453 8110

of

160 Sin ming Drive #04-01

Policy No:

DMPG4 3099 651701

Claim No:

SNM18D01599C01

Sum Insured:

Excess:

\$ 1500.00

Make of Veh:

D.O.A.

22032018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

02042018 9.11am

Person Contacted:

Jenny

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SEN 99193 - X
3/4/18	@ 404pm Jenny request for LS \$16K
3/4/18	Revert by merimen
4/4/18	@ 1125am Boon Sen want us to double check on the mv
5/4/18	@ 914am Kenneth explaint to Eddie on the mv

REF: C721

AS: C B

Kenneth

From: _____ Date: _____

Estimated Cost:

C

T/E/V/INV/MV

To: _____

at _____

C1 truck

of _____

Insured:

Policy:

Class:

Sum:

Excess:

1500

(If not stated)

Make:

(If not stated)

Remarks: VEH: _____

Location: _____

Bal: _____

\$68k

IDAC: _____

Insured: Yes or No

GIA: _____

Insured: Yes or No

Est. No:

21 days 30/8/18 Kenneth

Lump:

Insured: Yes or No

CA: _____

10/26

D: _____

3/4 File pass to Catherine

5/4/18 Rece approved \$18100 from Alfred by merimen

5/4/18 Informed Jenny CIA on LS \$16k ex \$1500 by email

10/8/18 @ 4:30pm Jenny will email us finalised

30/8/18 LS \$16000 confirmed by email (Recd 7028.04, 31/9)

RECEIVED 30 AUG 2018

Date/Time:

1)

Date/Time:

2) 30/8 - typist

Report:

merimen

Lump:

LS \$16,000/2

SGN 9918 Yr Regn: 10, 06

Vehicle / Bus / Van / Lorry / Taxi / Prime Mover /

Driver or

Mr B200

C.C.

2035

Mr. Gray

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

WDD 2452342 J144783

C Fair / Poor / Burnt

Damaged / Leaked / Burnt or

Damaged / Leaked / Burnt or

STD A/Rim or

215/45R17

GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

B.S

Rear

Z mm

R/Bal.

J mm

F mm

L/Bal.

P mm

22/3/18

D.O.I.

2/4/18

Rear / O/S / N/S / UIC / Rooftop or

Rear & O/S Rec

Body Structure affected due to collision.

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

227



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI18005959/Kvb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date : 02-04-2018	
			Code : CTI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SGN 9919J
Policy No.	DMPCSN3099651701	Coverage (\$)	0.00	
Claim No.	SNM18D01599C01	Excess (\$)	1,500.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	29/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/03/2018	Inspection Date	02/04/2018	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2018 Sendback Est	29 Mar 2018 10:54 S\$23,028.04	29 Mar 2018 15:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: YONG MEI YOKE VIOLA, ID: S1363856Z									
Vehicle Reg. No.: SGN9919J		Date of Loss: 22/03/2018 15:00 - :59							
Claim Type: OD / SNM18D01599C01		Policy/Cover Note No.: DMPCSN3099651701 (Comprehensive)							
		Excess: S\$1,500.00							
Repairer: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/04/2018]									
Driver/Custodian: YONG KIM YOONG RAYMOND (66 / Male), NRIC: S1140718H, Tel: +6596670230									
Adj Asg. Remarks: SURVEY REVERT ECONOMICAL TO REPAIR									
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

02042018 @ 9.11am
Jenny veh in

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 5 April 2018 2:22 PM
To: SUR; Jenny Lim
Subject: SGN 9919J-DOA: 22/3/2018 (CHINA TAIPING OD)
Attachments: UNDERTAKING LETTER.pdf

Dear Jenny,

As instructed by our client , please proceed to repair the insured vehicle **SGN 9919J on Lump Sum basis not exceeding \$16,000/- (Excess \$1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Attached letter of undertaking, please sign and forward back to us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SGN9919J (SNM18D01599C01)

OD

Mar 22 2018 3:00PM

[YONG MEI YOKE VIOLA]

Lai Huat (Meng Kee) Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **05/04/2018 11:40 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$18100.00) - SGN9919J - Claim Handler: Chong Boon Sen

Approved:18100.00:Please proceed to authorize repairs NO MORE THAN \$18,100.00 BEFORE Excess of \$1,500.00. RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

TO: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD CLAIM NO:

LETTER OF UNDERTAKING

FOR THE REPAIR OF VEHICLE NO. SGN 9919J

We, the undersigned, confirm that we will undertake to repair the vehicle bearing Registration No SGN 9919J to its pre-accident condition, and to the satisfaction of its owner, at a total cost not exceeding \$16,000/- (LUMP SUM) (before excess \$1500/-) subject to no breach of Terms & Condition of the POLICY, and to the legal requirement of the local Land Transport Authority (LTA).

There should be **no further supplementary** to the repair cost.

The repair job should not be exceeding _____ days to complete the entire repair.

Date

5/4/2018

Date

Workshop Stamp/ Signature

KENNETH KONG

Witness by Surveyor

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 03 Apr 2018

Preliminary Advice

Vehicle No	: SGN9919J	Accident Date	: 22/03/2018
Make	: MERCEDES-BENZ B200	Policy No.	: DMPCSN3099651701
Assignment Date	: 29/03/2018	Excess	: S\$1,500.00
Date of Inspection	: 02/04/2018	Est. Duration of Repair	: 0.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and o/s rear portion. The undercarriage and body structure affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,028.04
Revised Amount	:S\$	19,103.04
Check Items (Estimated)	:S\$	3,526.00
Total	:S\$	22,629.04

Lump Sum Repair (ESTIMATED)	:S\$	18,100.00
-----------------------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	48,437.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,563.00

Remarks

(x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/03/2018 11:19
Date Of Accident	22/03/2018 15:00
Exact Location Of Accident	ABOUT 9.3KM NORTHBOUND 2ND LINK HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN9919J
Insured/Policyholder	
Name Of Registered Owner	YONG MEI YOKE VIOLA
NRIC No	S1363856Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91019919
Alternative Phone No	OTHERS-91019919

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	B200 TURBO

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3099651701
Cover Note Number	

Driver

Name of Driver	YONG KIM YOONG RAYMOND
NRIC No	S1140718H
Date Of Birth	22/09/1951
Occupation	INDOOR
Date Of Driving Pass	26/07/1973
Driving Experience	44 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96670230
Fax Number	
Contact Number	
Email Address	RKYYONG@GMAIL.COM

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1


Name	YONG KIM YOONG RAYMOND (NRIC: S1140718H)
Approximate Age	66
Injuries Sustain	WHIPLASH
Injured person in which vehicle?	SGN9919J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	261 ARCADIA ROAD #02-03
Postcode	289853

DETAILS OF INJURED PERSON 2

Name	LEE CHUEN CHONG (NRIC: S0038394E)
Approximate Age	
Injuries Sustain	WHIPLASH
Injured person in which vehicle?	SGN9919J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	10 MERINO CRESCENT
Postcode	

Sketch Plan Pg. 2

To the best of my recollection; — 2nd Link Highway (Not drawn to scale)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attachment / police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder).
Date & Time: 26 MAR 2018

Reporting Centre Personnel's Signature
Name: Jenny Lim
NRIC/FIN No.: S6927273H

0045/00 Motor Vehicle / 004

Police Report Pg. 2

Report of Accident and Claims

Date of Accident: 22/03/2018

Time: approximately 3pm

Location: Johor Bahru, Johor Malaysia. (about 9.3km, Northbound, 2nd Link Highway. From Tanjong Kupang Toll Plaza towards Gelang Patah Interchange.)

Number of persons in car: 2 from Singapore

Driver: Yong Kim Yoong Raymond (NRIC: S1140718H) age: 66yrs

Passenger: John Lee Chuen Chong (NRIC: S0038394E)

Description of Event:

I was driving from Singapore to Johor Bahru on the 2nd Link Highway on the slow lane at the above location.

I momentarily lost control and the car banged into the lamp post, which fell down. And the car spurn around and came to a stop on hitting the retaining wall.

The 2 air bags on impact were deployed. Both the passenger and I suffered injuries.

I am attaching pictures of damaged car and lamp post for your reference. Also attached is a scan copy of the police report I made at Gelang Patah Police Station and a fine of Rm300/= was paid.

Yours,



Raymond Yong

23/03/18

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3856Z
Vehicle Details	
Vehicle No.:	SGN9919J
Vehicle to be Exported:	No
Intended De-registration Date:	29 Mar 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B200 TURBO
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	26698030265046
Chassis No.:	WDD2452342J144783
Maximum Power Output:	142.0 kW (190 bhp)
Open Market Value:	\$44,096.00
Original Registration Date:	13 Oct 2006
First Registration Date:	13 Oct 2006
Transfer Count:	2
Actual ARF Paid:	\$48,506.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Oct 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$56,751.00
COE Rebate Amount:	\$48,437.00
Total Rebate Amount:	\$48,437.00

The information contained herein is correct as at 29 Mar 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3856Z

Vehicle Details

Vehicle No.: SGN9919J
Vehicle to be Exported: Yes
Intended De-registration Date: 29 Mar 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: B200 TURBO
Primary Colour: Grey
Manufacturing Year: 2006
Engine No.: 26698030265046
Chassis No.: WDD2452342J144783
Maximum Power Output: 142.0 kW (190 bhp)
Open Market Value: \$44,096.00
Original Registration Date: 13 Oct 2006
First Registration Date: 13 Oct 2006
Transfer Count: 2
Actual ARF Paid: \$48,506.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 Oct 2026
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$56,751.00
COE Rebate Amount: \$48,437.00
Total Rebate Amount: \$48,437.00

The information contained herein is correct as at 29 Mar 2018

OK

Diagnostic Trouble Code

MERCEDES V48.81 > Automatically Search

DTC	Description	State
9103	The resistance value in the ignition circuit containing component R12/13(Driver airbag ignition squib 1) is too high.	Current and stored
9143	The resistance value in the ignition circuit containing component R12/4(Front passenger airbag ignition squib 1) is too high.	Current and stored
9123	The resistance value in the ignition circuit containing component R12/14(Driver airbag ignition squib 2) is too high	Current and stored



New Session



Search



Report



Help

Freeze Frame



Diagnostic Trouble Code

MERCEDES V48.81 > Automatically Search

DTC	Description	State
9202	The resistance value in the ignition circuit containing component R12/7(Right rear ETR ignition squib) is too low.	Current and stored
9203	The resistance value in the ignition circuit containing component R12/7(Right rear ETR ignition squib) is too high.	Stored
91C3	The resistance value in the ignition circuit containing component R12/6(Left rear ETR ignition squib) is too high.	Current and stored



New Session



Search



Report



Help

Freeze Frame



Diagnostic Trouble Code

MERCEDES V48.81 > Automatically Search

DTC

Description

State

9163

The resistance value in the ignition circuit containing component R12/5(Front passenger airbag ignition squib 2) is too high.

Current and stored

9183

The resistance value in the ignition circuit containing component R12/1(Driver ETR ignition squib) is too high.

Current and stored

91A3

The resistance value in the ignition circuit containing component R12/2(Front passenger ETR ignition squib) is too high

Current and stored



New Session



Search



Report

Freeze Frame



Help



**LAI HUAT (MENG KEE)
MOTOR PTE LTD
SIN MING INDUSTRIAL
ESTATE SECTOR A
BLK 21 #01-58
SINGAPORE 575679**

Claim Reference:
Assessment Number: LHM61039
Version: LAI HUAT/2
Date Calculated: 29/03/2018 03:40

Full Report - V1
Registration: SGN 9919J
Printed: 29/03/2018 10:41

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	22/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3099651701	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	B Class
Sub Model:	B 200 TURBO
Model Sheet Number:	322 44
Registration:	SGN 9919J
Registration Month:	
Registration Year:	
VIN Number:	WDD2452342J144783
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM VIN J 136548	AIR CONDITIONING
WINDSCREEN	SMOKER PACKAGE
RAIN SENSOR	FRT/RR ELECT WINDOWS
INTERIOR LAMP PACK	PARKTRONIC SYSTEM
LIGHT-/VIEW PACKAGE	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CD	CD AUTO CHANGER
SOUND SYSTEM	BI-XENON HEADLAMPS
FOG LAMPS	LEATHER TRIM
MOBILE PREPARATION	SPORT PACKAGE
CHILD SEAT MOUNTING	ILLUM SUN VISORS
FRT SEAT LUGGAGE NET	DIPPING INT MIRROR
FR SEAT COMFORT PACK	ELEC ADJ DRIVER SEAT
ELECT PASSENGER SEAT	LUGGAGE COMP COVER
ST/WHEEL/LEV LEATHER	S/WHEEL TIP SWITCHES
AUTOM-GEAR VARIABLE	ADJ STEERING COLUMN
SPORTS SUSPENSION	TYRES 215/45 ZR 17
WHEELS 7J X 17 ALLOY	SPARE WHEEL
BLADE SUNROOF	TWO COAT METALLIC
WATER BASED PAINT	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering:

Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Severity of Impact:

Vehicle Status on

Inspection:

Date of Inspection:

28/03/2018

*Not Authorised
Lily B?
Resurvey After Paint
Ex \$1500.*

LAI HUAT (MENG KEE) MOTOR PTE LTD**Claim Reference:****Assessment Number: LHM61039****Version: LAI HUAT/2****Date Calculated: 29/03/2018 03:40****Full Report - V1****Registration: SGN 9919J****Printed: 29/03/2018 10:41**

Tyres Condition:

Tread Depth LHF:



Tread Depth LHR:

Damage Areas:

Tread Depth RHF:

Tread Depth RHR:

Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$3,162.60
Total Paint/Material	\$405.44
Total Parts	\$19,110.00
Total of Additional Costs	\$350.00
Repair Cost Exc GST:	\$23,028.04
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,500.00
After Deduction -	
Grand Total Exc GST:	\$21,528.04
7 % GST:	\$1,506.96
Grand Total Inc GST:	\$23,035.00

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
40-6500 01	ALIGN VEHICLE	9.0	37.80
83-1762 01	DOES NOT INCLUDE: ADJUSTMENTS AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	37.80
60-1331 02	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT (FOR RENEWAL OF THE FRONT MODULE) INCLUDES: R + R CHARGE AIR COOLER IF NECESSARY	8.0	33.60
88-1964 02	ADD/WORK R + R FRONT MODULE (VEHICLE WITH HEADLAMP WASHER)	2.0	8.40
88-1102 03	R + R COMPLETE FRONT BUMPER INCLUDES: R + R L/F AND R/F PARTITION AND FOG LAMPS	9.0	37.80
88-1105 03	DIS + ASS FRONT BUMPER (REMOVED) INCLUDES: R + R FOG LAMPS, RENEW PARTS AFTER CHECK	7.0	29.40
88-1358 01	ADD TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARKING SYSTEM)	2.0	8.40
88-2506 02	RENEW BONNET	18.0	75.60

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/2

Date Calculated: 29/03/2018 03:40

Full Report - V1

Registration: SGN 9919J

Printed: 29/03/2018 10:41

	INCLUDES: R + R BONNET, CONVERT ALL PARTS		
88-2657 02	RENEW BONNET HINGE/S	5.0	21.00
60-2297 01	R + R BOTH XENON HEADLAMPS (BUMPER REMOVED)	4.0	16.80
20-7450 ZAX	R + R UPPER COOLANT HOSE	3.0	12.60
88-4701 02	R + R L/F PARTITION SECTION	3.0	12.60
88-4702 02)	RENEW L/F PARTITION SECTION (REMOVED)	1.0	4.20
88-4704 02)	RENEW R/F PARTITION SECTION (REMOVED)	1.0	4.20
62-1270 01	RENEW RADIATOR CARRIER (STRIPPED)	3.0	12.60
20-1140 02	DRAIN + REFILL COOLANT	6.0	25.20
09-6820 03)	R + R CHARGE AIR COOLER (BUMPER REMOVED)	3.0	12.60
20-4300 01	ADDITIONAL TO R + R RADIATOR (VEHICLE WITH AUTOMATIC GEARBOX)	7.0	29.40
20-4008 01	RENEW RADIATOR (RADIATOR CARRIER REMOVED)	6.0	25.20
83-6523 03	R + R AIR CONDITIONING FLUID RESERVOIR, RENEW AFTER CHECK	4.0	16.80
83-6545 01	CONDENSER REMOVE AND REFIT/RENEW (RADIATOR REMOVED)	3.0	12.60
61-1091 02	R + R R/ENGINE COMPARTMENT SIDE COVER	3.0	12.60
83-7820 ZAX	RENEW REFRIGERANT PIPE D	3.0	12.60
83-7825 ZAX	RENEW REFRIGERANT PIPE	3.0	12.60
83-7805 ZAX	RENEW REFRIGERANT PIPE A	3.0	12.60
20-6461 01	R + R FAN UNIT	7.0	29.40
62-1266 01	RENEW FRONT CROSSMEMBER AND REINFORCEMENT BETWEEN WHEELHOUSES CPL	15.0	63.00
82-7200 02	R + R WASHER RESERVOIR	5.0	21.00
88-5205 02	R + R L/SILL SIDEMEMBER TRIM	6.0	25.20
88-5232 02	R + R R/SILL SIDEMEMBER TRIM	6.0	25.20
88-8802 03	R + R REAR BUMPER INCLUDES: R + R REAR CENTREPIECE PANELLING	7.0	29.40
88-8805 03	DIS + ASS REAR BUMPER AFTER FINDING: RENEW PARTS (REMOVED)	2.0	8.40
88-8883 02	ADDITIONAL FOR DISS/ASS REAR BUMPER (VEHICLE WITH PARK ASSISTENT)	3.0	12.60
68-3055 02)	R + R R/BOOT TRIM	3.0	12.60
88-3501 01	R + R TAILGATE MERCEDES STAR	3.0	12.60
88-3512 01	RENEW TAILGATE BADGE	4.0	16.80
88-3511 01	R + R TAILGATE TYPE BADGE	3.0	12.60
82-4903 03	R + R RIGHT REAR TAILLAMP	3.0	12.60
91-1042 01)	R + R L/F SEAT BELT	2.0	8.40
91-1012 01)	R + R R/F SEAT BELT	2.0	8.40
91-5414 02	R + R R/R SEAT BACKREST	7.0	29.40
91-1087 01)	R + R LEFT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	8.40
91-1097 01)	R + R RIGHT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	8.40
68-4605 01	R + R INSTRUMENT PANEL	25.0	105.00
68-4635 01	RENEW INSTRUMENT PANEL (REMOVED)	7.0	29.40

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/2

Date Calculated: 29/03/2018 03:40

Full Report - V1

Registration: SGN 9919J

Printed: 29/03/2018 10:41

68-4727 01	R + R L/LOWER INSTRUMENT PANEL COVER	2.0	8.40
68-4910 01	ADDITION TO R + R GLOVE BOX (VEHICLE WITH CD CHANGER)	1.0	4.20
68-4745 01	R + R L/INSTRUMENT PANEL COVER	1.0	4.20
68-1093 01	R + R L/B-PILLAR TRIM	5.0	21.00
68-1093 01	R + R R/B-PILLAR TRIM	5.0	21.00
68-1110 02	R + R LEFT C-PILLAR TRIM	5.0	21.00
68-1110 02	R + R RIGHT C-PILLAR TRIM	5.0	21.00
91-2162 01)	R + R PASSENGER AIRBAG UNIT	3.0	12.60
91-2157 01	R + R DRIVER AIRBAG	3.0	12.60
61-1124 01	R + R L/UNDERBODY COVER (EXHAUST SYSTEM REMOVED)	5.0	21.00
NO NUMBER	LOWER + LIFT ENGINE AND FRONT AXLE BRACKET	18.0	75.60
22-1260 02)	RENEW F/ENGINE MOUNTS ASS WORK	3.0	12.60
22-1268 01	RENEW FRONT ENGINE SUSPENSION BEARING	5.0	21.00
NO NUMBER	R + R ENGINE COVER	3.0	12.60
09-1030 01	R + R AIR FILTER CPL	5.0	21.00
09-8680 01)	R + R L/AIR CHANNEL	4.0	16.80
33-1835 01)	R + R FRONT AXLE CARRIER	38.0	159.60
33-1840 01	RENEW FRONT AXLE CARRIER (REMOVED)	7.0	29.40
	INCLUDES : R + R ALL ATTACHED PARTS AND RENEW ACCORDING TO CONDITION		
32-2050 01	R + R FRONT STABILIZER	14.0	58.80
49-7000 02	R + R EXHAUST SYSTEM CPL	9.0	37.80
9973	CARRY OUT TEST DRIVE	5 10.0*	42.00
1482	REPAIR RIGHT FRONT DOOR	20 20.0*	84.00 X
2102	REPAIR R/SILL PANEL	15 30.0*	126.00
2237	REPAIR L/A-PILLAR PANEL	10 20.0*	84.00
2931	REPAIR TAILGATE	15 20.0*	84.00
3482	REPAIR R/R WING	40 60.0*	252.00
1000	REPAIR WIRING + SUPPLY CONNECTOR	20 40.0*	168.00
LABOUR COST			
Total Work Units		580.0	
Panel / Mechanical Labour		57.1HRS	\$2,398.20
Visual Alignment Labour		0.9HRS	\$37.80
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		58.0HRS	\$2,436.00
Paint Labour		17.3HRS	\$726.60
Total Labour		75.3HRS	\$3,162.60

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- WATER BASED PAINT		
471	BONNET NEW PART PAINTING	24.0	
475	LEFT BONNET HINGE SURFACE PAINT	4.0	
476	RIGHT BONNET HINGE SURFACE PAINT	4.0	
283	FRONT BUMPER NEW PART PAINT K1R	14.0	

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/2

Date Calculated: 29/03/2018 03:40

Full Report - V1

Registration: SGN 9919J

Printed: 29/03/2018 10:41

2205	L/SILL PANEL COVER NEW PART PAINT K1R	6.0
2206	R/SILL PANEL COVER NEW PART PAINT K1R	6.0
2583	REAR BUMPER COVER NEW PART PAINT K1R	13.0
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	17.0
2102	R/SILL PANEL REPAIR PAINTING <50%	10.0
2237	L/A-PILLAR PANEL REPAIR PAINTING <50%	8.0
2931	TAILGATE REPAIR PAINTING <50%	22.0
3482	R/R WING REPAIR PAINTING <50%	11.0
1782	R/R DOOR SURFACE PAINT	8.0
LABOUR COST - PAINT		
	TIME(PAINT)	147.0
	Preparation Main Work Metal	21.0
	Preparation Comp. Work Plastic	5.0
	Preparation Work Multi Layer Paint	0.0
	Total Work Units (10WU/HR)	173.0
	Total Paintwork Labour	17.3HRS
MATERIAL COST - PAINT		
	New Part Painting	\$726.60
	New Part Painting - Plastic K1R	Cost Price
	Surface-/Blend Paint	\$79.98
	Repair Painting	\$178.09
	Material-Const Main Work Metal	\$22.41
	Material-Const Comp. Work Plastic	\$97.86
	Total Excluding Pearlescent Uplift	\$18.10
	Pearlescent Uplift @ 0.0%	\$9.00
	Total Paint Material Cost	\$405.44

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)	
1000	1	AIR CON DECAL	Renew		0%	18.00*	—
8391	1	AIR FILTER ASSY	266 090 0101		0%	173.00*	—
7751	1	AIR GUIDE PANEL	169 505 0930		0%	170.00*	—
1392	1	AIR INTAKE GRILLE	169 836 0018		0%	110.00*	—
471	1	BONNET	169 880 0257		0%	590.00*	✓
1017	1	BONNET LANDING PANEL	169 620 1634		0%	410.00*	—
4483	1	COMPR-/CONDENS PIPE	169 830 1615		0%	142.00*	2
4485	1	COMPR/EXP VALVE PIPE	169 830 1815		0%	120.00*	2
4465	1	CONDENSER	169 500 1254		0%	560.00*	✓
7445	1	DRIVER AIRBAG	164 860 1902 9051	Aur	0%	1,360.00*	✓
4482	1	DRYER/EXP VALVE PIPE	169 830 1715		0%	142.00*	X
7792	1	ELECTRIC FAN	169 820 3642		0%	880.00*	✓
1000	1	ENG TOP CVR BUSH	Renew		0%	3.00*	—
8820	1	EXH PIPE/CATALYST	169 490 0619		0%	525.00*	2
1000	1	EXT FRT PIPE BOLT	Renew		0%	5.00*	X
7011	1	FRONT AXLE SUPPORT	169 620 0787		0%	1,085.00*	—
283	1	FRONT BUMPER	169 885 2825		0%	950.00*	✓
8777	1	FRONT CENTRE TRIM	169 524 1430		0%	49.00*	—
8624	1	FRONT ENGINE SUPPORT	266 223 0604		0%	50.00*	—
7261	1	FRONT STABILISER	169 323 0965		0%	140.00*	—
432	1	FRONT STAR EMBLEM	207 817 0316		0%	33.00*	—
293	1	FRT BUMPER GRILLE	169 885 0123		0%	64.00*	✓
8631	1	FRT ENGINE MOUNTING	169 240 1517		0%	50.00*	2

Price Valid: 01/06/2015

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/2

Date Calculated: 29/03/2018 03:40

Full Report - V1

Registration: SGN 9919J

Printed: 29/03/2018 10:41

8633	1	FRT G-BOX RUBBER BRG	169 240 1517
320	1	FRT LWR BUMPER SUPP	169 885 0136
1001	1	FRT LWR CROSSMEMBER	169 620 1734
8888	1	GEARBOX OIL COOLER	169 500 0600
1000	1	HID WARNING DECALX2	Renew
9645	1	HIGH TONE HORN	006 542 4420
4331	1	INSTRUMENT PANEL	169 680 2287
			9D84
8730	1	INTERCOOLER	169 500 0900
8737	1	L/CHARGE AIR HOSE	169 528 0582
303	1	L/F BUMPER GRILLE	169 885 1122
313	1	L/F BUMPER TRIM	169 885 1374
1393	1	L/F COVER	169 830 0375
637	1	L/F FOG LAMP	251 820 0756
4661	1	L/F SEAT BELT	169 860 8385
7047	1	L/F TRACK CONT ARM	169 330 0907
833	1	L/F W-HOUSE FRT CVR	169 698 2530
559	1	L/HEADLAMP COVER	169 821 0336
605	1	L/HEADLAMP WASH TRIM	169 887 0325 9696
2615	1	L/R BUMPER TRIM	169 885 1574
4841	1	L/R SEAT BELT	169 860 7985
3011	1	L/R TYPE BADGE	169 817 1315
2205	1	L/SILL PANEL COVER	169 611 1308
4259	1	L/UNDERB HEAT SHIELD	169 610 3708
7776	1	L/UPP RADIATOR HOSE	169 501 1382
475	1	LEFT BONNET HINGE	169 880 0328
561	1	LEFT HEADLAMP ASSY	169 820 6961
9646	1	LOW TONE HORN	006 542 2720
493	1	LOWER BONNET LOCK	169 880 0560
8829	1	MAIN SILENCER	169 490 1122
1000	1	NOZZLE CVR SPRING LH	Renew
1000	1	NOZZLE CVR SPRING RH	Renew
4325	1	PASSENGER AIRBAG	169 860 0600
8228	1	R/ENGINE COVER	266 141 0121
304	1	R/F BUMPER GRILLE	169 885 1222
314	1	R/F BUMPER TRIM	169 885 1474
1394	1	R/F COVER	169 830 0275
638	1	R/F FOG LAMP	251 820 0856
4662	1	R/F SEAT BELT	169 860 6885
7048	1	R/F TRACK CONT ARM	169 330 1007
834	1	R/F W-HOUSE FRT CVR	169 698 2630
560	1	R/HEADLAMP COVER	169 821 0436
606	1	R/HEADLAMP WASH TRIM	169 887 0425 9696
3012	1	R/R BADGE	202 817 2115
2616	1	R/R BUMPER TRIM	169 885 1674
3282	1	R/R OUTER LAMP	169 820 2664
4842	1	R/R SEAT BELT	169 860 8085
2206	1	R/SILL PANEL COVER	169 611 1408
2622	1	R/STICKER REFLECTING	169 989 0285
1000	1	RAD COOLANT	Renew
1000	1	RAD SUPP BOLT	Renew
1000	1	RAD SUPP RUBB MOUNT	Renew

0%	nn	0.00F	X
0%	mi's	111.00*	✓
0%	R	375.00*	✓
0%	Bu	585.00*	✓
0%	Re	8.00*	✓
0%	CM	93.00*	✓
0%	Tu	1,020.00*	✓
0%	TT	505.00*	✓
0%	ad	130.00*	✓
0%	mi's	45.00*	✓
0%	mi's	59.00*	✓
0%	mi's	15.00*	✓
0%	mi's	138.00*	✓
0%	Tu	295.00*	✓
0%	Di's	330.00*	✓
0%	Re	44.00*	X
0%	mi's	10.00*	✓
0%	Re	44.00*	X
0%	mi's	72.00*	✓
0%	Tu	170.00*	✓
0%	Re	38.00*	X
0%	Bu	180.00*	✓
0%	R	260.00*	X
0%	Re	44.00*	X
0%	Re	42.00*	X
0%	mi's	1,450.00*	✓
0%	Re	93.00*	X
0%	Di's	89.00*	✓
0%	R	400.00*	X
0%	Re	5.00*	X
0%	Re	5.00*	X
0%	Bu	1,110.00*	✓
0%	mi's	75.00*	✓
0%	mi's	45.00*	✓
0%	mi's	59.00*	✓
0%	mi's	15.00*	✓
0%	mi's	138.00*	✓
0%	Tu	295.00*	✓
0%	Di's	330.00*	✓
0%	Re	44.00*	X
0%	mi's	10.00*	✓
0%	Re	44.00*	X
0%	Re	52.00*	✓
0%	Re	72.00*	X
0%	CM	180.00*	✓
0%	Tu	170.00*	✓
0%	Di's	180.00*	✓
0%	Re	22.00*	✓
0%	Re	40.00*	✓
0%	Re	12.00*	✓
0%	Re	8.00*	X

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/2

Date Calculated: 29/03/2018 03:40

Full Report - V1

Registration: SGN 9919J

Printed: 29/03/2018 10:41

7761	1	RADIATOR	169 500 2103	0%	Pr	400.00*	✓
405	1	RADIATOR COVER	169 880 0883	0%	Sn	300.00*	✓
7772	1	RADIATOR CROSSMEMBER	169 620 0485	0%	Bu	245.00*	✓
1000	1	RADIATOR TOP CLIP	Renew	0%	nn	14.00*	✓
2583	1	REAR BUMPER COVER	169 885 2138	0%	Bu	735.00*	✓
476	1	RIGHT BONNET HINGE	169 880 0428	0%	Dis	42.00*	✓
1000	1	SILL PNL CLIPS(B)	Renew	0%	me	24.00*	✓
1000	1	SILL PNL CLIPS(W)	Renew	0%	me	30.00*	✓
1000	1	SILL PNL CVR CLIPX2	Renew	0%	me	8.00*	✓
3010	1	STAR EMBLEM	221 758 0058	0%	me	24.00*	✓
492	1	UPPER BONNET LOCK	169 880 0160	0%	Dis	18.00*	✓
1000	1	WARNING DECAL - 1	Renew	0%	me	5.00*	✓
1000	1	WARNING DECAL - 2	Renew	0%	me	3.00*	✓
1435	1	W-WASHER BOTTLE	169 869 0320	0%	me	77.00*	✓
f: OEM Parts			Saving			\$31.01	
g: Original			Sub Total			\$19,110.00	
h: Secondhand			Sundry Parts	(Fixed)		\$0.00	
p: Parallel			Total Parts			\$19,110.00	
x: Exchange							

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
WHEEL ALIGNMENT SPECIALIST	0%	\$80.00
AIR CON GAS SPECIALIST		\$50.00
SRS CONTROL UNIT REPROGRAM	0%	\$120.00
SUNDRY PARTS SPECIALIST		\$100.00
Total Extras		\$350.00

Final Calculation

Total Parts		\$19,110.00
Labour		
Total Panel/Mechanical	\$2,398.20	1999.20 1957.00
Total Paintwork	\$726.60 ✓	709.80
Total Visual Alignment work	\$37.80 ✓	37.80
Total Labour		\$3,162.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$350.00	
Total of Additional Costs		\$350.00
Total Paint/Material Costs		\$405.44 405.19
Repair Costs Excludes GST		\$23,028.04
Deductions		
Deduction for Excess (Fixed)	-\$1,500.00	
Total Deductions		-\$1,500.00
Grand Total Excludes GST (After Deduction)		\$21,528.04
GST @ 7 %		\$1,506.96
Grand Total Includes GST (After Deduction)		\$23,035.00

24302.04

Assessment Notes

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/2

Date Calculated: 29/03/2018 03:40

Full Report - V1

Registration: SGN 9919J

Printed: 29/03/2018 10:41

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: LHM61039
Version: LAI HUAT/3
Date Calculated: 03/04/2018 05:09

Full Report - V1
Registration: SGN 9919J
Printed: 03/04/2018 12:09

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	MR LAU	Date of Incident:	22/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3099651701	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	B Class
Sub Model:	B 200 TURBO
Model Sheet Number:	322 44
Registration:	SGN 9919J
Registration Month:	
Registration Year:	
VIN Number:	WDD2452342J144783
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM VIN J 136548	AIR CONDITIONING
WINDSCREEN	SMOKER PACKAGE
RAIN SENSOR	FRT/RR ELECT WINDOWS
INTERIOR LAMP PACK	PARKTRONIC SYSTEM
LIGHT-/VIEW PACKAGE	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CD	CD AUTO CHANGER
SOUND SYSTEM	BI-XENON HEADLAMPS
FOG LAMPS	LEATHER TRIM
MOBILE PREPARATION	SPORT PACKAGE
CHILD SEAT MOUNTING	ILLUM SUN VISORS
FRT SEAT LUGGAGE NET	DIPPING INT MIRROR
FR SEAT COMFORT PACK	ELEC ADJ DRIVER SEAT
ELECT PASSENGER SEAT	LUGGAGE COMP COVER
ST/WHEEL/LEV LEATHER	S/WHEEL TIP SWITCHES
AUTOM-GEAR VARIABLE	ADJ STEERING COLUMN
SPORTS SUSPENSION	TYRES 215/45 ZR 17
WHEELS 7J X 17 ALLOY	SPARE WHEEL
BLADE SUNROOF	TWO COAT METALLIC
WATER BASED PAINT	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	28/03/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/3


Date Calculated: 03/04/2018 05:09

Full Report - V1


Registration: SGN 9919J

Printed: 03/04/2018 12:09

Damage Areas:



Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$2,763.60
Total Paint/Material	\$405.44
Total Parts	\$19,110.00
Total of Additional Costs	\$350.00
Repair Cost Exc GST:	\$22,629.04
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,500.00
After Deduction -	
Grand Total Exc GST:	\$21,129.04
7 % GST:	\$1,479.03
Grand Total Inc GST:	\$22,608.07

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
40-6500 01	ALIGN VEHICLE	9.0	37.80
	DOES NOT INCLUDE: ADJUSTMENTS		
83-1762 01	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	37.80
60-1331 02	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT (FOR RENEWAL OF THE FRONT MODULE) INCLUDES: R + R CHARGE AIR COOLER IF NECESSARY	8.0	33.60
88-1964 02	ADD/WORK R + R FRONT MODULE (VEHICLE WITH HEADLAMP WASHER)	2.0	8.40
88-1102 03	R + R COMPLETE FRONT BUMPER INCLUDES: R + R L/F AND R/F PARTITION AND FOG LAMPS	9.0	37.80
88-1105 03	DIS + ASS FRONT BUMPER (REMOVED) INCLUDES: R + R FOG LAMPS, RENEW PARTS AFTER CHECK	7.0	29.40
88-1358 01	ADD TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARKING SYSTEM)	2.0	8.40
88-2506 02	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ALL PARTS	18.0	75.60
88-2657 02	RENEW BONNET HINGE/S	5.0	21.00

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: LHM61039

Registration: SGN 9919J

Version: LAI HUAT/3

Printed: 03/04/2018 12:09

Date Calculated: 03/04/2018 05:09

60-2297 01	R + R BOTH XENON HEADLAMPS (BUMPER REMOVED)	4.0	16.80
20-7450 ZAX	R + R UPPER COOLANT HOSE	3.0	12.60
88-4701 02	R + R L/F PARTITION SECTION	3.0	12.60
88-4702 02)	RENEW L/F PARTITION SECTION (REMOVED)	1.0	4.20
88-4704 02)	RENEW R/F PARTITION SECTION (REMOVED)	1.0	4.20
62-1270 01	RENEW RADIATOR CARRIER (STRIPPED)	3.0	12.60
20-1140 02	DRAIN + REFILL COOLANT	6.0	25.20
09-6820 03)	R + R CHARGE AIR COOLER (BUMPER REMOVED)	3.0	12.60
20-4300 01	ADDITIONAL TO R + R RADIATOR (VEHICLE WITH AUTOMATIC GEARBOX)	7.0	29.40
20-4008 01	RENEW RADIATOR (RADIATOR CARRIER REMOVED)	6.0	25.20
83-6523 03	R + R AIR CONDITIONING FLUID RESERVOIR, RENEW AFTER CHECK	4.0	16.80
83-6545 01	CONDENSER REMOVE AND REFIT/RENEW (RADIATOR REMOVED)	3.0	12.60
61-1091 02	R + R R/ENGINE COMPARTMENT SIDE COVER	3.0	12.60
83-7820 ZAX	RENEW REFRIGERANT PIPE D	3.0	12.60
83-7825 ZAX	RENEW REFRIGERANT PIPE	3.0	12.60
83-7805 ZAX	RENEW REFRIGERANT PIPE A	3.0	12.60
20-6461 01	R + R FAN UNIT	7.0	29.40
62-1266 01	RENEW FRONT CROSSMEMBER AND REINFORCEMENT BETWEEN WHEELHOUSES CPL	15.0	63.00
82-7200 02	R + R WASHER RESERVOIR	5.0	21.00
88-5205 02	R + R L/SILL SIDEMEMBER TRIM	6.0	25.20
88-5232 02	R + R R/SILL SIDEMEMBER TRIM	6.0	25.20
88-8802 03	R + R REAR BUMPER INCLUDES: R + R REAR CENTREPIECE PANELLING	7.0	29.40
88-8805 03	DIS + ASS REAR BUMPER AFTER FINDING: RENEW PARTS (REMOVED)	2.0	8.40
88-8883 02	ADDITIONAL FOR DISS/ASS REAR BUMPER (VEHICLE WITH PARK ASSISTENT)	3.0	12.60
68-3055 02)	R + R R/BOOT TRIM	3.0	12.60
88-3501 01	R + R TAILGATE MERCEDES STAR	3.0	12.60
88-3512 01	RENEW TAILGATE BADGE	4.0	16.80
88-3511 01	R + R TAILGATE TYPE BADGE	3.0	12.60
82-4903 03	R + R RIGHT REAR TAILLAMP	3.0	12.60
91-1042 01)	R + R L/F SEAT BELT	2.0	8.40
91-1012 01)	R + R R/F SEAT BELT	2.0	8.40
91-5414 02	R + R R/R SEAT BACKREST	7.0	29.40
91-1087 01)	R + R LEFT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	8.40
91-1097 01)	R + R RIGHT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	8.40
68-4605 01	R + R INSTRUMENT PANEL	25.0	105.00
68-4635 01	RENEW INSTRUMENT PANEL (REMOVED)	7.0	29.40
68-4727 01	R + R L/LOWER INSTRUMENT PANEL COVER	2.0	8.40
68-4910 01	ADDITION TO R + R GLOVE BOX (VEHICLE WITH CD CHANGER)	1.0	4.20

Claim Reference:

Full Report - V1

Assessment Number: LHM61039

Registration: SGN 9919J

Version: LAI HUAT/3

Printed: 03/04/2018 12:09

Date Calculated: 03/04/2018 05:09

68-4745 01	R + R L/INSTRUMENT PANEL COVER	1.0	4.20
68-1093 01	R + R L/B-PILLAR TRIM	5.0	21.00
68-1093 01	R + R R/B-PILLAR TRIM	5.0	21.00
68-1110 02	R + R LEFT C-PILLAR TRIM	5.0	21.00
68-1110 02	R + R RIGHT C-PILLAR TRIM	5.0	21.00
91-2162 01)	R + R PASSENGER AIRBAG UNIT	3.0	12.60
91-2157 01	R + R DRIVER AIRBAG	3.0	12.60
61-1124 01	R + R L/UNDERBODY COVER (EXHAUST SYSTEM REMOVED)	5.0	21.00
NO NUMBER	LOWER + LIFT ENGINE AND FRONT AXLE BRACKET	18.0	75.60
22-1260 02)	RENEW F/ENGINE MOUNTS ASS WORK	3.0	12.60
22-1268 01	RENEW FRONT ENGINE SUSPENSION BEARING	5.0	21.00
NO NUMBER	R + R ENGINE COVER	3.0	12.60
09-1030 01	R + R AIR FILTER CPL	5.0	21.00
09-8680 01)	R + R L/AIR CHANNEL	4.0	16.80
33-1835 01)	R + R FRONT AXLE CARRIER	38.0	159.60
33-1840 01	RENEW FRONT AXLE CARRIER (REMOVED)	7.0	29.40
	INCLUDES : R + R ALL ATTACHED PARTS AND RENEW ACCORDING TO CONDITION		
32-2050 01	R + R FRONT STABILIZER	14.0	58.80
49-7000 02	R + R EXHAUST SYSTEM CPL	9.0	37.80
9973	CARRY OUT TEST DRIVE	5.0*	21.00
2102	REPAIR R/SILL PANEL	15.0*	63.00
2237	REPAIR L/A-PILLAR PANEL	10.0*	42.00
2931	REPAIR TAILGATE	15.0*	63.00
3482	REPAIR R/R WING	40.0*	168.00
1000	REPAIR WIRING + SUPPLY CONNECTOR	20.0*	84.00

LABOUR COST

Total Work Units	485.0	
Panel / Mechanical Labour	47.6HRS	\$1,999.20
Visual Alignment Labour	0.9HRS	\$37.80
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	48.5HRS	\$2,037.00
Paint Labour	17.3HRS	\$726.60
Total Labour	65.8HRS	\$2,763.60

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- WATER BASED PAINT		
471	BONNET NEW PART PAINTING	24.0	
475	LEFT BONNET HINGE SURFACE PAINT	4.0	
476	RIGHT BONNET HINGE SURFACE PAINT	4.0	
283	FRONT BUMPER NEW PART PAINT K1R	14.0	
2205	L/SILL PANEL COVER NEW PART PAINT K1R	6.0	
2206	R/SILL PANEL COVER NEW PART PAINT K1R	6.0	
2583	REAR BUMPER COVER NEW PART PAINT K1R	13.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	17.0	

Claim Reference:

Full Report - V1

Assessment Number: LHM61039

Registration: SGN 9919J

Version: LAI HUAT/3

Printed: 03/04/2018 12:09

Date Calculated: 03/04/2018 05:09

2102	R/SILL PANEL REPAIR PAINTING <50%	10.0	
2237	L/A-PILLAR PANEL REPAIR PAINTING <50%	8.0	
2931	TAILGATE REPAIR PAINTING <50%	22.0	
3482	R/R WING REPAIR PAINTING <50%	11.0	
1782	R/R DOOR SURFACE PAINT	8.0	
LABOUR COST - PAINT			
	TIME(PAINT)	147.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	173.0	
	Total Paintwork Labour	17.3HRS	\$726.60
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$79.98
	New Part Painting - Plastic K1R		\$178.09
	Surface-/Blend Paint		\$22.41
	Repair Painting		\$97.86
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$405.44
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$405.44

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	AIR CON DECAL	Renew		0%	18.00*
8391	1	AIR FILTER ASSY	266 090 0101		0%	173.00*
7751	1	AIR GUIDE PANEL	169 505 0930		0%	170.00*
1392	1	AIR INTAKE GRILLE	169 836 0018		0%	110.00*
471	1	BONNET	169 880 0257		0%	590.00*
1017	1	BONNET LANDING PANEL	169 620 1634		0%	410.00*
4483	1	COMPR-/CONDENS PIPE	169 830 1615		0%	142.00*
4485	1	COMPR/EXP VALVE PIPE	169 830 1815		0%	120.00*
4465	1	CONDENSER	169 500 1254		0%	560.00*
7445	1	DRIVER AIRBAG	164 860 1902 9051		0%	1,360.00*
4482	1	DRYER/EXP VALVE PIPE	169 830 1715		0%	142.00*
7792	1	ELECTRIC FAN	169 820 3642		0%	880.00*
1000	1	ENG TOP CVR BUSH	Renew		0%	3.00*
8820	1	EXH PIPE/CATALYST	169 490 0619		0%	525.00*
1000	1	EXT FRT PIPE BOLT	Renew		0%	5.00*
7011	1	FRONT AXLE SUPPORT	169 620 0787		0%	1,085.00*
283	1	FRONT BUMPER	169 885 2825		0%	950.00*
8777	1	FRONT CENTRE TRIM	169 524 1430		0%	49.00*
8624	1	FRONT ENGINE SUPPORT	266 223 0604		0%	50.00*
7261	1	FRONT STABILISER	169 323 0965		0%	140.00*
432	1	FRONT STAR EMBLEM	207 817 0316		0%	33.00*
293	1	FRT BUMPER GRILLE	169 885 0123		0%	64.00*
8631	1	FRT ENGINE MOUNTING	169 240 1517		0%	50.00*
8633	1	FRT G-BOX RUBBER BRG	169 240 1517		0%	0.00F
320	1	FRT LWR BUMPER SUPP	169 885 0136		0%	111.00*
1001	1	FRT LWR CROSSMEMBER	169 620 1734		0%	375.00*
8888	1	GEARBOX OIL COOLER	169 500 0600		0%	585.00*

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/3

Date Calculated: 03/04/2018 05:09

Full Report - V1

Registration: SGN 9919J

Printed: 03/04/2018 12:09

1000	1	HID WARNING DECALX2	Renew	0%	8.00*
9645	1	HIGH TONE HORN	006 542 4420	0%	93.00*
4331	1	INSTRUMENT PANEL	169 680 2287 9D84	0%	1,020.00*
8730	1	INTERCOOLER	169 500 0900	0%	505.00*
8737	1	L/CHARGE AIR HOSE	169 528 0582	0%	130.00*
303	1	L/F BUMPER GRILLE	169 885 1122	0%	45.00*
313	1	L/F BUMPER TRIM	169 885 1374	0%	59.00*
1393	1	L/F COVER	169 830 0375	0%	15.00*
637	1	L/F FOG LAMP	251 820 0756	0%	138.00*
4661	1	L/F SEAT BELT	169 860 8385	0%	295.00*
7047	1	L/F TRACK CONT ARM	169 330 0907	0%	330.00*
833	1	L/F W-HOUSE FRT CVR	169 698 2530	0%	44.00*
559	1	L/HEADLAMP COVER	169 821 0336	0%	10.00*
605	1	L/HEADLAMP WASH TRIM	169 887 0325 9696	0%	44.00*
2615	1	L/R BUMPER TRIM	169 885 1574	0%	72.00*
4841	1	L/R SEAT BELT	169 860 7985	0%	170.00*
3011	1	L/R TYPE BADGE	169 817 1315	0%	38.00*
2205	1	L/SILL PANEL COVER	169 611 1308	0%	180.00*
4259	1	L/UNDERB HEAT SHIELD	169 610 3708	0%	260.00*
7776	1	L/UPP RADIATOR HOSE	169 501 1382	0%	44.00*
475	1	LEFT BONNET HINGE	169 880 0328	0%	42.00*
561	1	LEFT HEADLAMP ASSY	169 820 6961	0%	1,450.00*
9646	1	LOW TONE HORN	006 542 2720	0%	93.00*
493	1	LOWER BONNET LOCK	169 880 0560	0%	89.00*
8829	1	MAIN SILENCER	169 490 1122	0%	400.00*
1000	1	NOZZLE CVR SPRING LH	Renew	0%	5.00*
1000	1	NOZZLE CVR SPRING RH	Renew	0%	5.00*
4325	1	PASSENGER AIRBAG	169 860 0600	0%	1,110.00*
8228	1	R/ENGINE COVER	266 141 0121	0%	75.00*
304	1	R/F BUMPER GRILLE	169 885 1222	0%	45.00*
314	1	R/F BUMPER TRIM	169 885 1474	0%	59.00*
1394	1	R/F COVER	169 830 0275	0%	15.00*
638	1	R/F FOG LAMP	251 820 0856	0%	138.00*
4662	1	R/F SEAT BELT	169 860 6885	0%	295.00*
7048	1	R/F TRACK CONT ARM	169 330 1007	0%	330.00*
834	1	R/F W-HOUSE FRT CVR	169 698 2630	0%	44.00*
560	1	R/HEADLAMP COVER	169 821 0436	0%	10.00*
606	1	R/HEADLAMP WASH TRIM	169 887 0425 9696	0%	44.00*
3012	1	R/R BADGE	202 817 2115	0%	52.00*
2616	1	R/R BUMPER TRIM	169 885 1674	0%	72.00*
3282	1	R/R OUTER LAMP	169 820 2664	0%	180.00*
4842	1	R/R SEAT BELT	169 860 8085	0%	170.00*
2206	1	R/SILL PANEL COVER	169 611 1408	0%	180.00*
2622	1	R/STICKER REFLECTING	169 989 0285	0%	22.00*
1000	1	RAD COOLANT	Renew	0%	40.00*
1000	1	RAD SUPP BOLT	Renew	0%	12.00*
1000	1	RAD SUPP RUBB MOUNT	Renew	0%	8.00*
7761	1	RADIATOR	169 500 2103	0%	400.00*
405	1	RADIATOR COVER	169 880 0883	0%	300.00*
7772	1	RADIATOR CROSSMEMBER	169 620 0485	0%	245.00*
1000	1	RADIATOR TOP CLIP	Renew	0%	14.00*

Claim Reference:

Assessment Number: LHM61039

Registration: SGN 9919J

Version: LAI HUAT/3

Printed: 03/04/2018 12:09

Date Calculated: 03/04/2018 05:09

2583	1	REAR BUMPER COVER	169 885 2138	0%	735.00*
476	1	RIGHT BONNET HINGE	169 880 0428	0%	42.00*
1000	1	SILL PNL CLIPS(B)	Renew	0%	24.00*
1000	1	SILL PNL CLIPS(W)	Renew	0%	30.00*
1000	1	SILL PNL CVR CLIPSX2	Renew	0%	8.00*
3010	1	STAR EMBLEM	221 758 0058	0%	24.00*
492	1	UPPER BONNET LOCK	169 880 0160	0%	18.00*
1000	1	WARNING DECAL - 1	Renew	0%	5.00*
1000	1	WARNING DECAL - 2	Renew	0%	3.00*
1435	1	W-WASHER BOTTLE	169 869 0320	0%	77.00*
f: OEM Parts			Saving		\$31.01
g: Original			Sub Total		\$19,110.00
h: Secondhand			Sundry Parts	(Fixed)	\$0.00
p: Parallel			Total Parts		\$19,110.00
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
WHEEL ALIGNMENT SPECIALIST	0%	\$80.00
AIR CON GAS SPECIALIST		\$50.00
SRS CONTROL UNIT REPROGRAM	0%	\$120.00
SUNDRY PARTS SPECIALIST		\$100.00
Total Extras		\$350.00

Final Calculation

Total Parts		\$19,110.00
Labour		
Total Panel/Mechanical	\$1,999.20	
Total Paintwork	\$726.60	
Total Visual Alignment work	\$37.80	
Total Labour		\$2,763.60
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$350.00	
Total of Additional Costs		\$350.00
Total Paint/Material Costs		\$405.44
Repair Costs Excludes GST		\$22,629.04
Deductions		
Deduction for Excess (Fixed)	-\$1,500.00	
Total Deductions		-\$1,500.00
Grand Total Excludes GST (After Deduction)		\$21,129.04
GST @ 7 %		\$1,479.03
Grand Total Includes GST (After Deduction)		\$22,608.07

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Finalised

Claim Reference:
Assessment Number: LHM61039
Version: LKKAUTOC/2
Date Calculated: 30/08/2018 04:50

Full Report - V1
Registration: SGN 9919J
Printed: 30/08/2018 11:50

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	22/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3099651701	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	B Class
Sub Model:	B 200 TURBO
Model Sheet Number:	322 44
Registration:	SGN 9919J
Registration Month:	
Registration Year:	
VIN Number:	WDD2452342J144783
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM VIN J 136548	AIR CONDITIONING
WINDSCREEN	SMOKER PACKAGE
RAIN SENSOR	FRT/RR ELECT WINDOWS
INTERIOR LAMP PACK	PARKTRONIC SYSTEM
LIGHT-/VIEW PACKAGE	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CD	CD AUTO CHANGER
SOUND SYSTEM	BI-XENON HEADLAMPS
FOG LAMPS	LEATHER TRIM
MOBILE PREPARATION	SPORT PACKAGE
CHILD SEAT MOUNTING	ILLUM SUN VISORS
FRT SEAT LUGGAGE NET	DIPPING INT MIRROR
FR SEAT COMFORT PACK	ELEC ADJ DRIVER SEAT
ELECT PASSENGER SEAT	LUGGAGE COMP COVER
ST/WHEEL/LEV LEATHER	S/WHEEL TIP SWITCHES
AUTOM-GEAR VARIABLE	ADJ STEERING COLUMN
SPORTS SUSPENSION	TYRES 215/45 ZR 17
WHEELS 7J X 17 ALLOY	SPARE WHEEL
BLADE SUNROOF	TWO COAT METALLIC
WATER BASED PAINT	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	28/03/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR: