

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 03 Apr 2018

Preliminary Advice

Vehicle No	: SGN9919J	Accident Date	: 22/03/2018
Make	: MERCEDES-BENZ B200	Policy No.	: DMPCSN3099651701
Assignment Date	: 29/03/2018	Excess	: S\$1,500.00
Date of Inspection	: 02/04/2018	Est. Duration of Repair	: 0.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and o/s rear portion. The undercarriage and body structure affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,028.04
Revised Amount	:S\$	19,103.04
Check Items (Estimated)	:S\$	3,526.00
Total	:S\$	22,629.04
Lump Sum Repair (ESTIMATED)	:S\$	18,100.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	48,437.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,563.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :