



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 5717 S

Parts	(a) Cost / List Price Items	\$	17,664.85
	Plus/Less 25%	\$	4,416.21
	Total of Cost / List	\$	13,248.64
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	250.00
Total Parts Cost		\$	13,498.64
Labour		\$	2,870.00
Total		\$	16,368.64

Not Authorized

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : CKK

Survey conducted on : 21/4/18 at 11.45am

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 21/4/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	SLN 5717 S	Submit By :	Carmen Lim
Make & Model :	TOYOTA PRIUS	Year Manufacture :	2017
Chassis No. :	JTDKB3FU403557605	Engine No. :	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>CM</i>	1	\$2,561.60		✓
2	Front support panel centre	1	\$338.50		?
3	Front support panel RH	1	\$213.50		?
4	Headlamp panel RH	1	\$89.20		?
5	Support panel lower <i>R</i>	1	\$387.95		X
6	Headlamp RH <i>Repaired</i>	1	\$2,531.60		X
7	Headlamp ballast RH	1	\$881.36		?
8	Front bumper <i>CM</i>	1	\$450.80		✓
9	Front bumper clip <i>R</i>	10	\$40.00		✓
10	Front bumper reinforcement - upper <i>R</i>	1	\$711.50		X
11	Front bumper reinforcement - lower <i>R</i>	1	\$245.30		X
12	Front bumper side retainer RH <i>CM</i>	1	\$107.20		✓
13	Front bumper lower grille <i>Sn</i>	1	\$148.60		X
14	Front bumper emblem <i>R</i>	1	\$87.10		✓
15	Front bumper tow cover RH	1	\$25.70		?
16	Front bumper sponge - upper <i>Sn</i>	1	\$89.81		X
17	Front bumper sponge - lower <i>Sn</i>	1	\$135.70		X
18	Fog lamp RH <i>CM</i>	1	\$910.70		✓
19	Engine under cover centre	1	\$198.30		?
20	Engine under cover RH	1	\$105.20		?
21	Engine under cover clip	10	\$35.00		?
22	Washer tank <i>Det</i>	1	\$195.60		✓
23	Washer tank motor	1	\$196.74		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLN 5717 S
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU403557605

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front fender <i>Bu</i>	1	\$868.70		✓
25	RH front fender undershield <i>Tn</i>	1	\$185.64		✓
26	RH front fender undershield clip <i>Nu</i>	10	\$25.00		✓
27	RHF fender wording "HYBRID" <i>Nu</i>	1	\$44.17		✓
28	RH front lower arm	1	\$492.65		?
29	RH front shock absorber	1	\$462.70		?
30	RH front shock absorber top mouting	1	\$195.07		?
31	RH front shock absorber stopper	1	\$37.02		?
32	RH front knuckle arm <i>As</i>	1	\$476.75		✓
33	RH front knuckle bearing <i>As</i> }	1	\$573.20		✓
34	RH front wheel hub }	1			
35	RH front wheel hub lock nut	1	\$28.02		?
36	RH front tie rod	1	\$1,721.85		?
37	RH front tie rod end	1	\$116.40		?
38	RH front hub cab <i>As</i>	1	\$195.62		✓
39	RH front rim	1	\$1,555.10		?
40	RH front tyre <i>As</i>	1	\$250.00	S.N	5075x
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLN 5717 S Submit By : Carmen Lim
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,SUPPORT PANEL,RH FRONT FENDER)	\$1,200.00	600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,SUPPORT PANEL,RH FRONT FENDER)	\$1,000.00	600
3	To check wiring	\$50.00	200
4	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	?
5	To remove & refit undercarriage to assist work load.	\$250.00	200
6	To do wheel alignment.	\$120.00	600
7	To tuff coat	\$100.00	300

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.