

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : Lim Kar Foo

Accident Date : 19-Mar-18

Vehicle No : JPX 8145

Vehicle Model : Yamaha Jupiter

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tubes assy	\$ 640.00 ?
1	Front wheel rim	\$ 280.00
1	Front rim shaft	\$ 45.00
1	Front rim bearing	\$ 38.00
1	Front brake disc	\$ 155.00 X
1	Handle bar	\$ 75.00
1	Handle bar end	\$ 28.00
1	Hand grip (1 set)	\$ 45.00 X
1	Handle bar inner bracket	\$ 68.00 X
2	Side mirrors	\$ 110.00
1	Windshield	\$ 28.00 X
2	Front signals	\$ 130.00 ?
1	Front signal lower garnish	\$ 85.00
1	Headlamp	\$ 185.00 X
1	Fairing assy (1 set)	\$ 425.00
2	Side cowling inner garnishes	\$ 180.00
1	Centre inner panel	\$ 145.00
1	Radiator	\$ 458.00 X
1	Front footrest bracket	\$ 65.00
2	Front footrest rubbers	\$ 70.00
1	Gear pedal	\$ 42.00 X
1	Brake pedal	\$ 42.00 X
1	Water pump cover	\$ 105.00 X
1	Clutch cover	\$ 180.00
1	Rear footrest -L/H	\$ 40.00
1	Rear footrest bracket -L/H	\$ 78.00 X
1	Side stand	\$ 75.00 X
1	Main stand	\$ 95.00 X
1	Rear fender	\$ 120.00 X
		\$ 4,032.00
	Less 10%	\$ 403.20
		\$ 3,628.80

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Lim Kar Foo

Accident Date : 19-Mar-18

Vehicle No : JPX 8145

Vehicle Model : Yamaha Jupiter

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$ 11	28.00	
2	Fork oils	\$ m	30.00	✓
2	Fork oil seals	\$ m	56.00	✓
1	Steering cone (1 set)	\$ m	90.00	✓
1	Rear box	\$ m	180.00	150
1	Rear box bracket	\$ m	100.00	✓
		\$	484.00	

S/No. Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing.	\$ 11	80.00	2
3	To provide labour.	\$	380.00	250
		\$	510.00	

Grand Total

\$ 4,622.80

Dollars: Four Thousand Six Hundred Twenty-Two And Eighty Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: