

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : Ng Jun Rong

Accident Date : 23-Mar-18

Vehicle No : FBJ 780 E

Vehicle Model : Yamaha Tmax
530

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fender	\$ 185.00 X
1	Front side fork assy	\$ 1,020.00 X
1	Headlamp assy	\$ 844.00 X
1	Side mirror assy -R/H	\$ 178.00
1	Handle bar	\$ 188.00
1	Handle bar balancer	\$ 60.00
1	Brake lever	\$ 78.00 X
2	Front side cowlings	\$ 900.00
2	Front signals	\$ 840.00
1	Lower side skirt -R/H	\$ 320.00
1	Exhaust assy	\$ 1,380.00 X
1	Exhaust protector set	\$ 250.00
1	Exhaust link pipe cover	\$ 90.00
1	Exhaust end cap cover	\$ 120.00 X
		\$ 6,453.00
Exhaust pipe front cover 120		\$ 645.30
Less 10%		\$ 5,807.70

cu1 60 ✓

not about

note

the photo other rep-
42.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Ng Jun Rong

Accident Date : 23-Mar-18

Vehicle No : FBJ 780 E

Vehicle Model : Yamaha Tmax
530

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set) <i>then</i>	\$ <i>12</i>	28.00	<i>10</i>
1	Fork oil	\$ <i>11</i>	15.00	<i>9</i>
1	Fork oil seal	\$ <i>11</i>	28.00	<i>9</i>
1	Steering cone (1 set)	\$ <i>11</i>	185.00	<i>2</i>
1	Rear box	\$ <i>611</i>	700.00	<i>✓</i>
1	Rear box bracket	\$ <i>11</i>	250.00	<i>X</i>
		\$	1,206.00	


S/No. Labour

1	To provide towing service.	\$ <i>11</i>	50.00	<i>X</i>
2	To remove, refit and align front fork tubes.	\$	200.00	<i>60</i>
3	To check wiring and reset headlamp focusing.	\$ <i>11</i>	80.00	<i>2</i>
4	To provide labour.	\$	480.00	<i>300</i>
		\$	810.00	

Grand Total

\$ 7,823.70

Dollars: Seven Thousand Eight Hundred Twenty-Three And Seventy Cents Only.


EROFIA MOTOR TRADING PTE LTD