

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AXA18005976/APS3Q2  
**Date:** 12/10/2021REFERENCE

|                              |                       |                             |          |
|------------------------------|-----------------------|-----------------------------|----------|
| Handling Insurer:            | AXA Insurance Pte Ltd | Policy No:                  | P1680520 |
| <b>Claimant Vehicle No :</b> | SLK840S               | <b>Insured Vehicle No :</b> | SHB9952M |
| Date of Loss:                | 28/03/2018            | Nature of Claim:            | TP       |
|                              |                       | Claim No:                   | C0472773 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLK840S</b>                    |             |                   |
| Make & Model:               | MERCEDES-BENZ SLK350, 3.5 (A)     | Engine No:  | 27296330281710    |
| Reg. Date:                  | 29/03/2006 (Man. Year: 2006)      | Chassis No: | WDB1714562F114687 |
| Colour:                     | Grey                              | Odometer:   | 85007 km          |
| Engine Capacity:            | 3498 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 245/35 R18    | Rear Tyre Size:  | 245/35 R18    |
| Front Left Side:  | Goodyear 6 mm | Rear Left Side:  | Goodyear 6 mm |
| Front Right Side: | Goodyear 6 mm | Rear Right Side: | Goodyear 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 20,759.00         | 5,600.98          | 15,158.02         | 73.02         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 3,570.00          | 890.00            | 2,680.00          | 75.07         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>24,329.00</b>  | <b>6,490.98</b>   | <b>17,838.02</b>  | <b>73.32</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>5,200.00</b>   |                   |               |

|                          |                  |                                                  |                  |              |
|--------------------------|------------------|--------------------------------------------------|------------------|--------------|
| <b>Nett Amount (S\$)</b> | <b>24,329.00</b> | <b>5,200.00</b>                                  | <b>19,129.00</b> | <b>78.63</b> |
|                          |                  | <b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b> | 500.00           |              |
|                          |                  | <b>Nett Liability (S\$)</b>                      | <b>5,700.00</b>  |              |

INSPECTION

Date of Assignment: 29/03/2018

Date Inspected: 02/04/2018

Estimated Period of Repair: 4.0 days

Inspected At:

New Hock Teck Motor Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit  
 Singapore 417883

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 03 Sep 2021)                                                                                                                                             |                                                                |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | MERCEDES-BENZ SLK350 3.5 (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLK840S)                                                                                                                                     |                                                                |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition                     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|-------------------------------|-------------|--------------|
| 1   | 1   |          | *REAR BOOT LID                        | Not Necessary                 | 2,661.00 F  | *- FL        |
| 2   | 1   |          | *REAR BOOT LID EMBLEM LOGO            | Not Necessary                 | 46.00 F     | *- FL        |
| 3   | 1   |          | *REAR BOOT LID SLK350 LOGO            | Not Necessary                 | 85.00 F     | *- FL        |
| 4   | 1   |          | *REAR BOOT LID AMG LOGO               | Not Necessary                 | 135.00 F    | *- FL        |
| 5   | 1   |          | *REAR BOOT LID NUMBER PLATE           | Not Necessary                 | 50.00 F     | *- FL        |
| 6   | 1   |          | *REAR TAIL LAMP                       | N/S Not Necessary/O/S Cracked | 980.00 F    | *490.00 FL   |
| 7   | 1   |          | *REAR BUMPER                          | Deformed                      | 2,430.00 F  | *1,550.00 FL |
| 8   | 10  |          | *REAR BUMPER CLIP                     | Necessary                     | 65.00 F     | *30.00 FL    |
| 9   | 2   |          | *REAR BUMPER SIDE RETAINER            | Necessary                     | 318.20 F    | *318.20 FL   |
| 10  | 1   |          | *REAR BUMPER REINFORCEMENT            | Not Necessary                 | 641.00 F    | *- FL        |
| 11  | 1   |          | *REAR BUMPER TOWING COVER             | Not Necessary                 | 55.00 F     | *- FL        |
| 12  | 1   |          | *REAR BUMPER REVERSE SENSOR<br>(4PCS) | Damaged(1Pc Only)             | 956.00 F    | *239.00 FL   |
| 13  | 1   |          | *REAR REVERSE CAMERA                  | Not Necessary                 | 550.00 FS   | *- FS        |
| 14  | 1   |          | *REAR END PANEL                       | Not Necessary                 | 671.00 F    | *- FL        |
| 15  | 1   |          | *REAR END PANEL TOP GARNISH           | Not Necessary                 | 202.00 F    | *- FL        |
| 16  | 1   |          | *REAR EXHAUST (AMG)                   | Bent                          | 3,400.00 F  | *2,780.00 FL |
| 17  | 1   |          | *REAR EXHAUST CHROME PIPE             | O/S Bent                      | 450.00 FS   | *200.00 FS   |
| 18  | 2   |          | *REAR EXHAUST MOUNTING                | Not Necessary                 | 102.00 F    | *- FL        |
| 19  | 1   |          | *REAR CENTRE EXHAUST                  | Not Necessary                 | 2,256.80 F  | *- FL        |
| 20  | 1   |          | *CAR BODY STICKER                     | Necessary                     | 4,500.00 FS | *350.00 FS   |
| 21  | 1   |          | *REAR BUMPER INNER SPONGE             | Deformed                      | 205.00 F    | *205.00 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                 |
|-----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>20,759.00</b> | <b>6,162.20</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b> | 0.00             | 561.22          |
| <b>Total Parts (\$\$)</b>                                 | <b>20,759.00</b> | <b>5,600.98</b> |

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----------------------------------------------|-----|----------|-------------|-----------|------------|--------|
| Report was unsubmitted during this print-out. |     |          |             |           |            |        |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                             | Lab.Type | Repairer's      | Amount        |
|--------------------------------|-----------------------------------------|----------|-----------------|---------------|
| <b><u>Labour Items</u></b>     |                                         |          |                 |               |
| 1                              | TO REMOVE & REFIT CUSHION               | New      | 280.00          | 0.00          |
| 2                              | TO REMOVE & REFIT REVERSE SENSOR        | New      | 100.00          | 60.00         |
| 3                              | TO REMOVE & REFIT REAR CAMERA           | New      | 180.00          | 0.00          |
| 4                              | TO REMOVE & REFIT REAR & CENTRE EXHAUST | New      | 380.00          | 200.00        |
| 5                              | TO REMOVE & REFIT TOP SPOILER           | New      | 280.00          | 0.00          |
| 6                              | TO RESET COMPUTER SYSTEM                | New      | 100.00          | 0.00          |
| 7                              | TO CHECK WIRING                         | New      | 100.00          | 30.00         |
| 8                              | TUFF KOTE                               | New      | 150.00          | 0.00          |
| 9                              | PANEL BEATING                           | New      | 1,000.00        | 350.00        |
| 10                             | SPRAY PAINTING                          | New      | 1,000.00        | 250.00        |
| <b>Gross Labour Cost (S\$)</b> |                                         |          | <b>3,570.00</b> | <b>890.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >