



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk C #01-41 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

KIN WONG

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

04 DAY

TP AXA

Xiao Tong

29/03/2018

WDB1714562F114687

5200

Accident date: 28/03/2018

Estimated repair cost for vehicle no: SLK840S MERCEDES SLK350 3.5 A '06

CHASSIS: WDB1714562F114687

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$2,661.00 *
2	1	Rear Boot Lid Emblem Logo		\$46.00 *
3	1	Rear Boot Lid SLK350 Logo		\$85.00 *
4	1	Rear Boot Lid AMG logo		\$135.00 *
5	1	Rear Boot Lid Number Plate		\$50.00 *
6	2	Rear Tail Lamp L & R New, RH Zauland	\$490.00	\$980.00 2490
7	1	Rear Bumper Deformed.		\$2,430.00 1950
8	10	Rear Bumper Clip New	\$6.50	\$65.00 30
9	2	Rear Bumper Side Retainer New	\$159.10	\$318.20 *
10	1	Rear Bumper Reinforcement Not New		\$641.00 *
11	1	Rear Bumper Inner Sponge Deformed.		\$205.00 *
12	1	Rear Bumper Towing Cover Not New		\$55.00 *
13	4	Rear Bumper Reverse Sensor 7 Piece damaged	\$239.00	\$956.00 239
14	1	Rear Reverse Camera (Special Nett) Not New		\$550.00 *
15	1	Rear End Panel Not New		\$671.00 *
16	1	Rear End Panel Top Garnish Not New		\$202.00 *
17	1	Rear Exhaust (AMG) Best.		\$3,400.00 2780
18	2	Rear Exhaust Chrome Pipe RH Best	\$225.00	\$450.00 200/SN
19	2	Rear Exhaust Mounting Not New	\$51.00	\$102.00 *
20	1	Rear Centre Exhaust Not New		\$2,256.80 *
21	1	Car Body Sticker (Special Nett) New		\$4,500.00 3906

Subtotal :- \$20,759.00

561220

5050.98

S-N: 550

Labour charges

To remove & refit cushion	\$280.00 x
To remove & refit reverse sensor	\$100.00 60.
To remove & refit rear camera	\$180.00 x.
To remove & refit rear & centre exhaust	\$380.00 200.
To remove & refit top spoiler	\$280.00 x.
To reset computer system	\$100.00 x.
To check wiring	\$100.00 30
Tuff kote	890 \$150.00 x.
Panel beating	\$1,000.00 350
Spray painting	\$1,000.00 250

Subtotal :- \$3,570.00Total:- \$24,329.00

Adrian Lin

L/s 02/04/18.

~~03-04 Days.~~

Total: 6490.98

L/s: 5.2/K

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: