

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 4	REAR W/SCREEN SEALANT	Reviewing	80	NECESSARY	
☐	 5	REVERSE SENSOR (4EYE)	Reviewing	250	NECESSARY	
☐	 6	NUMBER PLATE & HOLDER INCLUDING PARTS-FRONT AND REAR (ADDITIONAL DISC 5%)	Reviewing	114	BENT	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
	2		PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL. (ADDITIONAL DISC 5%)	114	0	0	Reviewing	
	3		REPLACE REVERSE SENSOR. NECESSARY ADJUSTMENT & FUNCTION TEST. (ADDITIONAL DISC 5%)	104.5	0	0	Reviewing	
	4		APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA. (ADDITIONAL DISC 5%)	190	0	0	Reviewing	
	5		REMOVE / INSTALL REAR BUMPER, END PANEL, BACK DOOR, LH REAR BUMPER AND AFFECTED PORTION, REPAIR TRUNK. (NPA)	0	0	0	Reviewing	
	6		TRUNK FLOOR PANEL AND RH REAR FENDER. (ADDITIONAL DISC 5%)	1306.25	0	0	Reviewing	
	7		RESPRAY PAINT REAR BUMPER, END PANEL, TRUNK FLOOR PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER. (ADDITIONAL DISC 5%)	1235	0	0	Reviewing	
	8		REMOVE / INSTALL REAR SEAT AND CARPET TO FACILITATE THE REPAIR. (ADDITIONAL DISC 5%)	114	0	0	Reviewing	
	9		REMOVE / INSTALL ROOF LINING ASSY TO FACILITATE THE REPAIR. (ADDITIONAL DISC 5%)	142.5	0	0	Reviewing	
	10		RENEW BACK DOOR WINDSCREEN GLASS. (ADDITIONAL DISC 5%)	228	0	0	Reviewing	
	11		RENEW LH REAR QUARTER GLASS.	0	0	0	Reviewing	
	12		RENEW BACK DOOR AND LH REAR QUARTER GLASS SOLAR FILM. (ADDITIONAL DISC 5%)	142.5	0	0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC CUNT%	SALV AGE%	PART PRICE(NET)
	38	2			DRIVE UNIT- POWER BACK DOOR			Serviceable	0		20		0
	39	1			WEATHER STRIP - BACK DOOR			Necessary	133.8	5	20		101.69
	40	2			BUMPER RUBBER - BACK DOOR			Necessary	6.5	5	20		9.88
	41	1			EMBLEM - REAR			Necessary	101.3	5	20		76.99
	42	1			EMBLEM - REAR			Necessary	59.7	5	20		45.37
	43	1			FINISHER ASSY - BACK DOOR			Serviceable	0		20		0
	44	1			RUBBER - DUM			Necessary	60.2	5	20		45.75
	45	1			GLASS-BACK DOOR WINDOW			Necessary	1302	5	20		989.52
	46	1			DOOR ASSY- BACK			Deformed	4200	5	20		3192
	47	1			RH REAR BUMPER STAY			Bent	174.8	5	20		132.85
	48	1			LH REAR BUMPER STAY			Bent	174.8	5	20		132.85
	49	1			REAR BUMPER REINFORCEMENT			Bent	533.8	5	20		405.69
	50	1			LH REAR BUMPER SIDE BRACKET			Necessary	35.8	5	20		27.21
	51	1			RH REAR BUMPER SIDE BRACKET			Necessary	35.9	5	20		27.28

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPL/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐		11	1		LH FRONT BUMPER SIDE BRACKET			Necessary	20.9	5	20		15.88
☐		12	1		RH FRONT BUMPER SIDE BRACKET			Necessary	20.9	5	20		15.88
☐		13	4		CLIP-FRONT BUMPER GRILLE			Necessary	1.2	5	20		3.65
☐		14	1		GRILLE-FRONT BUMPER			Serviceable	0		20		0
☐		15	1		MOULDING-FRONT BUMPER			Serviceable	0		20		0
☐		16	2		FRONT BUMPER CLIP			Necessary	1.2	5	20		1.82
☐		17	2		FRONT BUMPER CLIP			Necessary	2.5	5	20		3.8
☐		18	1		COVER - BUMPER BRACKET			Serviceable	0		20		0
☐		19	1		FRONT BUMPER FASCIA			Deformed	534.7	5	20		406.37
☐		20	2		CLIP - HEADLAMP ASSY			Necessary	1.2	5	20		1.82
☐		21	1		HEADLAMP ASSY - RH			Serviceable	0		20		0
☐		22	1		HEADLAMP ASSY - LH			Serviceable	0		20		0
☐		23	8		CLIP - REAR MOULDING FILLET			Serviceable	0		20		0
☐		24	4		CLIP - REAR MOULDING FILLET			Serviceable	0		20		0

Detailed Assessment

Inspection Date *

04/09/2018



Condition of Vehicle at time of survey

General condition

Fair

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/60R18

Rear Tyre Size

225/60R18

FNOL INFORMATI... 60 PUNGOL WALK #08-21, 828780,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7705050G

POLICY INFORMAT... TPVD NISSAN

ASSESSMENT INFO...

NISSAN

CATEGORY

Model

POLICY INFORMAT... X-TRAIL

ASSESSMENT INFO...

X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

JN1JANT32Z0001474

CATEGORY

Date of Birth

FNOL INFORMATI...

February 21, 1977

POST SURVEY INF...

mm/dd/yyyy

CATEGORY

Age

FNOL INFORMATI...

41

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

Pending verification -
Direct Settlement

TAN Jas
6568804844
jas.tan@axa.com.sg

- Messages
- Invoices
- History

Additional Instructions

Add

Documents	Assessment	Metrics	Notes	STATUS	SHARE	CLONE
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT			
NIKAM Santosh Pandurang	3/29/18 11:53 AM	13100.39	13100.39	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SLA2396Y TP.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	March 26, 2018

TAN Jas
6568804844
jas.tan@axa.com.sg

Pending verification -
Direct Settlement

Additional Instructions

Messages

Invoices

History

Documents	Assessment	Metrics	Notes	Document Type	Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
RENTAL.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 11, 2018
REVISED TP ESTIMATE - MARKED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	May 11, 2018
LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	April 24, 2018
LKK Resurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	April 24, 2018