

INS. CASE-OWNER:

CC 3/EQ11800 5982, *9/2/18*


LKK:
IDAC:

Surveyor: Kenneth

DOI: 21/3/18


Date / Time: 21/3/18
Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: 6B6 8707L
Name of Insured: EMU TAT LEE FURNITURE CONTRACTOR
Insured Tel No.: HP:
Excess Sec II :\$ D.O.A.: 27/3/18
Is driver the owner? (YES / NO) Nature of Accident:
If NO, Driver Name / Age: NEOW FOR TAT
Driver Tel No.: 81129577 (V/L: YES / NO)


Claim No.: DM18NOU0812/OT
Policy No.: DMUPHRT-006890
Make / Model: TOYOTA
Place of Accident: UE




INSRS:
WSP:
Tel:
Liability:
RMKS: 01



INSRS: Trans Cab
WSP:
Tel:
Liability:
RMKS: TP



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
<u>6/4/18</u>	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: <u>CH 10/9/18</u>	
<u>2/4/18</u>	After call ltr to OI: Documentation Check List: Handler Typist	
<u>14/8/18</u>	Notification ltr (if non-pickup): After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA : Medical Bill: PIR: Mandate/Reject Instruction: LOD	
<u>27/9/18</u>	Payment Breakdown Form: Post-Repair Photos: Others:	
<u>1/10/18</u>		

PRELIMINARY ADVICE Date/Time: 2/4/18 Sent By: Tom

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$S (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: Confirm with: Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28 (Sec 01 last) If NO or B 28, Ass. Lia:

Repair Cost: \$S
Loss of Rental (LOR): \$S (days)
Loss of Use (LOU): \$S (\$ x days)
Loss of Income (LOI): \$S (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI (Tick only one)
GIA/LTA Search: \$S
Medical: \$S
Disbursement: \$S (e.g. Tow/ Independent)
Legal Cost: \$S

Total: \$S Global Sum \$S: Email Call

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$S Name 1:
Payee 2: (Strike if N.A.) \$S Name 2:
Payee 3: (Strike if N.A.) \$S Name 3:

COPY SENT
17/10/18

1) Claim status: Normal/Reject/Private Settle
2) Report Format: WP
3) Survey fee: #300/-

REF: EQ /

ASS. BY: _____

Kenneth

INSTRUMENT

From: _____ Date: _____

Estimated Cost: _____

OD RES / OD RES / EVA / INV / MV

To In: _____ Vehicle No: _____

at Workshop n/s Trans Cab

of _____

Insured: _____

Policy: _____

Claim: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make: _____

(Police Condition)

Remarks: The veh had commenced its
journey at the time of inspection.



Bal. of _____

IDAC A/R Report _____ Consistent? : Yes or No

GIA / I. Report _____ Consistent? : Yes or No

Est. Report 07 days Res.: Yes or No

Lum S 20 % 3 Val.: Yes or No

CA / E. Report / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: _____

Date: _____ Instruction

214 File pass to Catherine

2719 1/2mp @ 12450L confirmed

Yr Regn: 07, 13

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Year: Merault 1985 c.c. 1985

Colour: M. White / Red A/C: Insured / Std / NI / NA

Registration: 578804 T/Radio: Insured / Std / NI / NA

Motor: _____

Plate: VI1ABL15AUC - 273278

Cond: Good / Fair / Poor / Burnt

Engine: In order / Jammed / Leaked / Burnt or

Transmission: In order / Jammed / Leaked / Burnt or

Wheels: Nil / S/Rim / STD A/Rim or

Tires: F: Giti 215/60R16

R: Falken

Accessories: _____

Options: EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Other: YOKO or _____

Front: 9 mm

Rear: 7 mm

Left: 9 mm

Right: 7 mm

Front: 271318

Rear: 29/3/18

Location: _____

Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& 1st

Chassis frame / Body Structure affected due to collision.

TOTAL

Date/Time: _____ : Prell. Report

1) _____ : Final Report

Date/Time: _____

2) _____

Add P

Report Fee: _____

Lump Sum: _____

Survey Fee: _____
Transportation: _____
\$ - RS. \$
Photos
Others
TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI18005982/Kpb3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 02-04-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 8707L	Veh. Inspected	SHB 9730L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/03/2018	Inspection Date	29/03/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQ118005982/Kpb3

Date: 02.04.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB9730L


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29.03.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	<u>73,607.64</u>
Revised Estimate Amount	: S\$	<u>15,540.03</u>
"Check" Items Amount	: S\$	<u>-</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

AAD1803-251

*Not Authored
L/Sing &*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHB 9730L

VF1ABL15AUC280344

RENAULT

LATITUDE

27.3.2018

EQ

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>Reu</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sen</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	<i>Sen</i> 394.68 X
4	1	BUMPER RETAINER FRT LH	\$	<i>Sen</i> 151.41 X
5	1	BUMPER SUPPORT FRT	\$	<i>Sen</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 150.77 ✓
7	1	BUMPER SUPPORT FRT	\$	<i>Sen</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sen</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Dis</i> 266.80 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sen</i> 207.21 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sen</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
13	1	TOW COVER FRT	\$	<i>Sen</i> 28.61 X
14	1	RADIATOR GRILLE	\$	<i>Sen</i> 1,707.78 X
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sen</i> 225.36 X
16	1	RADIATOR GRILLE FRAME	\$	<i>Sen</i> 1,353.75 X
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sen</i> 615.90 X
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>Sen</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>Sen</i> 314.17 X
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>Sen</i> 1,184.43 X
23	1	HEADLAMP RH	\$	<i>Sen</i> 1,184.43 X
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
26	1	BONNET	\$	<i>R</i> 1,941.63 X
27	1	BONNET INSULATOR	\$	<i>Sen</i> 405.73 X
28	1	BONNET STRUT LH	\$	<i>Sen</i> 88.61 X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

Item No.	Quantity	Description	Unit Price (\$)	Material Code	Material Price (\$)	Notes
29	1	BONNET STRUT RH	\$	Sm	88.61	
30	1	BONNET HINGE LH	\$	R	348.31	
31	1	BONNET HINGE RH	\$	R	348.31	
32	1	BONNET LOCK	\$	R	305.48	
33	1	BONNET CABLE	\$	Sm	119.19	
34	1	BONNET CABLE COVER	\$	Sm	161.03	
35	1	BONNET SEAL OUTER	\$	Sm	92.36	X
36	1	BONNET SEAL INNER	\$	Sm	157.28	
37	1	FENDER PANEL FRT LH	\$	R	783.83	
38	1	FENDER PANEL FRT RH	\$	R	783.83	
39	1	WHEELARCH FRT LH	\$	Sm	278.84	
40	1	WHEELARCH FRT RH	\$	Sm	278.84	
41	1	FENDER BRACKET LOWER LH	\$	Sm	15.79	
42	1	FENDER BRACKET LOWER RH	\$	Sm	15.79	
43	1	FENDER INSULATOR LH	\$	Sm	130.84	
44	1	FENDER INSULATOR RH	\$	Sm	130.84	
45	1	BUMPER COVER REAR	\$	B	1,108.46	✓
46	1	BUMPER LOWER REAR	\$	M/S	768.84	✓
47	1	BUMPER BRACKET CTR REAR	\$	D/I	113.47	✓
48	1	BUMEPR BRACKET SIDE RH REAR	\$	Sm	135.97	X
49	1	BUMEPR RETAINER RH REAR	\$	Sm	44.99	X
50	1	BUMPER REFLECTOR RH	\$	CPA	43.61	✓
51	1	BUMEPR BRACKET SIDE LH REAR	\$	Sm	135.97	X
52	1	BUMEPR RETAINER LH REAR	\$	D/I Sm	44.99	✓
53	1	BUMPER REFLECTOR LH	\$	CPA	43.61	✓
54	1	BUMPER BEAM REAR	\$	B	777.52	✓
55	1	BUMPER BEAM BRACKET LH REAR	\$	B	225.95	✓
56	1	BUMPER BEAM BRACKET RH REAR	\$	B	225.95	✓
57	1	BOOT REAR	\$	B	2,872.68	✓
58	1	BOOT FINISHER	\$	CPA	470.06	✓
59	1	BOOT WHEATERSTRIP	\$	D/I / CP	323.05	✓
60	1	BOOT REFLECTOR LAMP LH	\$	CPA	493.35	✓
61	1	BOOT REFLECTOR LAMP RH	\$	CPA	493.35	✓
62	1	BOOT BADGE 'RENAULT'	\$	R	225.36	✓
63	1	BOOT BADGE	\$	R	225.36	✓
64	1	BOOT STRUT LH	\$	Sm	276.08	X
65	1	BOOT STRUT RH	\$	Sm	276.08	X
66	1	BOOT HINGE LH	\$	R	367.84	X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

67	1	BOOT HINGE RH	\$	R	367.84	X
68	1	BOOT INNER TRIM	\$	Sn	586.45	X
69	1	BOOT SWITCH	\$	Sn	168.13	X
70	1	BOOT LOCK	\$	Nu	202.67	✓
71	1	BOOT LOCK CATCH	\$	R	74.40	X
72	2	LICENCE PLATE LAMP	\$	Sn	50.52	X
73	2	BOOT RUBBER PLUG	\$	Sn	221.81	X
74	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
75	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
76	1	WHEELARCH REAR LH	\$	Sn	543.47	X
77	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	X
78	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
79	1	WHEELARCH REAR RH	\$	Sn	543.47	X
80	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
81	1	WHEELARCH REAR LH	\$	Sn	543.47	X
82	1	TAILLAMP RH	\$	MJCM	552.55	✓
83	1	TAILLAMP PANEL RH	\$	R	986.70	X
84	1	TAILLAMP LH	\$	MJCM	552.55	✓
85	1	TAILLAMP PANEL LH	\$	R	986.70	X
86	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
87	1	OUTER PANEL REAR (End Panel)TRIM	\$	Nu	404.56	✓
88	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
89	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
90	1	EXHAUST REAR	\$	R	7,489.05	X
91	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	57,866.80
10%	\$	5,786.68
	\$	52,080.12

Special Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	Rn	52.00	X
2	1SET	BUMPER CLIP FRT	\$	Rn	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	Rn	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	Rn	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	Rn	12.00	X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50 X
7	1	TOW COVER FRT	\$	sn	14.50 X
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00 X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nc	69.00 —
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nr	70.00 X
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00 X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00 X
13	1	Windscreen moulding	\$	na	100.00 X
14	1SET	Front licence plate with holder	\$	nr	80.00 45sn
15	1SET	PARKING AID	\$	short	700.00 —
16	1SET	REAR BUMPER CLIP	\$	nr	66.00 —
17	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00 —
18	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na	10.00 X
19	1SET	BUMEPR RETAINER RH CLIP RR	\$	na	20.00 X
20	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	10.00 X
21	1SET	BUMEPR RETAINER CLIP LH RR	\$	na	20.00 X
22	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00 X
23	1SET	BUMPER LOWER REAR CLIP	\$	nc	66.00 —
24	1	EXHAUST MOUNTING REAR	\$	sn	17.82 X
25	1SET	BOOT FINISHER CLIP	\$	na	24.20 X
26	1	BOOT STICKER "Trans-cab"	\$	nc	30.00 —
27	1	BOOT STICKER "6555-3333"	\$	na	30.00 —
28	1	BOOT INNER TRIM CLIP	\$	na	45.00 X
29	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00 X
30	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00 X
31	1	FENDER INNER TRIM CLIP LH	\$	na	28.00 X
32	1	FENDER INNER TRIM CLIP LH	\$	na	28.00 X
33	1	TAILLAMP CLIP RH	\$	nc	5.00 —
34	1	TAILLAMP CLIP LH	\$	nr	5.00 —
35	2	REAR WINDSCREEN SELANT	\$	na	80.00 X
36	1	WINDSCREEN MOULDING	\$	na	100.00 X
37	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00 X
38	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00 X
39	1	SPARE TYRE	\$	sn	330.00 X
			\$		2,787.52

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

TOTAL PARTS \$ 54,867.64

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,400.00 ^{100d}
Towing Fees.	\$	~ 120.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	~ 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 ^{110d}
To rust-proofing of the affected areas.	\$	170.00 ^{60d}
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 ^{80d}
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 ^{20d}
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
To lift-up engine with gear box and refit.	\$	~ 440.00 X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>na</i> 440.00 X
To remove and refit air bag system and reset.	\$	<i>na</i> 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>na</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>na</i> 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i> 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00 X
To Rust-Proofing Of The Affected Areas.	\$	<i>Revised</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00
		} <i>601</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 <i>X</i>

TOTAL \$ 18,740.00

Over All Total \$ 73,607.64

(LUMP SUM) Repair Days

20 DAYS

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHB9730L

Vehicle to be Exported: Yes

Intended De-registration Date: 28 Mar 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2013

Engine No.: M9R8839C000205

Chassis No.: VF1ABL15AUC273278

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 18 Jul 2013

First Registration Date: 18 Jul 2013

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 Jul 2021

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 17 Jul 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$51,810.00

COE Rebate Amount: \$21,379.00

Total Rebate Amount: \$30,752.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Mar 2018

OK

Shu Pei (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Thursday, 5 April 2018 10:38 AM
To: Shu Pei (LKKAuto)
Cc: Hsiao Tong (LKKAuto)
Subject: FW: Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018
Attachments: TP ESTIMATE- MARKED.PDF; TP GIA REPORT.PDF; Preliminary_Advice.pdf; GBG8707G.PDF

Dear Shu Pei

OI report as attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Monday, April 2, 2018 5:34 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBG8707L (OI : EQI - TBA) and SHB9730L (TP : LKK REF - CC3/EQI18005982/Kpb3) on 27.03.2018

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHB 9730L at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 10 April 2018 5:04 PM
To: 'janet.tan@eqinsurance.com.sg'
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018
Attachments: Status Of DL_OID.pdf

Hi Janet,

3 vehicles chain collision: -

GBG 8707G(Insured) -> SHB 9730L(Third Party) -> SJZ 1940A

We noted that our insured driver is holding class 3C driving licence which only allow the drivers to drive motorcars only.

Kindly advise if there is any policy issue and whether we can proceed DS for this matter.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Thursday, 5 April 2018 10:38 AM
To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: FW: Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018

Dear Shu Pei

OI report as attached.

Regards,

Janet Tan

Senior Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately.

From: Shu Pei (LKKAuto) [<mailto:shupei@lkkauto.com>]

Sent: Monday, April 2, 2018 5:34 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBG8707L (OI : EQI - TBA) and SHB9730L (TP : LKK REF - CC3/EQI18005982/Kpb3) on 27.03.2018

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHB 9730L at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 11 August 2018 9:09 AM
To: 'Janet Tan'
Cc: Admin A
Subject: RE: *URGENT* : Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018

Hi Janet,

We refer to our tele-conversation on 02 Aug 2018, we will proceed DS for this matter.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Thursday, 2 August 2018 1:49 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: *URGENT* : Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018

Dear Hsiao Tong,

Is there an issue on his driving licence? Based on his licence, he has a Class 3 licence since 14/10 2011 or 31 May 2017?

Please enlighten. Thank you.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Saturday, July 28, 2018 11:17 AM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: *URGENT* : Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018

Hi Janet,

We refer to our email dated 10/04/2018, 28/04/2018, 02/06/2018 & 07/07/2018.

3 vehicles chain collision: -

GBG 8707G(Insured) -> SHB 9730L(Third Party) -> SJZ 1940A

We noted that our insured driver is holding class 3C driving licence which only allow the drivers to drive motorcars only.

Kindly advise if there is any policy issue and whether we can proceed DS for this matter.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 7 July 2018 11:53 AM

To: 'janet.tan@eqinsurance.com.sg' <janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018

Hi Janet,

We refer to our email dated 10/04/2018, 28/04/2018 & 02/06/2018

3 vehicles chain collision: -

GBG 8707G(Insured) -> SHB 9730L(Third Party) -> SJZ 1940A

We noted that our insured driver is holding class 3C driving licence which only allow the drivers to drive motorcars only.

Kindly advise if there is any policy issue and whether we can proceed DS for this matter.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 2 June 2018 1:28 PM

To: 'janet.tan@eqinsurance.com.sg' <janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018

Hi Janet,

We refer to our email dated 10/04/2018 & 28/04/2018.

3 vehicles chain collision: -

GBG 8707G(Insured) -> SHB 9730L(Third Party) -> SJZ 1940A

We noted that our insured driver is holding class 3C driving licence which only allow the drivers to drive motorcars only.

Kindly advise if there is any policy issue and whether we can proceed DS for this matter.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 28 April 2018 2:22 PM

To: 'janet.tan@eqinsurance.com.sg' <janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018

Hi Janet,

We refer to our email dated 10/04/2018.

3 vehicles chain collision: -

GBG 8707G(Insured) -> SHB 9730L(Third Party) -> SJZ 1940A

We noted that our insured driver is holding class 3C driving licence which only allow the drivers to drive motorcars only.

Kindly advise if there is any policy issue and whether we can proceed DS for this matter.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Tuesday, 10 April 2018 5:04 PM

To: 'janet.tan@eqinsurance.com.sg' <janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBG8707L (OI : EQI - DM18HO00813/jt) and SHB9730L (TP : LKK REF -CC3/EQI18005982/Kpb3) on 27.03.2018

Hi Janet,

3 vehicles chain collision: -

GBG 8707G(Insured) -> SHB 9730L(Third Party) -> SJZ 1940A

We noted that our insured driver is holding class 3C driving licence which only allow the drivers to drive motorcars only.

Kindly advise if there is any policy issue and whether we can proceed DS for this matter.