

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L**AAD1803-251***Not Authored
L/Sing &*

Vehicle No.:	SHB 9730L
Chassis No.:	VF1ABL15AUC280344
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	27.3.2018
Third Party Insurer :	EQ

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>Per</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sen</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	<i>Sen</i> 394.68 X
4	1	BUMPER RETAINER FRT LH	\$	<i>Sen</i> 151.41 X
5	1	BUMPER SUPPORT FRT	\$	<i>Sen</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 150.77 ✓
7	1	BUMPER SUPPORT FRT	\$	<i>Sen</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sen</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Dis</i> 266.80 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sen</i> 207.21 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sen</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
13	1	TOW COVER FRT	\$	<i>Sen</i> 28.61 X
14	1	RADIATOR GRILLE	\$	<i>Sen</i> 1,707.78 X
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sen</i> 225.36 X
16	1	RADIATOR GRILLE FRAME	\$	<i>Sen</i> 1,353.75 X
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sen</i> 615.90 X
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>Sen</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>Sen</i> 314.17 X
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>Sen</i> 1,184.43 X
23	1	HEADLAMP RH	\$	<i>Sen</i> 1,184.43 X
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
26	1	BONNET	\$	<i>R</i> 1,941.63 X
27	1	BONNET INSULATOR	\$	<i>Sen</i> 405.73 X
28	1	BONNET STRUT LH	\$	<i>Sen</i> 88.61 X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

29	1	BONNET STRUT RH	\$	Sm	88.61	
30	1	BONNET HINGE LH	\$	R	348.31	
31	1	BONNET HINGE RH	\$	R	348.31	
32	1	BONNET LOCK	\$	R	305.48	
33	1	BONNET CABLE	\$	Sm	119.19	
34	1	BONNET CABLE COVER	\$	Sm	161.03	
35	1	BONNET SEAL OUTER	\$	Sm	92.36	X
36	1	BONNET SEAL INNER	\$	Sm	157.28	
37	1	FENDER PANEL FRT LH	\$	R	783.83	
38	1	FENDER PANEL FRT RH	\$	R	783.83	
39	1	WHEELARCH FRT LH	\$	Sm	278.84	
40	1	WHEELARCH FRT RH	\$	Sm	278.84	
41	1	FENDER BRACKET LOWER LH	\$	Sm	15.79	
42	1	FENDER BRACKET LOWER RH	\$	Sm	15.79	
43	1	FENDER INSULATOR LH	\$	Sm	130.84	
44	1	FENDER INSULATOR RH	\$	Sm	130.84	
45	1	BUMPER COVER REAR	\$	Bz	1,108.46	✓
46	1	BUMPER LOWER REAR	\$	M/S	768.84	✓
47	1	BUMPER BRACKET CTR REAR	\$	D/I	113.47	✓
48	1	BUMEPR BRACKET SIDE RH REAR	\$	Sm	135.97	X
49	1	BUMEPR RETAINER RH REAR	\$	Sm	44.99	X
50	1	BUMPER REFLECTOR RH	\$	CPA	43.61	✓
51	1	BUMEPR BRACKET SIDE LH REAR	\$	Sm	135.97	X
52	1	BUMEPR RETAINER LH REAR	\$	D/I Sm	44.99	✓
53	1	BUMPER REFLECTOR LH	\$	CPA	43.61	✓
54	1	BUMPER BEAM REAR	\$	Bz	777.52	✓
55	1	BUMPER BEAM BRACKET LH REAR	\$	Bz	225.95	✓
56	1	BUMPER BEAM BRACKET RH REAR	\$	Bz	225.95	✓
57	1	BOOT REAR	\$	Bz	2,872.68	✓
58	1	BOOT FINISHER	\$	CPA	470.06	✓
59	1	BOOT WHEATERSTRIP	\$	D/I / Com	323.05	✓
60	1	BOOT REFLECTOR LAMP LH	\$	CPA	493.35	✓
61	1	BOOT REFLECTOR LAMP RH	\$	CPA	493.35	✓
62	1	BOOT BADGE 'RENAULT'	\$	Ma	225.36	✓
63	1	BOOT BADGE	\$	Ma	225.36	✓
64	1	BOOT STRUT LH	\$	Sm	276.08	X
65	1	BOOT STRUT RH	\$	Sm	276.08	X
66	1	BOOT HINGE LH	\$	R	367.84	X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

67	1	BOOT HINGE RH	\$	R	367.84	X
68	1	BOOT INNER TRIM	\$	Sn	586.45	X
69	1	BOOT SWITCH	\$	Sn	168.13	X
70	1	BOOT LOCK	\$	Ru	202.67	✓
71	1	BOOT LOCK CATCH	\$	R	74.40	X
72	2	LICENCE PLATE LAMP	\$	Sn	50.52	X
73	2	BOOT RUBBER PLUG	\$	Sn	221.81	X
74	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
75	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
76	1	WHEELARCH REAR LH	\$	Sn	543.47	X
77	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	X
78	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
79	1	WHEELARCH REAR RH	\$	Sn	543.47	X
80	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
81	1	WHEELARCH REAR LH	\$	Sn	543.47	X
82	1	TAILLAMP RH	\$	mgcm	552.55	✓
83	1	TAILLAMP PANEL RH	\$	R	986.70	X
84	1	TAILLAMP LH	\$	mgcm	552.55	✓
85	1	TAILLAMP PANEL LH	\$	R	986.70	X
86	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
87	1	OUTER PANEL REAR (End Panel)TRIM	\$	Ru	404.56	✓
88	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
89	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
90	1	EXHAUST REAR	\$	R	7,489.05	X
91	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	57,866.80
10%	\$	5,786.68
	\$	52,080.12

Special Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	na	52.00	X
2	1SET	BUMPER CLIP FRT	\$	na	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50 X
7	1	TOW COVER FRT	\$	su	14.50 X
8	1SET	RADAITOR GRILLE SCREW	\$	na	16.00 X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00 —
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00 X
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00 X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00 X
13	1	Windscreen moulding	\$	na	100.00 X
14	1SET	Front licence plate with holder	\$	na	80.00 455m
15	1SET	PARKING AID	\$	short	700.00 —
16	1SET	REAR BUMPER CLIP	\$	na	66.00 —
17	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00 —
18	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na	10.00 X
19	1SET	BUMEPR RETAINER RH CLIP RR	\$	na	20.00 X
20	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	10.00 X
21	1SET	BUMEPR RETAINER CLIP LH RR	\$	na	20.00 X
22	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00 X
23	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00 —
24	1	EXHAUST MOUNTING REAR	\$	su	17.82 X
25	1SET	BOOT FINISHER CLIP	\$	na	24.20 X
26	1	BOOT STICKER "Trans-cab"	\$	na	30.00 —
27	1	BOOT STICKER "6555-3333"	\$	na	30.00 —
28	1	BOOT INNER TRIM CLIP	\$	na	45.00 X
29	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00 X
30	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00 X
31	1	FENDER INNER TRIM CLIP LH	\$	na	28.00 X
32	1	FENDER INNER TRIM CLIP LH	\$	na	28.00 X
33	1	TAILLAMP CLIP RH	\$	na	5.00 —
34	1	TAILLAMP CLIP LH	\$	na	5.00 —
35	2	REAR WINDSCREEN SELANT	\$	na	80.00 X
36	1	WINDSCREEN MOULDING	\$	na	100.00 X
37	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00 X
38	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	su	385.00 X
39	1	SPARE TYRE	\$	su	330.00 X
			\$		2,787.52

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L**TOTAL PARTS \$ 54,867.64**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,400.00	1000/
Towing Fees.	\$	120.00	na X
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	na X
Putty and spray painting of the affected portion.	\$	6,000.00	1100/
To rust-proofing of the affected areas.	\$	170.00	60/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	80/
To check steering geometry and computer wheel alignment	\$	220.00	na X
To transfer of tire, rim and on wheel balancing.	\$	170.00	na X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	na X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	na X
To lift-up engine with gear box and refit.	\$	440.00	na X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>na</i> 440.00 X
To remove and refit air bag system and reset.	\$	<i>na</i> 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>na</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>na</i> 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i> 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00 X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>Gal</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>Gal</i>
To repair and realign rear exhaust pipe.	\$	170.00 } <i>Gal</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 }
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1803-251

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9730L

To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X

TOTAL	\$	18,740.00
--------------	-----------	------------------

Over All Total	\$	73,607.64
-----------------------	-----------	------------------

(LUMP SUM) Repair Days

20 DAYS

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: