

REPAIR ESTIMATE*

VEHICLE NO : SHC 8279A

DATE 29/3/2018 9:02

MAKE :

MODEL : HYUNDAI i40

QBE / LKK
LEFT FRONT

F2

Fauzy

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Mirror (LH) <i>x 1/2</i>			\$ 980.50
	<i>Front Fender (LH) x rep</i>			\$ 980.50
	<i>Front Door (LH) x rep</i>			\$ 196.10
	DISCOUNTED TOTAL			\$ 784.40
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00 Nett
	Front Door Comfort Logo (LH) ✗ ✓			\$ 75.00 Nett
	Front Door Advertisement Logo (LH) ✗			\$ 100.00 Nett
				\$ 275.00
	Labour Charge			<i>200</i>
	Panel Beating-Fender/Door			\$ 250.00
	Spray Painting Charge			\$ 600.00 <i>450</i>
	Wiring Charge			\$ 50.00 ✗
	Tuff Kote			\$ 50.00 ✗
	TOTAL LABOUR			\$ 950.00
	ESTIMATE TOTAL			\$ 2,009.40
<p><i>Katun (11/16)</i> <i>29/3/18 13 45 hrs.</i> <i>2 days.</i> <i>PIP</i> <i>After Repair photo</i></p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 				
<p>Acknowledged by Repairer</p> <p>Signature: _____ Date: _____</p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				