



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : SKK8584R
ACCIDENT DATE : 27-03-2018 19:15
THIRD PARTY REF. : SKG5427C

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SKK8584R TOYOTA WISH

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BOOT COVER / BUC	1218.45
2	1	REAR BOOT CENTRE EMBLEM / MCL	121.20
3	1	REAR BOOT VALVE EMBLEM / MCL	132.15
4	1	REAR BOOT LOCK X	371.75
5	1	REAR BOOT RUBBER / Twi	381.90
6	1	REAR END PANEL / BUC	781.45
7	1	REAR END PANEL TOP GARNISH X	374.40
8	1	REAR BUMPER / BUC	481.90
9	2	REAR BUMPER BRACKET@\$132.25 X	264.50
10	2	REAR BUMPER SIDE RETAINER LONG@\$131.10 ?	262.20
11	2	REAR BUMPER SIDE RETAINER SHORT@\$141.50 ?	283.00
12	10	REAR BUMPER CLIP@\$5.00 / MCL.	50.00
13	1	FRONT BONNET / BT	581.25
14	1	FRONT BONNET LOCK / BT	141.45
15	1	FRONT BONNET EMBLEM / MCL	132.25
16	1	FRONT BRACE PANEL / BT	141.85
17	1	FRONT GRILLE / BR	374.45
18	8	FRONT GRILLE TOP GARNISH CLIP@\$5.00 / MCL	40.00
19	2	FRONT HEADLAMP@\$1398.10	2796.20
20	1	FRONT BUMPER / BUC	481.10
21	1	FRONT BUMPER FOAM / OPA	171.10
22	1	FRONT BUMPER REINFORCEMENT X NN	289.90
23	2	FRONT BUMPER SIDE RETAINER @\$130.25 / MCL	260.50
24	10	FRONT BUMPER CLIP@\$5.00 / MCL	50.00
25	1	AIR CON CONDENSER / Cut.	972.10

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No internal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE: 27-03-2018

Acknowledged by Repairer

Signature:

Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SKK8584R
ACCIDENT DATE : 27-03-2018 19:15
THIRD PARTY REF. : SKG5427C

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
			11,155.05
		LESS 30 %	3,346.52
		TOTAL (A)	7,808.54

SPECIAL NETT ITEMS

1	1	FRONT NUMBER PLATE <i>cut</i>	30.00
2	1	REAR WINDSCREEN GUM <i>mbc</i>	40.00
		TOTAL (C)	70.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM(FRONT & REAR)	<i>30</i> 50.00
2	1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	<i>/</i> 100.00
3	1	TO REMOVE/REFIT/REFILL AIR CON GAS	<i>60</i> 80.00
4	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR)	<i>600</i> 980.00
5	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	<i>400</i> 720.00
6	1	SPRAYPAINTING CHARGES (REAR)	<i>600</i> 820.00
7	1	SPRAYPAINTING CHARGES (FRONT)	<i>400</i> 750.00

TOTAL (D)	3,500.00
ESTIMATE TOTAL	11,378.54

7 Days.

lumpsum repair.

After repair photos.

Geo Qiang - 8288 0282

24/3/18.