

ASS. REC. BY:

REF: CS/FCL18005997/Kvbhz

Special Instruction:

Sunmajor

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS

Eileen Lee

of

FCL

Date/Time:

02042018 4:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 6678R

Insured:

SH 6088R

at Workshop m/s

Cheng Hoe

Tel:

67556142

of

Blk 1019 Yishun Ind Park A #01-374

Policy No:

Claim No:

D18002574MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

03042018

H.O.D. Endorsement:

Date/Time:

02042018 4:40pm

Person Contacted:

Efeeda

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 6678R - *
	SH 6088R - CS/FCL18006165/Hlgmsdl
	MA: 01042014
4/4/18	Email preli revised to FCI
10/5	11Lm 896001 Confirm E fide (Red 3468-98, 27/5)

REF: FCI

ASSIGNMENT

From

Date:

3/4/18

Veh No:

GBC 6678R

Yr Regn:

05 13

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / ~~Heavy~~ / Taxi / Prime Mover /OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: GBC 6678R

Make:

NIS NV350

C.C.

2488

at Workshop m/s

Cheng Hwe

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

of

Blk 1019 Yishun Ind Prk A #01-374

Sp. Reading

294485

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

JN1MC24E2670000175

Policy No.

C/No:

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)


Tyre Size:

F:

195R 15X8

R:

Remark: The veh had commenced its repair at the time of inspection.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

08

days

Res.: Yes or No

D.O.A.

28/3/18

D.O.I.

2/4/18

Lump Sum:

20

%

3 Val.: Yes or No

Survey held at

✓

CA / REV / REP. / 24 HRS ^{1 up}Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/4 File sent to Catherine.

RECEIVED 10 MAY 2018

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

8

1)

☐

Final Report

Resurvey No. of Trip:

2

Survey Fee:

Date/Time, File Return to?

Transportation

2)

10/5 - typist

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

1 \$ - PS \$

3 Photos

1 Others

Report Format:

CWS

Lump Sum / I.B.I. (\$)

9600/-

TOTAL

3x15 = 45

120 + 45

50

50 + 50

32

397



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005997/Kvb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6088R	Veh. Inspected	GBC 6678R
Policy No.		Coverage (\$)	0.00
Claim No.	D18002574MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	02/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/03/2018	Inspection Date	03/04/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	29-03-2018	Our Ref No. D18002574MFSH
Accident Date	28-03-2018	Claim Type. Third Party
Insured Vehicle	SH6088R	Third Party Vehicle. GBC6678R
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	EFEEDA	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 4 April 2018 3:26 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002574MFSH/1, GBC 6678R
Attachments: GBC 6678R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBC 6678R
Date of survey: 2/4/2018
Number of days: 9 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 2 April 2018 5:14 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002574MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 2 April, 2018 4:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002574MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: D18002574MFSH

Our ref: CS/FCI18005997/Kvb

Date: 4/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBC 6678R


We thank for your instruction on 2/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 2/4/2018 at the premises of M/s CHENG HOE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$12,584.42
Revised Estimate Amount	: S\$10,904.22
"Check" Items Amount	: S\$772.80
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9435H
Vehicle Details	
Vehicle No.:	GBC6678R
Vehicle to be Exported:	No
Intended De-registration Date:	29 Mar 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 URVAN 2.5 5AT ABS AB 5DR PANEL
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	YD25320465A
Chassis No.:	JN1MC2E26Z0000175
Maximum Power Output:	-
Open Market Value:	\$31,022.00
Original Registration Date:	31 May 2013
First Registration Date:	31 May 2013
Transfer Count:	1
Actual ARF Paid:	\$1,552.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$54,111.00
COE Rebate Amount:	\$27,971.00
Total Rebate Amount:	\$27,971.00

The information contained herein is correct as at 29 Mar 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBC 6678R
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 28/03/2018

TP Veh Reg No: SH6088R

Estimate No: ES1890321/YISHUN

Date: 29 Mar 2018

Policy No: MT20172846(CN)

Veh Reg No: GBC6678R

Make/Model: NISSAN NV350 URVAN
2.5 5AT ABS AB 5DR

Chassis No: JN1MC2E26Z0000175

Engine No: YD25320465A

Reg. Date: 31/05/2013

Estimate Repair Cost to Vehicle No :GBC6678R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR BUMPER	690.60	1 PC	690.60	✓
2 REAR BUMPER CENTRE STEP PANEL	169.00	1 PC	169.00	✓
3 REAR BUMPER CLIPS	3.00	6 PCS	18.00	✓
4 REAR TAILGATE	1,742.00	1 PC	1,742.00	✓
5 TAILGATE EMBLEM (URVAN NV350)	101.30	1 PC	101.30	✓
6 TAILGATE INNER LOCK	323.10	1 PC	323.10	✓
7 TAILGATE INNER RUBBER	156.50	1 PC	156.50	50% 78.25
8 TAILGATE INNER LOCK COVER	46.10	1 PC	46.10	✓
9 TAILLAMPS	209.80	2 PCS	419.60	✓
10 REAR PANEL OUTER	246.20	1 PC	246.20	✓
11 REAR PANEL INNER	464.40	1 PC	464.40	✓
12 REAR PANEL INNER TOP CHROME MOULDING	99.10	1 PC	99.10	X
13 REAR VIEW MIRROR	172.90	1 PC	172.90	X
			4,648.80	
		Less 10%	464.88	4,183.92
Special Net				
14 REAR EXHAUST PIPE	772.80	1 PC	772.80	✓
15 REAR PANEL CENTRE INNER BRACKET	207.70	1 PC	207.70	✓
16 REVERSE SENSOR	200.00	1 SET	200.00	✓
17 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
18 TAILGATE INNER PROTECTOR	380.00	1 PC	380.00	✓
19 REAR FLOOR BOARD PROTECTOR	3,200.00	1 PC	3,200.00	✓
20 REAR 8 PAX STICKER	10.00	1 PC	10.00	✓
21 SPEED LIMIT STICKER (70KM/H)	10.00	1 PCS	10.00	✓
			4,820.50	4,820.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 28/03/2018

TP Veh Reg No: SH6088R

Estimate No: ES1890321/YISHUN

Date: 29 Mar 2018

Policy No: MT20172846(CN)

Veh Reg No: GBC6678R

Make/Model: NISSAN NV350 URVAN
2.5 5AT ABS AB 5DR

Chassis No: JN1MC2E26Z0000175

Engine No: YD25320465A

Reg. Date: 31/05/2013

Estimate Repair Cost to Vehicle No :GBC6678R

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
23 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTCHMENT, REAR GARNISH, TO CUT, WELD & RENEW REAR END PANEL, KNOCK & REPAIR REAR FLOOR BOARD PANEL, REAR LH SIDE PANEL & REALIGN THE SAME	1,500.00	1 LA	1,500.00	1300
24 PUTTY & RESPRAY ON TAILGATE, REAR SIDE PANELS, REAR FLOOR BOARD PANEL, REAR END PANEL, REAR BUMPER & REAR AFFECTED AREAS	1,400.00	1 LA	1,400.00	1100
25 REMOVE & REFIX REAR FLOOR BOARD PROTECTOR	400.00	1 LA	400.00	300
26 REMOVE & REFIX REAR EXHAUST & CHECK LEAKING	60.00	1 LA	60.00	✓
27 REMOVE & REFIX REVERSE CAMERA & CHECK SYSTEM	60.00	1 LA	60.00	✓
28 RUSTPROOFING	60.00	1 LA	60.00	✓
			3,580.00	3,580.00
			Total	S\$ 12,584.42
13,068.98			Add GST @ 7%	880.91
			Total Amount Payable	S\$ 13,465.33

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBC6678R
SUPP 1

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 28/03/2018

TP Veh Reg No: SH6088R

Estimate No: ES1890321/YISHUN

Date: 06 Apr 2018

Policy No: MT20172846(CN)

Veh Reg No: GBC6678R

Make/Model: NISSAN NV350 URVAN
2.5 5AT ABS AB 5DR

Chassis No: JN1MC2E26Z0000175

Engine No: YD25320465A

Reg. Date: 31/05/2013

Estimate Repair Cost to Vehicle No :GBC6678R

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Net Price				
1 TAILGATE HINGES	69.90	2 PCS	139.80	X
2 TAILGATE DAMPER	199.30	2 PCS	398.60	✓
			538.40	
		Less 10%	53.84	484.56
Total				S\$ 484.56
GST Amount				S\$ 33.92
Total Amount Payable				S\$ 518.48

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005997/Kvbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6088R	Veh. Inspected	GBC 6678R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002574MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	02/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JN1MC2E26Z0000175	Colour	METALLIC SILVER	
Odometer	294485	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	5 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	5 mm	
R/H Rear Tyre	195 R15X8	BRIDGESTONE	5 mm	
L/H Rear Tyre	195 R15X8	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/03/2018	Inspection Date	02/04/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 6678R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	BENT	690.60	690.60
1	REAR BUMPER CENTRE STEP PANEL (N)	BENT	169.00	169.00
6	REAR BUMPER CLIPS @\$3.00 (N)	NECESSARY	18.00	18.00
1	REAR TAILGATE (N)	BENT	1,742.00	1,742.00
1	TAILGATE EMBLEM (URVAN NV350)(N)	NECESSARY	101.30	101.30
1	TAILGATE INNER LOCK (N)	DENTED	323.10	323.10
1	TAILGATE INNER LOCK COVER (N)	DENTED	46.10	46.10
2	TAILLAMPS @\$209.80 (N)	CRACKED	419.60	419.60
1	REAR PANEL OUTER (N)	BENT	246.20	246.20
1	REAR PANEL INNER (N)	BENT	464.40	464.40
1	REAR PANEL INNER TOP CHROME MOULDING (N)	NO SUCH PARTS	99.10	-
1	REAR VIEW MIRROR (N)	SERVICEABLE	172.90	-
2	TAILGATE HINGES @\$69.90 (ADDITIONAL)(N)	TO REPAIR SEE LABOUR	139.80	-
2	TAILGATE DAMPER @\$199.30 (ADDITIONAL)(N)	PUNCTURE	398.60	398.60
	LESS 10% DISCOUNT		-503.07	-461.89
			4,527.63	4,157.01
1	TAILGATE INNER RUBBER (50%)(SN)	DENTED / CUT	156.50	78.25
	LESS 10% DISCOUNT		-15.65	-
			140.85	78.25
SPECIAL NETT ITEMS				
1	REAR EXHAUST PIPE (SN)	BENT	772.80	772.80
1	REAR PANEL CENTRE INNER BRACKET (SN)	BENT	207.70	207.70
1	SET REVERSE SENSOR (SN)	TORN	200.00	200.00
1	REAR WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
1	TAILGATE INNER PROTECTOR (SN)	NECESSARY	380.00	380.00
1	REAR FLOOR BOARD PROTECTOR (SN)	BUCKLED	3,200.00	3,200.00
1	REAR 8 PAX STICKER (SN)	NECESSARY	10.00	10.00

Report Ref No. CS/FCI18005997/Kvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPEED LIMIT STICKER (70KM/H)(SN)	NECESSARY	10.00	10.00
			4,820.50	4,820.50
	LABOUR			
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		100.00	100.00
	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, REAR GARNISH, TO CUT, WELD & RENEW REAR END PANEL, KNOCK & REPAIR REAR FLOOR BOARD PANEL, REAR LH SIDE PANEL & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF TAILGATE HINGES.		1,500.00	1,300.00
	PUTTY & RESPRAY ON TAILGATE, REAR SIDE PANELS, REAR FLOOR BOARD PANEL, REAR END PANEL, REAR BUMPER & REAR AFFECTED AREAS.		1,400.00	1,100.00
	REMOVE & REFIX REAR FLOOR BOARD PROTECTOR.		400.00	300.00
	REMOVE & REFIX REAR EXHAUST & CHECK LEAKING.		60.00	60.00
	REMOVE & REFIX REVERSE CAMERA & CHECK SYSTEM.		60.00	60.00
	RUSTPROOFING.		60.00	60.00
			3,580.00	2,980.00
	GRAND TOTAL		13,068.98	12,035.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,600.00

Report Ref No. CS/FCI18005997/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.