

ASE REC. BY:

REF: CS/C7U18005998/Kqbs²

Special Instruction:

Surveyor
Mumma

Kenneth

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

02042018 14:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 3743M

Insured:

GBC 6676X

at Workshop m/s

Ah Lim Motor

Tel:

6483 1244

of

Bk 10 MK Ind Park 2A #D1-09

Policy No:

DMCRN3091611700

Claim No:

SNM18D0165200

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28032018

CA / REV / REP. / REV 24 HRS 'wp'

03042018

H.O.D. Endorsement:

Date/Time:

02042018 5pm

Person Contacted:

Zia

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 3743M - X
	GBC 6676X - NA / CTL18005998/13
	DXA : 02042018
	Kenneth finalised final Ag B 9581.62 (Red \$ 5267.04, 35%.)
	no lump sum.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18005998/Kqb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-04-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 6676X	Veh. Inspected	SLQ 3743M
Policy No.	DMCVSN3091611700	Coverage (\$)	0.00
Claim No.	SNM18D01652C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/03/2018	Inspection Date	03/04/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

You are returning to a previous page. This page may be outdated.
Please click 'Refresh' to refresh the page.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2018		02 Apr 2018 16:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S KIAN ANN ENTERPRISE PTE LTD, Co. Reg. No.: 199803657H								
Main Claimant:	THAM RUOH YI, ID: S6923437B								
Vehicle Reg. No.:	SLQ3743M	Date of Loss:	28/03/2018 09:00 - :59						
Claim Type:	TP / SNM18D01652C02	Policy/Cover Note No.:	DMCVSN3091611700 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBC6676X	Policy No. (Claimant):	GA241695/1						
		Excess:	S\$0.00						
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/04/2018]								
Driver/Custodian (Insured):	RAMARAJ KRISHNA UDAIYAPPAN (41 / Male), NRIC: G7799181L, Tel: +6584183802								
Adj Asg. Remarks:	EST \$15,876.07 , ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
☐ ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/03/2018 15:33
Date Of Accident	28/03/2018 09:50
Exact Location Of Accident	CTE SLIP RD TO PIE (CHANGI)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ3743M
Insured/Policyholder	
Name Of Registered Owner	THAM RUOH YI
NRIC No	S6923437B
Email Address	RUOHYI_THAM@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91807796
Alternative Phone No	OTHERS-96625468
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	GOLF GTI-2.0 L 5DR 5K19V3 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA241695/1
Cover Note Number	11/07/2017 - 1507/2018

Driver

Name of Driver	HO YEOW VONG
NRIC No	S6916283E
Date Of Birth	14/05/1969
Occupation	INDOOR
Date Of Driving Pass	09/06/1994
Driving Experience	23 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96625468
Fax Number	
Contact Number	OTHERS-91807796
EEmail Address	DEHO2004@YAHOO.COM

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name HO YEOW VONG

Approximate Age

Injuries Sustain NECK & BACK

Injured person in which vehicle? SLQ3743M

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO


Address

Postcode

Sketch Plan Pg. 2

Date of accident: 28/3/2018 Time: 0950 hrs Location: CTE Slip road to PIE (Changi)
 My Vehicle A: SLG 3743M Vehicle B: GBC 6676 X Vehicle C: XD 2230 J

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On this date (28-3-2018) at around 0950hrs, I was driving along slip road of CTE to the direction of PIE (Changi). Traffic was heavy. I hear one loud bang behind. Not long after, pick-up truck (GBC 6676X) bang into my car. Ferry (XD 2230J) bang into pick-up (GBC 6676X) which then bang into my car.

(Photos & car-camera video available)

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address : deho2004@yahoo.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

X [Signature]

Policyholder's Signature

Date & Time:

X [Signature]

Driver's Signature

(if driver is not the policyholder)

Date & Time:



Reporting Centre / Ah Lim Motor's Signature

Name:

NRIC/FIN No.:

707 0000000000000000


Sketch Plan Pg. 4



9662546B -

D/C
 buying - drive
 Heck 3 back.
 YES camera
 199x.

S 6923437B
 G1807796



Sketch Plan Pg. 6



redefining / insurance

Date: 28/07/18

To: Owner of Vehicle Number: SLQ371BN1

The following has been advised to you via your workshop, Ah Lim Motor Company through their staff, Zila Eileen / Mui Hong.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☒ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☐ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

☒ Others claim Third Party

Signed and acknowledge by:

☒ [Signature]
Name and signature of policyholder/authorised driver

W/H
Name and signature of workshop personnel including company stamp



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3437B

Vehicle Details

Vehicle No.: SLQ3743M
Vehicle to be Exported: No
Intended De-registration Date: 28 Mar 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: GOLF GTI 2.0L AT 5DR 5K19V3
Primary Colour: Black
Manufacturing Year: 2011
Engine No.: CCZ215172
Chassis No.: WVVZZZ1KZCW178726
Maximum Power Output: 155.0 kW (207 bhp)
Open Market Value: \$35,321.00
Original Registration Date: 16 Jan 2012
First Registration Date: 16 Jan 2012
Transfer Count: 1
Actual ARF Paid: \$35,321.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Jan 2022
PARF Rebate Amount: \$22,958.00

Intended COE Rebate Details

COE Expiry Date: 15 Jan 2022
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$63,600.00
COE Rebate Amount: \$24,157.00
Total Rebate Amount: \$47,115.00

The information contained herein is correct as at 28 Mar 2018

OK

30	RECORDING CAMERA - CHECK PRICE	1 PC		0.00	? KSV
31	NUMBER PLATE	1 PC	cm	35.00	✓
32	INNER SEAL	1 PC	re	20.00	✓
33	WINDSCREEN SEALANT	1 PC	re	40.00	✓



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : THAM RUOH YI
32 MAYFLOWER CRESCENT

SINGAPORE 568841

TEL: 96625468

ATTN:

Estimate No: MC0912969
Date: 28 Mar 2018
Policy No: GA241695/1
Veh Reg No: SLQ3743M
Make/Model: VOLKSWAGEN GOLF
GTI 2.0L AT 5DR

Your Ref No: SLQ3743M
Claim Type: Third Party
Accident Date: 28/03/2018
TP Veh Reg No: GBC6676X

Estimate Repair Cost to Vehicle No :SLQ3743M

Description	Quantity	List Price	Amount
			SS
		95.00	95.00
LABOUR			
34 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
35 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
36 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	120.00	601
37 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	80.00	501
38 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	601
39 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	601
40 TO RESET REVERSE SENSOR	1 PC	180.00	7xnn
41 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	120.00	601
42 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL, TAILAMP PANEL LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,400.00	8001
43 TO SPRAY TAILGATE,RR BUMPER,END PANEL,SPARE TYRE PANEL,TAILAMP PANEL LH & RH.	1 PC	1,200.00	8001
		3,420.00	3,420.00
Total			SS 14,837.45
Add GST @ 7%			1,038.62
Total Amount Payable			SS 15,876.07

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND EIGHT HUNDRED SEVENTY SIX AND CENTS SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

14938.65



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : THAM RUOH YI
32 MAYFLOWER CRESCENT

SINGAPORE 568841
TEL: 96625468
ATTN:

Estimate No: MC0912969
Date: 28 Mar 2018
Policy No: GA241695/1
Veh Reg No: SLQ3743M
Make/Model: VOLKSWAGEN GOLF
GTI 2.0L AT 5DR

Kenut

Your Ref No: SLQ3743M
Claim Type: Third Party - *china taiping*
Accident Date: 28/03/2018
TP Veh Reg No: GBC6676X

car in workshop

Not Notarized PBP 1.30 pm
Runny B & pain
7 days

Estimate Repair Cost to Vehicle No :SLQ3743M

Description	Quantity	List Price SS	Amount SS
SPARE PARTS			
1 REAR WINDSCREEN	1 PC	1,001.95	✓
2 TAILGATE	1 PC	1,903.15	✓
3 TAILGATE-HINGE-LH-&RH	2 PC	251.90	X
4 TAILGATE-EMBLEM	1 PC	101.05	X
5 TAILGATE GTI LOGO	1 PC	100.50	✓
6 TAILGATE LAMP LH & RH	2 PC	1,095.50	✓
7 TAILGATE INNER LOCK	1 PC	188.10	✓
8 TAILGATE RUBBER	1 PC	323.85	50% ✓
9 TAILGATE INNER TRIMBOARD TOP	1 PC	194.15	X
10 TAILGATE INNER TRIMBOARD LOWER	1 PC	289.30	✓
11 TAILGATE LOCK-STRIKER	1 PC	98.45	X
12 TAILGATE WIPER BLADE	1 PC	33.80	X
13 TAILGATE WIPER ARM	1 PC	67.05	X
14 TAILGATE WIPER MOTOR	1 PC	387.35	X
15 TAIL LAMP LH & RH	2 PC	1,147.50	X
16 TAIL LAMP LOWER BEAM LH & RH	2 PC	93.60	X
17 REAR BUMPER	1 PC	1,362.45	✓
18 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	93.50	✓
19 REAR BUMPER CLIPS	15 PC	37.50	✓
20 REAR BUMPER LOWER SPOILER	1 PC	438.25	✓
21 REAR BUMPER NO PLATE LAMP LH & RH	2 PC	160.30	✓
22 REAR BUMPER REVERSE SENSOR	1 PC	779.00	✓
23 REAR BUMPER REVERSE SENSOR HOLDER	4 PC	129.00	✓
24 REAR BUMPER REINFORCEMENT	1 PC	606.05	✓
25 REAR BUMPER SPONGE	1 PC	112.48	X
26 REAR BUMPER REFLECTOR LH & RH	2 PC	113.90	X
27 REAR END PANEL (ASSY)	1 PC	970.80	✓
28 REAR END PANEL TOP GARNISH	1 PC	161.05	✓
29 SPARE TYRE PANEL TOP COVER	1 PC	339.15	X
		12,580.50	
Less 10%		1,258.05	11,322.45
Special Nett			
30 RECORDING CAMERA CHECK PRICE	1 PC	0.00	X
31 NUMBER PLATE	1 PC	35.00	✓
32 INNER SEAL	1 PC	20.00	✓
33 WINDSCREEN SEALANT	1 PC	40.00	✓





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : THAM RUOH YI
32 MAYFLOWER CRESCENT

SINGAPORE 568841
TEL: 96625468
ATTN:

Estimate No: MC0912969
Date: 09 Apr 2018
Policy No: GA241695/1
Veh Reg No: SLQ3743M
Make/Model: VOLKSWAGEN GOLF
GTI 2.0L AT 5DR

Your Ref No: SNM18D01652
Claim Type: Third Party
Accident Date: 28/03/2018
TP Veh Reg No: GBC6676X

Estimate Repair Cost to Vehicle No :SLQ3743M

Description	Quantity	List Price S\$	Amount S\$
Supplementary Parts to Repair			
SPARE PARTS			
1 REAR BUMPER CENTRE BRACKET	CM 1 PC	112.45	✓
		112.45	
	Less 10%	11.25	101.21
		Total	S\$ 101.21
		GST Amount	S\$ 7.08
		Total Amount Payable	S\$ 108.29

*Photo Taken by Simon 9/4/18
Cancel this Booklet*

The above vehicle was surveyed by KENNETH KONG -LKK on 03/04/2018

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : THAM RUOH YI
32 MAYFLOWER CRESCENT

SINGAPORE 568841
TEL: 96625468
ATTN:

Estimate No: MC0912969
Date: 28 Mar 2018
Policy No: GA241695/1
Veh Reg No: SLQ3743M
Make/Model: VOLKSWAGEN GOLF
GTI 2.0L AT 5DR

Your Ref No: SLQ3743M
Claim Type: Third Party
Accident Date: 28/03/2018
TP Veh Reg No: GBC6676X

Estimate Repair Cost to Vehicle No :SLQ3743M

Description	Quantity	List Price	Amount
		SS	SS
LABOUR		95.00	95.00
34 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
35 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
36 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	120.00	601
37 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	80.00	501
38 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	601
39 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	601
40 TO RESET REVERSE SENSOR	1 PC	180.00	✓
41 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	120.00	601
42 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, TAILAMP PANEL LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,400.00	8001
43 TO SPRAY TAILGATE, RR BUMPER, END PANEL, SPARE TYRE PANEL, TAILAMP PANEL LH & RH.	1 PC	1,200.00	8001
		3,420.00	3,420.00
		Total	SS 14,837.45
		Add GST @ 7%	1,038.62
		Total Amount Payable	SS 15,876.07

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND EIGHT HUNDRED SEVENTY SIX AND CENTS SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before either spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singapore.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : THAM RUOH YI
32 MAYFLOWER CRESCENT

SINGAPORE 568841

TEL: 96625468

ATTN:

Claim No: MC0912969
No: MF0911089
Date: 01 Jun 2018
Policy No: GA241695/1
Veh Reg No: SLQ3743M
Make/Model: VOLKSWAGEN GOLF
GTI 2.0L AT 5DR

Your Ref No: SNM18D01652

Claim Type: Third Party

Accident Date: 28/03/2018

TP Veh Reg No: GBC6676X

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLQ3743M

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR WINDSCREEN	1 PC	1,001.95	
2 TAILGATE	1 PC	1,903.15	
3 TAILGATE GTI LOGO	1 PC	100.50	
4 TAILGATE LAMP RH	1 PC	547.75	
5 TAILGATE INNER LOCK	1 PC	188.10	
6 TAILGATE RUBBER (50% OF 323.85)	1 PC	161.93	
7 TAILGATE INNER TRIMBOARD LOWER	1 PC	289.30	
8 REAR BUMPER	1 PC	1,362.45	
9 REAR BUMPER CLIPS	15 PC	37.50	
10 REAR BUMPER LOWER SPOILER	1 PC	438.25	
11 REAR BUMPER NO PLATE LAMP RH	1 PC	80.15	
12 REAR BUMPER REVERSE SENSOR	1 PC	194.75	
13 REAR BUMPER REVERSE SENSOR HOLDER	4 PC	129.00	
14 REAR BUMPER REINFORCEMENT	1 PC	606.05	
15 REAR END PANEL (ASSY)	1 PC	970.80	
16 REAR END PANEL TOP GARNISH	1 PC	161.05	
17 REAR BUMPER CENTRE BRACKET	1 PC	112.45	
		8,285.13	
	Less 10%	828.51	7,456.62
Special Nett			
18 NUMBER PLATE	1 PC	35.00	
19 INNER SEAL	1 PC	20.00	
20 WINDSCREEN SEALANT	1 PC	40.00	
		95.00	95.00
LABOUR			
21 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
22 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
23 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	60.00	
24 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	50.00	
25 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	
26 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : THAM RUOH YI
32 MAYFLOWER CRESCENT

SINGAPORE 568841
TEL: 96625468
ATTN:

Claim No: MC0912969
No: MF0911089
Date: 01 Jun 2018
Policy No: GA241695/1
Veh Reg No: SLQ3743M
Make/Model: VOLKSWAGEN GOLF
GTI 2.0L AT 5DR

Your Ref No: SNM18D01652
Claim Type: Third Party
Accident Date: 28/03/2018
TP Veh Reg No: GBC6676X

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLQ3743M

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
27 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
28 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL, TAILAMP PANEL LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	
29 TO SPRAY TAILGATE,RR BUMPER,END PANEL,SPARE TYRE PANEL,TAILAMP PANEL LH & RH.	1 PC	800.00	
		2,030.00	2,030.00
		Total	S\$ 9,581.62 ✓/k
		Less Excess	S\$ 0.00
		Amount Before GST	S\$ 9,581.62
		Add GST @ 7%	670.71
		Total Amount Payable	S\$ 10,252.33

TOTAL: SINGAPORE DOLLAR TEN THOUSAND TWO HUNDRED FIFTY TWO AND CENTS THIRTY THREE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 03/04/2018

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	29 Mar 2018		02 Apr 2018 16:43 Edit Adj Rpt	S\$9,581.62 Edit Estimates	S\$9,581.62 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S KIAN ANN ENTERPRISE PTE LTD , Co. Reg. No.: 199803657H		
Main Claimant:	THAM RUOH YI , ID: S6923437B		
Vehicle Reg. No.:	SLQ3743M	Date of Loss:	28/03/2018 09:00 - :59 [74 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01652C02	Policy/Cover Note No.:	DMCVSN3091611700 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC6676X	Policy No. (Claimant):	GA241695/1
		Excess:	S\$0.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/04/2018]		
Driver/Custodian (Insured):	RAMARAJ KRISHNA UDAIYAPPAN (41 / Male), NRIC: G7799181L, Tel: +6584183802		
Adj. Asg. Remarks:	EST \$15,876.07 , ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ3743M (SNM18D01652C02)
[GBC6676X]
TP
THAM RUOH YI
Mar 28 2018 9:00AM
[M/S KIAN ANN ENTERPRISE PTE LTD]
Ah Lim Motor Company

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Video			1 per page ▼	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	28/03/18 15:45	Video - Accident [Linked Accident Report Documents]	 Load MP4	☐
2	28/03/18 15:45	Video - Accident [Linked Accident Report Documents]	 Load MP4	☐
Assessment Reports			1 per page ▼	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	28/03/18 16:39	Accident Statement	 Load HTM	☐
Photos/Images			3 per page ▼	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
11	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
12	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
13	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
14	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
15	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
16	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
17	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
18	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
19	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
20	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒

Video					
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
21	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
22	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
23	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
24	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
25	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
26	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
27	28/03/18 15:44	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
28	28/03/18 15:44	Driving License [Linked Accident Report Documents]	1	Load JPG	✓
29	28/03/18 15:44	Driving License [Linked Accident Report Documents]	1	Load JPG	✓
30	28/03/18 15:44	Driving License [Linked Accident Report Documents]	1	Load JPG	✓
31	28/03/18 15:44	Driving License [Linked Accident Report Documents]	1	Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/06/18 16:13	General View	1	Load JPG	✓
2	12/06/18 16:13	General View	1	Load JPG	✓
3	12/06/18 16:13	General View	1	Load JPG	✓
4	12/06/18 16:13	General View	1	Load JPG	✓
5	12/06/18 16:13	General View	1	Load JPG	✓
6	12/06/18 16:13	General View	1	Load JPG	✓
7	12/06/18 16:13	General View	1	Load JPG	✓
8	12/06/18 16:13	General View	1	Load JPG	✓
9	12/06/18 16:13	General View	1	Load JPG	✓
10	12/06/18 16:13	General View	1	Load JPG	✓
11	12/06/18 16:13	General View	1	Load JPG	✓
12	12/06/18 16:13	General View	1	Load JPG	✓
13	12/06/18 16:13	General View	1	Load JPG	✓
14	12/06/18 16:13	General View	1	Load JPG	✓
15	12/06/18 16:13	General View	1	Load JPG	✓
16	12/06/18 16:13	General View	1	Load JPG	✓
17	12/06/18 16:13	General View	1	Load JPG	✓
18	12/06/18 16:13	General View	1	Load JPG	✓
19	12/06/18 16:13	Odometer Reading	1	Load JPG	✓
20	12/06/18 16:13	Chassis Number	1	Load JPG	✓
21	12/06/18 16:15	Reinspection Photo	1	Load JPG	✓
22	12/06/18 16:15	Reinspection Photo	1	Load JPG	✓
23	12/06/18 16:15	Reinspection Photo	1	Load JPG	✓
24	12/06/18 16:15	Reinspection Photo	1	Load JPG	✓
25	12/06/18 16:15	Reinspection Photo	1	Load JPG	✓
26	12/06/18 16:15	Reinspection Photo	1	Load JPG	✓
27	12/06/18 16:15	Reinspection Photo	1	Load JPG	✓
Documentation			1 per page		
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/04/18 16:42	REPAIR EST	1	Load PDF	
2	02/04/18 16:43	OI GIA REPORT	1	Load PDF	
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print

Video				☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	28/03/18 16:39	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 15:52	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser	☒
No	Finalized On	Ah Lim Motor Company (AMK)	1 per page	Thumbnail	Print
1	28/03/18 15:45	Video - Accident	 Load MP4		
2	28/03/18 15:45	Video - Accident	 Load MP4		
Assessment Reports			1 per page	Thumbnail	Print
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print	
1	28/03/18 16:39	Accident Statement	 Load HTM		
Photos/Images			3 per page	Thumbnail	Print
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print	
1	28/03/18 15:44	Accident Photo	 Load JPG	☒	
2	28/03/18 15:44	Accident Photo	 Load JPG	☒	
3	28/03/18 15:44	Accident Photo	 Load JPG	☒	
4	28/03/18 15:44	Accident Photo	 Load JPG	☒	
5	28/03/18 15:44	Accident Photo	 Load JPG	☒	
6	28/03/18 15:44	Accident Photo	 Load JPG	☒	
7	28/03/18 15:44	Accident Photo	 Load JPG	☒	
8	28/03/18 15:44	Accident Photo	 Load JPG	☒	
9	28/03/18 15:44	Accident Photo	 Load JPG	☒	
10	28/03/18 15:44	Accident Photo	 Load JPG	☒	
11	28/03/18 15:44	Accident Photo	 Load JPG	☒	
12	28/03/18 15:44	Accident Photo	 Load JPG	☒	
13	28/03/18 15:44	Accident Photo	 Load JPG	☒	
14	28/03/18 15:44	Accident Photo	 Load JPG	☒	
15	28/03/18 15:44	Accident Photo	 Load JPG	☒	
16	28/03/18 15:44	Accident Photo	 Load JPG	☒	
17	28/03/18 15:44	Accident Photo	 Load JPG	☒	
18	28/03/18 15:44	Accident Photo	 Load JPG	☒	
19	28/03/18 15:44	Accident Photo	 Load JPG	☒	
20	28/03/18 15:44	Accident Photo	 Load JPG	☒	
21	28/03/18 15:44	Accident Photo	 Load JPG	☒	
22	28/03/18 15:44	Accident Photo	 Load JPG	☒	
23	28/03/18 15:44	Accident Photo	 Load JPG	☒	
24	28/03/18 15:44	Accident Photo	 Load JPG	☒	
25	28/03/18 15:44	Accident Photo	 Load JPG	☒	
26	28/03/18 15:44	Accident Photo	 Load JPG	☒	
27	28/03/18 15:44	Accident Photo	 Load JPG	☒	
28	28/03/18 15:44	Driving License	 Load JPG	☒	
29	28/03/18 15:44	Driving License	 Load JPG	☒	
30	28/03/18 15:44	Driving License	 Load JPG	☒	
31	28/03/18 15:44	Driving License	 Load JPG	☒	

Video				☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	28/03/18 16:39	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18005998/KQBS2
Date: 21/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. **Policy No:** DMCVSN3091611700
Claimant Vehicle No : SLQ3743M **Insured Vehicle No :** GBC6676X
Date of Loss: 28/03/2018 **Nature of Claim:** TP **Claim No:** SNM18D01652C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ3743M
Make & Model: VOLKSWAGEN GOLF GTI, 2.0 L 5DR 5K19V3 (A) **Engine No:** CCZ215172
Reg. Date: 16/01/2012 (Man. Year: 2011) **Chassis No:** WVVZZZ1KZCW178726
Colour: Metallic Black **Odometer:** 86168 km
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 225/40R18 **Rear Tyre Size:** 225/40R18
Front Left Side: Pirelli 5 mm **Rear Left Side:** Pirelli 5 mm
Front Right Side: Pirelli 5 mm **Rear Right Side:** Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,518.65	7,551.62	3,967.03	34.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	2,030.00	1,390.00	40.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,938.65	9,581.62	5,357.03	35.86
+ GST 7.00/7.00% (S\$)	1,045.71	670.71	375.00	35.86
Nett Amount (S\$)	15,984.36	10,252.33	5,732.03	35.86

INSPECTION

Date of Assignment: 02/04/2018
Date Inspected: 03/04/2018 **Inspected At:** Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
 Autopoint
 Singapore 568047
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_print&caseid=696720&extid=268603&CFID=35874992&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jun 2018)

Parts: 144 VOLKSWAGEN GOLF GTI 2.0 L 5DR 5K19V3 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ3743M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	1,001.95 FL	*1,001.95 FL
2	1		*TAILGATE	Bent	1,903.15 FL	*1,903.15 FL
3	2		*TAILGATE HINGE LH & RH	Repair	251.90 FL	*- FL
4	1		*TAILGATE EMBLEM	Not Necessary	101.05 FL	*- FL
5	1		*TAILGATE GTI LOGO	Necessary	100.50 FL	*100.50 FL
6	1		*TAILGATE LAMP LH & RH	N/s Serviceable / O/s Cut	1,095.50 FL	*547.75 FL
7	1		*TAILGATE INNER LOCK	Dented	188.10 FL	*188.10 FL
8	1		*TAILGATE RUBBER (50%)	Distorted / Dented	323.85 FL	*161.93 FL
9	1		*TAILGATE INNER TRIMBOARD TOP	Serviceable	194.15 FL	*- FL
10	1		*TAILGATE INNER TRIMBOARD LOWER	Cut	289.30 FL	*289.30 FL
11	1		*TAILGATE LOCK STRIKER	Repair	98.45 FL	*- FL
12	1		*TAILGATE WIPER BLADE	Serviceable	33.80 FL	*- FL
13	1		*TAILGATE WIPER ARM	Serviceable	67.05 FL	*- FL
14	1		*TAILGATE WIPER MOTOR	Serviceable	387.35 FL	*- FL
15	2		*TAILLAMP LH & RH	Serviceable	1,147.50 FL	*- FL
16	2		*TAILLAMP LOWER BEAM LH & RH	Repair	93.50 FL	*- FL
17	1		*REAR BUMPER	Buckled	1,362.45 FL	*1,362.45 FL
18	2		*REAR BUMPER SIDE RETAINERS LH & RH	Serviceable	93.50 FL	*- FL
19	15		*REAR BUMPER CLIPS	Necessary	37.50 FL	*37.50 FL
20	1		*REAR BUMPER LOWER SPOILER	Dented	438.25 FL	*438.25 FL
21	1		*REAR BUMPER NO PLATE LAMP LH & RH	O/s Cracked	160.30 FL	*80.15 FL
22	1		*REAR BUMPER REVERSE SENSOR	Shorted 1pc Only	779.00 FL	*194.75 FL
		4pcs				
23	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	129.00 FL	*129.00 FL
24	1		*REAR BUMPER REINFORCEMENT	Buckled	606.05 FL	*606.05 FL
25	1		*REAR BUMPER SPONGE	Serviceable	112.45 FL	*- FL
26	2		*REAR BUMPER REFLECTOR LH & RH	Serviceable	113.90 FL	*- FL
27	1		*REAR END PANEL (ASSY)	Bent	970.80 FL	*970.80 FL
28	1		*REAR END PANEL TOP GARNISH	Dented	161.05 FL	*161.05 FL
29	1		*SPARE TYRE PANEL TOP COVER	Serviceable	339.15 FL	*- FL
30	1		*RECORDING CAMERA (NPA)	Serviceable	0.00 FS	*- FS
31	1		*NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
32	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
33	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
34	1		*REAR BUMPER CENTRE BRACKET	Cracked	112.45 FL	*112.45 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	12,787.95	8,380.13
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,269.30	828.51
Total Parts (\$\$)	11,518.65	7,551.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
2	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR WINDSCREEN.	New	120.00	120.00
3	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH,, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	120.00	60.00
4	TO REMOVE & REINSTALL / REPLACE REVERSE CAMERA.	New	80.00	50.00
5	TO REMOVE AND REINSTALL / REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	New	80.00	60.00
6	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR BUMPER SENSORS.	New	80.00	60.00
7	TO RESET REVERSE SENSOR.	New	180.00	0.00
8	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	New	120.00	60.00
9	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, TAILLAMP PANEL LH & RH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	1,400.00	800.00
10	TO SPRAY TAILGATE, RR BUMPER, END PANEL, SPARE TYRE PANEL, TAILLAMP PANEL LH & RH.	New	1,200.00	800.00
Gross Labour Cost (\$\$)			3,420.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >