

AS REC. BY:

REF:

CS/MSG/18006002/Kgb¹²

Special Instruction:

SURVEYOR

ASSIGNMENT (Office)

MURPHY

From (Person):

Chnia Nyuk Pui

of

MSLH

Date/Time:

02042018 328pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GIBD 3753X

Insured:

SJP 6285C

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142.

of

Bk 7019 Yishun Ind Park A

Tel: 701-374

Policy No:

A28866395QMY

Claim No:

593940

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28032018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

02042018 4:09pm

Person Contacted:

Efeeda

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GIBD 3753X - X

SJP 6285C - CS/MSG/18001066/Gvt

D.O.A. = 150111

10/5 @ 4329.68 Confirmed Efeeda (Red 5250, 5%)

2/17/5

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

19 PM PCS to Catherine

RECEIVED 18 MAY 2018

Date/Time, File Pass to?

1) 18/5 11:45 AM

Date/Time, File Return to?

2) _____

☐

: Prell. Report

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

MER-TP

4329.68

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Veh No: _____

GBD3753X

Yr Regn: _____

09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Toy

Dyna

C.C.

2982

Colour: _____

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading: _____

104848

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

KD Y 231 - 801805

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A / Rim or

Tyre Size: _____

R: 195R15 X8

R: Yokohama 155R13 X8 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. _____

3

mm

L/Bal. _____

3

mm

D.O.A. _____

28/3/18

Rear

R/Bal. _____

22

mm

L/Bal. _____

22

mm

D.O.I. _____

4/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

150

10

160



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18006002/Kqb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 02-04-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJP 6285C	Veh. Inspected	GBD 3753X	
Policy No.	A28866395QMY	Coverage (\$)	0.00	
Claim No.	553940	Excess (\$)	0.00	
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	02/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/03/2018	Inspection Date		
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 10 Apr 2018

Preliminary Advice

Insured Vehicle No	: SJP6285C	Accident Date	: 28/03/2018
TP Vehicle No	: GBD3753X	Assignment Date	: 02/04/2018
Make	: TOYOTA DYNA	Est. Duration of Repair	: 5.00
Date of Inspection	: 04/04/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,261.68
Revised Amount	:S\$	3,491.78
Check Items (Estimated)	:S\$	519.90
Total	:S\$	4,011.68

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2018		02 Apr 2018 15:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

TAN WAH BEE, ID: S7318790G, Tel: +6594775123, Email: NOEMAIL

Main Claimant:

BAN SENG ENGINEERING PTE LTD, Co. Reg. No.: 200913401G

Vehicle Reg. No.:

GBD3753X

Date of Loss:

28/03/2018 17:00 - :59

Claim Type:

TP / 553940

Policy/Cover Note No.:

A28866395QMY (Comprehensive)
Coverage: 16/12/2017 - 30/03/2018

Vehicle Reg. No. (Insured):

SJP6285C

Policy No. (Claimant):

Excess:

S\$500.00

Repairer:

Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/04/2018]

Driver/Custodian (Insured):

TAN WAH BEE (44 / Male), NRIC: S7318790G, Tel: +6594775123

Adj Asg. Remarks:

W/s wld like Mr Kenneth Kong to survey the vehicle.

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3401G
Vehicle Details	
Vehicle No.:	GBD3753X
Vehicle to be Exported:	No
Intended De-registration Date:	29 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2433464
Chassis No.:	KDY2318016805
Maximum Power Output:	-
Open Market Value:	\$33,926.00
Original Registration Date:	25 Sep 2014
First Registration Date:	25 Sep 2014
Transfer Count:	1
Actual ARF Paid:	\$1,697.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$52,010.00
COE Rebate Amount:	\$34,227.00
Total Rebate Amount:	\$34,227.00

The information contained herein is correct as at 29 Mar 2018

OK



Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBD3753X
 TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402
 ATTN: Motor Claim Department

Estimate No: ES1890322/YISHUN
 Date: 02 Apr 2018
 Policy No: DMCV18S001958
 Veh Reg No: GBD3753X
 Make/Model: TOYOTA DYNA 3.0
 DIESEL TURBO M/T
 2WD LORRY

WS Ref: TP/MSIG/YS
 Claim Type: Third Party
 Accident Date: 28/03/2018
 TP Veh Reg No: SJP6285C

Chassis No: KDY2318016805
 Engine No: 1KD2433464
 Reg. Date: 25/09/2014

Estimate Repair Cost to Vehicle No :GBD3753X

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 TAILLAMPS	222.70	2 PCS	445.40	✓
2 LH TAILLAMP PANEL	101.80	1 PC	101.80	✓
3 REAR NUMBER PLATE PANEL	204.50	1 PC	204.50	✓
4 REAR EXHAUST PIPE	693.20	1 PC	693.20	✓
5 REAR LH TOOL BOX	649.20	1 PC	649.20	✓
6 TAILGATE STICKER (DYNA)	22.80	1 PC	22.80	✓
7 REAR TAILGATE	1,392.00	1 PC	1,392.00	✓
			3,508.90	
		Less 25%	877.23	2,631.68
Special Net				
8 TAILGATE STICKER (1500 KG)	25.00	1 PC	25.00	✓
9 REAR NUMBER PLATE	25.00	1 PC	25.00	✓
10 SPEED LIMIT STICKER (70KM/H)	10.00	1 PC	10.00	✓
11 REAR 13 PAX STICKER	10.00	1 PC	10.00	✓
12 REVERSE SENSOR	200.00	1 SET	200.00	✓
			270.00	270.00
Labour				
13 REMOVE & REFIX TAILLAMPS,REAR NUMBER PLATE,TAILGATE,STRAIGHEN,KNOCK & REPAIR TAILGATE LH LOWER MEMBER,RH TAILLAMP PANEL,TAILGATE LOWER PANEL & REALIGN THE SAME	700.00	1 LA	700.00	550
14 REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	60.00	1 LA	60.00	✓
15 PUTTY & RESPRAY ON TAILLAMP PANELS,REAR NUMBER PLATE PANEL,TAILGATE,TAILGATE LOWER PANEL & REAR AFFECTED AREAS	600.00	1 LA	600.00	500
			1,360.00	1,360.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Total S\$ 4,261.68
 Add GST @ 7% 298.32
 Total Amount Payable S\$ 4,560.00

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

4579.68

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBD3753X

SUPP 1

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES1890322/YISHUN

Date: 06 Apr 2018

Policy No: DMCV18S001958

Veh Reg No: GBD3753X

Make/Model: TOYOTA DYNA 3.0
DIESEL TURBO M/T
2WD LORRY

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 28/03/2018

TP Veh Reg No: SJP6285C

Chassis No: KDY2318016805

Engine No: 1KD2433464

Reg. Date: 25/09/2014

Estimate Repair Cost to Vehicle No :GBD3753X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 REAR TOOL BOX BRACKETS	212.00	2 PCS	424.00	
			424.00	
		Less 25%	106.00	318.00
			Total	S\$ 318.00
			GST Amount	S\$ 22.26
			Total Amount Payable	S\$ 340.26

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006002/KQBN2

Date: 18/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28866395QMY
Claimant Vehicle No :	GBD3753X	Insured Vehicle No :	SJP6285C
Date of Loss:	28/03/2018	Nature of Claim:	TP
		Claim No:	553940

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD3753X	Engine No:	1KD2433464
Make & Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Chassis No:	KDY2318016805
Reg. Date:	25/09/2014 (Man. Year: 2014)	Odometer:	104848 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R13X8 (D)
Front Left Side:	Condor 3 mm	Rear Left Side:	Yokohama 2/2 mm
Front Right Side:	Condor 3 mm	Rear Right Side:	Yokohama 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,219.67	3,219.67	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	1,110.00	250.00	18.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,579.67	4,329.67	250.00	5.46
+ GST 7.00/7.00% (\$\$)	320.58	303.08	17.50	5.46
Nett Amount (\$\$)	4,900.25	4,632.75	267.50	5.46

INSPECTION

Date of Assignment:	02/04/2018	
Date Inspected:	04/04/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents-Finalise amount: \$4329.68

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 May 2018)	
Parts:	N/A	TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD3753X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAILLAMPS	O/s Cracked/N/s Broken	445.40 FL	*445.40 FL
2	1		*LH TAILLAMP PANEL	Bent	101.80 FL	*101.80 FL
3	1		*REAR NUMBER PLATE PANEL	Distorted	204.50 FL	*204.50 FL
4	1		*REAR EXHAUST PIPE	Bent	693.20 FL	*693.20 FL
5	1		*REAR LH TOOL BOX	Bent	649.20 FL	*649.20 FL
6	1		*TAILGATE STICKER (DYNA)	Necessary	22.80 FL	*22.80 FL
7	1		*REAR TAILGATE	Bent	1,392.00 FL	*1,392.00 FL
8	1		*TAILGATE STICKER (1500 KG)	Necessary	25.00 FS	*25.00 FS
9	1		*REAR NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
10	1		*SPEED LIMIT STICKER (70KM/H)	Necessary	10.00 FS	*10.00 FS
11	1		*REAR 13 PAX STICKER	Necessary	10.00 FS	*10.00 FS
12	1		*SET REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
13	2		*REAR TOOL BOX BRACKETS	Bent/Distorted	424.00 FL	*424.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,202.90	4,202.90
- List Item Discount on L Items 25.00/25.00% (S\$)	983.23	983.23
Total Parts (S\$)	3,219.67	3,219.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX TAILLAMPS, REAR NUMBER PLATE, TAILGATE, STRAIGHTEN, KNOCK & REPAIR TAILGATE LH LOWER MEMBER, RH TAILLAMP PANEL, TAILGATE LOWER PANEL & REALIGN THE SAME	New	700.00	550.00
2	REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	New	60.00	60.00
3	PUTTY & RESPRAY ON TAILLAMP PANELS, REAR NUMBER PLATE PANEL, TAILGATE, TAILGATE LOWER PANEL & REAR AFFECTED AREAS	New	600.00	500.00
Gross Labour Cost (S\$)			1,360.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >